

HOME SAFETY ASSESSMENT REPORT · SAMPLE REPORT

Every risk found. Every fix *prioritized*.

- Every hazard ranked by safety impact per dollar, so the first dollar counts
- Every finding recorded on site and checked against a national standard
- Funding programs matched to the modifications that qualify
- A phased plan, so nothing has to happen all at once

PREPARED FOR

Margaret Smith

ASSESSMENT DATE

September 14, 2026

PROPERTY

123 Sample Street SW, Calgary, AB

ASSESSOR

Carl Christie, SHSS, RHFAC Professional

SHSS Designated

RHFAC Professional

143 checkpoints inspected

Sample report, shown in full so you can see the format, the method and the level of detail. The findings, the measurements and the costs are real and were recorded during an assessment of an occupied Calgary home. The occupant's name and the street address have been changed for legal reasons.

The short version.

Margaret Smith · 123 Sample Street SW · assessed September 14, 2026. Every figure on this page is carried in full detail through the rest of the report.

112

FINDINGS

41

HIGH PRIORITY

\$1,635–\$7,030

PHASE 1, THIS MONTH

\$7,985–\$26,570

ALL 112 FINDINGS

Start here — five fixes that buy the most safety per dollar

All five together: \$35–\$250, and none of them needs a contractor.

52	Cleaning chemicals are stored under the kitchen sink, unsecured	Alzheimer's & Dementia · \$10–\$50
53	Prescription medication is kept loose on the kitchen counter	Alzheimer's & Dementia · \$0–\$70
99	No emergency contact information posted in the home	Personal Safety · \$0–\$20
101	Medication routine may need assistance	Personal Safety · \$0–\$40
14	The non-slip tub mat is worn out	Bathroom Safety · \$25–\$70

It does not have to happen all at once

Everything in this report is grouped into three phases — this month, within three months, and within six to twelve months — with a cost total at each phase. Phase 1 comes to \$1,635–\$7,030 and needs a trade for only 7 of its 61 items. A further 28 checkpoints passed and need no action at all. Several government programs can offset the larger work; those are matched to specific findings in Section 08.

Questions before the family decides?

Carl Christie, SHSS, RHFAC Professional · info@novoseniorsafety.com · novoseniorsafety.com

01 · WHAT THIS REPORT IS

What this covers, and what it does not.

This report is

- A room-by-room survey of 143 checkpoints across all 12 safety categories, producing 112 findings
- A measured record, with dimensions and light levels recorded on site wherever a number decides the answer
- A comparison against CSA/ASC B652:23 *Accessible dwellings* where that standard speaks to the item, and a stated best-practice judgment where it does not
- A costed, phased plan that sequences the work by safety gained per dollar

This report is not

- A clinical or occupational therapy assessment. It describes the home, not Margaret's medical or functional needs
- A building code inspection or a certification of compliance with any standard, B652:23 included
- An engineering or structural report
- A contractor's quote. Estimates are planning figures — see Section 09

Contents

02	Executive summary	Findings, priorities, and what it costs
03	Who this report is for	Occupant, mobility and household context
04	Where the findings were recorded	Every finding mapped to the room it belongs to
05	Findings by category	Every finding, what was seen, what is recommended
06	Where the next dollar goes	Findings ranked by safety gained per dollar spent
07	Two-year capital plan	Three phases, reconciled to the total above
08	Funding programs	Matched to the findings that qualify
09	What the estimates are based on	Pricing basis, and what is not included
10	Recommended contractors	Vetted trades, no referral fees
11	What happens next	Sequence, funding and reassessment
12	Credentials and methodology	Who did this work and with what

02 · EXECUTIVE SUMMARY

Where the next dollar should go.

This report presents the findings of a home safety assessment carried out on September 14, 2026 at 123 Sample Street SW, Calgary, AB. Margaret is 60, owns the home and has lived in it for 30 years. The assessment was prompted by a change in mobility, and by one fall in the bathroom in the past twelve months — a trip on a rug that caused a sprain needing care.

You do not have to manage all of this at once. The findings are ordered so the smallest, fastest steps happen first — see Section 11 for the order to tackle the work and a recommended reassessment date.

112

TOTAL FINDINGS

41

HIGH PRIORITY

36

MEDIUM PRIORITY

35

LOW PRIORITY

The five findings that matter most

Ranked by hazard severity alone — the risks with the largest consequence if nothing changes, whatever they cost. Where severity is equal, the more substantial piece of work is listed first.

2	No handrail on either side of the front steps	Entrances & Exterior · \$500–\$1,100
51	The stove can be turned on and left on	Alzheimer's & Dementia · \$80–\$450
50	The front and back doors have nothing to prevent an unnoticed exit	Alzheimer's & Dementia · \$120–\$340
54	A hunting rifle is stored in the hall closet	Alzheimer's & Dementia · \$0–\$300
85	No carbon monoxide alarm anywhere in the home	Fire Safety · \$90–\$250

WHAT IT COSTS	LOW	HIGH
The 41 high-priority fixes	\$3,735	\$12,480
Phase 1 — this month	\$1,635	\$7,030
Phase 2 — within 3 months	\$5,870	\$17,690
Phase 3 — within 6–12 months	\$480	\$1,850
All 112 findings	\$7,985	\$26,570

Every figure on this page is the sum of the itemized estimates in Section 05. The three phase totals add to the full total exactly; no finding sits outside a phase.

03 · WHO THIS REPORT IS FOR

Who this report is for.

OCCUPANT	Margaret Smith, age 60
ADDRESS	123 Sample Street SW, Calgary, AB
HOME TYPE	Single-family detached, three levels. Owned, lived in for 30 years.
LIVING SITUATION	Shares the home. A caregiver attends.
MOBILITY	No walking aid in regular use — no walker, rollator or wheelchair in the home. A cane is kept at the bedside and used occasionally. Independent on stairs using the railing, and rises from a chair with an arm push-off.
FALLS HISTORY	One fall in the past twelve months, in the bathroom — tripped on a rug, sprain needing care. Near misses reported about monthly.
VISION AND HEARING	Mild vision impairment. Mild hearing loss, no aid — which is why the smoke and carbon monoxide alarms in Section 05 are specified as interconnected.
COGNITIVE CONTEXT	Memory changes under assessment, no diagnosis yet. Occasional disorientation in the evening and one instance of leaving the house unnoticed — which is why the Alzheimer's & Dementia category was opened and every checkpoint in it inspected.
REASON FOR ASSESSMENT	A change in mobility, and a concern about continuing to live independently.
WHAT THE FAMILY ASKED FOR	Safety and convenience throughout the home, and confidence moving from room to room.
ASSESSMENT SCOPE	12 safety categories, 143 checkpoints.

04 · WHERE THE FINDINGS WERE RECORDED

Every finding, mapped to where it was recorded.

The numbered markers below correspond to the findings in Section 05, grouped by the part of the home each was recorded in. A scaled floor plan of the property accompanies this report.

Exterior Route and Entry

10 findings

1 2 3 4 6 7 23 30
36 92

Entryway and Vestibule

5 findings

5 8 26 27 37

Bathroom

12 findings

9 10 11 12 13 14 15 16
17 18 19 109

Bedroom

10 findings

20 24 29 39 42 45 46 49
97 105

Closets and Storage

4 findings

21 32 43 44

General Home Safety

13 findings

22 85 86 87 88 89 91 93
94 95 96 99 104

Laundry

6 findings

25 31 33 34 35 38

Living and Dining Areas

6 findings

28 40 41 47 48 98

Cognitive Safety

14 findings

50 51 52 53 54 55 56 57
58 59 60 61 62 63

Kitchen

10 findings

64 65 66 67 68 69 70 71
72 90

Interior Stairs

9 findings

73 74 75 77 78 79 81 82
83

Hallways and Circulation

3 findings

76 80 84

Personal Safety

4 findings

100 101 102 103

Crime Prevention

6 findings

106 107 108 110 111 112

Room grouping follows the rooms walked on site. A finding recorded in one room may be reported in a different category in Section 05 — bathroom lighting, for example, is reported under Lighting & Electrical.

05 · FINDINGS BY CATEGORY

112 findings across 12 categories.

Every checkpoint on the assessment scope was inspected. Each finding below carries what was observed, what is recommended, and the standard or best-practice basis for calling it a finding. Costs are planning estimates — Section 09 explains how they were built.

How the standard is applied here

CSA/ASC B652:23 is written for new dwellings and for alterations built to be accessible. It does not require an existing 30-year-old house to be brought up to its numbers, and nothing in this report says otherwise. Where a clause is quoted, it is quoted as the target a fix should aim at — the figure a contractor should build to when the work is done anyway. Findings with no clause reference are stated best practice and are labelled that way.

Entrances & Exterior

8 FINDINGS

1 Front steps are uneven and cracked, with no handrail TRADE HIGH \$400–\$1,200

Have the step treads levelled and the cracked concrete repaired so every riser is the same height. Do this at the same time as the handrail work in Finding 2 — one trade, one visit.

OBSERVED Risers measurably inconsistent in height; surface cracked and uneven; no handrail on either side.

STANDARD B652 §5.2.1 (via §4.6.3) — Firm, stable, no cracks > 13mm or vertical lift > 6mm.

2 No handrail on either side of the front steps TRADE HIGH \$500–\$1,100

Install handrails on both sides of the flight, 860–1070 mm above the tread nosing, each running the full length with a 300 mm horizontal extension past the top and bottom risers.

OBSERVED Neither side of the flight has a rail of any kind.

STANDARD B652 §5.6.3 — Sturdy, easy to grasp, both sides for any step over single.

3 Front step treads are cracked and worn TRADE HIGH \$300–\$900

Repair or resurface the treads so the walking surface is continuous, level and slip-resistant wet or dry.

OBSERVED Treads cracked, uneven, and without a rail to steady a slip.

STANDARD B652 §5.6.1 — Even height, no broken or rotted treads, slip-resistant.

4

The front doorway is 750 mm clear — too narrow for a walker or wheelchair

TRADE
HIGH
\$80–\$180

Fit swing-clear offset hinges, which recover 40–50 mm at no structural cost. Widening the opening is the full fix if a wheelchair is ever needed.

LONGER-TERM OPTION
Widen the opening to 850 mm — \$1,800–\$2,500

OBSERVED
Measured 750 mm clear. A walker needs 800 mm; a wheelchair route wants 850 mm.

STANDARD
B652 §5.7.1 — Min 860mm clear opening.

5

Nowhere safe to sit to change shoes

BUY
HIGH
\$120–\$350

Place a stable bench or chair with arms in the entry, 430–485 mm seat height. Sitting on a stair to change shoes is a fall waiting for a distraction.

OBSERVED
The only place to sit is a step on the stairs.

BASIS
Best practice — no CSA/ASC B652:23 requirement applies to this item.

6

Garbage and recycling can only be reached down the unsafe front steps

FAMILY
MEDIUM
No cost

Relocate the bins to a route that avoids the steps, or arrange for the bins to be brought out. Carrying anything down these steps, with no rail, is the highest-consequence routine trip in the home.

LOWER PRIORITY IN THIS CATEGORY — 2 ITEMS

- 7

The front door has a round knob

\$60–\$180
- Replace the knob set with a lever handle. A lever opens with a forearm or a closed fist when hands are full or arthritic.
- 8

A shoe rack sits in the entry pathway

\$0–\$60
- Move the rack out of the walking line, against the wall clear of the door swing.

Bathroom Safety11 FINDINGS

9

No seat in the tub or shower

OT FIRST
HIGH
\$150–\$450

Fit a transfer bench, 400 mm minimum width with the seat 435–485 mm above the floor. This item is likely AADL-eligible — see Section 8; an occupational therapist authorizes it.

OBSERVED
No seat present.

STANDARD
B652 §5.9.13.8 — Min 400mm wide, top 435–485mm above floor, not spring-loaded, rated to 1.3kN load, smooth non-slip surface.

10	No hand-held shower head	TRADE	HIGH	\$120–\$350
	Install a hand-held shower on a slide bar with a 1.5 m hose. It is what makes a seated wash possible, and it pairs with the bench in Finding 9.			
	OBSERVED Fixed head only.			
	STANDARD B652 §5.9.13.4 — Handheld type, hose min 1800mm, adjustable 860–2030mm above floor, usable in a fixed position.			
11	All bathroom faucets have knob handles	TRADE	HIGH	\$250–\$700
	Replace with single-lever mixers at the sink and tub.			
	OBSERVED Knob handles throughout.			
	STANDARD B652 §4.5.5 — Lever rather than knob (operable with a closed fist).			
12	No grab bar at the toilet, and no wall backing to mount one	TRADE	MEDIUM	\$250–\$600
	Add solid blocking inside the wall, then mount a load-rated grab bar beside the toilet. Blocking has to go in first — a bar fixed to drywall alone will pull out under the load it is there to take.			
13	No grab bars at the tub	TRADE	MEDIUM	\$250–\$600
	Install two load-rated bars: one horizontal inside the tub, one vertical at the entry. Same blocking requirement as Finding 12.			
14	The non-slip tub mat is worn out	BUY	MEDIUM	\$25–\$70
	Replace with a full-length rubber-backed mat, or apply adhesive non-slip strips to the tub floor.			
15	The toilet sits at 365 mm — too low to rise from safely	OT FIRST	MEDIUM	\$80–\$180
	Fit a raised toilet seat to bring the height to 430–485 mm, or replace with a comfort-height toilet. The raised seat has to be the model that bolts to the bowl, not one that sits loose on the rim.			
16	No anti-scald valve at the tub or shower	TRADE	MEDIUM	\$300–\$800
	Fit a thermostatic mixing valve limiting delivered water to 49 °C. At 60 °C, a scald takes about five seconds on older skin.			
17	The bathroom floor has holes in the surface	TRADE	MEDIUM	\$400–\$1,400
	Replace the floor covering with a slip-resistant sheet vinyl. The holes are a trip hazard and the surface can no longer be cleaned properly.			

LOWER PRIORITY IN THIS CATEGORY – 2 ITEMS

18	Bathroom lighting is good	No cost
	Light level is good. Add a plug-in night light at the door so the main light is not needed at 3am.	
19	The bathroom is warm enough	No cost
	Temperature is comfortable. Keep a wall or fan heater out of the room — a portable heater on a bathroom floor is a shock hazard.	

- 20 No flashlight at the bedside BUY HIGH **\$20–\$60**
- Put a touch-on flashlight or a plug-in emergency light on the bedside table. In a power failure this is the difference between waiting and walking.

OBSERVED None present.

BASIS Best practice — no CSA/ASC B652:23 requirement applies to this item.

- 21 No usable light inside the closet BUY HIGH **\$25–\$90**
- Fit a battery or rechargeable motion-activated LED closet light.

OBSERVED No fixture; closet interior effectively dark.

STANDARD B652 §5.13 — Light within closet, reachable and working.

- 22 Outlets and switches are original and unserviced TRADE HIGH **\$200–\$900**
- Have an electrician inspect the receptacles and switches through the house and replace any that are loose, discoloured or no longer gripping a plug.

OBSERVED Original devices throughout, no record of inspection.

BASIS Best practice — no CSA/ASC B652:23 requirement applies to this item.

- 23 The front steps are badly lit after dark TRADE MEDIUM **\$150–\$400**
- Upgrade the entry fixture to a 100 W-equivalent LED and add two motion-activated path lights covering the steps.

- 24 Clutter and cords on the bedroom floor BUY MEDIUM **\$20–\$90**
- Clear the floor around the bed and along the route to the door, and route cords along the baseboard under a cord cover.

- 25 The laundry area is too dark to work in TRADE MEDIUM **\$60–\$250**
- Add an LED ceiling fixture or a plug-in LED work light over the machines.

LOWER PRIORITY IN THIS CATEGORY — 4 ITEMS

- 26 Entry lighting is adequate but not switched from both ends **\$30–\$90**
- Add a motion sensor at the entry so the light is on before the door opens, rather than reaching for a switch in the dark.

- 27 Cords are clear of the entry route **No cost**
- Keep the route clear as devices are added — a phone charger or a lamp cord run across this floor would undo it. A single wall outlet near the bench in Finding 5 removes the temptation.

- 28 Living area lighting is good **No cost**
- Daytime light is good. Add a lamp on a timer or a smart plug so the room is never entered dark in the evening.

Lamp is within reach. Fit a touch or rocker switch so it does not need a twist of the fingers in the dark.

Flooring & Trip Hazards

9 FINDINGS

30 The entry threshold is a 150 mm step in itself

TRADE

HIGH

\$250–\$900

Fit an exterior threshold ramp, or rebuild the landing so the step into the house is no more than 13 mm. This is the single change that most improves entering the home carrying anything.

OBSERVED Measured 150 mm — effectively an extra step at the door.

STANDARD B652 §5.7.4 — $\leq 13\text{mm}$; if $> 6\text{mm}$, bevelled at slope $\leq 1:2$.

31 The laundry is down a narrow, poorly lit stairwell

BUY

HIGH

\$0–\$200

Treat this route as the priority it is: the nosing contrast, second handrail and lighting in Finding 77, Finding 74 and Finding 25 all serve this trip. Longer term, a main-floor laundry removes the trip altogether.

OBSERVED Narrow stairwell, low light, and a cramped basement working space.

BASIS Best practice — no CSA/ASC B652:23 requirement applies to this item.

32 Closet floor is covered in stored items

FAMILY

MEDIUM

No cost

Clear the floor. The closet floor is inside the walking route the moment the door is open.

33 Stacked washer and dryer with controls at the back

TRADE

MEDIUM

\$0–\$180

Unstack the units if the space allows, or add a sturdy platform and a reaching aid. Reaching over and behind a machine at height is a balance hazard.

34 Appliance control markings cannot be read

BUY

MEDIUM

\$15–\$40

Add tactile marker dots at the settings in daily use, and fix the area lighting in Finding 25.

35 Items stored across the laundry floor

FAMILY

MEDIUM

No cost

Clear the floor around the machines. A basement laundry floor is walked on with a full basket and no free hand.

LOWER PRIORITY IN THIS CATEGORY — 3 ITEMS

36 The doormat is torn and lifting

\$30–\$80

Replace with a low-profile rubber-backed mat, or remove it. A torn mat catches a toe on the way in.

37 Entry rugs are unsecured

\$20–\$60

Fit a non-slip pad under each rug and tape the edges, or remove them. They are lying flat today; that changes the first time a wheel or a toe catches an edge.

38 Laundry supplies are stored within reach

No cost

Storage height is right. Decant heavy detergent jugs into a smaller bottle so nothing over a few pounds is lifted at arm's length.

- 39 The electric blanket is a fire hazard BUY HIGH **\$60–\$200**
- Replace it. Older electric blankets with worn wiring are one of the more common bedroom fire sources, and this one is past its service life.

OBSERVED Blanket in use, wiring and condition beyond safe service.

BASIS Best practice — no CSA/ASC B652:23 requirement applies to this item.

- 40 An old chair is being used for balance and is not sound BUY MEDIUM **\$0–\$300**
- Remove it from service. Furniture that is grabbed for balance has to hold a person's full weight, and this one does not.

- 41 Window blind cords hang loose BUY MEDIUM **\$20–\$200**
- Fit cord cleats or convert to cordless blinds. A loose cord is both a strangulation and a snag hazard.

- 42 Bedroom windows are old and stiff to operate TRADE MEDIUM **\$150–\$400**
- Service or replace the windows. A window that has to be forced is both an exit problem and a balance problem.

- 43 Closet shelving is disordered and overloaded BUY MEDIUM **\$0–\$120**
- Sort the closet so daily-use items sit between hip and shoulder height, and nothing has to be pulled down blind from above.

- 44 The closet door sticks and pulls hard TRADE MEDIUM **\$80–\$300**
- Plane or re-hang the door, or convert to a bypass or bi-fold that runs freely. A door that gives way suddenly takes balance with it.

LOWER PRIORITY IN THIS CATEGORY — 5 ITEMS

- 45 Bed height is slightly low for a safe transfer **\$30–\$120**
- Fit bed risers to bring the mattress top to roughly 500 mm — feet flat on the floor with the knees at or just below hip height.

- 46 Dresser drawers are awkward to reach **No cost**
- Move everyday clothing to the middle drawers and rearrange so nothing in daily use is at floor level or above shoulder height.

- 47 Pathways through the living area are clear **No cost**
- Route is clear. Keep this line to the bathroom furniture-free — it is the route walked at night.

- 48 No chair in the living area suited to standing up from **\$250–\$900**
- Add one chair with firm arms and a 430–485 mm seat height as the everyday seat. This is the cheapest fall prevention in the room.

- 49 The path from the bed to the bathroom is clear **No cost**

Alzheimer's & Dementia

14 FINDINGS

50 The front and back doors have nothing to prevent an unnoticed exit **TRADE** **HIGH** **\$120–\$340**

Fit a secondary lock high on the door frame, above eye level, on both exterior doors. Pair it with the door chime in Finding 55 so a caregiver hears the door before anyone is outside.

OBSERVED Single thumb-turn deadbolt on each exterior door, reachable and operable without a key.

BASIS Best practice — no CSA/ASC B652:23 requirement applies to this item.

51 The stove can be turned on and left on **TRADE** **HIGH** **\$80–\$450**

Have an automatic stove shut-off fitted, or remove the control knobs and keep them in a drawer. A shut-off is the better answer where cooking is still part of the daily routine.

OBSERVED Front-mounted knobs, no shut-off device, one burner found switched to low and unattended.

BASIS Best practice — no CSA/ASC B652:23 requirement applies to this item.

52 Cleaning chemicals are stored under the kitchen sink, unsecured **BUY** **HIGH** **\$10–\$50**

Move bleach, drain cleaner and degreaser to a high cupboard, or fit a latch to the sink cupboard. Decanted product in unlabelled bottles should be discarded rather than relabelled.

OBSERVED Bleach, drain cleaner and two unlabelled decanted bottles, under the sink, no latch.

BASIS Best practice — no CSA/ASC B652:23 requirement applies to this item.

53 Prescription medication is kept loose on the kitchen counter **BUY** **HIGH** **\$0–\$70**

Move all prescriptions to a locked box and dispense a week at a time, or ask the pharmacy for blister packs dated by day. Blister packs cost nothing and remove the counting.

OBSERVED Four prescription bottles and a pill cutter, open shelf beside the kettle.

BASIS Best practice — no CSA/ASC B652:23 requirement applies to this item.

54 A hunting rifle is stored in the hall closet **BUY** **HIGH** **\$0–\$300**

Remove the rifle and the ammunition from the home. Where removal is refused, a locked cabinet with ammunition stored separately is the minimum, and the key does not stay in the house.

OBSERVED Unlocked closet, rifle in a soft case, box of ammunition on the shelf above.

BASIS Best practice — no CSA/ASC B652:23 requirement applies to this item.

55 No door chime or alarm on either exterior door **BUY** **MEDIUM** **\$40–\$120**

Add a battery door chime to the front and back doors. A caregiver in another room then hears the door open without having to watch it.

56	The basement stairwell has no gate at the top	BUY	MEDIUM	\$90–\$220
	Fit a pressure-mounted safety gate at the head of the basement stairs. The stairwell is unlit and the door stands open through the day.			
57	Knives are stored in an open block on the counter	BUY	MEDIUM	\$15–\$60
	Move the knife block into a drawer with a simple latch. Everything else on the counter can stay.			
58	The route from the bedroom to the bathroom is dark	BUY	MEDIUM	\$30–\$90
	Fit three motion-activated night-lights along the hallway. This is the single change that most reduces a night-time fall, and it works whether or not memory is the issue.			
59	Plastic bags are stored in a low kitchen drawer	FAMILY	MEDIUM	No cost
	Move the bag stash to a high cupboard, and keep dry-cleaner bags out of the house altogether.			

LOWER PRIORITY IN THIS CATEGORY – 4 ITEMS

60	The patio door is full-height glass with no marking			\$20–\$60
	Apply eye-level decals or a frosted band across the glass at 1500 mm so the door reads as a surface.			
61	No wayfinding cue to the bathroom from the bedroom			\$0–\$40
	Put a simple picture sign on the bathroom door and leave the door open when the room is not in use. Pair it with the night lighting in Finding 58.			
62	Decorative wax fruit sits in the dining room bowl			No cost
	Remove the wax fruit and the two food-shaped fridge magnets. Replace with real fruit or nothing.			
63	No daily routine posted anywhere in the home			\$20–\$60
	Put a large-print week-to-view board in the kitchen showing the day, the date and what is planned. It answers the question without anyone having to be asked.			

Kitchen Safety

9 FINDINGS

64	Everyday items are stored at 1727 mm — above shoulder height	BUY	HIGH	\$0–\$120
	Move daily-use items to between hip and shoulder height. Reaching overhead on a stool is how kitchen falls happen.			
	OBSERVED Measured 1727 mm to the shelf in daily use.			
	STANDARD B652 §5.10.8 — Closed overhead storage max 1100mm above floor (300mm deep) or drop-down mechanism; drawer-style storage under counters.			
65	An overturned bucket is being used as a step stool	BUY	HIGH	\$60–\$150
	Replace with a stable step stool with a handhold and non-slip feet, and only after the reorganisation in Finding 64 has removed most of the need for it.			
	OBSERVED No step stool in the home; a bucket is used instead.			
	BASIS Best practice — no CSA/ASC B652:23 requirement applies to this item.			

66 Stove controls are at the back, behind the burners FAMILY HIGH **No cost**

Reaching across a live burner is the hazard. A front-control range is the full fix; in the meantime, use the back burners only and keep sleeves clear.

LONGER-TERM OPTION Replace with a front-control range — **\$1,200–\$2,200**

OBSERVED All controls mounted at the rear of the cooktop.

STANDARD B652 §5.10.9.3 — Controls located in front of or beside the hot surface, automatic ignition on gas burners.

67 No anti-scald protection at the kitchen sink TRADE HIGH **\$80–\$400**

Fit a thermostatic mixing valve, or lower the water heater setting to 49 °C. See Finding 93 — one change at the tank covers both.

OBSERVED No anti-scald device at this sink.

BASIS Best practice — no CSA/ASC B652:23 requirement applies to this item.

68 The range has no automatic shut-off TRADE MEDIUM **\$200–\$800**

Fit an aftermarket stove shut-off timer, or a motion-sensing shut-off that cuts power when no one is in the kitchen.

69 Kitchen faucet has a knob handle TRADE MEDIUM **\$150–\$450**

Replace with a single lever faucet. A lever works with a wrist or a forearm when grip fails or hands are full.

70 The microwave sits in a corner at an awkward reach BUY MEDIUM **\$0–\$120**

Relocate it to a clear counter run at or below shoulder height. Lifting hot liquid at an angle is how kitchen burns happen.

LOWER PRIORITY IN THIS CATEGORY — 2 ITEMS

71 Kitchen task lighting is good **No cost**

Light levels are above the target. Keep the under-cabinet lamps replaced as they fail rather than working by the ceiling light alone.

72 Kitchen floor is sound **No cost**

Floor is sound. Wipe spills straight away — hardwood gives no warning once wet, and this is the room where spills happen.

- 73 Neither handrail extends past the top or bottom step TRADE HIGH **\$120–\$300**
- Fit 300 mm horizontal return extensions at both ends of each rail. This is the part of the rail that tells a hand the stairs have ended.
- OBSERVED** Rails stop level with the first and last riser.
- STANDARD** B652 §5.6.3 — Extends min 300mm past top and bottom.
- 74 Stair nosings have no contrast strip BUY HIGH **\$60–\$180**
- Apply contrasting non-slip nosing tape to the front edge of every tread, on both flights.
- OBSERVED** No visual contrast at any tread edge.
- STANDARD** B652 §5.6.2 — Horizontal contrast strip 50 (+/-10)mm deep at the leading edge of each tread, luminance-contrasted with tread and riser, slip-resistant.
- 75 The top and bottom steps are not highlighted BUY HIGH **\$40–\$120**
- Mark the first and last tread of each flight in a strongly contrasting colour. These two steps are where most stair falls begin.
- OBSERVED** No highlighting at either end of either flight.
- STANDARD** B652 §5.6.2 — Contrast strip present at leading edge of first and last step per nosing requirement.
- 76 The hallway is 914 mm wide BUY HIGH **\$0–\$100**
- Keep the full width clear of furniture and storage. Widening is not practical here; protecting the width that exists is.
- OBSERVED** Measured 914 mm. An interior route in an altered dwelling is meant to be 1000 mm.
- STANDARD** B652 §5.8.1 — Min 1000mm for existing home alterations (1200mm new construction).
- 77 Interior stairs have a handrail on one side only TRADE MEDIUM **\$300–\$650**
- Install a second handrail on the open side, running the full flight, and extend both rails 300 mm horizontally past the top and bottom risers.
- 78 Stair riser heights vary from 150 mm to 175 mm TRADE MEDIUM **\$400–\$1,500**
- Have a carpenter shim the treads to a uniform rise. Until that is done, mark the odd riser with contrasting tape so it is visible on the way down.

LOWER PRIORITY IN THIS CATEGORY – 6 ITEMS

- 79 Items are being stored on the stairs No cost
- Clear the stairs and keep them clear. Nothing should be stored on a tread, even briefly.
- 80 No night lighting along the hallway **\$40–\$110**

Install three motion-activated LED night lights — bedroom, hallway, bathroom entrance — so the route to the bathroom is never walked in the dark.

- | | | |
|----|---|-------------|
| 81 | Handrail height measures 865 mm
Height is correct. Match the second rail in Finding 77 to this height so both hands find the rail at the same place. | No cost |
| 82 | Handrail is graspable
Profile is fine. Keep the rail clear of coats and bags — anything hung on it takes the handhold away. | No cost |
| 83 | Stair carpet is worn in places
Re-secure or replace the worn sections. Sound overall — this is maintenance, not a repair. | \$100–\$500 |
| 84 | Hallway carpet is secure
Carpet is sound. Check the edges once a season; a lifting edge in a 914 mm hallway has nowhere to be stepped around. | No cost |

Fire Safety

7 FINDINGS

- | | | | |
|---|---|----------|------------|
| 85 | No carbon monoxide alarm anywhere in the home | BUY HIGH | \$90–\$250 |
| Install CO alarms on every level, and within 5 m of each sleeping room. With fuel-burning appliances in the house this is not optional. | | | |

OBSERVED None present on any level.

STANDARD NBC(AE) Subsection 9.33.4 — On every level, near sleeping areas.

- | | | | |
|--|----------------------------------|----------|------------|
| 86 | No fire extinguisher in the home | BUY HIGH | \$60–\$160 |
| Mount a 2A:10B:C extinguisher in the kitchen within easy reach of the exit, and a second one near the furnace. | | | |

OBSERVED None present.

BASIS Best practice — no CSA/ASC B652:23 requirement applies to this item.

- | | | | |
|---|--|--------------|-------------|
| 87 | One smoke alarm for a three-level home | TRADE MEDIUM | \$150–\$450 |
| Install interconnected smoke alarms on every level and outside the sleeping area — so when one sounds, they all sound. Five to six units for this home. | | | |

- | | | | |
|--|--|--------------|-------------|
| 88 | The chimney has not been inspected in 16 years | TRADE MEDIUM | \$200–\$500 |
| Book a WETT-certified chimney inspection and sweep before the fireplace is used this winter. | | | |

LOWER PRIORITY IN THIS CATEGORY — 3 ITEMS

- | | | |
|----|---|---------|
| 89 | Space heater clearance is 50 cm
Keep the 50 cm clear on all sides, never run it on an extension cord, and switch it off when leaving the room. | No cost |
| 90 | Flammable items stored 900 mm from the range
Move them further from the cooktop, or to a lower cabinet away from the range. | No cost |

91	Flammable storage is kept outside the home	No cost
	Correct storage. Keep it that way — no fuel, propane or paint thinner inside the house or attached garage.	

Technology & Emergency

7 FINDINGS

- 92 The doorbell does not work BUY HIGH \$40–\$120

Replace with a wireless doorbell with a loud chime and a visual flash unit inside. Choose one with a second chime on the lower level.

OBSERVED Existing bell does not ring.

STANDARD B652 §5.7.10 — Mounted at reachable height, visible, working.

- 93 Water heater temperature has not been checked or limited BUY HIGH \$0–\$120

Set the tank to 49 °C and confirm with a thermometer at the tap. Lowering the tank is the first step and the cheapest one; it does not replace the mixing valves in Finding 67 and Finding 16, which hold the temperature at the fixture even when the tank is later turned back up.

OBSERVED No setting recorded and no anti-scald protection downstream.

STANDARD B652 §5.9.13.4, §5.9.13.7, §5.9.14.3, §5.12.7 — B652 requires point-of-use mixing valves limiting temperature to max 49°C at shower head, shower controls, bathtub, and laundry sink (not a whole-house tank-setting requirement).

- 94 No GFCI protection in the wet areas TRADE HIGH \$250–\$700

Have an electrician fit GFCI receptacles at the kitchen, bathroom and laundry outlets.

OBSERVED No GFCI devices found at the wet-area outlets.

STANDARD CEC Rule 26–700(11) — All bathroom, kitchen, and exterior receptacles GFCI-protected, tested.

- 95 No emergency exit plan has been discussed FAMILY HIGH No cost

Agree two ways out of every level, a meeting point outside, and who calls who. Write it down and put a copy by the phone. It costs nothing.

OBSERVED Nothing discussed among the family.

BASIS Best practice — no CSA/ASC B652:23 requirement applies to this item.

- 96 No way to summon help from the floor BUY HIGH \$50–\$120

A monitored pendant or watch with fall detection is the single highest-value item in this report. It is the only measure here that summons help when a fall happens away from a phone, and the only one that works when the person cannot get back up. Worn, not left on a table.

OBSERVED No personal emergency response system in the home, and nothing that could be reached from the floor in any room. Raised with the family during the visit.

BASIS Best practice — no CSA/ASC B652:23 requirement applies to this item.

- 97 No telephone within reach of the bed BUY MEDIUM **\$40–\$150**
- Put a cordless handset or a charged mobile on the bedside table every night. A phone across the room is no phone at all at three in the morning.

LOWER PRIORITY IN THIS CATEGORY – 1 ITEM

- 98 The telephone is not reachable from a likely fall location \$40–\$150
- Move the phone within reach of the main seating, or add a cordless handset on the floor level where a fall is most likely. See also Finding 96 – a pendant does this job better.

Personal Safety

7 FINDINGS

- 99 No emergency contact information posted in the home BUY HIGH **\$0–\$20**
- Post one card by the main phone and one on the refrigerator: name, address, family contacts, doctor, medications, allergies. First responders look for exactly this.

OBSERVED Nothing posted anywhere in the home.

BASIS Best practice – no CSA/ASC B652:23 requirement applies to this item.

- 100 Socks are worn indoors all day BUY HIGH **\$40–\$120**
- Switch to a firm, non-slip indoor shoe or slipper with a back and a fastening. Socks on hardwood is the most common indoor slip in this age group, and the cheapest one to remove.

OBSERVED Stocking feet indoors throughout the visit.

BASIS Best practice – no CSA/ASC B652:23 requirement applies to this item.

- 101 Medication routine may need assistance BUY HIGH **\$0–\$40**
- Set up a weekly pill organiser, and ask the pharmacy about blister packing – most Calgary pharmacies do it at no charge. A family member checks it once a week.

OBSERVED No organiser or system in place; assistance likely needed.

BASIS Best practice – no CSA/ASC B652:23 requirement applies to this item.

- 102 No first aid supplies in the home BUY HIGH **\$30–\$80**
- Keep one stocked first aid kit in a known location and tell the family where it is.

OBSERVED None present.

BASIS Best practice – no CSA/ASC B652:23 requirement applies to this item.

- 103 The bedside cane is not fitted, and its tip is worn OT FIRST MEDIUM **\$15–\$60**
- Set the cane so the handgrip sits at the wrist crease with the arm relaxed, and replace the rubber tip. A worn tip on a hard floor is the failure that puts the cane out from under the hand.

LOWER PRIORITY IN THIS CATEGORY – 2 ITEMS

- 104** Medication storage could be better organised **\$20–\$120**
Move medications to one locked or latched cabinet out of the bathroom — heat and humidity degrade them — and use a weekly organiser. See also Finding 101.
- 105** The cane is kept within reach of the bed **No cost**
Good habit. Keep the cane on the same side every night — a cane on the wrong side is worse than no cane at all.

Crime Prevention

7 FINDINGS

- 106** No door viewer usable from a lowered position TRADE HIGH **\$40–\$250**

Fit a wide-angle viewer at 1200 mm, or a video doorbell with an indoor screen. Pairs with the doorbell replacement in Finding 92.

OBSERVED No viewer at any height.

STANDARD B652 §5.7.8 — Dual door viewers at 1500–1700 mm and 1000–1200 mm above the finished floor, or a video doorbell with an interior view.

- 107** The patio sliding door has no secondary lock BUY HIGH **\$30–\$90**

Fit a security bar in the track and an anti-lift device at the head of the door.

OBSERVED Factory latch only; door lifts in its track.

BASIS Best practice — no CSA/ASC B652:23 requirement applies to this item.

- 108** Ground-level windows have no locks TRADE HIGH **\$60–\$250**

Fit key or thumb locks on the accessible ground-level windows.

OBSERVED No locks fitted on the ground-level windows.

BASIS Best practice — no CSA/ASC B652:23 requirement applies to this item.

- 109** The bathroom door swings inward, with no lock and fixed hinge pins TRADE MEDIUM **\$150–\$400**

Rehang the door to swing outward, or fit lift-off hinges. If someone falls against the inside of an inward door, no one can get in.

- 110** The entry deadbolt is fixed with 19 mm screws BUY MEDIUM **\$10–\$60**

Replace the strike plate screws with 75 mm screws that reach the wall framing. Ten minutes, and it is the difference between a door that holds and one that does not.

- 111** A spare key is kept under the doormat FAMILY MEDIUM **No cost**

Remove it today. Give the spare to a trusted neighbour or family member, or fit a keypad lock so no key needs hiding.

112 The back entrance is well lit

No cost

Light level is good. Put the backlight on the same motion sensor as the front so neither is left to a switch.

What passed

28 checkpoints were inspected and need no action. Nothing on this list belongs in a phase, a budget or a contractor's quote — it is here so you know it was looked at, and so the next assessment has a baseline to measure against.

- **The front walkway is wide enough** — No width restriction along the route to the door.
- **No food hoarding or spoiled food found** — Refrigerator and freezer in normal order; nothing past date.
- **Over-the-counter medication is stored in a high cupboard** — Second shelf, above shoulder height, out of the daily routine.
- **Alcohol is stored out of sight in a low cabinet** — Two bottles, cabinet closed, no daily access.
- **Lighting is even through the main living area** — No deep shadows or bright pools between the kitchen, dining and living rooms.
- **No mirror causes distress** — Two mirrors in the home, both reported as untroubling.
- **No distressing artwork in any room** — Landscapes and family photographs throughout.
- **The bathroom door is left open when the room is not in use** — Household habit already in place.
- **An audio monitor links the bedroom to the family room** — Monitor in place and working, tested on site.
- **Unused outlets are covered** — Childproof plugs already fitted in the living room and bedroom.
- **No exposed hot water pipes within reach** — Basement pipes insulated; nothing exposed on the main floor.
- **The back yard is fenced with a latching gate** — Six-foot fence on three sides, self-latching gate, latch at adult height.
- **A spare key is held by the daughter, off site** — Key held off site, not hidden outdoors.
- **The storage room is kept locked** — Door locked, key kept by the family.
- **Vehicle keys are kept in the daughter's bag, not in the home** — No vehicle keys found in the house; the car is no longer driven.
- **Financial paperwork is stored in a locked filing drawer** — Cabinet locked; cheque book and statements inside.
- **Valuables and mail are not visible from outside** — Nothing of value visible through the ground-level windows.
- **Floor transitions in the entry are flush** — Tile-to-hardwood transition level and sound.
- **Stair lighting is good at both ends** — Measured 55 lx at the top and bottom of the flight.
- **The hallway is clear of clutter** — Full width clear at the time of the visit.
- **Doorway thresholds are flush** — Smooth transitions room to room.
- **Walls show marks where they have been used for balance** — Hand marks along the wall, confirmed on interview as balance support during an earlier period.
- **Living area floor is slip-resistant** — Hardwood in sound condition, no slipping underfoot.
- **No loose rugs in the living area** — No rugs present.
- **Table edges are rounded** — All accessible edges rounded.
- **Cords are routed safely** — No cords crossing a walking route.
- **Toilet paper is reachable from the seat** — Holder positioned within reach beside the toilet.
- **No loose rugs in the bedroom** — None present.

06 · WHERE THE NEXT DOLLAR GOES

Ranked by safety gained per dollar spent.

The order below weighs three things together: how much the checkpoint matters to a fall or a fire, how serious the finding was, and what the fix costs. It is the order to spend in when the budget is the constraint rather than the time. The twenty-four highest-return findings are listed; the same ranking drives the phases in Section 07.

How the order is calculated

Return = (checkpoint weight × severity) ÷ √cost. Checkpoint weight is fixed at 1 to 5 before the visit and reflects how much that checkpoint contributes to a fall, a fire or a delayed rescue. Severity is 1 to 5, scored on site. Cost is the midpoint of the estimate in Section 05. The square root is deliberate: it keeps an expensive fix from being buried by a cheap one when the expensive fix removes a far larger risk. Nothing else is weighted in — no judgment is applied after the number is produced.

#	FINDING	CATEGORY	PRIORITY	ESTIMATE
52	Cleaning chemicals are stored under the kitchen sink, unsecured	Alzheimer's & Dementia	High	\$10–\$50
53	Prescription medication is kept loose on the kitchen counter	Alzheimer's & Dementia	High	\$0–\$70
59	Plastic bags are stored in a low kitchen drawer	Alzheimer's & Dementia	Medium	No cost
66	Stove controls are at the back, behind the burners	Kitchen Safety	High	No cost
79	Items are being stored on the stairs	Stairs & Hallways	Low	No cost
95	No emergency exit plan has been discussed	Technology & Emergency	High	No cost
99	No emergency contact information posted in the home	Personal Safety	High	\$0–\$20
101	Medication routine may need assistance	Personal Safety	High	\$0–\$40
14	The non-slip tub mat is worn out	Bathroom Safety	Medium	\$25–\$70
96	No way to summon help from the floor	Technology & Emergency	High	\$50–\$120
110	The entry deadbolt is fixed with 19 mm screws	Crime Prevention	Medium	\$10–\$60

#	FINDING	CATEGORY	PRIORITY	ESTIMATE
57	Knives are stored in an open block on the counter	Alzheimer's & Dementia	Medium	\$15–\$60
103	The bedside cane is not fitted, and its tip is worn	Personal Safety	Medium	\$15–\$60
64	Everyday items are stored at 1727 mm — above shoulder height	Kitchen Safety	High	\$0–\$120
93	Water heater temperature has not been checked or limited	Technology & Emergency	High	\$0–\$120
32	Closet floor is covered in stored items	Flooring & Trip Hazards	Medium	No cost
35	Items stored across the laundry floor	Flooring & Trip Hazards	Medium	No cost
89	Space heater clearance is 50 cm	Fire Safety	Low	No cost
111	A spare key is kept under the doormat	Crime Prevention	Medium	No cost
20	No flashlight at the bedside	Lighting & Electrical	High	\$20–\$60
100	Socks are worn indoors all day	Personal Safety	High	\$40–\$120
24	Clutter and cords on the bedroom floor	Lighting & Electrical	Medium	\$20–\$90
76	The hallway is 914 mm wide	Stairs & Hallways	High	\$0–\$100
58	The route from the bedroom to the bathroom is dark	Alzheimer's & Dementia	Medium	\$30–\$90

07 · TWO-YEAR CAPITAL PLAN

Three phases, and what each one costs.

Every finding sits in exactly one phase. The three phase totals add to the report total — there is nothing outside a phase and nothing counted twice. Items marked **TRADE** need a licensed or skilled trade; everything else is a purchase, a rearrangement or a habit.

Start with the 10 that cost nothing

These need no purchase and no contractor — a decision, a conversation or an afternoon of moving things. Closing them costs nothing and removes 10 of the 112 findings from the list.

- | | |
|--|--|
| 6 Garbage and recycling can only be reached down the unsafe front steps | 66 Stove controls are at the back, behind the burners |
| 32 Closet floor is covered in stored items | 79 Items are being stored on the stairs |
| 35 Items stored across the laundry floor | 89 Space heater clearance is 50 cm |
| 46 Dresser drawers are awkward to reach | 95 No emergency exit plan has been discussed |
| 59 Plastic bags are stored in a low kitchen drawer | 111 A spare key is kept under the doormat |

Then the 19 under \$100

A hardware store and an afternoon. All 19 together come to \$295–\$1,250.

14	The non-slip tub mat is worn out	\$25–\$70	60	The patio door is full-height glass with no marking	\$20–\$60
20	No flashlight at the bedside	\$20–\$60	61	No wayfinding cue to the bathroom from the bedroom	\$0–\$40
21	No usable light inside the closet	\$25–\$90	76	The hallway is 914 mm wide	\$0–\$100
24	Clutter and cords on the bedroom floor	\$20–\$90	99	No emergency contact information posted in the home	\$0–\$20
34	Appliance control markings cannot be read	\$15–\$40	101	Medication routine may need assistance	\$0–\$40
36	The doormat is torn and lifting	\$30–\$80	102	No first aid supplies in the home	\$30–\$80
52	Cleaning chemicals are stored under the kitchen sink, unsecured	\$10–\$50	103	The bedside cane is not fitted, and its tip is worn	\$15–\$60
53	Prescription medication is kept loose on the kitchen counter	\$0–\$70	107	The patio sliding door has no secondary lock	\$30–\$90
57	Knives are stored in an open block on the counter	\$15–\$60	110	The entry deadbolt is fixed with 19 mm screws	\$10–\$60
58	The route from the bedroom to the bathroom is dark	\$30–\$90			

Phase I – this month

\$1,635–\$7,030

Low-cost, high-return work. Most of it is an afternoon, a hardware store and a family member. 61 findings.

4	The front doorway is 750 mm clear — too narrow for a walker or wheelchair	TRADE	\$80–\$180
20	No flashlight at the bedside		\$20–\$60
21	No usable light inside the closet		\$25–\$90
31	The laundry is down a narrow, poorly lit stairwell		\$0–\$200
39	The electric blanket is a fire hazard		\$60–\$200
52	Cleaning chemicals are stored under the kitchen sink, unsecured		\$10–\$50
53	Prescription medication is kept loose on the kitchen counter		\$0–\$70
54	A hunting rifle is stored in the hall closet		\$0–\$300
64	Everyday items are stored at 1727 mm — above shoulder height		\$0–\$120
65	An overturned bucket is being used as a step stool		\$60–\$150

66	Stove controls are at the back, behind the burners	No cost
73	Neither handrail extends past the top or bottom step TRADE	\$120–\$300
74	Stair nosings have no contrast strip	\$60–\$180
75	The top and bottom steps are not highlighted	\$40–\$120
76	The hallway is 914 mm wide	\$0–\$100
85	No carbon monoxide alarm anywhere in the home	\$90–\$250
86	No fire extinguisher in the home	\$60–\$160
92	The doorbell does not work	\$40–\$120
93	Water heater temperature has not been checked or limited	\$0–\$120
95	No emergency exit plan has been discussed	No cost
96	No way to summon help from the floor	\$50–\$120
99	No emergency contact information posted in the home	\$0–\$20
100	Socks are worn indoors all day	\$40–\$120
101	Medication routine may need assistance	\$0–\$40
102	No first aid supplies in the home	\$30–\$80
106	No door viewer usable from a lowered position TRADE	\$40–\$250
107	The patio sliding door has no secondary lock	\$30–\$90
108	Ground-level windows have no locks TRADE	\$60–\$250
6	Garbage and recycling can only be reached down the unsafe front steps	No cost
14	The non-slip tub mat is worn out	\$25–\$70
15	The toilet sits at 365 mm — too low to rise from safely	\$80–\$180
24	Clutter and cords on the bedroom floor	\$20–\$90
25	The laundry area is too dark to work in TRADE	\$60–\$250
32	Closet floor is covered in stored items	No cost
33	Stacked washer and dryer with controls at the back TRADE	\$0–\$180
34	Appliance control markings cannot be read	\$15–\$40
35	Items stored across the laundry floor	No cost
40	An old chair is being used for balance and is not sound	\$0–\$300
41	Window blind cords hang loose	\$20–\$200
43	Closet shelving is disordered and overloaded	\$0–\$120

44	The closet door sticks and pulls hard	TRADE	\$80–\$300
55	No door chime or alarm on either exterior door		\$40–\$120
56	The basement stairwell has no gate at the top		\$90–\$220
57	Knives are stored in an open block on the counter		\$15–\$60
58	The route from the bedroom to the bathroom is dark		\$30–\$90
59	Plastic bags are stored in a low kitchen drawer		No cost
70	The microwave sits in a corner at an awkward reach		\$0–\$120
97	No telephone within reach of the bed		\$40–\$150
103	The bedside cane is not fitted, and its tip is worn		\$15–\$60
110	The entry deadbolt is fixed with 19 mm screws		\$10–\$60
111	A spare key is kept under the doormat		No cost
36	The doormat is torn and lifting		\$30–\$80
45	Bed height is slightly low for a safe transfer		\$30–\$120
46	Dresser drawers are awkward to reach		No cost
60	The patio door is full-height glass with no marking		\$20–\$60
61	No wayfinding cue to the bathroom from the bedroom		\$0–\$40
79	Items are being stored on the stairs		No cost
80	No night lighting along the hallway		\$40–\$110
89	Space heater clearance is 50 cm		No cost
98	The telephone is not reachable from a likely fall location		\$40–\$150
104	Medication storage could be better organised		\$20–\$120

Phase 2 – within three months

\$5,870–\$17,690

The work that needs a trade booked, a quote compared, or a funding application started. 26 findings.

1	Front steps are uneven and cracked, with no handrail	TRADE	\$400–\$1,200
2	No handrail on either side of the front steps	TRADE	\$500–\$1,100
3	Front step treads are cracked and worn	TRADE	\$300–\$900
5	Nowhere safe to sit to change shoes		\$120–\$350
9	No seat in the tub or shower		\$150–\$450
10	No hand-held shower head	TRADE	\$120–\$350
11	All bathroom faucets have knob handles	TRADE	\$250–\$700

22	Outlets and switches are original and unserviced	TRADE	\$200–\$900
30	The entry threshold is a 150 mm step in itself	TRADE	\$250–\$900
50	The front and back doors have nothing to prevent an unnoticed exit	TRADE	\$120–\$340
51	The stove can be turned on and left on	TRADE	\$80–\$450
67	No anti-scald protection at the kitchen sink	TRADE	\$80–\$400
94	No GFCI protection in the wet areas	TRADE	\$250–\$700
12	No grab bar at the toilet, and no wall backing to mount one	TRADE	\$250–\$600
13	No grab bars at the tub	TRADE	\$250–\$600
16	No anti-scald valve at the tub or shower	TRADE	\$300–\$800
17	The bathroom floor has holes in the surface	TRADE	\$400–\$1,400
23	The front steps are badly lit after dark	TRADE	\$150–\$400
42	Bedroom windows are old and stiff to operate	TRADE	\$150–\$400
68	The range has no automatic shut-off	TRADE	\$200–\$800
69	Kitchen faucet has a knob handle	TRADE	\$150–\$450
77	Interior stairs have a handrail on one side only	TRADE	\$300–\$650
78	Stair riser heights vary from 150 mm to 175 mm	TRADE	\$400–\$1,500
87	One smoke alarm for a three-level home	TRADE	\$150–\$450
88	The chimney has not been inspected in 16 years	TRADE	\$200–\$500
109	The bathroom door swings inward, with no lock and fixed hinge pins	TRADE	\$150–\$400

Phase 3 — within six to twelve months

\$480–\$1,850

Larger or lower-urgency work, and the items worth doing when a room is next being worked on anyway. 25 findings.

7	The front door has a round knob		\$60–\$180
8	A shoe rack sits in the entry pathway		\$0–\$60
18	Bathroom lighting is good		No cost
19	The bathroom is warm enough		No cost
26	Entry lighting is adequate but not switched from both ends		\$30–\$90
27	Cords are clear of the entry route		No cost
28	Living area lighting is good		No cost
29	A light is reachable from the bed		No cost
37	Entry doors are unsecured		\$20–\$60

38	Laundry supplies are stored within reach	No cost
47	Pathways through the living area are clear	No cost
48	No chair in the living area suited to standing up from	\$250–\$900
49	The path from the bed to the bathroom is clear	No cost
62	Decorative wax fruit sits in the dining room bowl	No cost
63	No daily routine posted anywhere in the home	\$20–\$60
71	Kitchen task lighting is good	No cost
72	Kitchen floor is sound	No cost
81	Handrail height measures 865 mm	No cost
82	Handrail is graspable	No cost
83	Stair carpet is worn in places TRADE	\$100–\$500
84	Hallway carpet is secure	No cost
90	Flammable items stored 900 mm from the range	No cost
91	Flammable storage is kept outside the home	No cost
105	The cane is kept within reach of the bed	No cost
112	The back entrance is well lit	No cost
All three phases		\$7,985 \$26,570

How to read these three numbers

No family spends the full range. The low figure is what this comes to if the simplest compliant option is taken everywhere and the household does the work that does not need a trade; the high figure is every item done by a licensed trade with standard-grade materials. Most homes land between the two, closer to the low end in Phase 1 and closer to the high end in Phase 2, where the work is structural.

The phases are a sequence, not a deadline. Nothing breaks if Phase 2 takes five months instead of three — the order matters more than the calendar, because each phase removes the risks that the next phase's work would otherwise have to be carried out around. The funding in Section O8 applies mostly to Phase 2, and those applications are worth starting while Phase 1 is under way.

08 · FUNDING PROGRAMS

Money already available to help.

These programs are matched to findings in this report. Eligibility rules and amounts change; the program itself is always the final word, and this report supplies the written cost detail the applications ask for.

AADL

EQUIPMENT COST-SHARE, VARIES BY ITEM

Alberta Aids to Daily Living

Equipment authorization requires AADL-authorized assessor (typically OT). SHSS not authorized to submit AADL forms. SHS can identify potential AADL-eligible items but OT authorization is required.

VERIFY AT alberta.ca/aadl**MATCHED TO** The bath seat and the hand-held shower in the bathroom findings. Authorization requires an AADL-authorized assessor, normally an occupational therapist.**SHARP**

UP TO \$40,000 LOW-INTEREST HOME EQUITY LOAN

Seniors Home Adaptation and Repair Program (Alberta)

Loan: homeowners 65+, household income \$75,000 or less, at least 25% equity kept after the loan, repaid on sale. A separate SHARP grant covers basic, essential repairs for lower-income seniors who do not qualify for the loan (single \$32,690 or less, couple \$53,800 or less; up to \$5,000 a year). Check alberta.ca before quoting.

VERIFY AT alberta.ca (search SHARP)**MATCHED TO** The structural work in this report — step and stair repair, bathroom floor, threshold, window and electrical work.**HATC**

15% OF UP TO \$20,000 IN ELIGIBLE EXPENSES PER YEAR

Home Accessibility Tax Credit (Federal)

Tax credit, not grant. Requires receipts. 65+ or disability tax credit recipient.

VERIFY AT canada.ca (search HATC)**MATCHED TO** Grab bars, handrails, lever hardware, threshold work, bathroom modification and lighting upgrades.

09 · WHAT THE ESTIMATES ARE BASED ON

Where these numbers come from.

Every dollar figure in this report is a planning estimate, not a quote. Knowing how the estimate was built is what lets you tell a fair contractor price from a high one.

PRICING BASIS	Calgary-area materials and labour as of September 2026, from published supplier pricing and current quoted trade rates in this market.
RANGES	The low figure assumes the simplest compliant solution and, where marked, work the family can do without a trade. The high figure assumes a licensed trade, standard-grade materials and a single site visit.
NOT INCLUDED	GST. Permits; structural alterations; asbestos-era material handling; repairs discovered once a wall or floor is opened; finishing and paint beyond the immediate work area; equipment subscriptions beyond the first year.
WHERE TWO OPTIONS ARE SHOWN	Report totals use the near-term option. The longer-term option is priced beside it so the family can see the difference before choosing.
RECURRING COSTS	A monitored emergency response service carries a monthly fee beyond the equipment cost shown. Confirm it with the provider before signing.
IF A QUOTE COMES BACK HIGHER	Senior Home Safety checks its estimates against real quotes and corrects this report's pricing as the market moves. A quote above the range shown here is useful information, not a complaint.

Always get two quotes

For any item over roughly \$300, two independent quotes is the norm and costs nothing but time. The measurements and specifications in Section 05 let a contractor quote accurately without a second site visit.

10 · RECOMMENDED CONTRACTORS

Hiring the work out.

Senior Home Safety takes no referral fee or commission from any contractor, in either direction. Any company named in this report is named because the work fits, not because anyone paid to be listed.

Where this report names a contractor, that company has been checked for business registration, WCB standing and provincial licensing. Insurance is the one thing that has to be current on the day the work happens, so it is worth confirming yourself.

When you call for a quote, ask for two documents

- A certificate of insurance. You are looking for \$2 million general liability. Ask for it to be emailed to you by their insurer or broker rather than shown to you on a phone. These people will be working inside the home.
- A WCB clearance letter. Whoever hires a contractor without WCB coverage can be held responsible for that contractor's unpaid premiums. The letter is free and takes them a minute to produce.

Any established contractor has both to hand and will not be offended by the question. Hesitation is itself an answer.

Who does what

Every finding in Section 05 carries one of four labels, so nobody has to work out who to call. Only the first group needs a contractor at all.

TRADE	32	A licensed or skilled trade. Grouped by trade in Section 10.	\$6,140–\$19,100
OT FIRST	5	Equipment that an occupational therapist authorizes before it is bought. AADL may cover part of the cost — see Section 08.	\$525–\$1,710
BUY	47	Bought and fitted without a trade. A hardware store, a pharmacy or an online order.	\$1,320–\$5,760
FAMILY	28	No purchase at all — something to move, clear, decide or talk about.	\$0–\$0

Start with the Family group: 28 findings, no money, and nothing to book. The Buy group is 47 findings at \$1,320–\$5,760 — one trip and an afternoon. Only then does the trade work need scheduling, and the OT items need a phone call before anything is bought.

Book by trade, not by room

32 of the 112 findings need a trade; the other 80 are a purchase, a rearrangement or a habit. Grouped below by who does the work, with three companies and the finding numbers that belong to each group.

One visit per trade instead of one visit per room is what keeps the cost and the disruption down — and each group can be quoted from the measurements in Section 05 without a second site visit.

Concrete and exterior

\$950–\$3,000

Front steps and the entry landing — one visit covers all three.

- ✓ Bow Valley Step & Walkway Ltd.
- ✓ Redstone Concrete & Landing Co.
- ✓ Highfield Exterior Works

All three carry the five checks. **PLACEHOLDER NAMES**

FINDINGS 1, 3, 30

Carpenter

\$2,500–\$6,870

Handrails, door hardware, blocking for the grab bars, and the doors that stick or swing the wrong way.

- ✓ Elbow Park Carpentry & Home Modification
- ✓ Glenmore Finish Carpentry Ltd.
- ✓ Aspen Ridge Accessible Carpentry

All three carry the five checks. **PLACEHOLDER NAMES**

FINDINGS 2, 4, 12, 13, 42, 44, 50, 73, 77, 78, 106, 108, 109

Plumber

\$900–\$2,700

Mixing valves and lever hardware. Book after the carpenter has the bathroom blocking in.

- ✓ Nose Hill Plumbing & Heating Ltd.
- ✓ Fish Creek Plumbing Co.
- ✓ Riverbend Mechanical Ltd.

All three carry the five checks. **PLACEHOLDER NAMES**

FINDINGS 10, 11, 16, 67, 69

Electrician

\$1,010–\$3,500

Alarms, receptacles and the fixtures that need wiring rather than a plug.

- ✓ Sandstone Electric Ltd.
- ✓ Silver Springs Electrical Services
- ✓ Crowfoot Electric Co.

All three carry the five checks. **PLACEHOLDER NAMES**

FINDINGS 22, 23, 25, 68, 87, 94

Flooring

\$500–\$1,900

The bathroom floor and the worn stair carpet.

- ✓ Chinook Floor & Surface Co.
- ✓ Deerfoot Floor & Tile Ltd.
- ✓ Westbrook Flooring Group

All three carry the five checks. **PLACEHOLDER NAMES**

FINDINGS 17, 83

Appliance installer

\$80–\$630

The stacked laundry pair.

- ✓ Prairie Appliance Service
- ✓ Midnapore Appliance Installation
- ✓ Shepard Home Appliance Co.

All three carry the five checks. **PLACEHOLDER NAMES**

FINDINGS 33, 51

WETT-certified chimney sweep

\$200–\$500

The fireplace inspection.

- ✓ Foothills Chimney & Venting
- ✓ Cedar Crest Chimney Services
- ✓ Bearspaw Hearth & Flue Ltd.

All three carry the five checks. **PLACEHOLDER NAMES**

FINDINGS 88

Sequence matters in the bathroom: the carpenter puts blocking in the wall before the plumber and the grab bars go in, and the flooring goes down last.

About the company names above

Three companies are listed for every trade so quotes can be compared without hunting for a second and third name. Every company on this page is invented, and is marked **PLACEHOLDER NAMES** to say so. They are here to show what a delivered report looks like once vetting is finished. A real report names three real Calgary trades per group with working phone numbers, each one carried through the five checks below, and the names are refreshed as vetting is redone.

- ✓ Active Alberta business registration
- ✓ Provincial prepaid contracting licence
- ✓ Introduction call completed
- ✓ WCB clearance letter, current
- ✓ \$2M general liability confirmed

11 · WHAT HAPPENS NEXT

You don't have to manage this alone.

Most families juggle several contractors, funding paperwork and a parent's changing needs at the same time as their own job and household. Here is the order we would suggest.

- 1** Start Phase 1 this month
The 61 Phase 1 items come to \$1,635–\$7,030 and need a trade for only 7 of them. Several can be done the same afternoon.
- 2** Remove the spare key from under the mat today
Finding 111 costs nothing and takes a minute. It is the only item in this report that can be closed before you finish reading it.
- 3** Order the alarms and the emergency pendant first
Findings 87, 85 and 96 — interconnected smoke alarms, carbon monoxide alarms and a monitored pendant with fall detection. These three cover the events where minutes decide the outcome.
- 4** Book the bathroom as one job, not five
Grab bars, blocking, mixing valve, hand-held shower, raised toilet and floor are cheaper booked together than one at a time, and the room is out of service once instead of five times.
- 5** Apply for funding before booking the trades
SHARP and HATC applications move faster with this report's written estimates already in hand. Apply first, then book.
- 6** Get an occupational therapist involved for the AADL items
The bath seat and the hand-held shower need an occupational therapist's authorization. Senior Home Safety will supply the relevant measurements to the therapist on request, which keeps that visit short.
- 7** Keep the report on file
Section 05 carries the measurements a contractor needs to quote, so nothing has to be re-measured. At the reassessment the report becomes the baseline progress is measured against.
- 8** Reassess in 12 months
A follow-up assessment within twelve months is recommended, sooner if mobility changes noticeably. Returning clients pay \$195 for a reassessment of the same property, which re-scores every category and shows what improved.

Questions about any of the above?

Reach Carl directly at info@novoseniorsafety.com

12 · CREDENTIALS AND METHODOLOGY

Credentials behind every finding.

SHSS · Senior Home Safety Specialist

Carl Christie holds the Senior Home Safety Specialist designation, a 17–module certification covering fall prevention, fire safety, home modification, accessibility, technology, crime prevention, personal safety and how to conduct a complete home safety assessment. Administered by Age Safe America and distributed in Canada through the Canadian Association of Occupational Therapists.

RHFAC Professional · Rick Hansen Foundation Accessibility Certification

Carl is an RHFAC Professional, a credential administered by the Rick Hansen Foundation and recognised as Canada’s leading rating system for the accessibility of the built environment. It is the basis for reading and applying CSA/ASC B652:23 in a residential setting.

ASSESSMENT METHOD	Room-by-room survey across 12 safety categories and 143 checkpoints, with dimensions and light levels recorded on site and a structured client interview.
REFERENCE STANDARD	CSA/ASC B652:23 Accessible dwellings, referenced for technical alignment on the findings where it applies. Findings without a clause reference are stated best practice.
MEASUREMENT	Dimensions recorded with a measuring tape to the nearest millimetre; light levels recorded with a calibrated light meter in lux.
SITE VISIT	125 minutes on site on September 14, 2026, with written consent obtained beforehand and a caregiver present throughout. Report issued September 14, 2026.
PHOTOGRAPHS	One photograph is taken of each high-priority finding, and of nothing else. A photograph of something that needs no change is of no use to you, and a report full of them buries the ones that matter.
PHOTOGRAPHS AND DATA	Photographs and measurements are held securely and deleted 24 months after report delivery, or sooner on request.

Disclaimer

This assessment identifies environmental fall and safety risks and recommends modifications. It is not a clinical assessment of medical, occupational or rehabilitation needs, and does not replace assessment by a regulated health professional. Senior Home Safety does not certify any home against a regulatory standard; findings cited against CSA/ASC B652:23 are referenced for technical alignment only. Implementation should be carried out by qualified contractors, and AADL-eligible equipment must be authorized by an AADL-authorized assessor. Funding rules and amounts change and must be verified with the program at the time of application. Cost estimates are approximate and subject to market conditions. Senior Home Safety accepts no liability for work performed by any contractor.

APPENDIX · REPORT ACKNOWLEDGMENT

Received and reviewed.

This page records that the report was delivered and discussed. It does not authorize any contractor, purchase or expense.

CLIENT	Margaret Smith
PROPERTY	123 Sample Street SW, Calgary, AB
REPORT VERSION	3.1, issued September 14, 2026
FINDINGS	112 across 12 categories · 41 high priority

Sample report

Published by Novo Industries Inc. to demonstrate report format and method. The findings, measurements and costs are real and were recorded during an assessment of an occupied Calgary home; the occupant's name and the street address have been changed for legal reasons. This page is reproduced to show what a client signs on delivery.

RECEIVED BY (PRINT NAME)

RELATIONSHIP TO CLIENT

SIGNATURE

DATE

Reassessment — \$195

A follow-up assessment of this property within twelve months is \$195, a reduction from the full assessment fee. It re-scores every category, records what has been completed, and produces a fresh phased plan. Reply to info@novoseniorsafety.com to book.

Report acknowledgment

info@novoseniorsafety.com · a copy is always kept on file