

HOME SAFETY ASSESSMENT REPORT

A clear, prioritized
plan to help **Margaret**
stay safely at home.

PREPARED FOR

Margaret Chen

ASSESSMENT DATE

April 28, 2026

PROPERTY ADDRESS

142 Maple Ridge Drive SW
Calgary, AB T3E 4R7

ASSESSOR

Carl Christie, SHSS, RHFAC
Professional

SHSS Designated

RHFAC Professional

Vulnerable Sector Check

Fully Insured

Indigenous Business Directory

Contents **What is inside this report**

- 01** Executive Summary
 - 02** Client Profile
 - 03** Site-Measured Floor Plan
 - 04** Assessment Findings by Category
 - 05** Next Dollar Impact
 - 06** Two-Year Capital Plan
 - 07** Government Funding Programs
 - 08** Recommended Contractors
 - 09** Assessor Credentials and Methodology
 - 10** Appendix A: Photo Evidence
-

01 Executive Summary

This report presents the findings of a comprehensive home safety assessment conducted on April 28, 2026, at 142 Maple Ridge Drive SW, Calgary. The assessment was requested by Sarah Chen on behalf of her mother, Margaret Chen (age 78), following a fall in the bathroom three months prior. Margaret uses a four-wheeled walker for mobility and was diagnosed with early-stage Alzheimer's disease approximately six months ago.



Top 5 priority actions

- 1 Install grab bars at the toilet and bathtub (Bathroom) **START HERE**
- 2 Add a stove auto-shutoff device (Kitchen / Dementia)
- 3 Install a handrail on the left side of the front steps (Entrance)
- 4 Install a secondary lock with an alert system on the front door (Dementia)
- 5 Install a gate or barrier at the basement stairs (Dementia / Stairs)

EST. COST, ALL HIGH PRIORITY FINDINGS \$3,200 to \$5,100	EST. COST, ALL 32 FINDINGS \$6,800 to \$11,400
---	---

Several findings qualify for provincial and federal funding programs, detailed in Section 7.

02 Client Profile

OCCUPANT	Margaret Chen, age 78
ADDRESS	142 Maple Ridge Drive SW, Calgary, AB T3E 4R7
HOME TYPE	Single-story bungalow with basement, approximately 2,000 sq ft total (1,200 main floor, 800 basement). Built in 1974.
LIVING SITUATION	Lives alone. Daughter Sarah Chen is the primary caregiver, a 20-minute drive away.
MOBILITY	Uses a four-wheeled walker (rollator) full-time indoors and outdoors. Mild balance impairment. One fall in the bathroom (January 2026).
COGNITIVE STATUS	Diagnosed with early-stage Alzheimer's disease (October 2025). Occasional disorientation, especially at night. Has left the stove on unattended twice. The front door was found unlocked and open once.
CURRENT AIDS	Four-wheeled walker (rollator), a raised toilet seat that was self-purchased and not properly fitted.
REASON FOR ASSESSMENT	Fall in the bathroom (January 2026). Family is concerned about cognitive decline and Margaret's ability to remain safely at home.
ASSESSMENT REQUESTED BY	Sarah Chen (daughter)

03 Site-Measured Floor Plan

The floor plan below reflects on-site laser measurements taken during the assessment visit. Red numbered markers correspond to the findings documented in Section 4.



- 1

Front steps: no handrail (left)
- 2

Stove: no auto-shutoff
- 3

Kitchen floor curling
- 4

No grab bars at toilet / tub
- 5

Tub: step-over entry
- 6

Hallway: no nightlight
- 7

Loose area rug
- 8

Dresser clearance 62 cm
- 9

Front door: no alert system
- 10

Basement stairs: no gate
- 11

Extension cord across path
- 12

Dryer vent lint buildup

Room dimensions captured on site with a Bosch GLM 50-27 CG laser distance measurer. Numbered markers correspond to the findings referenced in Section 4. Diagram is a layout reference, not to exact scale.

04 Assessment Findings by Category

Each finding is classified by priority. **HIGH** indicates an immediate safety risk. **MEDIUM** should be addressed within six months. **LOW** is a recommended improvement, addressed within twelve months. Delivered client reports include a photograph for every numbered finding, cross-referenced by number in Appendix A.

4.1 Entrances and Exterior

#	FINDING	PRIORITY	RECOMMENDATION	EST. COST
1	Front steps: no handrail on left side	HIGH	Install a second handrail on the left side of the front steps, extending the full length plus 12 inches beyond the top and bottom steps.	\$400 to \$600
2	Front door threshold: 2 cm raised lip creates a trip hazard for the walker	MEDIUM	Install a beveled threshold ramp or replace the threshold with a flush profile.	\$80 to \$150
3	Exterior pathway: concrete displacement of 1.5 cm at two joints	MEDIUM	Grind or shim the displaced concrete to eliminate trip points. Mark with contrasting paint if grinding is deferred.	\$150 to \$300
4	Exterior lighting: single 40W bulb at the front door. Pathway is unlit after dark.	HIGH	Install motion-activated LED pathway lights (minimum 3) and upgrade the front door fixture to a 100W-equivalent LED.	\$200 to \$400

4.2 Bathroom Safety

#	FINDING	PRIORITY	RECOMMENDATION	EST. COST
5	No grab bars at the toilet or bathtub. Occupant uses the towel rack for support, which is not load-rated.	HIGH	Install load-rated grab bars: one beside the toilet, one inside the tub (horizontal), one at the tub entry (vertical). Wall blocking may be required.	\$300 to \$600
6	Bathtub requires an 18-inch step-over entry. No transfer bench or non-slip surface.	HIGH	Install a transfer bench and non-slip strips inside the tub. Consider a tub-to-shower conversion with zero-threshold entry as a longer-term step.	\$150 to \$400
7	Bath mat is not secured. It slides on the tile floor when stepped on.	MEDIUM	Replace with a suction-cup bath mat or adhesive non-slip strips on the tile floor adjacent to the tub.	\$20 to \$40
8	Hot water temperature is not limited. Measured at 140F (60C) at the bathroom faucet.	MEDIUM	Reduce the hot water tank thermostat to 120F (49C) or install an anti-scald valve at the bathroom faucet.	\$20 to \$80

4.3 Lighting and Electrical

#	FINDING	PRIORITY	RECOMMENDATION	EST. COST
9	Hallway between the bedroom and bathroom has no nightlight. The route is taken multiple times per night.	HIGH	Install motion-activated LED nightlights in the hallway, bathroom entrance, and bedroom (minimum 3 units).	\$30 to \$60
10	Kitchen under-cabinet lighting is absent. The counter workspace is shadowed.	MEDIUM	Install LED under-cabinet light strips. Battery-operated adhesive strips are a low-cost option.	\$30 to \$80
11	Light switches are standard toggle, not illuminated, and are difficult to locate in the dark.	LOW	Replace switches on primary routes (bedroom, hallway, bathroom) with illuminated or glow-in-the-dark switch plates.	\$30 to \$60

4.4 Flooring and Trip Hazards

#	FINDING	PRIORITY	RECOMMENDATION	EST. COST
12	Loose area rug (3 x 5 ft) in the living room, with no non-slip backing. Edges curl upward.	HIGH	Remove the rug entirely, or secure it with a heavy-duty non-slip rug pad and carpet tape on all edges.	\$0 to \$40
13	Carpet-to-hardwood transition strip is raised 8 mm in the hallway.	MEDIUM	Replace with a flush or beveled transition strip rated for walker and wheelchair traffic.	\$40 to \$80
14	Extension cord runs across the hallway from the living room to the bedroom.	HIGH	Reroute the cord along the baseboard with cord covers, or install an additional outlet to eliminate the crossing.	\$40 to \$200
15	Kitchen linoleum is curling at the edge near the refrigerator, with a 3 cm exposed gap.	MEDIUM	Re-adhere the linoleum edge with flooring adhesive. If the floor is worn, consider full replacement with non-slip vinyl.	\$30 to \$800

4.5 Bedroom and Living Spaces

#	FINDING	PRIORITY	RECOMMENDATION	EST. COST
16	Bed height is 42 cm (16.5 in). The standard for a safe transfer with a walker is 48 to 55 cm (19 to 22 in).	MEDIUM	Install bed risers to raise the bed to 50 cm (20 in), or replace the frame with an adjustable-height model.	\$20 to \$80
17	Furniture clearance between the dresser and bed measured 62 cm. A walker requires a minimum of 75 cm.	HIGH	Relocate the dresser to the opposite wall, or replace it with a narrower unit. A minimum of 75 cm of clearance is required for walker passage.	\$0 to \$200
18	Sofa seat depth is 65 cm and seat height is 38 cm, making it difficult for the occupant to stand without assistance.	MEDIUM	Add a firm seat cushion to raise the height and reduce the depth, or consider a lift chair.	\$50 to \$800

4.6 Kitchen Safety

#	FINDING	PRIORITY	RECOMMENDATION	EST. COST
19	Gas stove has no automatic shutoff. The occupant has left a burner on unattended twice in the past month.	HIGH	Install a stove guard or automatic stove shutoff device with a motion or timer sensor. Consider switching to an induction cooktop.	\$200 to \$800
20	Upper cabinets store frequently used items above shoulder height, and a step stool is in use.	MEDIUM	Relocate frequently used items to lower cabinets, or install pull-down shelf hardware in the upper cabinets.	\$0 to \$300

4.7 Stairs and Hallways

#	FINDING	PRIORITY	RECOMMENDATION	EST. COST
21	Basement stairs have a single handrail on the right side only. 12 steps, carpeted, with adequate tread depth.	HIGH	Install a second handrail on the left side. Given the cognitive decline, also consider restricting basement access (see Section 4.9).	\$300 to \$500
22	No gate or barrier at the top of the basement stairs. The basement door does not self-close.	HIGH	Install a self-closing hinge on the basement door, and add a keyed deadbolt or childproof lock on the hallway side.	\$60 to \$150

4.8 Fire Safety

#	FINDING	PRIORITY	RECOMMENDATION	EST. COST
23	Smoke detectors (3) are battery-operated. When the batteries were last tested is unknown.	MEDIUM	Replace with 10-year sealed-battery smoke and CO combo detectors. Install one in every bedroom plus the hallway.	\$80 to \$150
24	No fire extinguisher on the main floor.	MEDIUM	Install a 2.5 lb ABC fire extinguisher in the kitchen, mounted at an accessible height for a walker user.	\$30 to \$50
25	Dryer vent shows visible lint accumulation at the exterior outlet.	HIGH	Schedule a professional dryer vent cleaning, and inspect annually thereafter.	\$100 to \$150

4.9 Alzheimer's and Dementia Safety

The following findings are specific to the occupant's early-stage Alzheimer's diagnosis and address environmental factors related to cognitive decline, wandering risk, and unsupervised activity.

#	FINDING	PRIORITY	RECOMMENDATION	EST. COST
26	Front door has no secondary lock or exit alert. The door was found open and unlocked by a family member.	HIGH	Install a door contact alarm or smart lock with caregiver notification. Add a deadbolt that requires a key from inside.	\$80 to \$300
27	Cleaning supplies are accessible, unlocked, under the kitchen and bathroom sinks.	MEDIUM	Install childproof locks on all cabinets containing cleaning supplies, chemicals, or sharp objects.	\$20 to \$40
28	Medications are stored in an unlocked kitchen cabinet, with multiple prescriptions visible on the counter.	MEDIUM	Move medications to a locked medication box or cabinet. Use a weekly pill organizer managed by the caregiver.	\$20 to \$60
29	No wayfinding cues exist between rooms. All door frames, walls, and flooring are similar neutral tones.	LOW	Add color-contrast strips or decals to the bathroom and bedroom door frames for visual wayfinding.	\$10 to \$30
30	No visible clock or calendar is present in the main living area.	LOW	Place a large digital clock and calendar displaying the day, date, and time in the living room at eye level.	\$30 to \$60

4.10 Technology and Emergency Systems

#	FINDING	PRIORITY	RECOMMENDATION	EST. COST
31	No personal emergency response system (PERS) is in the home, and the occupant lives alone.	HIGH	Install a PERS pendant or wristband with 24/7 monitoring. Ensure it is waterproof for bathroom use.	\$30 to \$50/mo
32	No smart home devices are in use: no door sensors, motion lights, or caregiver notification system.	LOW	Consider smart door sensors, motion-activated lighting, and a caregiver notification hub. This can be phased in over time.	\$100 to \$400

05 Next Dollar Impact

The table below ranks findings by safety impact per dollar spent, so the family knows exactly where the next dollar delivers the greatest safety improvement.

RANK	FINDING	PRIORITY	EST. COST	IMPACT / \$
1	Remove loose area rug in living room	HIGH	\$0 to \$40	Highest
2	Reroute extension cord from hallway	HIGH	\$40 to \$200	Highest
3	Install nightlights on bedroom-to-bathroom route	HIGH	\$30 to \$60	Highest
4	Install grab bars at toilet and bathtub	HIGH	\$300 to \$600	Highest
5	Install stove auto-shutoff device	HIGH	\$200 to \$800	Highest
6	Install front door exit alert system	HIGH	\$80 to \$300	Highest
7	Install gate and lock at basement stairs	HIGH	\$60 to \$150	High
8	Install handrail on front steps, left side	HIGH	\$400 to \$600	High
9	Relocate dresser for walker clearance	HIGH	\$0 to \$200	High
10	Install exterior pathway lighting	HIGH	\$200 to \$400	High
11	Secure or replace bath mat	MEDIUM	\$20 to \$40	Moderate
12	Lock cleaning supplies and medications	MEDIUM	\$40 to \$100	Moderate
13	Reduce hot water temperature	MEDIUM	\$20 to \$80	Moderate
14	Install transfer bench in bathtub	HIGH	\$150 to \$400	Moderate
15	Schedule professional dryer vent cleaning	HIGH	\$100 to \$150	Moderate

Ranked by safety impact per dollar spent. Rows 1 through 5 are highlighted as the highest-impact, lowest-cost fixes, showing where the next dollar delivers the greatest safety improvement. Full list of 32 findings is available on request.

06 Two-Year Capital Plan

This phased plan organizes every recommended modification by timeframe, addressing the highest-risk items first while giving the family room to budget over time.

Phase 1 IMMEDIATE, WITHIN 30 DAYS Remove loose area rug in living room \$0 Reroute extension cord along baseboard \$40 to \$80 Install motion-activated nightlights (3) \$30 to \$60 Reduce hot water temperature to 120F \$0 Relocate dresser for walker clearance \$0 Lock cleaning supplies and medication cabinet \$40 to \$100 Secure or replace bath mat \$20 to \$40 Phase total \$130 to \$280	Phase 2 WITHIN 3 MONTHS Install grab bars at toilet and bathtub (3 bars) \$300 to \$600 Install stove auto-shutoff device \$200 to \$800 Install front door exit alert or smart lock \$80 to \$300 Install gate and lock at basement stairs \$60 to \$150 Install transfer bench in bathtub \$150 to \$400 Install personal emergency response system \$30 to \$50/mo Schedule professional dryer vent cleaning \$100 to \$150 Phase total \$920 to \$2,450	Phase 3 WITHIN 6 TO 12 MONTHS Install second handrail on front steps \$400 to \$600 Install exterior motion-activated pathway lights \$200 to \$400 Replace smoke detectors with sealed 10-year units \$80 to \$150 Install bed risers or an adjustable bed frame \$20 to \$80 Replace hallway transition strip with a flush profile \$40 to \$80 Repair kitchen linoleum or replace the flooring \$30 to \$800 Repair exterior concrete pathway \$150 to \$300 Phase total \$920 to \$2,410
--	---	--

ALL THREE PHASES COMBINED

\$1,970 to \$5,140

07 Government Funding Programs

The following programs may help offset the cost of recommended modifications. Eligibility varies by program; the official program pages carry the most current requirements.

SHARP ALBERTA Seniors Home Adaptation and Repair Program Low-interest home equity loans and grants for home adaptations. Grants are available up to \$5,000 per benefit year for lower-income seniors. This report provides the written cost estimates SHARP requires. APPLICABLE FINDINGS IN THIS REPORT Phase 2 and Phase 3 modifications: grab bars, handrails, flooring, lighting	AADL ALBERTA Alberta Aids to Daily Living Funds essential medical equipment such as walkers, bathing equipment, and home care beds. This is a cost-share program covering 25% of cost up to \$500 per family per year, and requires a clinical assessment by an OT, PT, or RN. This report provides the environmental data to support that clinical assessment. APPLICABLE FINDINGS IN THIS REPORT Transfer bench, PERS device, properly fitted raised toilet seat
HATC FEDERAL, NATIONWIDE Home Accessibility Tax Credit A non-refundable tax credit of 15% on up to \$20,000 in eligible accessibility expenses, for a maximum credit of \$3,000 per year. Available to anyone age 65 or older, or eligible for the Disability Tax Credit. APPLICABLE FINDINGS IN THIS REPORT Grab bars, handrails, walk-in shower conversion, threshold modifications, lighting upgrades	MHRTC FEDERAL, NATIONWIDE Multigenerational Home Renovation Tax Credit A refundable tax credit of 15% on up to \$50,000, for a maximum credit of \$7,500, for creating a self-contained secondary unit for a senior or a person with a disability. One claim is allowed per qualifying individual per lifetime. APPLICABLE FINDINGS IN THIS REPORT Applicable only if the family decides to create a secondary suite for Margaret in a family member's home

08 Recommended Contractors

Contractor Referral Disclosure

Senior Home Safety operates as an independent assessment service. Carl Christie holds no financial interest, referral fee arrangement, or business relationship with any contractor listed in this report. Contractors are provided for informational purposes only. The client retains full and sole discretion in selecting a contractor for any work. Senior Home Safety plays no role in contractor selection, pricing negotiation, scheduling, or oversight of any resulting work, and listing a contractor here is not an endorsement of their work quality, pricing, or fit for your project.

Vetting standard

Every contractor below met all five criteria before being added to this list.

- ✓ Active Alberta business registration
- ✓ Certificate of general liability insurance, \$2M minimum
- ✓ Personal introduction call completed by Carl Christie
- ✓ WCB clearance letter (Alberta WCB, current)
- ✓ Google rating of 4.5 or higher, with 10 or more reviews

Westview Home Modifications Ltd.

Bathroom safety modifications, grab bars, transfer benches, tub-to-shower conversions

Mike Dravecky · 403-555-0182 · westviewhomemod.ca

RELEVANT TO FINDINGS #5, #6, grab bars and transfer bench

4.8 ★★★★★

34 reviews

Prairie Handyman Services Inc.

Handrails, door hardware, gates, carpentry, minor interior modifications

Tom Kowalski · 403-555-0247 · prairiehandyman.ca

RELEVANT TO FINDINGS #1, #21, #22, handrails, basement gate, and door hardware

4.6 ★★★★★

22 reviews

Foothills Floor & Threshold Co.

Flooring, transition strips, exterior concrete repair, threshold modifications

Jason Mercer · 403-555-0319 · foothillsthreshold.ca

RELEVANT TO FINDINGS #3, #13, #15, concrete pathway, transition strip, and linoleum

4.7 ★★★★★

18 reviews



Scan for the current list

The three contractors above reflect the trade categories relevant to this report. Novo maintains a continuously updated, full contractor list online, so removed or added contractors always reflect the latest performance tracking rather than the date this report was printed.

novoseniorsafety.com/contractors

These three contractors were selected for the specific work recommended in this report, one per primary trade category. Always obtain at least two independent quotes before proceeding with any work. Senior Home Safety contacts every client roughly 30 days after report delivery to check whether work was completed and how the contractor performed; a contractor with two or more poor ratings is removed and replaced. This list is maintained on a rolling basis and may differ between reports issued at different times.

09 Assessor Credentials and Methodology

SHSS · Senior Home Safety Specialist Carl Christie holds the Senior Home Safety Specialist (SHSS) designation, a 17-module certification program covering fall prevention, fire safety, home modifications, accessibility, technology, Alzheimer's and dementia considerations, crime prevention, personal safety, communication with older adults, and how to perform a complete home safety assessment. The designation is administered by Age Safe America and distributed in Canada through the Canadian Association of Occupational Therapy (CAOT). RHFAC · Rick Hansen Foundation Accessibility Certification Carl is also an RHFAC Professional, a credential administered by the Rick Hansen Foundation and recognized as Canada's leading rating system for the accessibility of the built environment. This training grounds each assessment in a formal accessibility methodology alongside senior-specific safety expertise, so recommendations hold up against a recognized national standard.	
BACKGROUND CHECK	Carl holds a current Vulnerable Sector Check, the police background check required for work directly with seniors and vulnerable individuals in their homes.
INSURANCE	Novo Industries Inc. holds comprehensive liability insurance covering all assessment activities.
INDIGENOUS BUSINESS DIRECTORY	Novo Industries Inc. is registered in the federal Indigenous Business Directory.
ASSESSMENT STANDARD	Conducted in accordance with the SHSS assessment standard, covering the 10 safety categories detailed in Section 4.
MEASUREMENT EQUIPMENT	All clearance measurements, doorway widths, threshold heights, and fixture dimensions were captured using a Bosch GLM 50-27 CG professional laser distance measurer, with a stated accuracy of 1.5 mm.

SITE VISIT

The on-site visit lasted approximately 2.5 hours. All findings, recommendations, and cost estimates reflect the assessor's professional judgment, current product pricing, and applicable standards. Cost estimates are approximate and may vary by contractor.

CONTACT

This report was prepared by Senior Home Safety, a service of Novo Industries Inc., Calgary, Alberta. For questions about this report or to discuss the findings, contact info@novoseniorsafety.com.

DISCLAIMER

This report is based on a visual and measurement-based assessment of the home environment. It does not constitute an engineering inspection, a building code compliance review, or a clinical health assessment. Recommendations are advisory. Consult qualified contractors for installation and licensed health professionals for clinical assessments. Cost estimates are approximate and subject to market conditions. The contractor referrals in Section 8 are provided as a courtesy only; Senior Home Safety assumes no liability for the quality, safety, or outcome of any work performed by referred contractors.

A Appendix A: Photo Evidence

ABOUT THIS SAMPLE

This report is a fictional illustration prepared for novoseniorsafety.com and does not represent a real client or property, so no property photographs exist to include here. Delivered client reports carry a full-resolution photograph for every numbered finding below, matched to the finding numbers used throughout Section 4.



PHOTO OMITTED
FROM SAMPLE

1 Front steps: no handrail on left side



PHOTO OMITTED
FROM SAMPLE

2 Front door threshold: 2 cm raised lip creates a trip...



PHOTO OMITTED
FROM SAMPLE

3 Exterior pathway: concrete displacement of 1.5 cm at...



PHOTO OMITTED
FROM SAMPLE

4 Exterior lighting: single 40W bulb at the front door...



PHOTO OMITTED
FROM SAMPLE

5 No grab bars at the toilet or bathtub. Occupant uses...



PHOTO OMITTED
FROM SAMPLE

6 Bathtub requires an 18-inch step-over entry. No...



PHOTO OMITTED
FROM SAMPLE

7 Bath mat is not secured. It slides on the tile floor...



PHOTO OMITTED
FROM SAMPLE

8 Hot water temperature is not limited. Measured at 140F...



PHOTO OMITTED
FROM SAMPLE

9 Hallway between the bedroom and bathroom has no...



PHOTO OMITTED
FROM SAMPLE

10 Kitchen under-cabinet lighting is absent. The counter...



PHOTO OMITTED
FROM SAMPLE

11 Light switches are standard toggle, not illuminated,...



PHOTO OMITTED
FROM SAMPLE

12 Loose area rug (3 x 5 ft) in the living room, with no...



PHOTO OMITTED
FROM SAMPLE

13 Carpet-to-hardwood transition strip is raised 8 mm in...



PHOTO OMITTED
FROM SAMPLE

14 Extension cord runs across the hallway from the living...



PHOTO OMITTED
FROM SAMPLE

15 Kitchen linoleum is curling at the edge near the...



PHOTO OMITTED
FROM SAMPLE

16 Bed height is 42 cm (16.5 in). The standard for a safe...



PHOTO OMITTED
FROM SAMPLE

17 Furniture clearance
between the dresser and bed...



PHOTO OMITTED
FROM SAMPLE

18 Sofa seat depth is 65 cm
and seat height is 38 cm,...



PHOTO OMITTED
FROM SAMPLE

19 Gas stove has no
automatic shutoff. The
occupant has...



PHOTO OMITTED
FROM SAMPLE

20 Upper cabinets store
frequently used items above...



PHOTO OMITTED
FROM SAMPLE

21 Basement stairs have a
single handrail on the right...



PHOTO OMITTED
FROM SAMPLE

22 No gate or barrier at the
top of the basement stairs...



PHOTO OMITTED
FROM SAMPLE

23 Smoke detectors (3) are
battery-operated. When the...



PHOTO OMITTED
FROM SAMPLE

24 No fire extinguisher on the
main floor.



PHOTO OMITTED
FROM SAMPLE

25 Dryer vent shows visible
lint accumulation at the...



PHOTO OMITTED
FROM SAMPLE

26 Front door has no
secondary lock or exit alert.
The...



PHOTO OMITTED
FROM SAMPLE

27 Cleaning supplies are
accessible, unlocked, under
the...



PHOTO OMITTED
FROM SAMPLE

28 Medications are stored in
an unlocked kitchen cabinet,...



PHOTO OMITTED
FROM SAMPLE

29 No wayfinding cues exist
between rooms. All door...



PHOTO OMITTED
FROM SAMPLE

30 No visible clock or
calendar is present in the
main...



PHOTO OMITTED
FROM SAMPLE

31 No personal emergency
response system (PERS) is in
the...



PHOTO OMITTED
FROM SAMPLE

32 No smart home devices
are in use: no door sensors,...