

N76E003 Series Errata Sheet

Errata Sheet for 8-bit 8051 Family

Document Information

Al	bstract	This errata sheet describes the functional problems known at the release date of this document.
Apply to N76E003 Series.		N76E003 Series.

The information described in this document is the exclusive intellectual property of Nuvoton Technology Corporation and shall not be reproduced without permission from Nuvoton.

Nuvoton is providing this document only for reference purposes of NuMicro microcontroller based system design.

Nuvoton assumes no responsibility for errors or omissions.

All data and specifications are subject to change without notice.

For additional information or questions, please contact: Nuvoton Technology Corporation.

www.nuvoton.com



Table of Contents

1	OVERVIEW	3
2	FUNCTIONAL PROBLEM	4
	2.1 POR issue after Power down Wake up	4



1 Overview

Functional Problem	Description		
POR issue after Power down Wake up	Wake-up from Power-down mode can cause Power-on Reset (POR). It can be worked around by Disable POR function before the N76E003 enters Power-down mode to prevent the problem.		



2 Functional Problem

2.1 POR issue after Power down Wake up

Description:

Wake-up from Power-down mode can cause Power-on Reset (POR). <u>It can be worked around</u> by disable the POR function before the N76E003 enters Power-down mode to prevent the problem.

Problem:

The N76E003 provides power-on detection to prevent incorrect execution during power up and power drop. The power-on detection function is designed for detecting power up after power voltage reaches a level where system can work. The N76E003 POR-detect-voltage is stable at one value which falls between 1.3 V and 1.5 V. When the N76E003 runs in Power-down mode, the core runs under a low power consumption condition. Every time the N76E003 wakes up from Power-down mode, power consumption condition changes to normal power consumption. This may cause the core voltage glitch to be less than 1.5 V. The POR will be triggered, and N76E003 will reset.

Workaround:

POR is for use by V_{DD} power-on. After power-on, the system uses LVR for power detection. It is strongly suggested to disable the POR function every time after power-on reset (POR) at the initial part of customer code.

How to disable POR:

At SFR address, FDH is the PORDIS register to control POR function disable through software.

PORDIS - POR disable (TA protected)

7	6	5	4	3	2	1	0
PORDIS[7:0]							
W							

Address: FDH, Page: 0 Reset value: 0000 0000b

Bit	Name	Description
7:0	PORDIS[7:0]	POR disable Writing 5AH to the PORDIS first and immediately followed by a writing of A5H will disable POR.



Since the PORDIS register is TA protected, please always follow the code sequence below to disable POR.

```
sfr PORDIS = 0XFD;
    TA =0XAA;
    TA= 0X55;
    PORDIS = 0X5A;
    TA=0XAA;
    TA=0XS5;
    PORDIS = 0XA5;
```



Revision History

Date	Revision	Description
2017.05.01	1.00	1. Initially issued.



Important Notice

Nuvoton Products are neither intended nor warranted for usage in systems or equipment, any malfunction or failure of which may cause loss of human life, bodily injury or severe property damage. Such applications are deemed, "Insecure Usage".

Insecure usage includes, but is not limited to: equipment for surgical implementation, atomic energy control instruments, airplane or spaceship instruments, the control or operation of dynamic, brake or safety systems designed for vehicular use, traffic signal instruments, all types of safety devices, and other applications intended to support or sustain life.

All Insecure Usage shall be made at customer's risk, and in the event that third parties lay claims to Nuvoton as a result of customer's Insecure Usage, customer shall indemnify the damages and liabilities thus incurred by Nuvoton.

Please note that all data and specifications are subject to change without notice.

All the trademarks of products and companies mentioned in this datasheet belong to their respective owners.