

Oxford Flying Club Confidential Safety Report							
Name of Reporting Member Note: Optional and will be redacted.	Aircraft # or Approximate Location: Note: Optional and will be redacted.				Date Reported:		
	_						
1. Date of Event: Local Time (24hr approx okay): 0945							
2. Type of Event - check all appropriate responses							
Aborted Takeoff	_	Foreign Object Damage	<u> </u>		Collision Hazard		
Abnormal Landing	Ļ	Weather			Airport Hazard		
Hangar Safety	<u></u>	Maintenance Issue/Discrepancy		Other (Please add description)			
3. Weather Conditions - check all appropriate responses							
IMC or VMC	<u> </u>	Thunderstorm	<u> </u>	Icing			
Cold/Heat Related	<u> </u>	Turbulence	<u> </u>	Crosswind			
Precipitation	<u> </u>	Windshear		Other (Please add description)			
4. Phase of Operation - check all appropriate responses							
Ramp/Hangar Area	<u> </u>	Takeoff	<u> </u>	Descent			
Preflight	_	Climb	<u>_</u>	Approach			
✓ Taxi-Out	Ļ	Enroute		Landing			
5. Pilot Action - check all appropriate responses							
Declared Emergency	<u> </u>	Trouble Shooting In Flight	┢	Diverted From Planned Dest.			
Emergency Checklist	~	Trouble bricking on browne	느	Requested Medical Assist.			
Requested Crash/Rescue	<u> </u>	NASA Report Filed	<u></u>	Aircraft Grounded			
Contact Airport Manager		Activated ERP	뇩	Other (I	Please add descrip	tion)	
6. Comments or Suggestions: <i>Is additional information attached:</i> -No Reporting Member Summary:							
While requesting IFR release, entire airplane electrical failure occurred. All radios, navigation equipment and transpoder shut off. The equipment briefly turned on several times for approximately before completely shutting down. Takeoff was aborted and tower notifed of the issue via portable radio. Aircraft taxiied to the ramp and then grounded. Video taken of this failure and all circuit breakers were checked and set, master switch was on, ammeter did not show a discharge and both warning bulbs were missing from the aircraft.							
7. Name of Safety Officer or Des	ee:	Date Reviewed:					
Probability: - 3 Severity:		Investigation Summary Attached: - No					
Resulting Risk Code: - 4	Assigned Tracking	Assigned Tracking # OFC-CSR 2021-008					
Committee Summary:							
The issue resulting with multiple repairs shows a series of misdiagnosing and miscommunication between our club and our mechanics. Although the actual mechanical irregularity discovered was a masked issue, we believe a test flight of vital system repairs increases the safety and allows the mechanics a better, immediate diagnosis rather than it becoming a repeated member squawk. Once a plane is considered back in service, it is challenging to control the members knowledge of the recent work or necessary flight conditions. This is why the safety committee is recommending a test flight rather than just run-ups when electrical, flight controls, engine, or nav/comm repair is completed. This additional step will ensure that the test flight will be briefed on the issue suspected, corrective action, and that all work is properly recorded with suitable flight conditions to test. Two wires were found frayed and contacting baffling from alternator to electrical bus. This arcing did fail the entire electrical system instead of appear as an alternator failure which was originally assumed.							
Note: Risk Assessment Code of 4 or more resets the OFC Safety Clock							
Note: Risk Assessment Code of 5 requires immediate notification of Club President.							
Note: Information identifying any member will be redacted for anonymity. Please provide as much as possible.							
		for your interest in your Safety P					

Revision: Initial Date: February 23, 2021