CORKTOWN AUDIO WORKS

17241 Prairie St, Detroit, MI 48221 | (313) 555-0147 | kofi@corktownaudio.com

BENCH REPORT

Service and function test

SKU	UNIT	BENCH DATE	TECHNICIAN
CAW-1115	Pioneer PL-12D turntable	2026-08-25	Kofi Mensah

INCOMING CONDITION

Turns at both speeds, but the speed wanders on the strobe at 33 1/3 and 45. Looks clean.

WORK PERFORMED

1. New belt fitted.
2. Motor cleaned and oiled: pulley wiped down, light oil on the motor bearings, none on the rubber.
3. Speed pots adjusted on the strobe at 33 1/3 and 45.

MEASUREMENTS *(strobe disc under a 60 Hz lamp, after the belt and adjustment)*

Test	Method	Reading	Result
33 1/3 rpm	Set on speed, read over ten minutes	Drifts 2 to 3% slow within ten minutes	Fail
45 rpm	Set on speed, read over ten minutes	Won't hold either	Fail

FUNCTIONAL CHECKS

Check	Notes	Result
Platter and spindle bearing	Spins free by hand, no drag.	OK
Belt and pulley	New belt runs true, no slip on the pulley.	OK
Motor	Won't hold speed after the belt and adjustment.	Fail
Wow and flutter	Not measured, the speed won't hold.	Skipped
Plinth and tonearm	Nice. No damage to either.	OK

RESULT

Signed off: Kofi Mensah, bench tech, 2026-08-25

FAIL. For Parts, sell as-is.

Motor won't hold speed after the belt and adjustment.
Failed the bench test, so For Parts under Grading Guide v3. Good as a donor or a motor project.