CORKTOWN AUDIO WORKS

Bench Test Report

17241 Prairie St, Detroit, MI 48221 | (313) 555-0147 | kofi@corktownaudio.com

SKU	CAW-1124	**Serial**	64137
Unit	Marantz 2230 stereo receiver, walnut WC-22 cabinet		
Acquired	2026-07-18, estate sale, Boston-Edison	**On bench**	2026-09-24 to 2026-09-30
Technician	Kofi Mensah	**Report date**	2026-09-30

INCOMING CONDITION

Brought up slowly on the dim-bulb tester. Hum in both channels with high ripple on the main supply rail. Two dial lamps out. Controls and input selector scratchy.

WORK PERFORMED

1. Power supply recapped: main filter capacitors and all electrolytics on the regulator board replaced. Ripple on the main rail now normal, hum gone.
2. Two dial lamps replaced with new 8 V incandescent bulbs. Meter and stereo indicator lamps checked and working.
3. Controls, input selector and switches cleaned and exercised.
4. Bias and DC offset set to service manual values, rechecked after a 1-hour warm-up.
5. Faceplate, knobs and cabinet cleaned.

MEASUREMENTS (8 ohm resistive load, 1 kHz, both channels driven)

Measurement	Left	Right
Power output	30 W RMS	30 W RMS
THD at 30 W RMS	0.07%	0.08%
DC offset	8 mV	11 mV
Residual hum and noise	Inaudible at full volume, inputs shorted	

FUNCTIONAL CHECKS

Phono, Aux, Tape monitor	**Pass**
FM stereo lock, tuning and signal meters, AM	**Pass**
Speakers A, B, A+B, headphone jack	**Pass**
Bass, mid, treble, balance, loudness, filters, mono	**Pass**
Dial, meter and stereo lamps	**All lit**
Burn-in: 2 hours at 1/3 rated power	**No faults**

COSMETIC NOTES

Cabinet top	One light hairline, rear left, about 2 cm long: roughly 3 cm in from the left edge and 4 cm from the back, angled toward the corner, beside a dark grain streak. Shows only up close or under raking light. No chips, dents or veneer damage.
Faceplate and knobs	Clean, no marks.

RESULT

All functions to spec. Ready for photos and grading.

Signed off
Kofi Mensah, 2026-09-30