

WI-1042 Torque Sequence — Front Housing

Preparation

1. Verify the torque wrench calibration sticker is current. Do not proceed if the calibration date has expired; tag the tool and notify the line lead immediately.
2. Set the torque wrench to 12.5 Nm. Confirm the setting with a second operator and record both initials on the traveler.
3. Clean the mating face of the front housing with an approved lint-free wipe and IPA. Allow thirty seconds of flash-off time before assembly.

Fastener Installation

4. Place the front housing onto the chassis locating pins. The housing must seat fully with no visible gap at any corner.
5. Hand-start all eight M6 fasteners. Never use a power tool to start a fastener, as cross-threading will scrap the chassis casting.
6. Torque the fasteners in a star pattern beginning at position one, then five, then three, then seven, then two, then six, then four, then eight.
7. WARNING: Do not exceed two passes on any single fastener. Repeated torquing degrades the thread-locking patch and will cause the joint to loosen in service.

Verification

8. Perform a witness-mark check on all eight fasteners using the yellow torque-seal pen.
9. Scan the chassis serial barcode into the MES station and confirm the green pass indicator before releasing the unit downstream.