Date amended: 24/09/25 Revision No: 023 Date Implemented: 24/09/25

# Hinton Skydiving Centre Risk Assessment Form

**Stay safe**

Please read the guidance (BS Form 244a) before completing this form

Please remember:
1 The Assessor must identify if additional control measures are needed to reduce the level of risk. If so, these should be listed in column 5 'Additional Controls'.
2 Copies of this document should be retained and readily available for inspection.
3 The risk assessment must be reviewed if changes occur to the tasks/activity undertaken, equipment, personnel, legislative, BS or SOP requirements. Otherwise, the risk assessment will remain valid for a period of up to two years after which it must be reviewed and updated as necessary.

## PART A: Assessment details

| | | | |
|---|---|---|---|
| **Name of Club or Centre:** | Hinton Skydiving Centre | **Person carrying out this Risk Assessment:** | Geoff Wood |
| **Address:** | Hinton Airfield, Steane, Brackley, Northants. NN13 5NS | **Signature:** | *R G Wood* |
| **Telephone Number:** | 01295 812300 | **Date of Assessment:** | 24/09/25 |
| **Club Chief Instructor:** | Stuart Meacock | **Latest Review Date:** | 24/09/25 |

## PART B: Risk level matrix

**Likelihood:**

| | |
|---|---|
| **1** | **Improbable** |
| **2** | **Unlikely** |
| **3** | **Even chance** |
| **4** | **Likely** |
| **5** | **Almost certain** |

**Severity:**

| | |
|---|---|
| **1** | **No or trivial injury / ill health** |
| **2** | **Minor or slight injury / illness** |
| **3** | **Significant injury / ill health** |
| **4** | **Incapacity** |
| **5** | **Fatal** |

**Risk Level Matrix:**

| Likelihood | | | | | | |
|---|---|---|---|---|---|---|
| | 5 | 5 | 10 | 15 | 20 | 25 |
| | 4 | 4 | 8 | 12 | 16 | 20 |
| | 3 | 3 | 6 | 9 | 12 | 15 |
| | 2 | 2 | 4 | 6 | 8 | 10 |
| | 1 | 1 | 2 | 3 | 4 | 5 |
| | | 1 | 2 | 3 | 4 | 5 |
| | | Severity | | | | |

**Key**

| | |
|---|---|
| | **Intolerable** |
| | **High** |
| | **Moderate** |
| | **Low** |
| | **Insignificant (ignore)** |

Date amended: 24/09/25 Revision No: 023 Date Implemented: 24/09/25

# Hinton Skydiving Centre Risk Assessment Form

| HAZARD / TASK OR ACTIVITY | WHO MIGHT BE HARMED? | PRE-CONTROL RISK RATING | EXISTING CONTROLS | ADDITIONAL CONTROLS | POST CONTROL RISK RATING |
|---|---|---|---|---|---|
| Training equipment and associated activities | Students undertaking training | 2 x 2 | All students under supervision are trained by competent instructors. The training area is cleaned daily by the full time staff. The training area is always inspected prior to commencement of training by the duty instructor.<br><br>PLF and aircraft exits mats are provided to cushion impact on feet and additionally prevent injury should any student fall over. Only lightweight demo equipment is used for aircraft exits and drills to reduce possible injuries. All students must be of a physical condition to be able to undertake the training. Warm up exercises are completed prior to any physical activity.<br><br>Students are required to declare themselves physically fit by completion of medical either self declaration or via GP. | All students are weighed to assure compliance with weight limits imposed by the Centre and wing loadings on the student equipment. | 1 x 2 |

# Hinton Skydiving Centre Risk Assessment Form

| HAZARD / TASK OR ACTIVITY | WHO MIGHT BE HARMED? | PRE-CONTROL RISK RATING | EXISTING CONTROLS | ADDITIONAL CONTROLS | POST CONTROL RISK RATING |
|---|---|---|---|---|---|
| Failure of Cypres unit. (conscious) | All skydivers | 2 x 3 | All Cypres units are serviced as per the manufacturers recommendations by the manufacturers. | Equipment records at the Centre highlight when each unit requires servicing, therefore no unit will be used when the service date or battery expires. | 1 x 1 |
| Failure of Cypres unit. (unconscious) | All skydivers | 2 x 5 | | | 1 x 3 |
| Failure of student radio | Student static line or freefall skydivers | 2 x 4 | All radios are checked before any skydiving takes place and batteries are recharged daily. (Section 6, BS Ops Manual). These are again tested once placed on the student equipment to confirm operation and that students can hear them. Any adjustments are completed before emplaning. Any radios that are found to be not working will be taken out of service until tested and repaired as part of the planned preventive maintenance. All students have been training in canopy control for both main and reserve parachutes.<br><br>Radio is a back up device and may breakdown or fail. | | 1 x 2 |

**Hinton Skydiving Centre Risk Assessment Form**

| HAZARD / TASK OR ACTIVITY | WHO MIGHT BE HARMED? | PRE-CONTROL RISK RATING | EXISTING CONTROLS | ADDITIONAL CONTROLS | POST CONTROL RISK RATING |
|---|---|---|---|---|---|
| Malfunction of main parachute - static line or freefall | Student skydivers | 2 x 4 | All student equipment at the Centre is packed by a competent person (approved packer, Section 6 Equipment, BS Ops Manual). All equipment has a packing log and is checked and signed at 4 stages. Each set of equipment is maintained and inspected at regular intervals (Section 14 Rigging, BS Ops Manual). All equipment is fitted with a reserve parachute, RSL and Cypres unit. All categories of parachutists have received training with regard to malfunction procedures. | Radio backup.<br><br>Stabilty is reinforced on every brief thoroughout students' progression.<br><br>Practical exits, with equipment on, are undertaken.<br><br>Reserve drills practiced daily. | 2 x 2 |
| Malfunction of main parachute Tandem | Tandem skydivers | 2 x 4 | As above including tandem equipment, instructor trained to be competent to identify and deal with a malfunctioning parachute. | Reserve drills practiced daily. | 2 x 2 |
| Malfunction of experienced skydiver's parachute | Experienced skydivers | 2 x 4 | Experienced skydivers competent in packing their own parachute and have knowledge and training of how to deal with a malfunction. | Reserve drills practiced daily. | 2 x 2 |

# Hinton Skydiving Centre Risk Assessment Form

| HAZARD / TASK OR ACTIVITY | WHO MIGHT BE HARMED? | PRE-CONTROL RISK RATING | EXISTING CONTROLS | ADDITIONAL CONTROLS | POST CONTROL RISK RATING |
|---|---|---|---|---|---|
| Static line hangup (conscious) | Any static line student | 1 x 3 | All students trained in stability and exits from aircraft (Section 5 Training, BS Ops Manual). Static line is checked prior to student exiting aircraft for any entaglements with student or equipment. Instructor is in full control of the static line of the student exiting the aircraft and observes the delpoyment sequence of their main parachute to prevent the possibilty of a hang up (Section 10 Safety, BS Ops Manual). Aircarft and door inspected before static line operations begin.<br><br>Students have been trained and briefed should a hangup occur. Instructor and pilot aware of procedures should this happen (Section 10 Safety, BS Ops Manual). Additional procedures are in place should the student become unconscious. | | 1 x 2 |
| Static line hangup (unconscious) | Any static line student | 1 x 5 | | | 1 x 3 |

# Hinton Skydiving Centre Risk Assessment Form

| HAZARD / TASK OR ACTIVITY | WHO MIGHT BE HARMED? | PRE-CONTROL RISK RATING | EXISTING CONTROLS | ADDITIONAL CONTROLS | POST CONTROL RISK RATING |
|---|---|---|---|---|---|
| Contacting moving aircraft or propellor | Student and experienced skydivers | 2 x 5 | Experienced skydivers are aware of precautions to take when emplaning the aircraft due to their experience and therefore present a lower potential risk. Designated jumpmaster on each lift will co-ordinate the safe emplaning procedure (Section 3 Jumpmasters, BS Ops Manual). Aircraft will be stationary before emplaning begins (Section 10 Safety, BS Ops Manual). | Skydivers must remain at the designated emplaning point with nominated JM or Instructor and will not approach aircraft until it is stationary. | 1 x 5 |
| | | 2 x 5 | Student skydivers will be under the supervision of a qualfied instructor. Aircraft will be stationary before emplaning begins. (Section 10 Safety, BS Ops Manual). All students have received training in how to approach the aircaft in a safe manner (Section 5, BS Ops Manual).<br><br>No skydiver, student or experienced, must approach any aircraft from forward of the wings (Section 10, BS Ops Manual). | Restrict aircraft movements on ground or do not allow to start up until parachute dropping is complete. | 1 x 5 |

Date amended: 24/09/25 Revision No: 023 Date Implemented: 24/09/25

# Hinton Skydiving Centre Risk Assessment Form

| HAZARD / TASK OR ACTIVITY | WHO MIGHT BE HARMED? | PRE-CONTROL RISK RATING | EXISTING CONTROLS | ADDITIONAL CONTROLS | POST CONTROL RISK RATING |
|---|---|---|---|---|---|

| | | | | | |
|---|---|---|---|---|---|
| Premature opening of main or reserve parachute whilst in aircraft | Student (S/L + F/F) Tandem and experienced skydivers | 2 x 3 | All skydivers have been trained should the event occur (Section 5 Training& Section 10 Safety, BS Ops Manual). Each aircraft lift will have a designated jumpmaster who will take charge if such an event occurs. (Section 3 Jumpmasters, BS Ops Manual). All equipment is checked before emplaning and prior to any student exiting the aircraft. All equipment is maintained as per manufactures' recommendations (Section 6 Equipment, BS Ops Manual).<br><br>Aircraft jump door is closed after reaching 1000' and only opened again on jump run. | Aircraft has inflight door to prevent prematurely deployed parachute escaping into slipstream.<br><br>Skydiver will be moved, where possible, away from the door and the aircraft will land with all remaining skydivers on board (Section 10 Safety, BS Ops Manual). | 1 x 3 |

## Hinton Skydiving Centre Risk Assessment Form

| HAZARD / TASK | WHO MIGHT BE | PRE-CONTROL | EXISTING | ADDITIONAL | POST |
|---|---|---|---|---|---|

Date amended: 24/09/25 Revision No: 023 Date Implemented: 24/09/25

| OR ACTIVITY | HARMED? | RISK RATING | CONTROLS | CONTROLS | CONTROL RISK RATING |
|---|---|---|---|---|---|
| Aircraft engine or structural failure | All skydivers and pilot | 2 x 5 | Aircraft must be suitable for skydiving and maintained as per manufactures recommendations (Section 9 Flying, BS Ops Manual). Aircraft has rigorous maintenance regime carried out by suitable approved and qualified aircraft engineers. Only suitably competent pilots authorised to fly. Aircraft checked before beginning of every day by duty pilot. Should aircraft emergency occur, pilot has knowledge of areas considered safe to land if away from DZ. Jumpmaster trained and competent in dealing with such situations (Section 3 Jumpmasters, BS Ops Manual). All skydivers have been trained in event of such emergency (Section 5 Training, BS Ops Manual) . Fuel is checked daily on aircraft and refueling system and recorded accordingly. Emergency vehicle available on airfield with access to all areas. | CAA CAP 748 Fuel management | 1 x 5 |

## Hinton Skydiving Centre Risk Assessment Form

| HAZARD / TASK OR ACTIVITY | WHO MIGHT BE HARMED? | PRE-CONTROL RISK RATING | EXISTING CONTROLS | ADDITIONAL CONTROLS | POST CONTROL |
|---|---|---|---|---|---|

| | | | | | RISK RATING |
|---|---|---|---|---|---|
| Body entanglement with main parachute on deployment | Any static line student, freefall student or experienced skydiver | 2 x 5 | All students are trained in stability and exits. Freefall students are briefed on procedures to stop instability on deployment of main parachute (Section 5 Training, BS Ops Manual).<br>Instructor will ensure students leave aircraft as square into relative slipstream as possible to prevent possible entanglement and control static line (Section 10 Safety, BS Ops Manual). All students have received training on how to react to this situation.<br>Any student progression will include re-inforcement of stability on delpoyment (Section 5 training BS Ops Manual).<br>Students practice exits from aircraft wearing dummy equipment to assist and familiarise them with the exit positions and weight of equipment (Section 5 Training, BS Ops Manual) Cypres units fitted on all student equipment. | | 2 x 3 |

# Hinton Skydiving Centre Risk Assessment Form

| HAZARD / TASK OR ACTIVITY | WHO MIGHT BE HARMED? | PRE-CONTROL RISK RATING | EXISTING CONTROLS | ADDITIONAL CONTROLS | POST CONTROL RISK RATING |
|---|---|---|---|---|---|
| Injury to skydiver on landing | All skydivers | 2 x 4 | Student (S/L + F/F) skydivers. All students are trained in parachute landing techniques for both main and reserve parachutes (Section 5 Training, BS Ops Manual). In addition all students are under radio instruction and supervision. Parachuting will only take place if conditions are suitable (Section 8, BS Ops Manual). All student skydivers are fully briefed on their descent they are to undertake on the flight line before emplaning.<br>Tandem students are trained and briefed to keep legs and feet up for landing and to remain with instructor until all skydivers have descended<br>Experienced Skydivers present a higher risk of injury on landings due to possible complacency. Equipment is checked for correct weight to canopy size ratio against their experience by the CCI.<br><br>All parachutists are reminded that low turns close to the ground are unacceptable. | If injury occurs to a skydiver who has landed on the runway and cannot be removed immediately, other suitable runways may be used to land.<br><br>Qualified first-aiders on site.<br><br>All skydivers to land under a flat and level canopy, into wind as designated by DZ control and shown on all DZ maps.<br><br>BS campaign and safety notices posted around DZ. | 2 x 3 |

# Hinton Skydiving Centre Risk Assessment Form

| HAZARD / TASK OR ACTIVITY | WHO MIGHT BE HARMED? | PRE-CONTROL RISK RATING | EXISTING CONTROLS | ADDITIONAL CONTROLS | POST CONTROL RISK RATING |
|---|---|---|---|---|---|
| Canopy collisons | Student skydivers | 2 x 3 | All students receive training in canopy control and collision avoidance (Section 5, BS Ops Manual). All students are under radio supervision. Students on static line and or freefall will exit one or two per pass depending on wind direction, with a substantial gap between each student. This is part of the jumpmaster's responsibility. No students will be despatched if the intended landing area is not visible (Section 8, BS Ops Manual). All students are under radio supervision. Large student landing area to avoid problems close to the ground. | Pilots are trained and briefed on student dispatching requirements and passess required. Lengths of circuits are timed to avoid descending student skydivers from catching up with previously dispatched students. Large docile student canopies are used. | 1 x 3 |
| | Experienced skydivers | 2 x 4 | Experienced skydivers track away to clear airspace and wave their intentions to deploy. All have knowledge in collision avoidance. | Landing patterns in force throughout the parachuting programme. | 2 x 4 |

# Hinton Skydiving Centre Risk Assessment Form

| HAZARD / TASK OR ACTIVITY | WHO MIGHT BE HARMED? | PRE-CONTROL RISK RATING | EXISTING CONTROLS | ADDITIONAL CONTROLS | POST CONTROL RISK RATING |
|---|---|---|---|---|---|
| Freefall collison and collision on deployment | Experienced Skydivers | 2 x 4 | Experienced skydivers are aware of the necessity to avoid freefall collisons and the potential risk should this occur. They are equipped with two serviceable parachutes and wear protective head gear.<br><br>Skydivers track away at the completion of their jump. All skydivers notify their intention of deployment by waving off. Minimum opening and breakoff heights are used (Section 8, BS Ops Manual).<br><br>All experienced skydivers have been trained in cutaway procedures. Each group exiting the aircraft will allow sufficent separation between groups as an additional precaution which is monitored by the jumpmaster. | All skydivers wear suitable protective head gear. Skydivers may use additional equipment such as Cypres units which are mandatory on all student equipment.<br><br>Jumpmaster may wish to nominate additional competent persons to assist control/ separation of exiting skydivers should the jumpmaster exit before aircraft is empty. | 1 x 4 |
| | AFF students and instructors | 2 x 5 | Students are under constant supervision. All are trained in stability and in air signals. All student equipment is fitted with Cypres. | Skydivers exit order is co-ordinated from low to high pull heights. | 1 x 4 |

Date amended: 24/09/25 Revision No: 023 Date Implemented: 24/09/25

# Hinton Skydiving Centre Risk Assessment Form

| HAZARD / TASK OR ACTIVITY | WHO MIGHT BE HARMED? | PRE-CONTROL RISK RATING | EXISTING CONTROLS | ADDITIONAL CONTROLS | POST CONTROL RISK RATING |
|---|---|---|---|---|---|

| | | | | | |
|---|---|---|---|---|---|
| Refuelling aircraft (fire and asscoiated risks) | Pilots | 2 x 5 | Refuelling station is some distance from any public area and is operated by Richard Harrison of Walltree Ltd.<br><br>No smoking or naked flames allowed within vicinty. No electrical radio equipment or mobile phones in vicinty of refuelling pocess. Fire fighting provision in place with appropraite vehicle and portable fire extingushiers. | Avgas and kerosene are approriatley marked to prevent filling aircraft with incorrect type.<br>Safe sytem of work in place for refueling, to incorporate emergency procedures and control of spillage sytsem. | 1 x 2 |
| Contaminated fuel | Pilot and skydivers | 1 x 5 | Aircraft fuel is checked and recorded at the beginning of every flight day by the duty pilot. | CAP 748 Aircraft fueling and fuel installation management and CAP 393 Articles for licensed airfields and Articles for unlicensed airfields. | 1 x 3 |
| Hazardous substances (aviation fuels and oils) | Pilots | 1 x 1 | Richard Harrison of Walltree Ltd keeps all relevant paperwork and enforces all necessary controls. | See Richard Harrison at Walltree Ltd | 1 x 1 |

## Hinton Skydiving Centre Risk Assessment Form

| HAZARD / TASK OR ACTIVITY | WHO MIGHT BE HARMED? | PRE-CONTROL RISK RATING | EXISTING CONTROLS | ADDITIONAL CONTROLS | POST CONTROL RISK RATING |
|---|---|---|---|---|---|

| | | | | | |
|---|---|---|---|---|---|
| Aircraft and glider infringments of DZ airspace. | Pilot and skydivers | 2 x 5 | LATCC, Birmingham Control and RAF Brize Norton Ops informed of start and potential finish times. FIR / FIS AND Turweston Tower also informed. All logged on ATSU form. If any infringments occur, all parachuting will be suspended until it is safe to continue parachuting (Section 1, BS Ops Manual).<br>Any infringement is logged on ATSU form and relative authorities notifed.<br><br>Visual observation is in place whilst parachuting is undertaken and no parachutists will be released from aircraft until clear drop authoristion is received from ground.<br><br>All registration details of infringing aircraft are recorded.<br><br>Operating agreement in place with Aquila Gliding Club and local PFA. | DZ control permantly staffed during parachuting sorties.<br><br>Additional radio contact with local flying club and Aquila gliding Club.<br><br>PFA and Aquila notified of cone of operation and map posted on airfield notice board and at glider HQ.<br><br>All aircraft registrations are traced on the CAA website and pilots contacted to remind them of their responsibilities. | 1 x 5 |

## Hinton Skydiving Centre Risk Assessment Form

| HAZARD / TASK OR ACTIVITY | WHO MIGHT BE HARMED? | PRE-CONTROL RISK RATING | EXISTING CONTROLS | ADDITIONAL CONTROLS | POST CONTROL |
|---|---|---|---|---|---|

| | | | | | RISK RATING |
|---|---|---|---|---|---|
| Serviceability of parachute equipment | Student skydivers | 2 x 5 | All equipment is maintained in a serviceable condition (Section 6, BS Ops Manual). Only qualified packers allowed to sign off the four stages checks. Each set of equipment is checked after each jump and is packed and inspected before being returned to stores. All equipment is inspected and repacked and signed off for servicability by Pat Jones, (Rigger), in a period not exceeding 6 months. Maintenance logs for each set of equipment are kept and updated accordingly. Any equipment found with a fault is withdrawn from service until repaired. This forms part of the Planned Preventative Maintenance for each set of equipment. All students are trained in use of equipment and this is documented where appropriate. | All auxillary equipment e.g. Cypres units, maintained to manufacturers' specification . | 1 x 5 |
| | Experienced skydivers | 2 x 5 | Responsible for their own equipmnet but all skydivers' equipment will be checked for reserve currency and that the equipment is serviceable. All equipment tagged with reserve repack date and will not be jumped without a kit tag. | Kit checked on flight line and will not be jumped unless reserve is in date. | 1 x 5 |

# Hinton Skydiving Centre Risk Assessment Form

| HAZARD / TASK OR ACTIVITY | WHO MIGHT BE HARMED? | PRE-CONTROL RISK RATING | EXISTING CONTROLS | ADDITIONAL CONTROLS | POST CONTROL RISK RATING |
|---|---|---|---|---|---|
| Descending skydivers; movement of aircraft; associated plant and machinery | Visitors and spectators at the Centre | 2 x 4 | Spectators and visitors area is fenced off away from parachute landing areas, aircraft and associated plant / machinery. Fence approx 1.5m height.<br><br>Notice posted of restricted access airside.<br><br>Access to airside restricted to authorised staff and emplaning skydivers only.<br><br>Viewing area monitored from DZ control point by DZ Controller, Club Chief Instructor and other competent persons (staff). | Controlled access and egress to Centre by motor vehicles by means of enforced speed limits and barriers.<br><br>Access restricted to airfield (airside) and runways.<br><br>Runway threshold is signed with warning notices. | 1 x 4 |

Date amended: 24/09/25 Revision No: 023 Date Implemented: 24/09/25

# Hinton Skydiving Centre Risk Assessment Form

| HAZARD / TASK OR ACTIVITY | WHO MIGHT BE HARMED? | PRE-CONTROL RISK RATING | EXISTING CONTROLS | ADDITIONAL CONTROLS | POST CONTROL RISK RATING |
|---|---|---|---|---|---|
| COVID 19 | | | | | |
| Please refer to covid protocol paperwork. | Instructors / Students | 2 X 2 | Track and Trace, temperature checks, masks in sensitive areas and on the aircraft at all times when the door is closed. | Limit of numbers on the aircraft. | 1 X 2 |

Date amended: 24/09/25 Revision No: 023 Date Implemented: 24/09/25

# Hinton Skydiving Centre Risk Assessment Form

| HAZARD / TASK OR ACTIVITY | WHO MIGHT BE HARMED? | PRE-CONTROL RISK RATING | EXISTING CONTROLS | ADDITIONAL CONTROLS | POST CONTROL RISK RATING |
|---|---|---|---|---|---|

Date amended: 24/09/25 Revision No: 023 Date Implemented: 24/09/25

# Hinton Skydiving Centre Risk Assessment Form

| HAZARD / TASK OR ACTIVITY | WHO MIGHT BE HARMED? | PRE-CONTROL RISK RATING | EXISTING CONTROLS | ADDITIONAL CONTROLS | POST CONTROL RISK RATING |
|---|---|---|---|---|---|
| | | | | | |

## REVIEW SHEET

| DATE | INCIDENT | RECOMMENDATIONS | CONCLUSION |
|---|---|---|---|
| 04/01/06 | Annual review | No change | N/A |
| 11/0107 | Annual review | No change | N/A |
| 22/04/07 | New A/c | Review of policy. | Notices In a/c updated to current reqiremets. |
| 10/01/08 | Annual review | No change | N/A |
| 06/06/08 | Addition of ATC at Turweston | Turweston tower to be contacted before starting parachuting. | Extra safety introduced as more pilots now notified. |
| 03/01/09 | Annual review | No change | N/A |
| 14/02/09 | Addtion of FIR/FIS notification to ATSU | Contact on start up. | Extra safety introduced as more pilots now notified. |
| 22/08/09 | Injury to Tetraplegic skydiver kitting up. | Not enough awareness from staff when dealing with SI jumpers | All staff attend a course on SI handling techniques. Completed 14/09/09 |
| 07/01/10 | Annual review | No change | N/A |

| | | | |
|---|---|---|---|
| **08/02/11** | **Annual review** | **No change** | **N/A** |

| DATE | INCIDENT | RECOMMENDATIONS | CONCLUSION |
|---|---|---|---|
| **16/03/12** | **Late Annual review** | **Spot check all BS memberships prior to new season.** | **Office staff to implement handover notes log.** |
| **12/02/13** | **Annual review** | **No change** | **N/A** |
| **10/02/14** | **Annual review** | **No Change** | **N/A** |
| **10/03/15** | **Injury to student on landing.**<br><br>**Annual review.** | **Reinforce landing position procedures for turbulent conditions.** | **All Tandem instructional staff briefed.** |
| **12/03/16** | **Annual review** | **No Change** | **N/A** |
| **08/02/17** | **Annual review** | **No change** | **N/A** |
| **16/09/17** | **Injury to student** | **Reinforce medical requirements to students.** | **All Tandem instructional staff briefed.** |
| **31/03/18** | **Annual review** | **No change** | **N/A** |
| **02/04/19** | **Annual review** | **No change** | **N/A** |

| | | | |
|---|---|---|---|
| **04/07/20** | **Covid 19 review** | **Please refer to new covid section.** | **Please refer to new covid section.** |

| DATE | INCIDENT | RECOMMENDATIONS | CONCLUSION |
|---|---|---|---|
| **20/04/21** | **HPLA implimentation** | **Refer to SOP's Appendix 5** | **All CT 3 CT 4 members Monitored by CI** |
| **30/05/21** | **Review after student injury J Seidler** | **No Change** | **N/A** |
| **21/01/22** | **Annual review** | **No Change** | **N/A** |
| **30/01/23** | **Annual review** | **No Change** | **N/A** |
| **17/09/23** | **Review after tandem student dislocation** | **No Change** | **N/A** |
| **24/09/25** | **Bi-Annual review** | **No Change** | **N/A** |
| | | | |
| | | | |
| | | | |
| | | | |