

2016.0 RANGE ROVER (LG), 100-00

GENERAL INFORMATION

DESCRIPTION AND OPERATION

BLINDSPOT MONITORING CONTROL MODULE (BMCM) - LEFT/RIGHT

CAUTION:

Diagnosis by substitution from a donor vehicle is **NOT** acceptable.
Substitution of control modules does not guarantee confirmation of a fault, and may also cause additional faults in the vehicle being tested and/or the donor vehicle.

NOTES:

- If a control module or a component is suspect and the vehicle remains under manufacturer warranty, refer to the Warranty Policy and Procedures manual, or determine if any prior approval programme is in operation, prior to the installation of a new module/component.
- Generic scan tools may not read the codes listed, or may read only 5-digit codes. Match the 5 digits from the scan tool to the first 5 digits of the 7-digit code listed to identify the fault (the last 2 digits give extra information read by the manufacturer-approved diagnostic system).
- When performing voltage or resistance tests, always use a digital multimeter accurate to three decimal places, and with an up-to-date calibration certificate. When testing resistance always take the resistance of the digital multimeter leads into account.
- Check and rectify basic faults before beginning diagnostic routines involving pinpoint tests.
- Inspect connectors for signs of water ingress, and pins for damage and/or corrosion.
- If DTCs are recorded and, after performing the pinpoint tests, a fault is not present, an intermittent concern may be the cause. Always check for loose connections and corroded terminals.
- Check DDW for open campaigns. Refer to the corresponding bulletins and SSMs which may be valid for the specific customer complaint and carry out the recommendations as required.

The table below lists all Diagnostic Trouble Codes (DTCs) that could be logged in the Blindspot Monitoring Control Module (BMCM) - Left/Right. For additional diagnosis and testing information, refer to the relevant Diagnosis and Testing section in the workshop manual.

For additional information, refer to: [Warning Devices](#) (413-09A Warning

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U0010-87	Medium Speed CAN Communication Bus - Missing message	Missing message from another control module via the medium speed CAN bus (comfort)	Using the manufacturer approved diagnostic system, check the snapshot data to determine the missing message source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index
U0010-88	Medium Speed CAN Communication Bus - Bus off	Medium speed CAN bus (comfort) circuit short circuit to ground, short circuit to power, open circuit, high resistance	Using the manufacturer approved diagnostic system, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the medium speed CAN bus (comfort) circuit for short circuit to ground, short circuit to power, open circuit, high resistance
U0300-00	Internal Control Module Software Incompatibility - No sub type information	- Car configuration file mismatch with vehicle specification - Left/right blindspot monitoring control module is not configured correctly - Incorrect left/right blindspot monitoring control module installed	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs - Using the manufacturer approved diagnostic system, check and up-date the car configuration file as necessary - Using the manufacturer approved diagnostic system, re-configure the left/right blindspot monitoring control module with the latest level software - Install a new left/right blindspot monitoring control module as necessary
U1000-00	Solid State Driver Protection	Left/right blindspot monitoring	Using the manufacturer approved diagnostic system, clear the DTCs and retest. If the fault persists, install a new

	Activated -Driver Disabled - No sub type information	control module internal failure	left/right blindspot monitoring control module
U1A00-88	Private Communication Network - Bus off	▪ Opposite side blindspot monitoring control module power or ground circuit open circuit, high resistance ▪ Private CAN bus circuit short circuit to ground, short circuit to power, open circuit, high resistance ▪ Opposite side blindspot monitoring system fault	▪ Refer to the electrical circuit diagrams and check the opposite side blindspot monitoring control module power and ground circuits for open circuit, high resistance ▪ Refer to the electrical circuit diagrams and check the private CAN bus circuit for short circuit to ground, short circuit to power, open circuit, high resistance ▪ Using the manufacturer approved diagnostic system, check the opposite side blindspot monitoring control module for related DTCs and refer to the relevant DTC index
U2100-00	Initial Configuration Not Complete - No sub type information	▪ Left/right blindspot monitoring control module is not configured correctly	▪ Using the manufacturer approved diagnostic system, re-configure the left/right blindspot monitoring control module with the latest level software
U2101-00	Control Module Configuration Incompatible - No sub type information	▪ Car configuration file mismatch with vehicle specification	NOTE: After updating the car configuration file, set the ignition to on and wait 30 seconds before clearing the DTCs ▪ Using the manufacturer approved diagnostic system, check and up-date the car configuration file as necessary
U3000-	Control	▪ Left/right	▪ Using the manufacturer approved

44	Module - Data memory failure	■ blindspot monitoring control module internal failure	diagnostic system, clear the DTCs and retest. If the fault persists, install a new left/right blindspot monitoring control module
U3000-45	Control Module - Program memory failure	■ Left/right blindspot monitoring control module internal failure	■ Using the manufacturer approved diagnostic system, clear the DTCs and retest. If the fault persists, install a new left/right blindspot monitoring control module
U3000-46	Control Module - Calibration / parameter memory failure	■ Blindspot monitoring control module internal failure	■ Using the manufacturer approved diagnostic system, clear the DTCs and retest. If the fault persists, install a new blindspot monitoring control module
U3000-48	Control Module - Supervision software failure	■ Left/right blindspot monitoring control module internal failure	■ Using the manufacturer approved diagnostic system, clear the DTCs and retest. If the fault persists, install a new left/right blindspot monitoring control module
U3000-49	Control Module - Internal electronic failure	■ Left/right blindspot monitoring control module internal failure	■ Using the manufacturer approved diagnostic system, clear the DTCs and retest. If the fault persists, install a new left/right blindspot monitoring control module
U3000-78	Control Module - Alignment or adjustment incorrect	■ Left/right blindspot monitoring control module incorrectly installed ■ Left/right blindspot monitoring control module internal failure	NOTE: If the DTC is cleared, a test drive of at least 40 minutes duration is required in order to confirm that the fault is rectified (the DTC will not set again prior to this interval) ■ Check the left/right blindspot monitoring control module for correct installation

- | | | | |
|--|--|--|---|
| | | | <ul style="list-style-type: none">▪ Using the manufacturer approved diagnostic system, clear the DTCs and retest. If the fault persists, install a new left/right blindspot monitoring control module |
|--|--|--|---|