

2016.0 RANGE ROVER (LG), 100-00

GENERAL INFORMATION

DESCRIPTION AND OPERATION

CAUTIONS:

- Diagnosis by substitution from a donor vehicle is **NOT** acceptable. Substitution of control modules does not guarantee confirmation of a fault, and may also cause additional faults in the vehicle being tested and/or the donor vehicle
- When probing connectors to take measurements in the course of the pinpoint tests, use the adaptor kit, part number 3548-1358-00

NOTES:

- If the control module or a component is suspect and the vehicle remains under manufacturer warranty, refer to the warranty policy and procedures manual (section B1.2), or determine if any prior approval programme is in operation, prior to the installation of a new module/component.
- Generic scan tools may not read the codes listed, or may read only 5-digit codes. Match the 5 digits from the scan tool to the first 5 digits of the 7-digit code listed to identify the fault (the last 2 digits give extra information read by the manufacturer-approved diagnostic system)
- When performing voltage or resistance tests, always use a digital multimeter accurate to three decimal places and with a current calibration certificate. When testing resistance, always take the resistance of the digital multimeter leads into account
- Check and rectify basic faults before beginning diagnostic routines involving pinpoint tests
- Inspect connectors and modules for signs of water ingress, and pins for damage and/or corrosion
- If diagnostic trouble codes are recorded and, after performing the pinpoint tests, a fault is not present, an intermittent concern may be the cause. Always check for loose connections and corroded terminals
- Where an 'on demand self-test' is referred to, this can be accessed via the 'diagnostic trouble code monitor' tab on the manufacturers approved diagnostic system

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
U0010-88	Medium Speed CAN Communication Bus - Bus off	▪ Medium speed CAN bus (comfort) circuit short circuit to ground, short circuit	▪ Using the manufacturer approved diagnostic system, perform a CAN network integrity test. Refer to the

		to power, open circuit, high resistance	electrical circuit diagrams and check the medium speed CAN bus (comfort) circuit for short circuit to ground, short circuit to power, open circuit, high resistance
U0011-81	Medium Speed CAN Communication Bus Performance - Invalid Serial Data Received	Invalid data received from another control module via the medium speed CAN bus (comfort)	Using the manufacturer approved diagnostic system, check the snapshot data to determine the invalid data source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index
U0011-87	Medium Speed CAN Communication Bus Performance - Missing Message	Missing message from another control module via the medium speed CAN bus (comfort)	Using the manufacturer approved diagnostic system, check the snapshot data to determine the missing message source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index
U2101-56	Control Module Configuration Incompatible - Invalid / Incomplete Configuration	Car configuration file mismatch with vehicle specification	Using the manufacturer approved diagnostic system, check and up-date the car configuration file as necessary
U3000-14	Control Module - Circuit Short To Ground Or Open	NOTE: Circuit reference - FAN CONTROL Short circuit to ground between the head up display cooling fan control module and the head-up display cooling fan	Refer to the electrical circuit diagrams and check the head-up display cooling fan circuit for short circuit to ground, open circuit

U3000-49	Control Module - Internal Electronic Failure	▪ Head up display cooling fan control module failure	▪ Using the manufacturer approved diagnostic system, clear the DTCs and retest. If the fault persists, install a new head up display cooling fan control module
----------	--	--	---