

2016.0 RANGE ROVER (LG), 100-00

GENERAL INFORMATION

DESCRIPTION AND OPERATION

OCCUPANT CLASSIFICATION SENSOR CONTROL MODULE (OCSCM)

WARNINGS:

- TO AVOID ACCIDENTAL DEPLOYMENT AND POSSIBLE PERSONAL INJURY, THE BACKUP POWER SUPPLY MUST BE DEPLETED BEFORE REPAIRING OR REPLACING ANY AIR BAG SUPPLEMENTAL RESTRAINT SYSTEM (SRS) COMPONENTS. TO DEplete THE BACKUP POWER SUPPLY ENERGY, DISCONNECT THE BATTERY GROUND CABLE AND WAIT ONE MINUTE. FAILURE TO FOLLOW THIS INSTRUCTION MAY RESULT IN PERSONAL INJURY.
- Do not use a multimeter to probe the restraints control module. It is possible for the power from the meter battery to trigger the activation of the airbags. Failure to follow this instruction may result in personal injury.

CAUTION:

Diagnosis by substitution from a donor vehicle is **NOT** acceptable. Substitution of control modules does not guarantee confirmation of a fault, and may also cause additional faults in the vehicle being tested and/or the donor vehicle.

NOTES:

- If a control module or a component is suspect and the vehicle remains under manufacturer warranty, refer to the Warranty Policy and Procedures manual, or determine if any prior approval programme is in operation, prior to the installation of a new module/component.
- Generic scan tools may not read the codes listed, or may read only 5-digit codes. Match the 5 digits from the scan tool to the first 5 digits of the 7-digit code listed to identify the fault (the last 2 digits give extra information read by the manufacturer-approved diagnostic system).
- When performing voltage or resistance tests, always use a digital multimeter accurate to three decimal places, and with an up-to-date calibration certificate. When testing resistance always take the resistance of the digital multimeter leads into account.
- Check and rectify basic faults before beginning diagnostic routines involving pinpoint tests.
- Inspect connectors for signs of water ingress, and pins for damage and/or corrosion.
- If DTCs are recorded and, after performing the pinpoint tests, a fault is not present, an intermittent concern may be the cause. Always check for loose connections and corroded terminals.
- Check DDW for open campaigns. Refer to the corresponding

bulletins and SSMS which may be valid for the specific customer complaint and carry out the recommendations as required.

- It is advisable not to use a cellular phone or to have a cellular phone in close proximity when working on the restraints control module or associated systems.
- Given the legal implications of a restraints system failure, harness repairs to Air Bag module circuits are not acceptable. Where the text refers to "REPAIR the circuit", this will normally mean the replacement of a harness.

The table below lists all Diagnostic Trouble Codes (DTCs) that could be logged in the Occupant Classification Sensor Control Module (OCSCM). For additional diagnosis and testing information, refer to the relevant Diagnosis and Testing section in the workshop manual.

For additional information, refer to: [Airbag Supplemental Restraint System](#) (501-20B Supplemental Restraint System, Diagnosis and Testing).

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B00C0-7B	Passenger Seat Occupant Classification Sensor "A" - Low fluid level	▪ Occupant detection sensor fault ▪ Silicon filled bladder hose is loose ▪ Seat unbolted and at an angle or not in correct installed position ▪ Silicon filled bladder has been damaged and requires replacement	NOTE: Do not try to solely change the module fitted to the bladder hose as it is calibrated as an integral assembly with the seat cushion foam ▪ Check if bladder hose with pressure sensor is loose. Attach hose and pressure sensor to the seat in original position. Clear DTC and retest ▪ If fault persists, check if the seat and associated fixings are correctly installed. Rectify installation as required. Clear DTC and retest ▪ If fault persists, check if the

			silicon filled bladder assembly for leaks. Clear DTC and retest ▪ If fault persists, check and install a new occupant classification sensor service kit as required (complete service kit consists of foam, occupant classification sensor bladder mat with attached smart digital pressure sensor)
B00C1-11	Passenger Seat Occupant Classification Sensor "B" - Circuit short to ground	NOTE: Circuit reference BTS / BTS-VREF ▪ Seatbelt tension sensor circuit short circuit to ground	▪ Refer to the electrical circuit diagrams and check the seatbelt tension sensor circuit for short circuit to ground
B00C1-12	Passenger Seat Occupant Classification Sensor "B" - Circuit short to battery	NOTE: Circuit reference IGN / BTS / BTS-VREF / GND ▪ Seatbelt tension sensor circuit short circuit to power	▪ Refer to the electrical circuit diagrams and check the seatbelt tension sensor circuit for short circuit to power
B00C1-13	Passenger Seat Occupant Classification Sensor "B" - Circuit open	NOTE: Circuit reference BTS / BTS-VREF ▪ Seatbelt tension sensor circuit open circuit, high resistance	▪ Refer to the electrical circuit diagrams and check the seatbelt tension sensor circuit for open circuit, high resistance

B00C1-97	Passenger Seat Occupant Classification Sensor "B" - Component or system operation obstructed or blocked	▪ Seatbelt tension sensor internal failure	▪ Using the manufacturer approved diagnostic system, clear the DTCs and retest. If the fault persists, install a new seatbelt tension sensor
U0001-87	High Speed CAN Communication Bus - Missing message	▪ Missing message from another control module via the high speed CAN bus (powertrain)	▪ Using the manufacturer approved diagnostic system, check the snapshot data to determine the missing message source control module. Check the relevant control module for related DTCs and refer to the relevant DTC index
U0001-88	High Speed CAN Communication Bus - Bus off	▪ High speed CAN bus (powertrain) circuit short circuit to ground, short circuit to power, open circuit, high resistance	▪ Using the manufacturer approved diagnostic system, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the high speed CAN bus (powertrain) circuit for short circuit to ground, short circuit to power, open circuit, high resistance
U0300-00	Internal Control Module Software Incompatibility - No sub type information	▪ Car configuration file mismatch with vehicle specification ▪ Incorrect occupant classification sensor control module installed	▪ Using the manufacturer approved diagnostic system, check and up-date the car configuration file as necessary ▪ Install a new occupant classification sensor control module as necessary
U2016-51	Control Module Main Software - Not programmed	▪ Occupant classification sensor control module is not configured correctly ▪ Occupant classification sensor control module internal failure	NOTE: Do not try to solely change the module fitted to the bladder hose as it is calibrated as an integral assembly with the seat cushion foam

			▪ Using the manufacturer approved diagnostic system, re-configure the occupant classification sensor control module with the latest level software ▪ If fault persists, check and install a new occupant classification sensor service kit as required (complete service kit consists of foam, occupant classification sensor bladder mat with attached smart digital pressure sensor)
U201A-51	Control Module Main Calibration Data - Not programmed	▪ Occupant classification sensor control module is not configured correctly ▪ Occupant classification sensor control module internal failure	NOTE: Do not try to solely change the module fitted to the bladder hose as it is calibrated as an integral assembly with the seat cushion foam ▪ Using the manufacturer approved diagnostic system, re-configure the occupant classification sensor control module with the latest level software ▪ If fault persists, check and install a new occupant classification sensor service kit as required (complete service kit consists of foam, occupant classification sensor bladder mat with attached smart digital pressure sensor)
U201A-54	Control Module Main Calibration Data - Missing calibration	▪ Occupant classification sensor control module internal failure	

			NOTE: Do not try to solely change the module fitted to the bladder hose as it is calibrated as an integral assembly with the seat cushion foam Using the manufacturer approved diagnostic system, clear the DTCs and retest. If fault persists, check and install a new occupant classification sensor service kit as required (complete service kit consists of foam, occupant classification sensor bladder mat with attached smart digital pressure sensor)
U3000-49	Control Module - Internal electronic failure	Occupant classification sensor control module internal failure	NOTE: Do not try to solely change the module fitted to the bladder hose as it is calibrated as an integral assembly with the seat cushion foam Using the manufacturer approved diagnostic system, clear the DTCs and retest. If fault persists, check and install a new occupant classification sensor service kit as required (complete service kit consists of foam, occupant classification sensor bladder mat with attached smart digital pressure sensor)
U3000-54	Control Module - Missing calibration	Routine failed - Learn Seat Occupant Classification Zero Position (5007)	

NOTE:

The following pre-conditions are required to run the routine correctly: ignition is switched on, the occupancy seat module has gone through the seat assembly plant calibration, no collision event received from the restraints control module during the current ignition cycle, no faults present in the current ignition cycle, occupancy seat module has settled for 10 seconds, temperature is between 6°C (42°F) and 36°C (97°F), seat is bolted in original installation position

- Using the manufacturer approved diagnostic system, perform routine - Learn Seat Occupant Classification Zero Position (5007)