

2016.0 RANGE ROVER (LG), 100-00

GENERAL INFORMATION

DESCRIPTION AND OPERATION

TOUCH SCREEN SWITCHPACK LEFT/RIGHT (TSSL/TSSR)

CAUTION:

Diagnosis by substitution from a donor vehicle is **NOT** acceptable.
Substitution of control modules does not guarantee confirmation of a fault, and may also cause additional faults in the vehicle being tested and/or the donor vehicle.

NOTES:

- If a control module or a component is suspect and the vehicle remains under manufacturer warranty, refer to the Warranty Policy and Procedures manual, or determine if any prior approval programme is in operation, prior to the installation of a new module/component.
- Generic scan tools may not read the codes listed, or may read only 5-digit codes. Match the 5 digits from the scan tool to the first 5 digits of the 7-digit code listed to identify the fault (the last 2 digits give extra information read by the manufacturer-approved diagnostic system).
- When performing voltage or resistance tests, always use a digital multimeter accurate to three decimal places, and with an up-to-date calibration certificate. When testing resistance always take the resistance of the digital multimeter leads into account.
- Check and rectify basic faults before beginning diagnostic routines involving pinpoint tests.
- Inspect connectors for signs of water ingress, and pins for damage and/or corrosion.
- If DTCs are recorded and, after performing the pinpoint tests, a fault is not present, an intermittent concern may be the cause. Always check for loose connections and corroded terminals.
- Check DDW for open campaigns. Refer to the corresponding bulletins and SSMs which may be valid for the specific customer complaint and carry out the recommendations as required.

The table below lists all Diagnostic Trouble Codes (DTCs) that could be logged in the Touch Screen Switchpack Left/Right (TSSL/TSSR). For additional diagnosis and testing information, refer to the relevant Diagnosis and Testing section in the workshop manual.

For additional information, refer to: [Information and Entertainment System](#)

(415-00 Information and Entertainment System - General Information, Diagnosis and Testing) /

[Parking Aid](#) (413-13 Parking Aid, Diagnosis and Testing).

DTC	DESCRIPTION	POSSIBLE CAUSES	ACTION
B10B8-94	Push Buttons - Unexpected operation	▪ Touch screen left/right switchpack switch stuck active ▪ Touch screen left/right switchpack internal failure	NOTE: This DTC is applicable to the touch screen left and right switchpacks ▪ Test the operation of the touch screen left and right switchpacks. Check for dirt or other contamination and clean as necessary ▪ Using the manufacturer approved diagnostic system, clear the DTCs and retest. If the fault persists, install a new touch screen left/right switchpack
B13FE-12	Semi-Automatic Advanced Parallel Park Request Output - Circuit short to battery	▪ Touch screen left switchpack park assist switch circuit short circuit to power	NOTE: This DTC is applicable to the touch screen left switchpack only ▪ Refer to the electrical circuit diagrams and check the touch screen left switchpack park assist switch circuit for short circuit to power
B13FE-14	Semi-Automatic Advanced Parallel Park Request Output - Circuit short to ground or open	▪ Touch screen left switchpack park assist switch circuit short circuit to ground, open circuit, high resistance	NOTE: This DTC is applicable to the touch screen left switchpack only

			Refer to the electrical circuit diagrams and check the touch screen left switchpack park assist switch circuit for short circuit to ground, open circuit, high resistance
B1401-12	Park Aid Request Output - Circuit short to battery	Touch screen left switchpack parking aid switch circuit short circuit to power	NOTE: This DTC is applicable to the touch screen left switchpack only Refer to the electrical circuit diagrams and check the touch screen left switchpack parking aid switch circuit for short circuit to power
B1401-14	Park Aid Request Output - Circuit short to ground or open	Touch screen left switchpack parking aid switch circuit short circuit to ground, open circuit, high resistance	NOTE: This DTC is applicable to the touch screen left switchpack only Refer to the electrical circuit diagrams and check the touch screen left switchpack parking aid switch circuit for short circuit to ground, open circuit, high resistance
B1A85-84	Ambient Light Sensor - Signal below allowable range	NOTE: This DTC will only set following the completion of an on demand test routine Touch screen left/right switchpack	NOTE: This DTC is applicable to the touch screen left and right switchpacks Check for obstructions to the lens on the front of the touch screen left/right switchpack. Ensure there is sufficient ambient light around the

		ambient light sensor obstructed ▪ Touch screen left/right switchpack internal failure	switchpack (ie: that the panel is not in darkness). Using the manufacturer approved diagnostic system, clear the DTCs and perform routine - On Demand Self Test (0x0202) ▪ Using the manufacturer approved diagnostic system, clear the DTCs and retest. If the fault persists, install a new touch screen left/right switchpack
U0055-88	Vehicle Communication Bus D - Bus off	▪ Medium speed CAN bus (comfort) circuit short circuit to ground, short circuit to power, open circuit, high resistance	NOTE: This DTC is applicable to the touch screen left and right switchpacks ▪ Using the manufacturer approved diagnostic system, perform a CAN network integrity test. Refer to the electrical circuit diagrams and check the medium speed CAN bus (comfort) circuit for short circuit to ground, short circuit to power, open circuit, high resistance
U0300-00	Internal Control Module Software Incompatibility - No sub type information	▪ Car configuration file mismatch with vehicle specification ▪ Incorrect touch screen left/right switchpack installed	NOTE: This DTC is applicable to the touch screen left and right switchpacks ▪ Using the manufacturer approved diagnostic system, check and up-date the car configuration file as necessary ▪ If the fault persists, install a new touch screen left/right switchpack

U201A-57	Control Module Main Calibration Data - Invalid/incomplete software component	▪ Touch screen left/right switchpack calibration files incorrect or corrupt	NOTE: This DTC is applicable to the touch screen left and right switchpacks ▪ Using the manufacturer approved diagnostic system, re-configure the touchscreen left/right switchpack with the latest level software. If the fault persists, install a new touchscreen left/right switchpack
U2100-00	Initial Configuration Not Complete - No sub type information	▪ Car configuration file mismatch with vehicle specification ▪ Incorrect touch screen left/right switchpack installed	NOTE: This DTC is applicable to the touch screen left and right switchpacks ▪ Using the manufacturer approved diagnostic system, check and up-date the car configuration file as necessary ▪ If the fault persists, install a new touch screen left/right switchpack