



TECHNICAL SERVICE BULLETIN

Vehicles Equipped With A 2.0L (Panther) Engine - Illuminated Malfunction Indicator Lamp (MIL) With Diagnostic Trouble Code (DTC) P2002

24-2130

28 June 2026

This bulletin supersedes 21-2416. Reason for update: Replace Awareness/Interim Message

This bulletin supersedes 22-2482. Reason for update: Replace Awareness/Interim Message

Model:

Ford 2019-2024 Transit	Assembly Plant: KOCAELI PLANT BUILD (AAGBX) Engine: 2.0L PANTHER
2019-2024 Tourneo Custom/Transit Custom	Assembly Plant: KOCAELI PLANT BUILD (AAGBX) Engine: 2.0L PANTHER

Issue: Some 2019-2024 Transit vehicles equipped with a 2.0L (Panther) engine may experience an illuminated MIL with DTC P2002-00-**.

Action: Should a vehicle present with the above condition, technicians are advised to follow the Service Procedure below.

NOTE: If multiple DTCs are stored in the Powertrain Control Module (PCM) in addition to P2002, address these DTCs separately after actioning this TSB.

NOTE: For parts selection always refer to the Parts Catalog and select the correct parts for the specific vehicle

Parts

Service Part Number	Package Order Quantity	Description
GK2Z-00812-B	4	BOLT, M8 X 48MM
GK2Z-9C334-A	2	CLAMP, CYLINDER 1, CYLINDER 2
GK2Z-9C334-B	2	CLAMP, CYLINDER 3, CYLINDER 4
HG9Z-9324-A	1	TUBE - FUEL SUPPLY, CYLINDER 2
HG9Z-9324-B	2	TUBE - FUEL SUPPLY, CYLINDER 3, CYLINDER 4
HG9Z-9324-C	1	TUBE - FUEL SUPPLY, CYLINDER 1
JB3Z-9E527-D	4	INJECTOR ASSEMBLY (2.0 ECOBLUE D OR 2.0 ECOBLUE E OR 2.0 ECOBLUE F OR 2.0 ECOBLUE G), EUROCODE 260
GK2Z-9F800-B	1	COVER
JK21-5L243-AJ	1	CATALYST AND PARTICULATE FILTER ASSEMBLY
GK2Z-5A215-C	1	CLAMP, 74.5MM
GK2Z-5J277-A	1	CLAMP, 37MM
CV6Z-9450-E	1	GASKET, 62MM x 105MM
GK2Z-9450-D	1	GASKET, 58MM
W700420-S403	2	NUT, M10, M10 x 1.5

Labor Times

Description	Operation No.	Time
Visually inspect the exhaust system	242130A	0.2 Hrs.
Transit V363E (VL TS) FWD catalyst and particulate filter assembly- Remove And Install	242130B	2.3 Hrs.

Transit V363E (VL TS) RWD and 4WD catalyst and particulate filter assembly- Remove And Install	242130C	2.1 Hrs.
Tourneo Custom Transit Custom V362 EU (VL TF)/Transit (VL TG) catalyst and particulate filter assembly- Remove And Install	242130D	2.2 Hrs.
Replace the fuel injectors and associated single use parts	242130E	1.6 Hrs.
Retrieve DTCs and clear PCM codes	242130F	0.3 Hrs.

Repair/Claim Coding

Causal Part:	9K546
Condition Code:	01

PDR Table

PDR Code	Description	Time
TSB242130A	Transit V363E (TS) FWD - Visually inspect the exhaust system and catalyst and particulate filter assembly. Remove and install the assembly, replace the fuel injectors and associated single-use parts, retrieve DTCs, and clear PCM codes	4.4 Hrs.
TSB242130B	Transit V363E (TS-RWD -4WD) - Visually inspect the exhaust system and catalyst and particulate filter assembly. Remove and install the assembly, replace the fuel injectors and associated single-use parts, retrieve DTCs, and clear PCM codes.	4.2 Hrs.
TSB242130C	Tourneo Custom /Transit Custom V362 EU (TF)/Transit (TG) - Visually inspect the exhaust system and catalyst and particulate filter assembly. Remove and install the assembly, replace the fuel injectors and associated single-use parts, retrieve DTCs, and clear PCM codes.	4.3 Hrs.

Service Procedure

1. Does the vehicle have P2002-00-** stored in the PCM and an illuminated MIL? Refer to the table below for exact "****" values under which conditions this TSB applies. Please list the exact value, including the last two digits on the repair order and warranty claim.

- (1). No - this TSB does not apply, refer to the Workshop Manual (WSM) for normal diagnostics/repair.
- (2). Yes - proceed to Step 2.

2. Visually inspect the exhaust system for the following (with the ignition OFF):

- (1). Damaged catalyst and particulate filter assembly
- (2). Leaks, cracks, or punctures
- (3). Aftermarket accessories and performance modifications
- (4). Tailpipe modifications that increase or decrease exhaust restriction
- (5). Leaks in the particulate filter pressure Bank 1, Sensor 1 sensor connecting hose

3. Does the vehicle exhibit any of the above concerns?

- (1). Yes - this TSB does not apply, refer to the WSM for normal diagnostics/repair.
- (2). No - proceed to Step 4.

4. Replace the catalyst and particulate filter assembly and associated single use parts. Refer to WSM Section 309-00.

5. Replace the fuel injectors and associated single use parts. Refer to WSM Section 303-04.

6. Connect the appropriate Ford diagnostic scan tool and clear the PCM DTCs.

7. Evaluate the vehicle to ensure correct operation.

Status byte must be greater than 8x; for the comprehensive list of required status bytes for this Technical Service Bulletin (TSB) see the list below:

DTC Code	Status Byte	DTC Code	Status Byte	DTC Code	Status Byte	DTC Code	Status Byte	DTC Code	Status Byte
P2002-00-	80	P2002-00-	9B	P2002-00-	B5	P2002-00-	CE	P2002-00-	E7
P2002-00-	81	P2002-00-	9C	P2002-00-	B6	P2002-00-	CF	P2002-00-	E8
P2002-00-	82	P2002-00-	9D	P2002-00-	B7	P2002-00-	D0	P2002-00-	E9
P2002-00-	83	P2002-00-	9E	P2002-00-	B8	P2002-00-	D1	P2002-00-	EA
P2002-00-	84	P2002-00-	9F	P2002-00-	B9	P2002-00-	D2	P2002-00-	EB
P2002-00-	85	P2002-00-	A0	P2002-00-	BA	P2002-00-	D3	P2002-00-	EC
P2002-00-	86	P2002-00-	A1	P2002-00-	BB	P2002-00-	D4	P2002-00-	ED
P2002-00-	87	P2002-00-	A2	P2002-00-	BC	P2002-00-	D5	P2002-00-	EF
P2002-00-	88	P2002-00-	A3	P2002-00-	BD	P2002-00-	D6	P2002-00-	EF
P2002-00-	89	P2002-00-	A4	P2002-00-	BE	P2002-00-	D7	P2002-00-	F0
P2002-00-	8A	P2002-00-	A5	P2002-00-	BF	P2002-00-	D8	P2002-00-	F1
P2002-00-	8B	P2002-00-	A6	P2002-00-	C0	P2002-00-	D9	P2002-00-	F2
P2002-00-	8C	P2002-00-	A7	P2002-00-	C1	P2002-00-	DA	P2002-00-	F3
P2002-00-	8D	P2002-00-	A8	P2002-00-	C2	P2002-00-	DB	P2002-00-	F4
P2002-00-	8E	P2002-00-	A9	P2002-00-	C3	P2002-00-	DC	P2002-00-	F5
P2002-00-	8F	P2002-00-	AA	P2002-00-	C4	P2002-00-	DD	P2002-00-	F6
P2002-00-	90	P2002-00-	AB	P2002-00-	C5	P2002-00-	DE	P2002-00-	F7
P2002-00-	91	P2002-00-	Ac	P2002-00-	C6	P2002-00-	DF	P2002-00-	F8
P2002-00-	92	P2002-00-	AD	P2002-00-	C7	P2002-00-	E0	P2002-00-	F9
P2002-00-	93	P2002-00-	AE	P2002-00-	C8	P2002-00-	E1	P2002-00-	FA
P2002-00-	94	P2002-00-	AF	P2002-00-	C9	P2002-00-	E2	P2002-00-	FB
P2002-00-	95	P2002-00-	B0	P2002-00-	CA	P2002-00-	E3	P2002-00-	FC
P2002-00-	96	P2002-00-	B1	P2002-00-	CB	P2002-00-	E4	P2002-00-	FD
P2002-00-	97	P2002-00-	B2	P2002-00-	CC	P2002-00-	E5	P2002-00-	FE
P2002-00-	98	P2002-00-	B3	P2002-00-	CD	P2002-00-	E6	P2002-00-	FF
P2002-00-	9A	P2002-00-	B4						

© 2026 Ford Motor Company

All rights reserved.

This bulletin represents technical service information only. Without exception all gratis repairs and replacements are subject to the individual warranty and policy procedures of the supervisory Ford Company. The illustrations, technical information, data and descriptive text in this issue, to the best of our knowledge, were correct at the time of publication.