



TECHNICAL SERVICE BULLETIN

26-2292

Engine Misfire With An Illuminated MIL And DTC(s) P0301, P0302, P0303, And/Or P0304 Stored In The PCM

26 June 2026

Model:

Ford 2024-2025 Explorer	Built on 1-Jun-2024 and through 31-Dec-2024 Engine: 2.3L EcoBoost
2024 Bronco	Built on 1-Jun-2024 and through 31-Dec-2024 Engine: 2.3L EcoBoost
2024-2025 Mustang	Built on 1-Jun-2024 and through 31-Dec-2024 Engine: 2.3L EcoBoost
Lincoln 2024-2025 Corsair	Built on 1-Jun-2024 and through 31-Dec-2024 Engine: 2.0L EcoBoost

Issue: Some of the vehicles listed in the Model statement above may exhibit all of the following conditions:

- Engine misfire condition.
- Illuminated MIL with DTCs P0301, P0302, P0303, and/or P0304 stored in the PCM.

Action: For vehicles that meet all of the criteria in the Issue and Model statements, follow the Service Procedure to inspect the date code on the suspect ignition coil and replace as necessary.

Parts

Service Part Number	Claim Quantity	Description
P2GZ-12029-A	Only If Necessary (Up To 4)	Ignition Coil

Claim Quantity refers to the total number of individual pieces required to repair the vehicle. This may differ from the number of service part number packages due to the unit of issue (UOI).

As Needed indicates the part is necessary but amount of the part may vary and/or is not a whole number. Parts can be billed out as non-whole numbers, including less than 1.

Only If Necessary indicates the part is not mandatory. Refer to the Service Procedure to determine the inspection/inclusion criteria.

Labor Times

Description	Operation No.	Time
2024-2025 Mustang 2.3L EcoBoost: Retrieve DTCs, Inspect Date Code On Related Ignition Coil(s) Replace One Ignition Coil	262292A	0.4 Hrs.
2024-2025 Mustang 2.3L EcoBoost: Retrieve DTCs, Inspect Date Code On Related Ignition Coil(s) Replace Two Or More Ignition Coils	262292B	0.5 Hrs.
2024 Bronco 2.3L EcoBoost: Retrieve DTCs, Inspect Date Code On Related Ignition Coil(s) Replace One Ignition Coil	262292C	0.4 Hrs.
2024 Bronco 2.3L EcoBoost: Retrieve DTCs, Inspect Date Code On Related Ignition Coil(s) Replace Two Or More Ignition Coils	262292D	0.5 Hrs.
2024-2025 Corsair 2.0L EcoBoost: Retrieve DTCs, Inspect Date Code On Related Ignition Coil(s) Replace One Ignition Coil	262292E	0.8 Hrs.
2024-2025 Corsair 2.0L EcoBoost: Retrieve DTCs, Inspect Date Code On Related Ignition Coil(s) Replace Two Or More Ignition Coils	262292F	1.0 Hrs.
2024-2025 Explorer 2.3L EcoBoost: Retrieve DTCs, Inspect Date Code On Related Ignition Coil(s) Replace One Ignition Coil	262292G	0.4 Hrs.
2024-2025 Explorer 2.3L EcoBoost: Retrieve DTCs, Inspect Date Code On Related Ignition Coil(s) Replace Two Or More Ignition Coils	262292H	0.6 Hrs.

Repair/Claim Coding

Causal Part:	12029
Condition Code:	42

PDR Table

PDR Code	Description	Time
TSB262292A	Retrieve DTCs, Inspect Date Code On Related Ignition Coil(s) Replace One Ignition Coil	0.4 Hrs.
TSB262292B	Retrieve DTCs, Inspect Date Code On Related Ignition Coil(s) Replace Two Or More Ignition Coils	0.5 Hrs.
TSB262292C	Retrieve DTCs, Inspect Date Code On Related Ignition Coil(s) Replace One Ignition Coil	0.4 Hrs.
TSB262292D	Retrieve DTCs, Inspect Date Code On Related Ignition Coil(s) Replace Two Or More Ignition Coils	0.6 Hrs.

Service Procedure

NOTE: Each ignition coil has an 11-character alphanumeric manufacture code printed on top. The second through sixth characters of the manufacture code are the date code (Figure 1). The date code can be interpreted using the chart below.

Figure 1



NOTE: The date code in Figure 1 is 24730 = 30-Jul-2024

Table 1

Manufacture year	Description	Figure 1 (Example)
	First and second characters indicate the manufacture year.	24 = 2024
Manufacture month	Third character indicates the manufacture month. Use 1-9 for January through September and X, Y or Z for October, November and December.	7 = July
Manufacture day	Fourth and fifth characters indicate the manufacture day.	30 = 30th day

1. Access the ignition coil for the cylinder setting the misfire DTC. Refer to the WSM, Section 303-07 > Removal and Installation > Ignition Coil-On-Plug. Perform only the steps necessary to view the date code located on the

top of the suspect ignition coil.

2. Inspect the date code on the ignition coil for the cylinder setting the misfire DTC. Is the ignition coil build date on 01-Apr-2024 and through 31-Oct-2024?

(1). Yes - install a new ignition coil on the suspect cylinder. Refer to the WSM, Section 303-07 > Removal and Installation > Ignition Coil-On-Plug.

(2). No - this article does not apply. Continue with normal diagnostics outside of this article. Refer to the WSM, Section 303-07.

© 2026 Ford Motor Company

All rights reserved.

This bulletin represents technical service information only. Without exception all gratis repairs and replacements are subject to the individual warranty and policy procedures of the supervisory Ford Company. The illustrations, technical information, data and descriptive text in this issue, to the best of our knowledge, were correct at the time of publication.