



TECHNICAL SERVICE BULLETIN

LED Headlamp Functional Concerns

26-2244

10 June 2026

Model:

Ford	
2021-2026 Next-Generation Everest	
2021-2026 Next-Generation Ranger	RA
2022-2026 Next-Generation Ranger	RB

Issue: Some 2021-2026 Next-Generation Ranger and Everest vehicles may experience LED headlamp (LED reflector and LED projector) functionality concerns such as:

LED Reflector Headlamps (Figure 1)

- Day time running lamp inoperable
- Low beam inoperable
- High beam inoperable

LED Projector Headlamps (Figure 2)

- Day time running lamp inoperable
- Low beam inoperable
- High beam inoperable
- Turn indicator inoperable

Action: Should a vehicle present with the above condition, technicians are advised to refer to the Service Procedure below.

NOTE: Only order the part(s) required for the specific vehicle application.

Parts

Service Part Number	Claim Quantity	Package Order Quantity	Description
13008	1	1	Headlamp Assembly - RH (RHD)
N1WZ 13008-AD	1	1	Headlamp Assembly - LH (RHD)
N1WZ 13008-AA	1	1	Headlamp Assembly - RH (LHD)
N1WZ 13008-AC	1	1	Headlamp Assembly - LH (LHD)
ML3Z 13C788-A	1 or 2	1 or 2	LED Control Module - RH/LH

Labor Times

Description	Operation No.	Time
Connect a battery tester and charger and set it to maintain 12.6 to 13.6 Volts	262244A	0.2 Hrs.
Connect the Ford Diagnosis and Repair System (FDRS) to monitor the voltage	262244B	0.2 Hrs.
Body Control Module (BCM) Software Update	262244C	0.1 Hrs.
Replace the headlamp - One Side	262244D	1.5 Hrs.
Replace the headlamp - Both Sides	262244E	1.7 Hrs.
Headlamp Control Module (HCM) Software Update	262244F	0.1 Hrs.
Replace the LED Control Module - One Side	262244G	1.5 Hrs.
Replace the LED Control Module - Both Sides	262244H	1.7 Hrs.

Repair/Claim Coding

Causal Part:	13008
Condition Code:	42

PDR Table

PDR Code	Description	Time
TSB262244A	Connect a battery tester and charger, Ford Diagnosis and Repair System (FDRS) to monitor the voltage and Update Body Control Module (BCM) Software (if available) and Local Interconnect Network (LIN) New Module Initialization	0.5 Hrs.
TSB262244B	Connect a battery tester and charger, Ford Diagnosis and Repair System (FDRS) to monitor the voltage and Update Headlamp Control Module (HCM) Software (if available), Reset HCM – Light Emitting Diode (LED) Control Module	0.5 Hrs.
TSB262244C	Connect a battery tester and charger, Ford Diagnosis and Repair System (FDRS) to monitor the voltage and Update Body Control Module (BCM) Software (if available) and Local Interconnect Network (LIN) New Module Initialization, Replace the headlamp One side - RH (RHD)	2.0 Hrs.
TSB262244D	Connect a battery tester and charger, Ford Diagnosis and Repair System (FDRS) to monitor the voltage and Update Body Control Module (BCM) Software (if available) and Local Interconnect Network (LIN) New Module Initialization, Replace the headlamp One side - LH (RHD)	2.0 Hrs.
TSB262244E	Connect a battery tester and charger, Ford Diagnosis and Repair System (FDRS) to monitor the voltage and Update Body Control Module (BCM) Software (if available) and Local Interconnect Network (LIN) New Module Initialization, Replace the headlamp Both sides - RHD	2.2 Hrs.
TSB262244F	Connect a battery tester and charger, Ford Diagnosis and Repair System (FDRS) to monitor the voltage and Update Body Control Module (BCM) Software (if available) and Local Interconnect Network (LIN) New Module Initialization, Replace the headlamp One side - RH (LHD)	2.0 Hrs.
TSB262244G	Connect a battery tester and charger, Ford Diagnosis and Repair System (FDRS) to monitor the voltage and Update Body Control Module (BCM) Software (if available) and Local Interconnect Network (LIN) New Module Initialization, Replace the headlamp One side LH (LHD)	2.0 Hrs.
TSB262244H	Connect a battery tester and charger, Ford Diagnosis and Repair System (FDRS) to monitor the voltage and Update Body Control Module (BCM) Software (if available) and Local Interconnect Network (LIN) New Module Initialization, Replace the headlamp Both sides - LHD	2.2 Hrs.
TSB262244I	Connect a battery tester and charger, Ford Diagnosis and Repair System (FDRS) to monitor the voltage and Update Headlamp Control Module (HCM) Software (if available), Reset HCM – Light Emitting Diode (LED) Control Module, Replace LED Exterior Headlamp Control Module One side	2.0 Hrs.
TSB262244J	Connect a battery tester and charger, Ford Diagnosis and Repair System (FDRS) to monitor the voltage and Update Headlamp Control Module (HCM) Software (if available), Reset HCM – Light Emitting Diode (LED) Control Module, Replace LED Exterior Headlamp Control Module Both sides.	2.2 Hrs.

Service Procedure

Figure 1 - LED Reflector Headlamp



Figure 2 - LED Projector Headlamp



1. Connect a battery tester and charger and set it to maintain 12.6 to 13.6 Volts (V) referring to Workshop Manual (WSM) Section 414-01. Connect the Ford Diagnosis and Repair System (FDRS) to monitor the voltage in real time using the indicator at the bottom right corner of the FDRS to make sure that it is within this range. The battery State of Charge (SOC) must be greater than 50% to continue with this procedure.

NOTE: Verify the negative cable of the charger is installed on a chassis or engine ground and not the 12V battery negative terminal, to prevent the battery saver mode from activating on the vehicle. Refer to WSM Section 414-01.

NOTE: If the diagnostic software does not load or if the vehicle cannot be identified properly, make sure there is a good internet connection and the Vehicle Communication Module (VCM) is properly connected to the Data Link Connector (DLC).

NOTE: It is highly recommended that a VCM3 is used. Using a VCM3 reduces the chances of programming failures.

2. Log into the FDRS.

NOTE: Vehicle information is automatically retrieved by the diagnostic software and a Network Test is run. Vehicle identification data appears on the screen when this is complete.

3. Select "Read VIN from Vehicle" or manually enter the Vehicle Identification Number (VIN).

NOTE: The available modules are shown on the Left Hand (LH) side of the screen and the available procedures are listed on the Right Hand (RH) side of the screen. Modules that are communicating are highlighted in green.

4. Select the Toolbox tab.

For the below steps, confirm if the vehicle has LED reflector or LED projector headlamps and follow accordingly.

LED Reflector Headlamp

1. From the list on the LH side of the screen, select BCM.
2. From the list on the RH side of the screen, select BCM – Body Control Module (BCM) Software Update (if available otherwise skip to Step 4).
3. Select Download and then Run and follow all on-screen instructions carefully.
4. From the list on the RH side of the screen, select BCM – Local Interconnect Network (LIN) New Module Initialization.
5. Select Download and then Run and follow all on-screen instructions carefully.
6. Select the Clear and Retest button at the top of the screen to clear the Diagnostic Trouble Codes (DTCs) in all modules.
7. Disconnect the battery charger from the 12V battery. Refer to WSM Section 414-01.
8. Conduct a headlamp functionality test. Has the concern been resolved?
 - (1). Yes - TSB complete.
 - (2). No - replace the headlamp (s). Refer to WSM Section 417-01.

LED Projector Headlamp

1. From the list on the LH side of the screen, select HCM.
2. From the list on the RH side of the screen, select HCM – Headlamp Control Module (HCM) Software Update (if available otherwise skip to Step 4).
3. Select Download and then Run and follow all on-screen instructions carefully.
4. From the list on the RH side of the screen, select HCM – Light Emitting Diode (LED) Control Module Reset.
5. Select Download and then Run and follow all on-screen instructions carefully.
6. Select the Clear and Retest button at the top of the screen to clear the Diagnostic Trouble Codes (DTCs) in all modules.
7. Disconnect the battery charger from the 12V battery. Refer to WSM Section 414-01.
8. Conduct a headlamp functionality test. Has the concern been resolved?
 - (1). Yes - TSB complete.
 - (2). No - replace the LED control module(s). Refer to WSM Section 417-01.

© 2026 Ford Motor Company

All rights reserved.

This bulletin represents technical service information only. Without exception all gratis repairs and replacements are subject to the individual warranty and policy procedures of the supervisory Ford Company. The illustrations, technical information, data and descriptive text in this issue, to the best of our knowledge, were correct at the time of publication.