



TECHNICAL SERVICE BULLETIN

Vehicles Built From 01-Aug-2022 To 26-Oct-2024 Equipped With Embedded Navigation (HKCAB) – Embedded Navigation Maps Out Of Date

26-2177

25 May 2026

Model:

Ford 2022-2023 Mustang Mach-E	Build Date: 01 August 2022 – 26 October 2024
2022-2023 F-150	Build Date: 01 August 2022 – 26 October 2024
2023 Kuga	Build Date: 01 August 2022 – 26 October 2024
2023 Transit Custom/Tourneo Custom	Build Date: 01 August 2022 – 26 October 2024
2024 Mustang	Build Date: 01 August 2022 – 26 October 2024
2022 Transit	Build Date: 01 August 2022 – 26 October 2024

Issue: Some vehicles listed in the Model statement built from 01-Aug-2022 to 26-Oct-2024 equipped with embedded navigation (HKCAB) may experience the embedded navigation maps are out of date.

Action: Should a vehicle present with the above concern; technicians are advised to follow the Service Procedure below.

Warranty Status: Information Only.

Repair/Claim Coding

Causal Part:	IN
Condition Code:	-1

TSB Applicability Check

NOTE: This article is for information only. Causal part number "IN" in this article refers to the Information Only status and is not able to be claimed. Map updates are not typically a warrantable concern, this TSB provides technical instructions only. Refer to local guidelines and Warranty Policy Manual for direction on Map Updates.

1. Was the vehicle built in the range above?

- (1). Yes - proceed to Step 2.
- (2). No – this TSB do not apply.

2. Access the PTS to confirm vehicle-build option HKCAB?

- (1). Yes – proceed to Step 3.
- (2). No – this TSB do not apply.

NOTE: Check the vehicle-build option in PTS;

- Log-in to PTS
- Select the "Vehicle ID" tab

PTS

No Vehicle Selected
No VIN Entered

Professional Technician

Ford

System

Home

Vehicle ID

Diagnostics

Connected Vehicle

TSB/GSB/SSM

Worksh

SLTS

Vehicle Selection

By VIN

Enter VIN

E453375 Read VIN

Figure 1

- Input the VIN and press GO

Professional Technician

Ford

LINCOLN

Welcom

System

ected Vehicle

TSB/GSB/SSM

Workshop

Wiring

PC/ED

Service Tips

MPBCMFF70PX555782

Previous VINs

GO

E453376

Figure 2

- See the OASIS information field available in the VIN search page
- Select “Additional Information”

06-MARCH-2025 / 01:17:25 EST
LOCAL TIME: 6-MARCH-2025 / 1:17:26 PM

ADDITIONAL INFORMATION

PAINT COLOR: ARCTIC WHITE.
PAINT CODE:
GROSS VEHICLE WEIGHT: CALCULAT GVW OR PICK FRM TABLE
RADIO: ASIAN RADIO FREQUENCY
SYNC VERSION: GEN4
VHR ACTIVATED:
MODEM: 4G

E453377

Figure 3

- Find HKCAB in the Build Information Table

HDKAA	LESS TACHOGRAPH
HIAAC	DUAL NOTE ELECTRIC HORN
HJGAX	MULTI FUNCTION DISPLAY - 12"
HKCAB ←	NAVIGATION CENTER
HKSAB	EMERGENCY ASSISTANCE
HLIAA	LESS SPD AUDIBLE WARN DEVICE
HLKAA	LESS MASS MOVEMENT SENSOR
HLLAG	BLIND SPT MNITRING W/TRAILERNG
HLNAC	LANE CHANGE WARNING AND AID

E453378

Figure 4

Service Procedure

NOTE: The time required to complete this procedure varies depending on several factors including the number of module software updates required, available internet bandwidth, USB flash drive variability, and the potential that CAN flashing (software update via the DLC with the FDRS) may be required. Connect to the internet with an ethernet cable, use a USB 3.2 Gen 2 or higher flash drive. When performing USB software updates, using high speed USB ports on the laptop is recommended for faster file transfer.

1. Start an FDRS session and navigate to the Toolbox tab - Datalogger - BCM and select the BATT_SOC PID. Verify the PID reads 50% or higher.

NOTE: Connecting the battery charger negative clamp directly to the battery negative terminal might result in the State of Charge (SOC) PID not immediately reflecting the improvement from charging.

- (1). If the SOC is less than 50%, charge the battery by attaching the battery charger's negative clamp to the engine or chassis ground and not the negative battery terminal. Refer to Workshop Manual (WSM), Section 414-01.
 - (2). If the battery is unable to achieve a 50% SOC, use the Rotunda GRX-3590 or DCA-8000 testers to verify if replacement is required.
 - If the battery does not need to be replaced, disconnect the Rotunda charger and perform a Battery Management System (BMS) reset using the FDRS scan tool.
 - If the battery is replaced, fully charge the new battery, disconnect the Rotunda charger and perform a BMS reset using the FDRS scan tool.
 2. Reconnect the battery charger and set it to maintain a vehicle voltage of 12.6-13.6 volts. A low battery voltage or SOC while performing a software update to any module may result in a repeat "Restart Required" message in the vehicle's center display screen or a message on the FDRS saying "Part Number Validation Failed" or "DID Validation Failed".
 3. Update and install the FDRS to the latest version.
 4. Log into the FDRS.
- NOTE:** Vehicle information is automatically retrieved by the diagnostic software and a Network Test is run. Vehicle identification data appears on the screen when this is complete.
5. Select the Toolbox tab.
 6. Run the "Read The Configuration Data" app in the FDRS, located in Toolbox - Multi- Module tab.
 7. Navigate to the SW Updates tab. Is there an Accessory Protocol Interface Module (APIM) software update?
 - (1). Yes - proceed to Step 8.
 - (2). No - this article does not apply.
 8. Prepare to update the software for the APIM.
 - (1). A 64GB or larger USB flash drive is required for APIM software updates. USB 3.2 Gen 2 or higher is recommended for faster file transfer on both the computer port and the USB drive.
 - (2). Make sure the USB flash drive being used is formatted correctly. To see the available drives, hold down the Windows icon keyboard key and press the E keyboard key. Right click on the USB flash drive and select

Properties. If File System under the General tab is not exFAT, the drive must be formatted.

(3). To format the USB flash drive:

- Right click on the USB flash drive.
- Select Format, select exFAT for the File System.
- Select Default Allocation Size for the Allocation Unit Size.

(4). De-selecting Quick Format is not necessary and results in a lengthier operation.

9. Go to the Software update tab on the RH side.

10. Select APIM – Accessory Protocol Interface Module (APIM) Software Update and follow the FDRS prompts.

11. Perform the software update for the APIM. Follow all update screens. If there is no APIM software update available, proceed to Step 12.

(1). Follow the center display screen prompts.

(2). Follow the FDRS prompts to complete the APIM programming.

12. Select “Special Feature” once the Menu Selection Box is available the app should prompt with a menu:

- SYNC Module APIM Software Update
- Special Features
- Exit

13. Select Special Features - The following screen will allow you to enter a code to download special software from the Ford server.

14. Enter the code in the textbox as directed by technical bulletin “UPDITEMAPS” and click OK.

15. When prompted, connect the USB flash drive to the FDRS.

16. When prompted by the FDRS, safely remove/eject the USB flash drive from the FDRS. Start the vehicle (KOER) then connect the USB flash drive to the USB media hub to install the software into the module. When the USB software update begins, the center display screen displays a message stating "Do Not Remove USB". The update may take 10 minutes or longer to complete.

NOTE: It may take up to 5 minutes for the vehicle to recognize the USB flash drive with software update.

17. When the vehicle's center display screen prompts to restart the vehicle:

- (1). Turn the vehicle OFF.
- (2). Wait 10 minutes.
- (3). Restart the vehicle (KOER). The update is still in process at this time.

18. Follow the FDRS on-screen prompts to complete the update.

NOTE: It may take up to 5 minutes before "Update Successful" appears in the vehicle's center display screen. After 5 minutes if "Update Successful" pop-up is not shown on the center display screen, remove the USB flash drive and select YES on the FDRS prompt stating "Was The USB Update Successful" (FDRS verifies if the module software update was successfully installed on the module).

19. Once the pop-up stating “Update Successful” appears in the center display screen:

- Select close and remove the USB flash drive from the USB media hub.
- Select “YES” on the FDRS indicating the update installed successfully.

This initiates the remaining automated configuration steps and reports the module software part numbers and application software levels to the Ford online database. Failure to follow this step results in an inaccurate database as well as omitted, improperly installed, or improperly configured applications (features) such as navigation (if equipped). It is normal for the module to reset during this step.

20. Get Available should be successful and GVMS response consist of new MAP part numbers.

21. Perform the USB update to install new MAPs.

22. Re-launch the FDRS menu and come back to APIM MR update, confirm no longer show Specific feature option as the vehicle is Up To Date with latest MAPs.

NOTE: New Garmin Map files required:

September 2024 level.

PU5T-14H008-CEC

PU5T-14H008-CFC

PU5T-14H008-CCC

PU5T-14H008-CDC

© 2026 Ford Motor Company

All rights reserved.

This bulletin represents technical service information only. Without exception all gratis repairs and replacements are subject to the individual warranty and policy procedures of the supervisory Ford Company. The illustrations, technical information, data and descriptive text in this issue, to the best of our knowledge, were correct at the time of publication.