



TECHNICAL SERVICE BULLETIN

Vehicles Equipped With Power Folding Mirrors - Exterior Mirror Noise When Folding/Unfolding

25-2327

30 June 2026

This bulletin supersedes 24-2144. Reason for update: Add/Remove/Update Vehicle Model Years

Model:

Ford
2021 Everest
2021 Ranger

Issue: Some 2021 Onwards Ranger and Everest vehicles equipped with power folding mirrors may experience noisy exterior mirrors when folding/unfolding (grinding/squawking/squeaking noise different to normal motor noise).

Action: Should a vehicle present with the above condition, technicians are advised to refer to the Service Procedure below.

Parts

Service Part Number	Package Order Quantity	Description
4U7Z M1CA	1	Grease - Lithium

Labor Times

Description	Operation No.	Time
Apply grease and repair the exterior mirrors as per the given service procedure - both sides	252327A	0.3 Hrs.

Repair/Claim Coding

Causal Part:	17682
Condition Code:	14

PDR Table

PDR Code	Description	Time
TSB252327	Apply grease and repair the exterior mirrors as per the given service procedure - both sides	0.3 Hrs.

Service Information

NOTE: If the vehicle has not previously had grease applied to help eliminate this concern, follow the Grease Application Procedure below.

NOTE: If the vehicle has had grease applied under a TSB or FSA previously and the concern has re-occurred, this TSB does not apply. Replace the exterior mirror(s) under normal warranty separate from this TSB. For additional information, refer to Workshop Manual (WSM) Section, 501-09. When replacing the mirror(s), apply grease as per the Grease Application Procedure below.

Grease Application Procedure

NOTE: Perform the Service Procedure below to BOTH exterior mirrors.

1. Manually fold the exterior mirror fully. (Figure 1)



Figure 1

2. Use a plastic applicator with a similar thickness to a credit card (Figure 2 Callout: 1) to apply 0.5ml of grease into the gap between the mirror base and mirror in the area shown (Figure 2 Callout 2). Ensure to insert the applicator until reaching the mirror rotation pivot all the way around the pivot (Figure 3).



E416094

Figure 2



Figure 3

3. Manually forward fold the exterior mirror fully. (Figure 4)



Figure 4

4. Insert the plastic applicator until reaching the mirror rotation pivot all the way around the pivot to distribute the grease. (Figure 5)



Figure 5

NOTE: In the event service grease (part number 4U7Z M1CA) is not available, please source Bechem Berulup FR16 locally or the following alternative lubricants:

- OSIXO aerosol spray
- Krytox GPL205 grade 0
- Klüberalfa RM 93-101

If Osixo spray is used, ensure application covers the area indicated.

5. Clean all excess grease from the outer surface of the exterior mirror in the folded position. (Figure 6)



Figure 6

6. Manually unfold the mirror.

7. Fold/unfold the exterior mirror 10 times electronically using the control switch. (Figure 7)



Figure 7

8. Clean all excess grease from the outer surface of exterior mirror in an unfolded position. (Figure 8)



Figure 8

NOTE: When the power folding mirrors are manually folded, they may not properly work even after you reposition them. You need to reset them if:

- The mirrors vibrate when you drive.
- The mirrors feel loose.
- The mirrors do not stay in the folded or unfolded position.
- One of the mirrors is not in its normal driving position.

To reset the power fold feature, switch the ignition on and use the power folding mirror control to fold and unfold the mirrors. A loud noise could occur when you reset the power folding mirrors, this sound is normal. Repeat this process as needed each time the mirrors are manually folded then switch the ignition off.

9. Check to ensure correct operation and that the noise is no longer present.

10. Perform Steps 1 to 9 on the other side of the vehicle.

NOTE: In the event the sound is still present after 10 folding cycles, replace the exterior mirror(s) under normal warranty separate from this TSB. For additional information, refer to WSM Section, 501-09. When replacing the mirror(s), apply grease as per the Grease Application Procedure above.

© 2026 Ford Motor Company

All rights reserved.

This bulletin represents technical service information only. Without exception all gratis repairs and replacements are subject to the individual warranty and policy procedures of the supervisory Ford Company. The illustrations, technical information, data and descriptive text in this issue, to the best of our knowledge, were correct at the time of publication.