PartSmith repair card

Replacement l-bracket

Family: bracket

BEST EFFORT

Max error: 3.10 mm (pass: <= 0.5 mm, IoU >= 0.97)
top: IoU 0.808, Hausdorff 3.10 mm, mean 1.69 mm
side: IoU 0.991, Hausdorff 0.67 mm, mean 0.15 mm
Part tests: 15/17 passed
- top: refined in the photo frame by +0.45 deg, (-0.42, -0.01) mm on the mat
- side: refined in the photo frame by -0.13 deg, (+0.41, +0.01) mm on the mat
- top view (photo frame): IoU 0.808 (needs >= 0.97), Hausdorff 3.10 mm (needs <= 0.5 mm) (worst at x=23.6,

Key dimensions

Length: 46.37 mm ± 0.09 [measured]
Width: 30.53 mm ± 0.09 [measured]
Thickness: 2.50 mm ± 0.30 [user stated]
hole_1 Ø: 3.59 mm ± 0.05 [measured]
hole_2 Ø: 3.60 mm ± 0.04 [measured]

Print settings (suggested)

PLA, 0.4 mm nozzle, 0.2 mm layers
4 walls, 40% infill, supports: yes
Orientation: -Z: mounting face (Z=0) on the bed, as modelled