

Incident Report: Pump P-204 Tripping Event

Incident ID: INC-2025-882. Date: 2025-06-15. Plant Area: Unit 3 Distillation.

Description: At 14:15, pump P-204 tripped on high vibration and motor overcurrent. The backup pump P-205 was started manually to maintain crude flow.

Root Cause Analysis (RCA): Inspection revealed mechanical bearing failure on the pump shaft. High vibration caused coupling misalignment. The shaft bearings showed severe scoring due to lack of lubrication and deferred maintenance.

Corrective Actions: Replaced bearings with SKF 6205. Realigned coupling. Updated maintenance schedule to inspect lubrication levels bi-weekly.