Callahan Auto & Diesel
255 West Main Street
Mesa, AZ 85201
(480) 969-3332
info@callahanautoaz.com
https://callahanautoaz.com

Invoice for RO #13110

Service Advisor: Preston Callahan
Date Created: 10/27/25 at 02:52 PM MST
Client: Sierra Kielma
Vehicle: 2020 GMC Sierra 2500 HD Denali

Sierra Kielma Phone: (770) 606-4588 Email: sierrakielma@ymail.com	**2020 GMC Sierra 2500 HD Denali 6.6L 8Cyl DIESEL L5P Turbocharged** VIN: 1GT49REY5LF110098 License: N/A Color: N/A Odometer In: 135152 / Out: 135152	**RO # 13110** Key Tag: P3 Time-In: 10/27/25 at 02:52 PM MST Save Parts: No

Client concerns:

- wants steering work
- re-estimate front end work with cognito steering rod kit w/ center link and readylift upper arm with high angle ball joints

1 - DVI and Inspection
Tech: L Cervantes

Labor:	DVI		$0.00
✓ **Approved on 11/26/25 at 11:19 AM MST**		*0*	**0**

2 - TURBO REPLACEMENT
Tech: J Leithtoff, L Cervantes

	Complete Turbocharger Replacement		
Labor:	Replacing the complete turbocharger assembly on the 6.6L L5P is a major repair that involves extensive disassembly and reassembly. Labor includes removing intake and charge air components, exhaust downpipe, oil feed and return lines, coolant lines, heat shields, and related brackets. The turbocharger is then removed as a complete unit, transferred components are inspected or replaced as required, and a new turbocharger assembly is installed. Final steps include priming the turbo, refilling fluids, clearing learned values, verifying proper vane operation, and performing a post-repair road test to confirm boost control and engine performance. This repair carries higher labor due to access limitations, multiple fluid systems involved, and the need to ensure long-term reliability of a high-dollar, high-load component.		$1,925.10
	A/C Evacuate & Recharge Required for Turbo Replacement		
	During turbocharger replacement, air conditioning components must be removed or repositioned to gain proper access to the turbocharger assembly. Any time the A/C system is opened or disconnected, refrigerant must be safely recovered to prevent environmental release and system contamination. After repairs are completed, the system is evacuated to remove air and moisture, then recharged with the correct amount of refrigerant to restore proper cooling performance and protect the compressor from damage. This procedure is a mandatory part of the turbo replacement process and ensures the A/C system operates correctly after reassembly.		$260.40
	Documentation Note: This service is required due to component access and system integrity, not as a maintenance upsell.		
	Service Regeneration Diesel Service Diesel Exhaust Particulate Filter Assembly.		$297.60
Parts:	GASKET,POSITIVE CRANKCASE VENTILATION TUBE	1	$16.70
	GASKET,TURBOCHARGER OIL RETURN PIPE	2	$47.26
	TURBOCHARGER,COMPRESSOR AIR INTAKE	1	$2,332.22
	GASKET,CATALYTIC CONVERTER	1	$31.35
	GASKET,EXHAUST SYSTEM FRONT	1	$6.40
	GASKET,TURBOCHARGER	1	$77.51
	GASKET,POSITIVE CRANKCASE VENTILATION OIL SEPARATOR // SEPARATOR KIT,POSITIVE CRANKCASE VENTILATION OIL	1	$10.68
	SEAL,OIL LEVEL INDICATOR TUBE(O RING)	1	$9.08
	FILTER,OIL	1	$20.03
	SEAL,AIR CONDITIONING COMPRESSOR & CONDENSER HOSE	1	$17.84
	SEAL,AIR CONDITIONING COMPRESSOR & CONDENSER HOSE	1	$17.84
	GASKET,TURBOCHARGER OIL FEED PIPE	1	$18.84
	GASKET,EXHAUST GAS RECIRCULATION PIPE	3	$54.72
	GASKET,TURBOCHARGER OIL FEED PIPE	3	$57.33

✓ **Approved on 01/07/26 at 01:22 PM MST** *Subtotal $5,200.90 + est. Tax $225.58* **$5,426.48**

3 - Engine Oil Cooler
Tech: J Leithtoff

Note: During turbocharger replacement and related diagnostic work, the engine cooling system was drained as required for component access. At that time, oil contamination was discovered inside the coolant. This condition was not visible prior to disassembly and could not be identified without draining the system.

The turbocharger removal was performed as part of ongoing diagnostics addressing electrical fault codes and power-related concerns, not due to any coolant-related symptoms. Coolant level and condition had been monitored during prior inspections and did not indicate contamination until the system was opened.

On the L5P Duramax engine, this type of oil-in-coolant condition is most commonly caused by an internal failure of the engine oil cooler, allowing pressurized engine oil to enter the cooling system. This condition is unrelated to the turbocharger failure itself but must be corrected to prevent damage to the cooling system and newly installed components.

Labor:	Remove & Replace Diesel, 4WD Engine Oil Cooler. DOES NOT include Radiator integral type Oil Cooler.		$911.40
	Remove & Replace ENGINE OIL - Drain & Refill Diesel Engine Oil Cooler. DOES NOT include Radiator integral type Oil Cooler.		$37.20
	Reverse Clean & Flush Engine Cooling System Cooling System. DOES NOT include R&R Thermostat and Hoses.		$186.00
Parts:	oil cooler and filter assy	1	$508.88
	coolant pipe to water pump oring	1	$60.88
	water pump to housing seal	1	$18.15
	90 degree adapter to housing seal seal	1	$20.76
	90 degree adapter to housing seal	1	$17.89
	M6 - 1 Bolts - Bolts for CCV	4	$6.44
	M8 bolt for oil cooler - Bolt for cooler	1	$7.71
	TANK,RADIATOR SURGE	1	$143.24
	CAP,RADIATOR SURGE TANK	1	$27.84
	Shop coolant	8	$143.92
Discount:	Package Deal		-$313.55

✓ **Approved on 01/30/26 at 01:28 PM MST** *Subtotal $1,776.76 + est. Tax $67.43* **$1,844.19**

4 - replace batteries
Tech: L Cervantes

Labor:	Remove & Replace Both Battery. Includes: Test.		$114.00
Part:	MTP Interstate Battery - 30 mo free replace 6 yr prorate	2	$449.90

✓ **Approved on 11/26/25 at 11:19 AM MST** *Subtotal $563.90 + est. Tax $37.34* **$601.24**

5 - Diesel Semi- Syn LOF w/o filter
Tech: J Leithtoff

Labor:	R&R Engine Oil & Filter		$57.00
Part:	15W40 Diesel Semi Synthetic	10	$32.99

Pending Authorization *Subtotal $89.99 + est. Tax $2.74* **$92.73**

6 - Upper Control arms and steering upgrade w/service

Tech: L Cervantes

Note: Replace factory upper control arms with high-angle performance arms to correct geometry and prevent ball joint stress from lift. Upgrade steering with Cognito center link, outer tie rods, idler, and pitman arms for improved durability, precision, and control with oversized tires. All parts are MAP locked with no additional mark-up ensuring manufacturer warranty Parts are required to be pre-paid prior to ordering due to special order and high restocking charges of 40%

Labor:	Remove & Replace Upper, Both Control Arm. DOES NOT include alignment.		$372.00
	Remove & Replace w/Variable Assist Steering, RPO NV8 Pitman Arm. DOES NOT include alignment.		$542.51
	Specialized tooling is used to safely extract and replace all old, worn fluid from the power steering system. The system is first treated with a pre-cleaner, the fluid is then replaced with a fortified and conditioned power steering fluid. The conditioners enhance the fluid, adds seal pliability, and allows for a smoother & quieter system operation. After completion of service the, vehicle is checked for leaks and road tested.		$93.00
	Remove & Replace Recirculating Ball Type Gears Outer, Both Tie Rod Or End. Includes: Adjust toe-in only. NOTE: Deduct .4 if alignment is also performed. NOTE: Manufacturer recommends removal of Rack and Pinion Steering Gear when replacing Inner Tie Rod End(s) on some models. If removal of the Rack and Pinion Gear is necessary, use Steering Gear (Complete) - R&R plus combinations.		$93.00
Parts:	20-C SILVERADO/SIERRA 2500/3500HD FABRICATED UPPER CONTROL ARMS W/ HIGH ANGLE BALL JOIN	1	$649.95
	11-C SILVERADO/SIERRA 2500/3500 EXTREME DUTY TIE ROD CENTER LINK KIT	1	$749.95
	PITMAN AND IDLER ARM SUPPORT KIT FOR 2020 GM 2500/ 3500	1	$293.61
	7 SPLINE WHEEL KEY	1	$18.57
	Steering Pitman Arm	1	$110.82
	Power Steering Service Kit	0	$0.00
	Steering Idler Arm Bracket	1	$111.88

✓ **Approved on 11/26/25 at 11:19 AM MST** *Subtotal $3,035.29 + est. Tax $160.59* **$3,195.88**

7 - Alignment

Sublet:	Alignment after front end work	$289.99

✓ **Authorized on 11/26/25 at 11:19 AM MST** *Subtotal $289.99 + est. Tax $24.07* **$314.06**

RO Fees

Fees:	Shop supplies	$40.00
	Hazmat	$25.00
	Card Fee	$452.69
	Shipping	$172.22
	ADMIN FEE	$80.00
	SNAP FEE	$49.00
	Subtotal	**$813.44**

By signing this I hereby authorized and am satisfied with the above repair work that was done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. 3 month Warranty work has to be done at the shop that performed the service & cannot exceed the original cost of repairs that were done nothing preexisting. I also agree to waive my warranty and not hold Callahan Auto & Diesel liable for any and all damages on any and all work that failed due to supplying my own parts and/or not following recommendations from Callahan Auto & Diesel. All warranties are void if: customer supplied parts are installed, proper maintenance is not done, vehicle runs hot or out of oil, If other repair facilities attempt to fix our work or remove any of our work. Only items listed on invoice and purchased from Callahan Auto is under warranty and items that are not replaced is possible to fail and void covered work and parts. No refunds for services rendered.

Total Repair Order & Signature:

Total Labor:	$4,832.21
Total Parts:	$6,058.19
Total Sublet:	$289.99
Total Fees:	$813.44
Discounts:	-$313.55
Subtotal:	**$11,680.28**
Taxes:	$518.32
Grand Total:	**$12,198.60**
BALANCE DUE:	**$5,040.68**

X

Completed Transactions

02/05/26	Sierra Kielma	$4,851.00	Other Payment	Financing (i.e. snap, synchrony...) snap	
11/20/25	Sierra Kielma	$2,306.92	Credit Card Payment	Mastercard**** 9123 Auth: 37619Z	Mastercard