## Polymeric Materials


**Instructor**: Prof. Bishakh Bhattacharya


Dept. of Mechanical Engineering

**IIT Kanpur** 

India


**E-mail** : bishakh@iitk.ac.in





Question 1: Why Seismic Waves travel faster between the poles than across the equator?

Question 2: What is the Crystal Structure of ... at 5400 degree celsius?



## Contents

- ✓ Introduction
- ✓ Concept of molecular weight
- ✓ Chemistry of polymers
- √ % Crystallinity
- ✓ Tacticity in polymers






Fig. 0.4. Energy requirements to produce metal alloys and plastics. For the plastics the energy required to manufacture the plastic is shown separately from the fuel equivalent of the raw material.



#### **Polymer Basics**

- > poly = many mer = parts
- degree of polymerization = DP





A macromolecule where each unit could either be an atom like Sulfur in Polysulfide or group of atoms.

## Typical Examples

$$-CH_2-CH_2-CH_2-CH_2-Poly(ethylene)$$





Number of monomer units in the chain N >> 1.



## **Polymer Configuration**

- linear


- branched

- network

Linear Structure: Soluble and Fusible

Branched Structure: More Soluble and Fusible

Networked Structure: Insoluble and Infusible



#### **Another Classification**

Polymers can be classified according to their **thermo physical behavior**.

Those which soften and flow upon heating are termed <a href="https://www.thermoset.com/thermoset">thermoset</a>; those which do not are called <a href="https://www.thermoset.com/thermoset">thermoset</a> polymers.

Thermoplastics may remain soluble and fusible under many cycles of heating and cooling.

**Thermosets** can be obtained in soluble or fusible stage in early or intermediate stage but once they get cured they will be infusible and insoluble.




## **Characteristics of Thermoplastic polymers:**

- Linear or branched structure
- Polymer melts and flows upon heating
- Heat sensitive properties
- Individual polymer molecules are held together by weak
   Secondary forces:
  - Van der Waals forces
  - Hydrogen bonds
  - Dipole-dipole interactions

#### Examples:

- Polypropylene
- Nylon
- Polymethyl methacrylate
- Polyethylene
- Polystyrene



## **Characteristics of Thermoset polymers:**

- Upon application of heat, liquid resin becomes rigid via <u>Vitrification</u> process
- •End polymer is less temperature sensitive than thermoplastics
- Cross linked network structure (formed from chemical bonds) exists throughout
- Cross linking provides thermal stability such that polymer will not melt or flow upon heating.

## **Examples**

- Epoxy
- Unsaturated polyesters
- Vinyl esters
- Phenol formaldehyde
- Urethane

# Advantages and Disadvantages of Thermoplastics

## Advantages of thermoplastics:

- Unlimited shelf life -- won't undergo polymerization during storage or in processing unit
- Easy to handle (no tackiness)
- Recyclable -- they undergo melt and solidify cycles
- Easy to repair by welding, solvent bonding, etc.
- Postformable

Disadvantages of thermoplastics: Thermoplastics are prone to creep Poor melt flow characteristics




# Advantages & Disadvantages of Thermosets

## Advantages of thermosets:

- Low resin viscosity
- Good fiber wet-out
- Excellent thermal stability once polymerized
- Chemically resistant
- Creep resistant

#### **Disadvantages of thermosets:**

- Brittle
- Non-recyclable via standard techniques
- Must mold polymer in shape of final part--not postformable




## **Classification Based on Polymerization Reactions**


There are two fundamental polymerization reactions: **Chain** polymerization and **Step polymerization**.


This classification is of particular importance to thermosetting systems which polymerize *in situ* when used in processes.

#### Chain Polymerization



#### Step Polymerization





## Chain (or Addition) Polymerization

Chain polymerization is characterized by the presence of a few active sites which react and propagate through a sea of monomers. Polymerization may occur by any of three mechanisms:

- free radical
- cationic
- anionic

Vinyl monomers frequently undergo chain polymerization. Polymers formed via this process include:

- Polyethylene
- Polystyrene
- Polypropylene
- Polymethyl methacrylate

## Typical Reaction in CP

#### **Initiator Decomposition:**

$$I \longrightarrow 2R^*$$

#### **Chain Initiation:**

$$R^* + M \longrightarrow RM_1^*$$

## **Chain Propagation:**

$$RM_1^* + M \longrightarrow RM_2^*$$

$$RM_{n-1}^* + M \longrightarrow RM_n^*$$

#### **Chain Termination:**

$$RM_n^* + RM_m^* \longrightarrow R-M_{m+n}-R$$

## **Step Polymerization**

In a step reaction mechanism, monomers can react with any nearby monomer. In contrast to chain polymerization, no special activation is needed to allow a monomer to react.

Frequently these reactions are **Copolymerizations**, where two types of monomer are present and each reacts only with the other (and not with monomers like itself)

This type of polymerization is also called condensation polymerization because water is often liberated when the polymer bonds form.



## Example of Condensation Polymerization:

- •Polyester formation: The monomers are diols and diacids. The acid groups react with the alcohol groups to form ester linkages.
- •Polyamide formation: amine groups react with carboxylic acids.


## Typical Reaction in SP

1<sup>st</sup> Step: HOROH+HOOCR/COOH – HOROOCR/COOH + H<sub>2</sub>O

2<sup>nd</sup> Step: HOROOCR/COOH +HOROH -

HOROOCR/COOROH+H<sub>2</sub>O

$$\Sigma M_n + \Sigma M_m - \Sigma M_{m+n} + H_2O$$



## **Step Polymerization vs Chain Polymerization**

Any two molecular species present can react - Reaction occurs only at active centers by adding repeating units one at a time to the chain

Monomer disappears early in the reaction - Monomer concentration decreases steadily throughout the reaction

Polymer molecular weight rises steadily throughout the reaction- High polymer is formed at once--polymer molecular weight changes little


At any stage all molecular species are present in a calculable distribution- Reaction mixture contains only monomer, high polymer, and a minuscule number of growing chains


#### CURING of THERMOSETS

Viscosity of the system rises until Gelation occurs.

At this point, two phases exist: a **gel phase** and a **sol phase**. The **gel phase** is the networked **gelled part**; the **sol phase** can be extracted with solvents.

The amount of sol phase present decreases as the reaction progresses further. **Upon further reaction**, **Vitrification (hardening) occurs.** 





#### Molecular Weight

- The molecular weight distribution is important in thermoplastics.
- In thermosets, a gelled network of essentially infinite molecular weight is formed, so
  the idea of a "molecular weight distribution" is non-sensical.

#### Two ways:-

a) Number average molecular weight  $(M_n)$ : Total weight of all the polymer molecules in a sample, divided by the total number of polymer molecules in a sample.

Number average molecular weight, 
$$\overline{M_n} = \frac{\sum M_i N_i}{\sum N_i}$$

Where,  $\mathbf{M_i}$  = molecular weight of  $i_{th}$  polymer chain;  $\mathbf{N_i}$  = number of chains of that molecular weight.

b) Weighted average molecular weight  $(M_w)$ : It's based on the fact that a bigger molecule contains more of the total mass of the polymer sample than the smaller molecules do.

Weighted average molecular weight, 
$$\overline{M_w} = \frac{\sum M_i^2 N_i}{\sum M_i N_i}$$

More appropriate


## Degree of Polymerization

$$DP = \frac{\overline{M}_n}{m}$$


where, $\overline{M_n}$  = Number average molecular weight m = repeat unit molecular weight (no. of atoms x atomic wt.)

Example: Suppose for **Polyvinyl chloride**,  $\overline{M}_n$  = 21,150 g/mol Then, repeat unit molecular weight, m = 2 x 12 + 3 x 1 + 1 x 35 = 62 g/mol

$$DP = \frac{21,150}{62} = 341$$




Reference: Kalpakjian, Schmid - Manufacturing Processes for Engineering Materials, 5th ed.



Repeat unit contains – 2 carbon, 3 hydrogen and 1 chlorine atom








#### Polydispersity Index

Polydispersity index, PI = 
$$\frac{M_w}{M_n}$$

- The larger the polydispersity index, the broader the molecular weight distribution.
- Monodisperse polymer, where all the chain lengths are equal (such as a protein) has an PI = 1.
- Step polymerization reactions typically yield values of PI ≈ 2.0
- Chain polymerization reactions yield values between PI = 1.5 - 20.



Distribution of molecular weights for a typical polymer

#### Example

No. of molecules (N <sub>i</sub> )	Mass of each molecule (M <sub>i</sub> ) (g/mol)	Total mass of each type of molecule, (N <sub>i</sub> M <sub>i</sub> ) in g/mol	$M_i^2 N_i$
1	800,000	800,000	6.4 x 10 <sup>11</sup>
3	750,000	2250,000	16.8 x 10 <sup>11</sup>
5	700,000	3500,000	24.5 x 10 <sup>11</sup>
8	650,000	5200,000	33.8 x 10 <sup>11</sup>
10	600,000	6000,000	36 x 10 <sup>11</sup>
13	550,000	7150,000	39.3 x 10 <sup>11</sup>
20	500,000	10,000,000	50 x 10 <sup>11</sup>
13	450,000	5850,000	26.3 x 10 <sup>11</sup>
10	400,000	4000,000	16 x 10 <sup>11</sup>
8	350,000	2800,000	98 x 10 <sup>11</sup>
5	300,000	1500,000	4.5 x 10 <sup>11</sup>
3	250,000	750,000	18.75 x 10 <sup>11</sup>
1	200,000	200,000	0.4x 10 <sup>11</sup>
$\sum N_i = 100$		$\sum M_i N_i = 50,000,000$ (Total mass)	$\sum M_i^2 N_i = 370.75 \times 10^{11}$


Number average molecular weight, 
$$\overline{M_n}=\frac{\sum M_i N_i}{\sum N_i}$$
 
$$=\frac{50,000,000}{100}=500,000 \text{ g/mol}$$

Weighted average molecular weight, 
$$\overline{M_W}=\frac{\sum M_i^2 N_i}{\sum M_i N_i}$$
 =  $\frac{370.75\times 1011}{50,000,000}=741,500$  g/mol


Polydispersity index, PI = 
$$\frac{M_w}{M_n}$$
 = 1.48

#### Chemistry of Polymer molecules

 When all the <u>mers</u> are the <u>same</u>, the molecule is called a **Homo-polymer**.



• When there is more than one type of mer present, the molecule is a **Co-polymer**.




 Mer units that have 2 active bonds to connect with other mers are called bi-functional.

 Mer units that have 3 active bonds to connect with other mers are called trifunctional. They form 3-D molecular network structures.

Phenol-formaldehyde (Bakelite

#### Possible Physical States for Polymer Materials


Traditional classification of physical states (gases, liquids, crystals) is not informative for polymer materials.




Classification of polymer materials:-


- Partially crystalline state
- Viscoelastic State (polymer melt)
- Highly elastic state (e.g. Rubbers)
- Glassy state (e.g. Organic glasses from poly(styrene), poly(methylmethacrylate), poly(vinyl chloride))

Most polymers don't stretch out fully, like this. Instead, they fold back on themselves after going straight for a short distance, like this.





- ✓ Lamella grow like the spokes of a bicycle wheel from a central nucleus.
- ✓ The whole assembly is called a *Spherulite*. In a sample of a crystalline polymer weighing only a few grams, there are many billions of Spherulites.



## Crystallinity

Crystalline region: Orderly arrangement of molecular chains.


✓ High crystallinity means - higher density, more strength, higher resistance to both dissolution and softening by heating.

#### Degree of crystallinity in Polymers

- Ranges from completely amorphous to about 95% crystalline.
- Metal specimens are almost always entirely crystalline.
- Ceramics are either totally crystalline or totally non-crystalline.


For same material & molecular weight

 $\rho_{crystalline\ polymer} > \rho_{amorphous\ polymer}$ (due to close packing)



Remember: No polymer is 100% crystalline


**Reference**: Kalpakjian, Schmid - Manufacturing Processes for Engineering Materials, 5th ed.



#### Crystallinity dependence


#### Degree of crystallinity is affected by:-

- ✓ Rate of cooling during solidification
  - More the rapid cooling lesser the time for alignment poorer the crystallinity.
- ✓ Chain configuration
  - ➤ More the side branching & cross linking <u>more the restriction</u> to prevent the <u>chain alignment</u> <u>lesser</u> the <u>crystallinity</u>.
  - > Thus, linear polymer have high degree of crystallinity.
  - Most network and crosslinked polymers are almost totally amorphous.



## Tacticity in Polymers

- ✓ Different atomic configurations for the same composition.
- ✓ Tacticity is the way pendant groups are arranged along the backbone chain of a polymer.
- ✓ Isotactic & Syndiotactic regular geometry facilitates fitting of adjacent chain, thus more crystalline.
- ✓ Atactic Poorly Crystalline due to irregularity of side group.
- ✓ Also, larger the side-bonded groups of atoms the less is the tendency for crystallization.



Stereoisomers

#### **Some Highly Crystalline Polymers:**

- ✓ Polypropylene
- ✓ Syndiotactic polystyrene
- ✓ Nylon
- ✓ Kevlar and Nomex

#### **Some Highly Amorphous Polymers**

- ✓ Poly(methyl-methacrylate), PMMA
- ✓ Atactic polystyrene
- ✓ Polycarbonate
- ✓ Polyisoprene

## % Crystallinity

% Crystallinity = 
$$\frac{\rho_c(\rho_s - \rho_a)}{\rho_s(\rho_c - \rho_a)} \times 100$$

where,  $\rho_s$ : Density of specimen

 $ho_a$ : Density of the totally amorphous polymer,  $ho_c$ : Density of the perfectly crystalline polymer

The values of  $\rho_s$ ,  $\rho_a$  and  $\rho_c$  are measured by experimental means.

#### In the **next lecture**, we will learn about:

- ✓ Glass Transition temperature (T<sub>g</sub>)
- ✓ Experimental method to determine T<sub>g</sub>
- ✓ Factors affecting T<sub>g</sub>

