

|                         |                                        |                  |                     |
|-------------------------|----------------------------------------|------------------|---------------------|
| ACME NucPower Procedure |                                        | OPS-N-0003-A     |                     |
| Title:                  | ACME NucPower Unit 1 Reactor Cool down |                  |                     |
| Author:                 | R.J.Smith                              | Authorised by:   | <i>John Hancock</i> |
| Review Date:            | 1 January 2025                         | Date Authorised: | 1 January 2025      |
| Associated Documents:   | None                                   |                  |                     |

| Rev | Date       | Author    | Authorised By | Modification | Status |
|-----|------------|-----------|---------------|--------------|--------|
| A   | 1 Jan 2025 | R.J.Smith | J. Hancock    | First draft  | Draft  |
|     |            |           |               |              |        |
|     |            |           |               |              |        |
|     |            |           |               |              |        |
|     |            |           |               |              |        |

## Summary

This procedure provides a step by step instruction for ACME NucPower Unit 1 Reactor cool down from Mode 3 condition (Hot Standby) until Mode 5 condition (Cold Shutdown) has been achieved. It shall be used as a reference each time this plant is started and a record kept of plant start up progress and any issues, events or error for future improvements.

The reactor has 5 operating modes as described below;

**Mode 5** Cold shutdown - reactor is sub-critical with 0% power output and primary coolant average temperature < 95 degC.

**Mode 4** Hot shutdown - reactor is sub-critical with 0% power output and primary coolant average temperature is > 95 degC and < 176 degC.

**Mode 3** Hot standby - reactor is sub-critical with 0% power output and primary coolant average temperature > 176 degC.

**Mode 2** Startup - reactor is critical with power output < 5%

**Mode 1** Power operations - reactor is critical with power output > 5%

## Reactor Cool Down procedure

1. SELECT Pressuriser heater controller (01JEF10AH002) to OFF.
2. Monitor primary circuit Pressure (01JKA10CP001) and Temperature (01JEC10/20/30/40CT001) as it slowly decreases.
3. STOP Reactor Coolant Pump (RCP) 3 (01JEB30AP001).
4. CLOSE SI isolation valves 01JNG60/70/80/90AA001 when primary circuit pressure (01JKA10CP001) is <140 but >125 bar.
5. STOP Reactor Coolant Pump (RCP) 4 (01JEB40AP001) when primary circuit pressure (01JKA10CP001) is < 100 bar.
6. STOP Reactor Coolant Pump (RCP) 2 (01JEB20AP001) when primary circuit pressure (01JKA10CP001) is < 60 bar.
7. START Residual Heat Removal pump (01JNA10AP001) when primary circuit pressure (01JKA10CP001) is < 30 bar.

8. STOP Reactor Coolant Pump (RCP) 1 (01JEB10AP001).
9. SELECT CVCS mode to FILL. This will increase the Pressuriser level to its Wet Storage level.
10. STOP Residual Heat Removal pump (01JNA10AP001) when primary circuit pressure (01JKA10CP001) is  $< 1$  bar.
11. When Turbine Rotor temperature  $< 100$  deg C.
  - STOP Turbine turning gear (01MAK10AH001). Turbine rotor speed will decrease to ZERO rpm.
  - STOP Auxiliary Lube Oil Pump (01MAV10AP001) when Turbine rotor is at standstill.
  - SELECT Lube Oil Heater (01MAV10AH001) to OFF.

# Cold Shutdown (Mode 5) Achieved

## Disclaimer

This document is provided by Richard J Smith 'as is' and 'with all faults'. The provider makes no representations or warranties of any kind concerning the safety, suitability, inaccuracies, typographical errors, or other harmful components of this document and software.

The sole purpose of this document is to provide a guide to the accompanying application.

Use the information contained at your own risk.