Five questions for Ramesh Vijayan, in order of importance

Ritika Raj Parekh · Humaniti AI Build Challenge · 6 November 2026 · Ranked by how much each answer would change my conclusions or what Westline should do next. F-numbers refer to the findings in Westline_Findings_Full.html.

1. Who receives TyreSense alerts, at what thresholds, and can we have the alert log for June and July?

Why it matters: the data shows what the tyres did, not which alarms fired or who saw them. Without the log I cannot say whether the Karwar failure was actionable at 03:40, or whether the Goa “nothing but alarms” are the afternoon cooling events (F12, F17).
What I would do with it: match each alert to the events I found, and route the candidate twin-difference warning to someone who can phone the driver (F13).

2. At Hubballi, who fills the tyres, at what time of day, and with which gauge?

Why it matters: the data shows Hubballi adjusting hot tyres in the afternoon to the cold card value, which leaves all three trucks 10 to 12 PSI under spec every morning. Confirming it from the depot side makes it the cheapest fix in the pack (F14, F15).
What I would do with it: move fills to the cold morning check, or give the fitter a hot-fill allowance table, and check his gauge against the TPMS reading on the same tyre.

3. For the Karwar 5RI on 11 July: what was fitted at the roadside, when and where was WL-T2-5RI-0901 fitted and with which sensor, and what did the fitter find on the failed tyre?

Why it matters: the register (fitted 12 July) and the transcript (changed at the roadside on 11 July) disagree, and the sensor battery jumped from 48% to 98%. The cause of failure, such as a puncture, valve or bead, decides whether a twin warning would catch the next one (F12).
What I would do with it: correct the register, and decide whether the warning rule is enough or the inspection routine needs to change.

4. Are Goa 4LI, Karwar 3LO, Gadag 5RO and City 5RI known to leak, or have any of them been repaired?

Why it matters: they lose air several times faster than the spec’s 3 PSI a month, but three of them also have the weakest sensors, so a leak and a failing sensor are not yet separated (F8, F16).
What I would do with it: if they are not known, have the workshop check valves, treads and sensors on all four this week, before one becomes the next roadside failure.

5. Can you get from TyreSense the fields Ramesh was told the box records but the export does not include (speed, altitude, vibration), plus sensor IDs and ignition if available?

Why it matters: without sensor IDs I cannot explain battery jumps or tell a moved sensor from a new one (F12, F18); without ignition I cannot tell a parked truck with the engine running from one switched off (F10); without speed and altitude I cannot test whether the Anmod descent heats the tyres (H6).
What I would do with it: ask for these fields in the next monthly export, and re-run the warning and leak checks with them.