I hereby authorize the repair work to be completed, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and /or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. There is up to 250 miles to be driven for diagnostics on vehicle. I have read and understand the above and acknowledge receipt of an estimate.

X _____

Terms: Check or cash. A processing fee may be added. Vehicles left after repair is completed may be subject to a storage fee.

Veloce Motorsports

13209 NE 126th Pl, Suite C-355
Kirkland, WA 98034
(206) 228-4485
billing@veloceservice.com

Invoice # 1364

Robert Standefer

1985 Ferrari 412 Base

VIN: ZFFYD245000060351
Engine: V12 4.9L, 4943cc, DOHC, GAS, FI
Trans:

License #
ODO In:23749 Out: 23787
Color:
Mfg. Date:

Unit #

Inv Date: 8/31/2024
Service Writer:
Status: Complete
Driver: Standefer, Robert
PO #
Key Tag / Hat #

Vehicle Problems	Requests for Service	Services Performed	Hrs	Qty	Price		Ext
Customer states that: The Radiator is leaking and needs inspection to determine the cause.							**4,228.97**
Labor Service - Inspected the radiator and found that there is a leak in the radiator itself. The small overflow tank is also leaking at the top. Disassembled the front end of vehicle and removed the lower valance. Removed the three front fans. Removed the HVAC condenser. Removed the complete radiator assembly and tank. Sublet out for radiator and tank repair and fix. Installed the radiator and tank. Replaced all cooling system hoses as needed. Tightened all of the AUX belts while we were there. Tested all fans for proper operation and they are good. Assembled all. Filled coolant system and test ran. The radiator and tank are not leaking at this time and all hoses are good and tight. Test drove and topped up fluid as needed. All ok.			7.00		225.00		1,575.00
Sublet	*Recore Radiator- Test and repair reservoir.*			1.00	2,360.00		2,360.00
New	*Radiator Cap*			1.00	78.75		78.75
New	*Coolant Hose*			2.00	30.83		61.66
New	*Hose*			1.00	40.55		40.55
New	*Coolant Hose*			1.00	36.67		36.67
New	*Antifreeze-Green*			2.00	29.48		58.96
New	*Brake Clean*			2.00	8.69		17.38
Customer states that: The brakes are not operating normal. Please inspect all brakes.							**4,772.71**
Labor Service - Inspected all brakes and they are not working at all. The calipers are stuck and the rotors are not freely spinning. Removed all tires and performed a brake system flush. No help. Removed all four calipers and found that they all are bad and need to be replaced. Replaced all calipers. Replaced all four brake flex lines. Replaced all of the brake pads, pins and plates. Assembled all and bled out the brake system. Not the calipers and working and the brakes are braking.			6.00		225.00		1,350.00
New	*Front Brake Caliper w/ Pads- Right*			1.00	782.47		782.47
New	*Front Brake Caliper w/ Pads- Left*			1.00	782.47		782.47
New	*Rear Brake Caliper w/ Pads- Right*			1.00	681.62		681.62
New	*Rear Brake Caliper w/ Pads- Left*			1.00	681.62		681.62
New	*Brake Hose-TR/512/360*			4.00	65.17		260.68
New	*Brake Fluid*			3.00	17.99		53.97
Sublet	*Freight. Tax and Duty*			1.00	179.88		179.88
Customer states that: The Front Wheel Bearings are making noise.							**2,636.12**
Labor Service - After the brake system was free, noticed that the front wheel bearings were in bad shape and grinding. They both are very loose and need to be replaced. Disassembled the front suspension and replaced the wheel bearings on both sides of the front. Replaced both hub nuts. Assembled all and torque to spec. Now the bearings are good and fit/feel great. All ok.			2.50		225.00		562.50
New	*Wheel Bearing-TR*			2.00	997.36		1,994.72
New	*Hub Nut- 412*			2.00	30.76		61.52
New	*Brake Clean*			2.00	8.69		17.38
Customer states to: Check all interior switch operation.							**798.06**
Labor Service - Checked all interior switches. Found that some of the electrical switches are not working correctly. (Gas door, front hood, trunk and passenger window) Inspected all of the switches for power and cleaned the contacts. Tested all			3.50		225.00		787.50

I hereby authorize the repair work to be completed, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and /or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. There is up to 250 miles to be driven for diagnostics on vehicle. I have read and understand the above and acknowledge receipt of an estimate.

X _____

Terms: Check or cash. A processing fee may be added. Vehicles left after repair is completed may be subject to a storage fee.

Veloce Motorsports
13209 NE 126th Pl, Suite C-355
Kirkland, WA 98034
(206) 228-4485
billing@veloceservice.com

Invoice # **1364**

Robert Standefer **1985 Ferrari 412 Base** License # Inv Date: 8/31/2024

	electrics at the fuse panel and they are good but the panel shows signs of overheating, high temps. Removed all of the fuses and all of the relays. Removed the fuse panel assembly. Tested and found that the window circuit is not working correctly for the passengers side at the fuse block. Repaired the fuse block as needed, now the window is working up and down. Assembled all of the panel and all of the switches, now they are working. The front hood and truck are working. The fuel door is working. The windows are all working. Assembled all of the electrics and all of the trim. Adjusted the front hood and cleaned, lubricated all parts. Assembled and tested, all ok. NOTES: Replaced a few trim clips as needed.				
New	*Clip- White*		3.00	3.52	10.56
Customer states to: Adjust the steering column up as needed.					**112.50**
	Labor Service - The steering column is loose and customer requests adjustment to as high as possible. Tightened the column and joints. Adjusted the column as high as it goes. Assembled and now the column feels great and is tight with high adjustment. All ok.	0.50		225.00	112.50
Customer states that: The starter is making a noise.					**1,562.50**
	Labor Service - Inspected the starter system. Found that when starting, the starter is making a loud noise and sometimes is not engaging correctly. Recommend removing the starter and sending out for rebuild. Disassembled the passengers side exhaust system. Removed and right rear header. Removed the starter and send out for repair. The starter was damaged inside and had a broken shaft that needed to be replaced while doing the rebuild. ETA 10- Days for part to get from Italy. Got rebuilt starter back and installed. Assembled starter into vehicle. Assembled the exhaust and all needed parts. Tested and now the starter is working great and with no issues. All ok.	3.50		225.00	787.50
Sublet	*Start Rebuild- Complete rebuild and with a new main shaft as it was cracked.*		1.00	775.00	775.00
Customer states to: Inspect all of the suspension and the SLS system for leaks and operation.					**814.26**
	Labor Service - Inspected the SLS and the suspension as needed. The SLS is leaking from the pressure hose. Removed the pressure and feed hoses. Replaced with new. The shock seems ok but could have a leak after time. There is no part available for the rear SLS shock replacement. Assembled and cleaned all of the area. Topped up fluid and test ran, all ok. NOTES: The left rear shock is leaking fluid. The suspension joints and bushings are cracking and showing age.	2.00		225.00	450.00
New	*Tube- Pressure*		1.00	249.77	249.77
New	*Misc part supply-*		1.00	78.73	78.73
New	*ATF- Dextron/Merc*		2.00	17.88	35.76
Customer states: Perform a complete oil change and vehicle inspection.					**932.95**
	Labor Service - Oil & Filter Service Only. Performed a lube, oil and filter change service. This service includes drain and refill the engine with factory specified oil. Removed and replace the engine oil filter with new filter. Lubricate any grease fittings on the chassis and driveline. Inspect and top off all fluids as needed. Includes checking tires for wear and inflation, wipers and exterior lights. NOTES: Replaced both wiper blades. Replaced the exhaust hanger mounts as needed since they were gone and/or cracked.		1.00	250.00	250.00
New	*Oil Filter- 412*		2.00	50.65	101.30
New	*20W50 Valvoline VR1 Racing Oil*		17.00	17.65	300.05
New	*Brake Clean*		1.00	8.69	8.69
New	*Wiper Blade- 412*		1.00	27.48	27.48
New	*Wiper Blade- 412*		1.00	27.48	27.48

I hereby authorize the repair work to be completed, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and /or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. There is up to 250 miles to be driven for diagnostics on vehicle. I have read and understand the above and acknowledge receipt of an estimate.

X _____

Terms: Check or cash. A processing fee may be added. Vehicles left after repair is completed may be subject to a storage fee.

Veloce Motorsports
13209 NE 126th Pl, Suite C-355
Kirkland, WA 98034
(206) 228-4485
billing@veloceservice.com

Invoice # **1364**

Robert Standefer **1985 Ferrari 412 Base** License # Inv Date: 8/31/2024

New	*Ring- Exhaust Support*	14.00	13.25	185.50
Sublet	*Fuel*	1.00	32.45	32.45

Customer states that: The brake booster need to be replaced. **2,737.99**

Labor Service - After all of the brakes were fixed, the brakes didn't have assisted help. The vacuum lines are cracked and seem to have failed. Smoke tested the system and found that the brake booster is bad and has a hole in the diaphragm causing the vacuum assist to not work. Removed and replaced the brake booster with a good, rebuilt part. Replaced all of the vacuum lines as needed and assembled. Test ran and now the brakes feel much better. Test drove and the brake system is now working correctly and feels very good. Assembled all, all ok.		3.00	299.00	897.00
Rebuilt	*Brake Booster- 412*	1.00	1,639.29	1,639.29
Sublet	*Freight*	1.00	63.64	63.64
New	*Vacuum/Booster Hose 5/8"*	9.00	15.34	138.06

Warranty

All repair work is warranted for 6 months and for the original owner of vehicle that was repaired. No warranty for aftermarket parts and customer supplied parts and labor for that repair line.

X _____

Customer acknowledges receipt of merchandise and services.

Invoice Summary

Parts	8,413.09
Labor	6,772.00
Sublet	3,410.97
Sub Total	18,596.06
Sales Tax (WA)	1,930.61
Total	**20,526.67**

Discard old parts

Original Estimate: 20,494.22