ROOFSCAN UK

Drone Roof Inspection Report

PROPERTY

Sample property, Hove, East Sussex

REPORT DETAILS

Date: 14 October 2026
Client: Sample Client
Ref: RSU-SAMPLE

ROOF TYPE	COVERING	APPROX. AGE	DEFECTS FOUND
Pitched, gable ends	Clay plain tiles	Approx. 60 years	4

Overview drone photo of the property appears here in your report

www.roofscanuk.co.uk | 07498 364197 | info@roofscanuk.co.uk

Contents

Executive Summary

1.0 About This Report
- 1.1 Scope
- 1.2 Limitations
- 1.3 Traffic-Light System

2.0 Observations & Recommendations
- 2.1 Chimneys & Leadwork
- 2.2 Roof Coverings
- 2.3 Rainwater Goods
- 2.4 Ancillary Elements

3.0 Terms, Limitations & Disclaimer

4.0 Schedule of Works

Executive Summary

Condition Dashboard

1	3	6
Urgent - Action Required	Monitor - Review Advised	Satisfactory

Overall Roof Condition

Poor	Fair	Moderate	**Good**	Excellent

RoofScore

78

/100

Good: some elements to monitor

Chimneys & leadwork: 64/100
Roof coverings: 84/100
Rainwater goods: 76/100
Ancillary: 92/100

Summary of Findings

The roof is in good overall condition for its age. The main concern is the lifted lead flashing on the rear of the chimney stack, which should be repaired within the next three months to stop water getting into the stack. Three other items are worth keeping an eye on: the chimney flaunching, two ridge tiles near the left-hand gable, and debris in the front gutter. No slipped or missing tiles were seen on either slope.

Findings by Zone

● Chimney area	**Repair Required**
● Ridge	**Monitor**
● Rear elevation	**Satisfactory**
● Left side	**Satisfactory**
● Guttering	**Monitor**
● Front elevation	**Satisfactory**

Key Risks

- Lifted lead flashing at the rear of the chimney stack could let water into the loft or chimney breast during heavy rain.
- Debris in the front gutter could cause overflowing and damp patches on the front wall if not cleared.

Maintenance Overview

- Have a roofer refix and seal the chimney flashing within 3 months.
- Clear the front gutter and check the outlet before winter.
- Repoint the two ridge tiles and recheck the chimney flaunching within 12 months.
- Book a follow-up drone inspection in 12 months to track the monitored items.

1.0

Report Details

Scope, limitations & rating system

1.0 About This Report

Property: Sample property, Hove, East Sussex
Inspection Date: 14 October 2026
Client: Sample Client
Prepared By: Takhy Ndiaye Marrero - RoofScan UK
Report Reference: RSU-SAMPLE

1.1 Scope

Instructions were received to attend the property and undertake a drone-based visual inspection. This report has been prepared based on drone imagery captured on-site. It does not constitute a full building survey.

1.2 Limitations

The inspection was carried out using an unmanned aerial vehicle (drone). All observations are based on visual imagery only - no physical contact with roof surfaces was made.

1.3 Traffic-Light System

Repair Required - A defect requiring remedial action.
Monitor - Warrants attention but not immediately critical.
Satisfactory - No immediate action required.

2.0

Observations & Recommendations

Drone inspection findings by element

2.0 Observations & Recommendations

Observations are made as if standing at the front of the property.

2.1 Chimneys & Leadwork

The chimney stacks are the most exposed elements and common sources of water ingress.

Inspection Limitation
Chimney elements inspected by drone only. No physical access to the stack was undertaken.

Ref 2.1.1 Chimney pots & flaunching | *Chimney area*

Drone photo of this item appears here in your report

Monitor

Observation
Hairline cracking to the cement flaunching around both chimney pots. Neither pot is loose or displaced. Cracks like these can let water into the stack over time, so they are worth rechecking.

Priority
Within 12 months

Ref 2.1.2 Flashings & saddle pieces | *Chimney area*

Drone photo of this item appears here in your report

Repair Required

Observation
The lead step flashing on the rear face of the chimney stack has lifted away from the brickwork along roughly 40cm, leaving a gap where rain can run behind it.

Priority
Within 3 months

Ref 2.1.3 Stack pointing & stonework | *Chimney area*

Drone photo of this item appears here in your report

Satisfactory

Observation
Mortar joints to the stack are generally sound. No open joints, loose bricks or spalling were seen.

Priority
N/A

2.2 Roof Coverings

The observations below relate to the primary roof covering.

Ref 2.2.1 Ridge tiles & pointing | *Ridge*

Drone photo of this item appears here in your report

Monitor

Observation
Two ridge tiles towards the left-hand gable have weathered mortar bedding. Both tiles are still in position and appear secure.

Priority
Within 12 months

Ref 2.2.2 Slates / tiles - general condition | *Rear elevation*

Drone photo of this item appears here in your report

Satisfactory

Observation
Clay plain tiles are generally well laid, with no slipped, cracked or missing tiles seen on the front or rear slopes. Light moss growth on the north-facing rear slope, which is typical for a roof of this age.

Priority
N/A

Ref 2.2.3 Verge detail | *Left side*

Drone photo of this item appears here in your report

Satisfactory

Observation
Verge tiles and mortar along both gables are intact, with no gaps or loose sections seen.

Priority
N/A

2.3 Rainwater Goods

The rainwater goods are critical to managing surface water away from the building fabric.

Inspection Limitation
Rainwater goods were not observed under live rainfall. Observe gutters during heavy rainfall.

Ref 2.3.1 Guttering condition & fixings | *Guttering*

Drone photo of this item appears here in your report

Monitor

Observation
The front gutter holds a build-up of moss and leaf debris near the downpipe outlet. This can cause overflowing in heavy rain. Gutter brackets appear secure.

Priority
Within 3 months

Ref 2.3.2 Fascias & soffits | *Front elevation*

Drone photo of this item appears here in your report

Satisfactory

Observation
uPVC fascias and soffits are in good order, with no sagging, splits or missing sections seen.

Priority
N/A

Ref 2.3.3 Downpipes & drainage | *Front elevation*

Drone photo of this item appears here in your report

Satisfactory

Observation
Downpipes are secure to the wall with brackets in place and joints intact.

Priority
N/A

2.4 Ancillary Elements

The following observations relate to elements outside the primary roof structure.

Ref 2.4.1 Aerial / satellite fixings | *Chimney area*

Drone photo of this item appears here in your report

Satisfactory

Observation
The TV aerial is fixed to the chimney with the bracket and lashing wire in place. No signs of movement.

Priority
N/A

3.0

Terms & Disclaimer

Limitations, liability & regulatory notes

3.0 Terms, Limitations & Disclaimer

3.1 Confidentiality

This report is prepared solely for the named client. No responsibility is accepted to any third party.

3.2 Scope Limitations

This is a visual-only drone inspection and is not a full structural survey.

3.3 Drone Operations

All drone operations are conducted in compliance with UK CAA regulations.

4.0

Schedule of Works

Summary table for contractor briefing

4.0 Schedule of Works

The table below summarises all observations. Obtain written quotations from suitably qualified contractors before any works commence.

Ref	Zone	Element	Observation Summary	Priority
2.1.1	Chimney area	Chimney pots & flaunching	Hairline cracking to the cement flaunching around both chimney pots. Neither pot is loose or displaced. Cracks like these can let water into the stack over time, so they are worth rechecking.	Within 12 months
2.1.2	Chimney area	Flashings & saddle pieces	The lead step flashing on the rear face of the chimney stack has lifted away from the brickwork along roughly 40cm, leaving a gap where rain can run behind it.	Within 3 months
2.1.3	Chimney area	Stack pointing & stonework	Mortar joints to the stack are generally sound. No open joints, loose bricks or spalling were seen.	N/A
2.2.1	Ridge	Ridge tiles & pointing	Two ridge tiles towards the left-hand gable have weathered mortar bedding. Both tiles are still in position and appear secure.	Within 12 months
2.2.2	Rear elevation	Slates / tiles - general condition	Clay plain tiles are generally well laid, with no slipped, cracked or missing tiles seen on the front or rear slopes. Light moss growth on the north-facing rear slope, which is typical for a roof of this age.	N/A
2.2.3	Left side	Verge detail	Verge tiles and mortar along both gables are intact, with no gaps or loose sections seen.	N/A
2.3.1	Guttering	Guttering condition & fixings	The front gutter holds a build-up of moss and leaf debris near the downpipe outlet. This can cause overflowing in heavy rain. Gutter brackets appear secure.	Within 3 months
2.3.2	Front elevation	Fascias & soffits	uPVC fascias and soffits are in good order, with no sagging, splits or missing sections seen.	N/A
2.3.3	Front elevation	Downpipes & drainage	Downpipes are secure to the wall with brackets in place and joints intact.	N/A
2.4.1	Chimney area	Aerial / satellite fixings	The TV aerial is fixed to the chimney with the bracket and lashing wire in place. No signs of movement.	N/A

End of Schedule of Works - RoofScan UK