



Vision Point II Release Notes

October 2026
Rev 2026.1.3

20283 State Road 7, Suite 350
Boca Raton, FL 33498
USA
+1 (561) 689-2899

info@kaya.vision
support@kaya.vision
www.kaya.vision

1 Revision History

Version	Date	Notes
2024.1.0	09.2024	Initial release
2024.1.1	09.2024	Vision Point II release 2024.1 (Service pack 1)
2023.1.2	10.2024	Vision Point II release 2024.1 (Service pack 2)
2023.1.3	10.2024	Vision Point II release 2024.1 (Service pack 3)
2025.1.0	12.2024	Vision Point II release 2025.1
2025.1.1	01.2025	Vision Point II release 2025.1 (Service pack 1)
2025.1.2	03.2025	Vision Point II release 2025.1 (Service pack 2)
2025.1.3	04.2025	Vision Point II release 2025.1 (Service pack 3)
2025.2.0	06.2025	Vision Point II release 2025.2.0
2025.2.1	07.2025	Vision Point II release 2025.2 (Service pack 1)
2025.2.2	07.2025	Vision Point II release 2025.2 (Service pack 2)
2025.2.3	09.2025	Vision Point II release 2025.2 (Service pack 3)
2025.2.4	11.2025	Vision Point II release 2025.2 (Service pack 4)
2026.1.0	12.2025	Vision Point II release 2026.1.0
2026.1.1	04.2026	Vision Point II release 2026.1 (Service pack 1)
2026.1.2	05.2026	Vision Point II release 2026.1 (Service pack 2)
2026.1.3	10.2026	Vision Point II release 2026.1 (Service pack 3)

Table 1 – Revision History

Table of Contents

1	Revision History	1
2	Figures and Tables.....	4
2.1	List of Tables	4
3	Introduction	5
3.1	Safety precautions.....	5
3.2	Disclaimer	6
4	Release notes	7
4.1	Release notes Vision Point II/API 2026.1 (Service pack 3)	7
4.1.1	New features	7
4.1.2	Fixes and improvements.....	7
4.2	Release notes Vision Point II/API 2026.1 (Service pack 2)	8
4.2.1	Fixes and improvements.....	8
4.3	Release notes Vision Point II/API 2026.1 (Service pack 1)	9
4.3.1	New features	9
4.3.2	Fixes and improvements.....	9
4.4	Release notes Vision Point II/API 2026.1.....	10
4.4.1	New features	10
4.4.2	Fixes and improvements.....	10
4.5	Release notes Vision Point II/API 2025.2 (Service pack 4)	11
4.5.1	New features	11
4.5.2	Fixes and improvements.....	11
4.6	Release notes Vision Point II/API 2025.2 (Service pack 3)	12
4.6.1	New features	12
4.6.2	Fixes and improvements.....	12
4.7	Release notes Vision Point II/API 2025.2 (Service pack 2)	13
4.7.1	Fixes and improvements.....	13
4.8	Release notes Vision Point II/API 2025.2 (Service pack 1)	14
4.8.1	New features	14
4.8.2	Fixes and improvements.....	14
4.9	Release notes Vision Point II/API 2025.2.0.....	15
4.9.1	New features	15
4.9.2	Fixes and improvements.....	15
4.10	Release notes Vision Point II/API 2025.1 (Service pack 3)	16
4.10.1	New features	16
4.10.2	Fixes and improvements.....	16

4.11	Release notes Vision Point II/API 2025.1 (Service pack 2)	17
4.11.1	New features	17
4.11.2	Fixes and improvements	17
4.12	Release notes Vision Point II/API 2025.1 (Service pack 1)	18
4.12.1	New features	18
4.13	Release notes Vision Point II/API 2025.1	19
4.13.1	New features	19
4.13.2	Fixes and improvements	19
4.14	Release notes Vision Point II/API 2024.1 (Service pack 3)	20
4.15	Release notes Vision Point II/API 2024.1 (Service pack 2)	21
4.15.1	New features	21
4.15.2	Fixes and improvements	21
4.16	Release notes Vision Point II/API 2024.1 (Service pack 1)	22
4.16.1	Fixes and improvements	22
4.17	Release notes Vision Point II/API 2024.1	23
4.17.1	Important API Notes and Limitations	23

2 Figures and Tables

2.1 List of Tables

Table 1 – Revision History	1
----------------------------------	---

3 Introduction

3.1 Safety precautions

Please take the time to read through the precautions listed below to prevent preventable and unnecessary injuries and damage to you, other personnel, or property. Read these safety instructions carefully before your first use of the product, as these precautions contain safety instructions that must be observed. Be sure to follow this manual to prevent misuse of the product.



Caution! Read Carefully and do not disregard these instructions.

In case of a failure, disconnect the power supply

Disconnect the power supply immediately and contact our sales personnel for repair. Continuing to use the product in this state may result in a fire or electric shock.

If an unpleasant smell or smoking occurs, disconnect the power supply.

Disconnect the power supply immediately! Continuing to use the product in this state may result in a fire or electric shock. After verifying that no smoking is observed, contact our sales personnel for repair.

Do not disassemble, repair or modify the product.

It might result in a fire or electric shock due to a circuit shortage or heat generation. Contact our sales personnel before inspection, modification, or repair.

Do not place the product on unstable surfaces.

Otherwise, it may drop or fall, resulting in injury to persons or the camera.

Do not use the product if dropped or damaged.

Otherwise, a fire or electric shock may occur.

Do not touch the product with metallic objects.

Otherwise, a fire or electric shock may occur.

Do not place the product in dusty or humid environments, nor where water may splash.

Otherwise, a fire or electric shock may occur.

Do not wet the product or touch it with wet hands.

Otherwise, the product may fail or cause a fire, smoking, or electric shock.

Do not touch the gold-plated sections of the connectors on the product.

Otherwise, the surface of the connector may be contaminated by sweat or skin oil, resulting in contact failure of a connector, malfunction, fire, or electric shock due to static electricity discharge.

Do not use or place the product in the following locations.

- Unventilated areas such as closets or bookshelves.
- Near oils, smoke, or steam.
- Next to heat sources.
- A closed (and not running) car where the temperature becomes high.
- Static electricity replete locations
- Near water or chemicals.

Otherwise, a fire, electric shock, accident, or deformation may occur due to a short circuit or heat generation.

Do not place heavy objects on the product.

Otherwise, the product may be damaged.

Be sure to discharge static electricity from the body before touching any sensitive electronic components.

The electronic circuits in your computer and the circuits on the camera are sensitive to static electricity and surges. Improper handling may seriously damage the circuits. In addition, do not let your clothing come in contact with the circuit boards or components. Otherwise, the product may be damaged.

3.2 Disclaimer

KAYA Vision assumes no responsibility for any damage that may ensue by using this product for any purpose other than intended, as previously stated. Without detracting from what was previously written, please be advised that the company will take no responsibility for any damages caused by:

- Earthquake, thunder strike, natural disasters, a fire caused by use beyond our control, willful and/or accidental misuse and/or use under other abnormal and/or unreasonable conditions.
- Secondary damages caused by the use of this product or its unusable state (business interruption or others).
- Use of this product in any manner that contradicts this manual or malfunctions due to connection to other devices. Damage to this product that is out of our control or failure due to modification
- Accidents and/or third parties that may be involved.

Additionally, **KAYA Vision** assumes no responsibility or liability for:

- Erasure or corruption of data caused by the use of this product.
- Any consequences or other abnormalities following the use of this product

4 Release notes

The purpose of this document is to describe the changes, enhancements, and bug fix report for the new version release of Vision Point II.

4.1 Release notes Vision Point II/API 2026.1 (Service pack 3)

4.1.1 New features

1. Added Save pictures/RAW files via GUI (AVI file).
2. Added new GUI feature "Color Level Threshold bar".
3. Added the Camera Link serial port library (clserxxx.dll) to the Vision Point II SDK.
4. Added support for modifying Chameleon II Device Control parameters (model name, version, etc.).

4.1.2 Fixes and improvements

1. Fixed an issue that caused the SerialPort Example crashes on Linux with double free or corruption.
2. Fixed an issue when GenTL producer caused dropped frames on FPS ~ 170+.
3. Fixed an issue when GUI crashes after setting binning to 2.

4.2 Release notes Vision Point II/API 2026.1 (Service pack 2)

4.2.1 Fixes and improvements

1. Various bug fixes and improvements.

4.3 Release notes Vision Point II/API 2026.1 (Service pack 1)

4.3.1 New features

1. Introduced a new GUI application, KAYA Vision Studio, which aims to replace Vision Point II in future.
2. Added the ability to save buffers as image files or RAW data (single file or batch mode).
3. Added ability to acquire a specified number of frames. (For precise control and accuracy, the use of triggers is recommended).
4. Implemented device event support via the extension library API, KYVPLibTL, and the GenTL producer.

4.3.2 Fixes and improvements

1. Fixed an issue that caused image corruption during the acquisition start/stop sequence on Komodo III CLHS compatible.
2. Fixed an issue where the GenTL producer in MATLAB could fail to detect devices in the Image Acquisition Toolbox ("no devices found" issue).
3. Fixed an issue in the Windows installation package (silent installation) where the /COMPONENTS="" command-line argument was ignored.
4. Fixed an issue where the installation process could fail during the driver build step on Ubuntu 24 with kernel 6.17.
5. Various bug fixes and improvements.

4.4 Release notes Vision Point II/API 2026.1

4.4.1 New features

1. Added support for Zinc PCIe cameras.
2. Added a new API sample "VP11_Example_Manual_Detection" demonstrating the correct procedure for configuring manual detection through XML parameters.
3. Updated the "VP11_Example_Acquisition_Queued_Buffers" API sample to demonstrate the usage of the direct stream callback.

4.4.2 Fixes and improvements

1. Fixed an issue that caused image corruption when packed-data mode was enabled on III generation frame grabbers used with cameras supporting Tap Geometry.
2. Fixed an issue that prevented streaming from starting on CLHS line scan cameras.
3. Various bug fixes and improvements.

4.5 Release notes Vision Point II/API 2025.2 (Service pack 4)

4.5.1 New features

1. Added manual camera discovery using frame grabber XML parameters (commonly used with the KAYA GenTL provider).
2. Improved Power over CoaXPress (PoCXP) management.
3. Added support for frame grabber event handling.

4.5.2 Fixes and improvements

1. Fixed an issue with incorrect CXP packet tag assignment.
2. Fixed an issue with CLHS frame grabber sharing.
3. Fixed an issue with stream failure on CLHS cameras when using the KAYA GenTL producer.

4.6 Release notes Vision Point II/API 2025.2 (Service pack 3)

4.6.1 New features

1. Added support for manual camera detection.
2. Added an option to retrieve the current software version through KYVPLibTL_TLGetInfo.

4.6.2 Fixes and improvements

1. Fixed a crash that occurred when creating a stream via CL over Fiber range extender.
2. Buffer metadata is now initialized using the first (master) logical DMA channel for streams composed of multiple DMA channels.

4.7 Release notes Vision Point II/API 2025.2 (Service pack 2)

4.7.1 Fixes and improvements

1. Fixed an issue where the timestamp in the KYVP_IO_AUX_DATA structure was reported incorrectly (multiplied by 8).
2. Added support for retrieving precise buffer reception timestamps via new commands:
 - KYVP_BUFFER_INFO_CMD_TIMESTAMP_NS_HW (activated by a debug setting)
 - KYVP_BUFFER_INFO_CMD_TIMESTAMP_NS_CHRONO

4.8 Release notes Vision Point II/API 2025.2 (Service pack 1)

4.8.1 New features

1. Added support for Ubuntu 24.04 with Kernel 6.8.
2. Added .NET wrapper via Legacy Vision Point API Adapter.
3. Added support for Packed data streaming.
4. Added Save image option via GUI.
5. Added enable/disable Grid Lines overlay via GUI.

4.8.2 Fixes and improvements

1. Fixed a bug causing corrupted stream images when using dual or quad link cameras with CLHS Frame Grabbers.
2. Bug fixes and improvements.

4.9 Release notes Vision Point II/API 2025.2.0

4.9.1 New features

1. Implemented serial API interface.
2. KYFG_StreamCreateAndAlloc was implemented to the adapter.
3. Hardware debayering support.
4. Color correction matrix support.
5. Added controll of number of buffers per stream in Vision Point II app.

4.9.2 Fixes and improvements

1. Improve performance of communication with cameras.
2. Various bug fixes and improvements.

4.10 Release notes Vision Point II/API 2025.1 (Service pack 3)

4.10.1 New features

1. Implemented IO auxiliary callback.
2. Implemented new API functions to locking/unlocking Frame Grabber links.

4.10.2 Fixes and improvements

1. Fixed a bug causing image corruption on the Komodo III Octo CoaXPress when changing the connection speed.

4.11 Release notes Vision Point II/API 2025.1 (Service pack 2)

4.11.1 New features

1. Added triggers support:
 - Digital I/O
 - Encoder
 - Link trigger
 - Timer
 - Stream trigger
 - Camera trigger
 - Pulse message trigger

4.11.2 Fixes and improvements

1. Added Vision Point II API Sample KYVP_QueuedBuffer_Example.
2. Fixed DMA management bugs in third-generation Frame Grabbers.
3. Restored missing files in API samples.

4.12 Release notes Vision Point II/API 2025.1 (Service pack 1)

4.12.1 New features

1. Added the Firmware update directly through the Vision Point II GUI.

4.13 Release notes Vision Point II/API 2025.1

4.13.1 New features

1. Support for multiple streams feature implemented by certain CoaXPress cameras.
2. Support for TapGeometry (1X-2YE) implemented by certain CoaXPress cameras.
3. Added support for CLHS compatible frame grabbers:
 - Predator II CLHS compatible
 - Komodo II CLHS compatible
 - Komodo III CLHS compatible
4. Added support for Komodo III CoF Frame Grabber.
5. Support for Ubuntu 20.04 with Kernel 5.15.0 and Ubuntu 22.04 with Kernel 6.5.0.

4.13.2 Fixes and improvements

1. Fixed issue with CXP 2.0 packet tags handling.
2. Fixed issue with image processing that made last acquired frame dark when pixel depth more than 8 bits.
3. Improved stream stability on the multiple camera links.

4.14 Release notes Vision Point II/API 2024.1 (Service pack 3)

Delivered the new version of Vision Point (see Vision Point release notes).

4.15 Release notes Vision Point II/API 2024.1 (Service pack 2)

4.15.1 New features

1. Support for Firmware update.
2. KYParametersHandler_GetParameterAttributeValue() function was added to the KYVP ParametersHandler library.
3. KYFG_LoadFirmware(), KYFG_GetFirmwareUpdateFileInfo(), KY_GetCameraPropertyParameterValue(), and KY_GetGrabberPropertyParameterValue() functions were added to the legacy Vision Point API Adapter.
4. New documents added.

4.15.2 Fixes and improvements

1. Fixed issue with multiple errors in logs while streaming.
2. Fixed problem with HEX view for 10, 12 bit Pixel format.
3. Fixed bug with application crash while opening a camera with non-numeric device serial numbers.

4.16 Release notes Vision Point II/API 2024.1 (Service pack 1)

4.16.1 Fixes and improvements

1. Added support for "Komodo II CoF Frame Grabber" and "Predator II CoF Frame Grabber"

4.17 Release notes Vision Point II/API 2024.1

4.17.1 Important API Notes and Limitations

1. Vision Point II does not support KAYA's I generation Frame Grabbers:
 - Predator Dual Frame Grabber
 - Komodo Quad CoaXPress with Data Forwarding Frame Grabber
 - Komodo Camera Link High Speed Compatible Frame Grabber
 - Komodo Quad CoaXPress Frame Grabber
 - Komodo Octo CoaXPress Frame Grabber
 - Chameleon
 - Virtual frame grabbers (emulators)
2. This version does not support CLHS compatible Frame Grabbers of any generation¹.
3. Does not support Chameleon camera simulators¹.
4. New SDK supports only Windows 10 OS and Windows 11 OS².

Remarks:

1. Will be supported in the next Vision Point II release.
2. Linux OS will be supported in the next Vision Point II release.
3. For Windows OS to support the latest version of Vision Point II, please make sure your Windows is up to date and all the latest updates and hotfixes are installed.