

# Mimaki TxF300-75

Roll-fed DTF film transfer · PHT50 pigment (W+CMYK) · 800mm · prints FILM only, not garments

ADPOST GROUP  
SHOP-FLOOR CARD

## GOLDEN RULE

Keep the printer **POWERED + CAPPED** during idle so MCTv2 keeps the white moving — don't power down over long weekends. Weigh the white cartridges before each shift and run a nozzle check before the first job. At install, get a full nozzle check during dealer commissioning to catch a DOA head in warranty.

### DAILY — tick each shift

- ☐ Nozzle check before the first job + after any idle period.
- ☐ Weigh the white cartridges; keep  $\geq 1$  spare per slot loaded.
- ☐ End-of-day cap-station + wiper clean (approved solution only).
- ☐ Keep the printer clear of the powder-shaker airflow (no adhesive drift onto the head).
- ☐ Check room temp / RH at print height (aim 20-26°C / 40-60%).

### WEEKLY / MONTHLY PM

- Inspect / replace white-side dampers + filters (every 2-4 weeks).
- Clean the carriage underside; replace a glazed cap sponge.
- Map the curing oven with thermal strips; run wash tests on production samples.
- Calibrate powder-shaker vibration + film tension; ground / add anti-static.

### TOP PROBLEMS » QUICK FIX

**White runs out mid-job »** weigh before shift + spare per slot (or UISS / TxF300-75 Plus upgrade).

**White nozzles drop »** auto-clean max 3x, then manual wipe, then cap soak; swap a suspect cartridge BEFORE blaming the head.

**Prints crack / peel / wash off »** it's the CURING: map oven temp + dwell, wash-test; powder must be glossy, not chalky.

**White halo / mis-registration »** RasterLink choke (shrink white base under colour); save a verified preset.

**Powder on blanks / clumping »** calibrate shaker, anti-static, keep powder dry + sifted.

### KEEP ON THE SPARES SHELF

- White-side dampers + filters.
- Cap sponge + approved cleaning solution.
- PHT50 ink (esp. White); DTF film + adhesive powder stock.

### SOFTWARE

- **RasterLink7**: RIP, white layering + choke; one licence covers up to 4 printers.
- **Mimaki Profile Master 3**: custom ICC / colour profiling.
- **Mimaki Remote Access (MRA)** + on-printer **NCU / NRS** nozzle recovery.

**CALL THE TECH IF** 1. a white channel won't recover after dampers + purge + clean (push warranty head swap, esp. if new) 2. repeated DOA-like nozzle loss 3. NCU / NRS faults

Full brief: [Docs/printers/printer-onboarding-brief.md](#) | Official manuals + videos: [Docs/printers/official-resources.md](#) | Some figures are platform/sibling-sourced — verify on your unit. v1 · 2026-06-19