

HP Latex R530

64" hybrid (rigid flatbed + roll) · water-based Latex · 7-colour + White

ADPOST GROUP
SHOP-FLOOR CARD

GOLDEN RULE

NEVER fully power the printer off. Leave it in Sleep / Low-Power mode 24/7 so the white ink keeps recirculating. A full shutdown clogs the white line and needs a certified-engineer flush to recover. Treat any power outage as an incident.

DAILY — tick each shift

- ☐ First thing: confirm the machine is in SLEEP, not OFF.
- ☐ Run a nozzle check / status before the first job.
- ☐ After any overnight power blip, check white-ink status immediately.
- ☐ Wipe rigid boards clean + handle with gloves (fingerprint oil = adhesion voids).
- ☐ Check rigid stock is FLAT before loading (warped board = carriage strike).
- ☐ Set up artwork bleed for edge-to-edge work (avoids white edge slivers).

WEEKLY / MONTHLY PM

- Run HP weekly + monthly maintenance routines (see video links).
- Check / re-seat the maintenance cartridge + ink collector; replace when prompted.
- Rotate white cartridges oldest-first — white expires in ~6 months (colour ~12).
- Build + test a media preset for every new substrate BEFORE production.

TOP PROBLEMS » QUICK FIX

White line clogged » was it powered off? Sleep only. Recovery = HP engineer flush.

"Nozzles out" / banding » reset drop-detection DB, run 3 detect cycles + nozzle check, reseal carriage cables BEFORE buying ~\$3k heads.

Prints scratch (dark solids) » slower/higher pass, Overcoat low (~1.0-1.5), laminate, let cure 24h.

ACP heat-marks / delaminates » side-B cure ~80°C, cool fully, wait >=4h before laminating.

Adhesion failure » clean board, glove-handle, cross-hatch tape-test the new batch.

KEEP ON THE SPARES SHELF

- Spare drop detector (cheap swap-to-test part).
- HP 875 inks — incl. White 9D7Q3A, Optimizer 9D7Q1A, Black 9D7P7A.
- HP 886 white printhead (G0Z21A) + colour printhead (G0Z24A).
- Maintenance cartridge + ink collector (HP 833 / 838).

SOFTWARE

- **RIP**: ONYX or Caldera or ErgoSoft (all certified — pick one house RIP).
- **HP PrintOS / Production Hub**: cloud workflow + remote monitoring.
- **On-board touchscreen**: job load, white recirculation, calibration.

CALL THE TECH IF 1. white line clogged after a shutdown 2. nozzles still out after drop-detector reset + cable reseal 3. adhesion fails across multiple profiled substrates

Full brief: [Docs/printers/printer-onboarding-brief.md](#) | Official manuals + videos: [Docs/printers/official-resources.md](#) | Some figures are platform/sibling-sourced — verify on your unit. v1 · 2026-06-19

Mimaki UJF-6042 MkII e

A2 UV-LED flatbed · direct-to-object (up to 153mm thick) · CMYK+W+Lc/Lm+Clear · Kebab rotary

ADPOST GROUP
SHOP-FLOOR CARD

GOLDEN RULE

Shake every **WHITE** ink bottle (~20 gentle tilts) before each shift and run daily white maintenance. White circulates only in the sub-tank, NOT through the head, so it settles fast. Never leave the machine idle longer than 1-2 weeks. Put it on a UPS / line conditioner.

DAILY — tick each shift

- ☐ Shake the white ink bottle(s) before the shift.
- ☐ Nozzle check before the first job; clean Head 4 (white) if it's dropping.
- ☐ Wipe the clear/primer head face with approved flushing fluid (F-200 / FL-007).
- ☐ Clean wiper, caps + flushing box; check the ionizer needle is clean.
- ☐ IPA-wipe slick parts (glass/acrylic); ionizer fan on in dry weather.
- ☐ Set head height to the part's true HIGH point + use the correct jig/spacer.

WEEKLY / MONTHLY PM

- Clean the X-axis encoder strip + homing sensor (prevents Error 533).
- Inspect dampers / filters / tubing; replace on schedule.
- Re-torque the table-base screws + re-check the table is level.
- Check ink expiry on delivery (firmware locks out expired ink); rotate FIFO.

TOP PROBLEMS » QUICK FIX

White drops out mid-job (Head 4) » shake bottle, white maintenance, syringe-flush/replace white solenoid (M015864), confirm Head 4 at temp.

Error 533 (X homing fail) » CLEAN the encoder strip + sensor FIRST — not the electronics.

White “blowout” / mist on art » ionizer + 35-65% RH, lower head gap (~1.5mm), IPA-wipe parts.

Ink scratches off glass/metal » PR-200 primer + IPA degrease; scratch-test new substrates.

Clear/primer head dead » cycle ink + clean daily; budget periodic head replacement.

KEEP ON THE SPARES SHELF

- White solenoid valve (M015864) — forum-sourced part, confirm against your unit.
- Wipers, caps, dampers, filters.
- Flushing fluid (F-200 / FL-007); spare X-axis encoder strip.

SOFTWARE

- **RasterLink7**: RIP + jig (object alignment) + variable-data / numbering.
- **Mimaki Clear Control (MCC)**: gloss / matte / 2.5D textured clear.
- **Kebab MkII control**: enter diameter for 360° cylindrical printing.

CALL THE TECH IF 1. auto-maintenance freezes >1h (temp sensor / valves / o-rings) 2. white won't recover after solenoid flush + cleaning 3. encoder strip is scratched (needs replacement)

Full brief: [Docs/printers/printer-onboarding-brief.md](#) | Official manuals + videos: [Docs/printers/official-resources.md](#) | Some figures are platform/sibling-sourced — verify on your unit. v1 · 2026-06-19

Mimaki TxF300-75

Roll-fed DTF film transfer · PHT50 pigment (W+CMYK) · 800mm · prints FILM only, not garments

ADPOST GROUP
SHOP-FLOOR CARD

GOLDEN RULE

Keep the printer **POWERED + CAPPED** during idle so MCTv2 keeps the white moving — don't power down over long weekends. Weigh the white cartridges before each shift and run a nozzle check before the first job. At install, get a full nozzle check during dealer commissioning to catch a DOA head in warranty.

DAILY — tick each shift

- ☐ Nozzle check before the first job + after any idle period.
- ☐ Weigh the white cartridges; keep ≥ 1 spare per slot loaded.
- ☐ End-of-day cap-station + wiper clean (approved solution only).
- ☐ Keep the printer clear of the powder-shaker airflow (no adhesive drift onto the head).
- ☐ Check room temp / RH at print height (aim 20-26°C / 40-60%).

WEEKLY / MONTHLY PM

- Inspect / replace white-side dampers + filters (every 2-4 weeks).
- Clean the carriage underside; replace a glazed cap sponge.
- Map the curing oven with thermal strips; run wash tests on production samples.
- Calibrate powder-shaker vibration + film tension; ground / add anti-static.

TOP PROBLEMS » QUICK FIX

White runs out mid-job » weigh before shift + spare per slot (or UISS / TxF300-75 Plus upgrade).

White nozzles drop » auto-clean max 3x, then manual wipe, then cap soak; swap a suspect cartridge BEFORE blaming the head.

Prints crack / peel / wash off » it's the CURING: map oven temp + dwell, wash-test; powder must be glossy, not chalky.

White halo / mis-registration » RasterLink choke (shrink white base under colour); save a verified preset.

Powder on blanks / clumping » calibrate shaker, anti-static, keep powder dry + sifted.

KEEP ON THE SPARES SHELF

- White-side dampers + filters.
- Cap sponge + approved cleaning solution.
- PHT50 ink (esp. White); DTF film + adhesive powder stock.

SOFTWARE

- **RasterLink7**: RIP, white layering + choke; one licence covers up to 4 printers.
- **Mimaki Profile Master 3**: custom ICC / colour profiling.
- **Mimaki Remote Access (MRA)** + on-printer **NCU / NRS** nozzle recovery.

CALL THE TECH IF 1. a white channel won't recover after dampers + purge + clean (push warranty head swap, esp. if new) 2. repeated DOA-like nozzle loss 3. NCU / NRS faults

Full brief: [Docs/printers/printer-onboarding-brief.md](#) | Official manuals + videos: [Docs/printers/official-resources.md](#) | Some figures are platform/sibling-sourced — verify on your unit. v1 · 2026-06-19