

SERVICE REPORT



SRV2-TEST long - Intermittent audio dropouts, display flicker and room booking panel offline across Level 3 meeting rooms

RAA

Job: SKS-90003

Date: 23/09/2026

CLIENT	RAA	CONTACT	Alexandra Papadopoulos-Whitfield alexandra.papadopoulos-whitfield@facilities.example.com.au
SITE	1 King William St, Adelaide SA 5000	ROOM	Level 3 · Boardrooms 3.01, 3.02 and Collaboration Hub
EQUIPMENT	Cisco Room Kit Pro, Ceiling Mic Pro ×4, Q-SYS Core 110f, Samsung QM85C ×3, Cisco Room Navigator	CONTRACT	Ad-hoc service
TECHNICIAN	Mark Stow	ATTENDED	23 Sept 2026 Ref PO-1003

Issue reported

Staff reported three related faults across the Level 3 meeting rooms over the past fortnight.

Audio dropped out for two to five seconds at a time during video calls in Boardroom 3.01 and the Collaboration Hub, usually several times an hour. The displays in Boardroom 3.02 flickered and occasionally lost signal when a laptop was connected through the table HDMI input. The room booking panel outside the Collaboration Hub showed "Offline" and would not accept bookings.

Work carried out

We attended on two days to diagnose the faults while the rooms were in use.

Audio dropouts: logging on the Q-SYS Core showed Dante clock slips every time the network switch in the Level 3 comms room re-negotiated its uplink. The switch had been set to energy-efficient Ethernet on the AV VLAN ports after a recent change. We worked with your IT team to turn EEE off on the AV ports, set the Q-SYS Core as the preferred Dante leader and locked the clock settings. We then ran a four-hour soak test with a call held open in each room and recorded no further dropouts.

Display flicker: the table HDMI cable in Boardroom 3.02 failed a signal-integrity test at 4K and the HDMI extender was running firmware two versions behind. We replaced the table cable with a certified active cable, updated the extender firmware on both ends and set the displays to a fixed 4K 30 Hz input. Laptops



from three different manufacturers were tested at the table and all connected first time with a stable image.

Booking panel: the Room Navigator had lost its DHCP reservation after the comms room change and picked up an address outside the device VLAN. We restored the reservation, re-registered the panel to the booking service and confirmed that bookings made in Outlook appear on the panel within one minute.

All three rooms were tested end to end with your facilities coordinator before we left site.

Parts and gear used

Qty	Item	Note
1	Certified active HDMI 2.1 cable, 5 m	Boardroom 3.02 table input
2	HDMI extender PSU	replaced failing units in 3.02
4	CAT6A patch lead, 1 m	comms room re-patch
4	CAT6A patch lead, 3 m	ceiling mic drops
1	Rack-mount power distribution unit, 8-way	Level 3 AV rack
2	Velcro cable ties, 25-pack	rack tidy
1	Wall plate, dual RJ45	Collaboration Hub
2	RJ45 keystone insert	Collaboration Hub wall plate
1	Label tape cartridge	port labelling
1	HDMI extender firmware licence	both ends

Advice for the client

- Keep energy-efficient Ethernet turned off on every AV port, and let us know before any switch configuration changes on the AV VLAN.
- Add the AV devices to your IT change-control checklist, so DHCP reservations are kept when network equipment is replaced.
- Book a 30-minute test after any network maintenance window, so faults are caught before meetings.
- Replace the remaining table HDMI cables in Boardrooms 3.01 and 3.03 with certified active cables at the next scheduled service.
- Consider a support contract upgrade to include quarterly firmware checks on the extenders and codecs.

TECHNICIAN

Mark Stow

SKS Technologies23 Sept 2026

CLIENT ACKNOWLEDGEMENT

NameDate