AVO Carbon INDIA	8D REPORT	Format no:F/QAD/8D/09 Rev no:01 Rev date:15.09.2023

D0 Problem Awareness

8D-no: 1 **Submit Date:** 01.07.2025

Status: Open

Problem: AEM5.578.148 the carbon brushes have different shapes(Tapper Grinding) **Supplier:** Avo Carbon India

Part No: AEM5.578.148 Avo Part # 9208-0 **Place:** Chennai

Reported Date: 24.06.2025

Editor: Saravanan.B **Supplier Agent:** P. Ramkumar

D1 Establish Team

Member		Phone	E-Mail	Department
1	N.Gayathri	+91 444 2926571	gayathti.n@avocarbon.com	Head QAD
2	Suresh.P	+91 444 2926541	suresh.p@avocarbon.com	Head Production
3	Adikesavan	+91 444 2926541	adikesavan @avocarbon.com	Deputy Manager- Production
4	Sundaresan.R	+91 444 2926525	sundaresan.r@avocarbon.com	Head Engg
5	Saravanan.B	+91 444 2926573	Saravanan.b@avocarbon.com	Asst manager-QAD
6	Suresh.A	+91 444 2926573	suresh.a@avocarbon.com	Sr.Engineer -QAD

D2 Problem Description

Problem no: 1 **Quantity** 800

Problem Date: 24.06.2025 **Tested Quantity**

Manufacturing Date/ Month: Nov-2024 **Failure Quantity** 3

Repeated Failure: [ ] Yes [x] No

Compliant Text: **AEM5.578.148 the carbon brushes have different shapes(Tapper Grinding)**

D3 -Interim Containment Action

	Title	Responsible	Plan End
1	**Sorters, Operators, Inspectors & Supervisors are alerted about the compliant. And displayed the signed copy of Q-Alert with respective area.**	A.Suresh	24.06.2025
2	**Availble Avo FG stock 1300 nos 100% containment by Visual parts are found ok**	A.Senthil	24.06.2025

D4 Root Causes Analysis Why- Why Analysis

Root cause-Occurrence	Responsible	Plan End
Why? - Carbon Brush have different Shape Why? - Size of Brush Thickness Tapper Why? - Parts feeding inclined and lifted up Why? -Brush Flexible is not straignten **Root cause:** After investigation, Carbon brushes are feeding into grinding machine manually, operator missed some parts straight the flexible, the bend flex brush move to thickness Grinding it is lifted up and brush grinded as taper, there is no control to brush lift up.	Adikesavan/saravanan	27.06.2025

Root cause-Escape	Responsible	Plan End
Final inspection visual standard not covered this tapper grinding defect,it leads to flowout the defective part to escape to customer.	sravanan	27.06.2025

D5 Systemic Corrective Action / long term Action

Title	Responsible	Plan End
1.We implemented Brush hold down plate with spring pusher,when bend flexible feed to grinding brush hold down plate automatic adjust the brush feeding and ensure uniform thickness grinding 2.SOP revised and updated, awareness given through one point lesson. 3.Visual inspection SOP this tapper grinding defectWe will be updated	Adikesavan/saravanan	01.07.2025

D6 Effectiveness of implemented Corrective Action		
Title	**Responsible**	**Plan End**
1.We implemented Brush hold down plate with spring pusher,when bend flexible feed to grinding brush hold down plate automatic adjust the brush feeding and ensure uniform thickness grinding 2.SOP revised and updated, awareness given through one point lesson. 3.Visual inspection SOP this tapper grinding defectWe will be updated	Adikesavan/saravanan	01.07.2025
Relevant Core Tools update		
Title	**Responsible**	**Plan End**
FMEA, CP and SOP to be updated	Saravanan	03.07.2025
D7 Horizontal Deployment Action		
Title	**Responsible**	**Plan End**
Will plan the actions to other applicable machines	Adikesavan/saravanan	01.07.2025
Preventive measure		
Title	**Responsible**	**Plan End**
1.First of inspection format updated and ensure the hold down plate working condition /PDI Inspection report added the tapper grinding 2.SOP revised and updated, awareness given through one point lesson. 3.Visual inspection SOP this tapper grinding defect We updated	Saravanan	01.07.2025
D8 Problem Closure		
Title	**Responsible**	**Plan End**
Team Congralations	N.Gayathri	01.07.2025

Revision history
01/00-16.08.2022 fresh issue
01/02-15.09.2023 overall Reviewed & Updated