1.welding machine of Hall Ic fork : pressure parameters during welding.	not prooply welding of Hall IC -fork		The pressure decrease from 3,5 to 2 bar without stop machine	>	Machine blocked due to the perturbation of cycle "Mouvment of the piston "Jacks"	>	-No sensor implemented to detct the position to launch new cycle in the machine	>	Risk n the pr guide rules)

2 Result(s)

NON DETECTION

Relevant factors from FTA	1st WHY?	1st Check	2nd Check	2nd WHY?	3rd WHY?	3rd Check	4th WHY?	4th Check
2.method of checking SOP	the quality agent didn't re-verification the pressure	>	>	There is no visual device to show the pressure in this welding machine	lack of standard to check the pressure after mainteance intervention	X		

1 Result(s)

Nidec Comment

Lesson Learned Card

LLC Type

Date of LLC: **12/5/2024**

Logistics: ☐ Management: ☐

Product: ☐ Detection: ☐

Occurence: ☑ Process: ☐

1. What was the problem?

What happened?

Intermittent Hall function - unwelded fork

Who detected it?

Customer - Adient Jimbolia

Where was it detected?

Adient Jimbolia production

How was it detected?

During production

Why is it a problem?

Intermittent Hall function - unwelded fork
No Hall sensor signal.

When did it happen?

10/3/2024 11:00:00 PM (your local time)

How many parts ?

1.00

2. What is the cause?

Not activate of pressure control after maintenance intervention
Manual setting of pressure controller (Not locked)

3. Description of the applied modification

BEFORE

Manual pressure controller: unlocked system

AFTER

Automatic pressure controller : Locked system by IHM

4. What we learned?

ERADICATION

What is the countermeasure that was put in place to avoid recurrence ?

CHECKING

SIGNALING

Automatic pressure controller: Locked system in the machine	What is the method (who, what, how) for the countermeasures? **SOP check list**	What is the countermeasure supposed to do or make c a non conformity ? **Audit workstation**

5. What has been modified?

a. Proces is modified according to Before/ After sheet:	☑	g. Visual aids are posted:	☐
b. All documents have been updated and has been validated with the operators:	☐	h. Operators and other functions are trained:	☑
c. Procedures and work instructions:	☑	i. Proof of training is avalaible (records,5 ' meeting):	☑
d. Control Plan and PFMEA:	☑	j. Operators can correctly describe what they must do:	☑
e. Maintenance instructions:	☑	k. Other:	☐
f. Records (start-up checklists, reaction sheets, preventive maintenance...):	☑		
An evidance of modification:			

6. Potential applicability

LLC Applicability Product: **All CM4 Products**

LLC Applicability Line / process: **CM4**

LLC Applicability Plant: **SCEET TUNISIA**

Sorting Approval

Approval of sorting / rework

This document must be sent to Nidec within 24 hour(s) after claim notification

Date of page: Update:

CLAIM ISSUER

Author: **Dudek Dominik**
Position: **SQA Engineer**
Phone: **+48 12 297 27 86**
Fax:
Email: **dominik.dudek@nidec-ma.com**

CLAIM RECEIVER

Name: **Othmani Anis**
Position: **Quality Manager**
Phone: **216**
Fax:
Email: **anis.othmani@avocarbon.com**

IMMEDIATE ACTIONS REQUIRED AT NIDEC

PROBLEM DESCRIPTION

Intermittent Hall function - unwelded fork

DESCRIPTION OF SORTING/REWORK

QUANTITY AND PART NUMBERS CONCERNED

Parts at Nidec plant: **0.00**
Parts at Nidec logistics platfrom: **0.00**
Parts at Nidec's customer (C1): **0.00**
Parts in transport: **0.00**
Part Number & Description: **Brush mounting plate assy (503-773-99-99)**

Suspected delivery notes and batches#: delevery of week W41

SORTING COMPANY CHOSEN TO DO THE SORTING/REWORK