	legs - material conformity of theram switch	reference 503-661-99-99 Document N°10000025735 version 00								

3 Result(s)

NON DETECTION

Factor	Control Point	Standard	OK Parts	NOK Parts	Std Meet?	Std OK?	Action to reproduce the defect	Date	Direct Link?
5.final control method	IC700 instruction	100% of visual control of all points mentionned in the IC700 instruction	OK parts were controled according to the work instruction IC700	NOK parts were controled according to the work instruction IC700	Yes	No	the choke wire leg and thermal switch are welded but with lack current --> the instruction of control did't mention that the welding point must be a little crushed		Yes

1 Result(s)

Nidec Comment

5 Whys's

Date of 5 why's: **8/21/2024** Update of 5 Why's:

PROBLEM DESCRIPTION

Problem description: **choke wire not welded**

OCCURENCE

Relevant factors from FTA	1st WHY?	1st Check	2nd WHY?	2nd Check	3rd WHY?	3rd Check	4th WHY?	4th C
1. control current in welding station thermal switch - choke	the claimed part were welded with lack current	>	The welding done with inadequate current	>	the parameters of control current not defined	X		

1 Result(s)

NON DETECTION

Relevant factors from FTA	1st WHY?	1st Check	2nd Check	2nd WHY?	3rd WHY?	3rd Check	4th WHY?	4th C
5.final control method	The control instruction missing description the control method	>	>	The control method, not enough to describe the defect	The risk not considerate	X		

1 Result(s)

Nidec Comment

Lesson Learned Card

LLC Type

Date of LLC: **10/9/2024**

Logistics: ☐ Management: ☐

Product: ☐ Detection: ☑

Occurence: ☑ Process: ☐

1. What was the problem?

What happened?

choke wire not welded

Who detected it?

operator

Where was it detected?

CM4

How was it detected?

During defect analysis

Why is it a problem?

motor was rejected on EOL

When did it happen?

7/7/2024 11:00:00 PM (your local time)

How many parts ?

1.00

2. What is the cause?

the current was controlled but not efficient , the intervall were not well defined , the claimed parts were welded with lack current

3. Description of the applied modification

BEFORE	AFTER
No control of current in welding machine	Implement control current in welding station to avoid any welding operation with lack of power

4. What we learned?

ERADICATION

What is the countermeasure that was put in place to avoid recurrence ?

For occurence
***/ Implement control current in welding station to avoid any welding operation with lack of power**
For non detection
***/ updated the control instruction to mention the method of control on the front and back of the part**
***/ training session for the control opeartor dedicate for the EOL control**

CHECKING

What is the method (who, what, how) for the countermeasures?

Who : AVO
What :
***/ For occurence : Each SOP check the activiation of control current and start the production**
***/ For non detection :**
follow up the final control opeartion and check the level of opeartor in control station

SIGNALING

What is the countermeasure supposed to do or mal non conformity ?

When is identifing non conformity, all transportatio pallets should be
inspected

5. What has been modified?

a. Proces is modified according to Before/ After sheet: ☐
b. All documents have been updated and has been validated with the operators: ☑
c. Procedures and work instructions: ☑
d. Control Plan and PFMEA: ☐
e. Maintenance instructions: ☑
f. Records (start-up checklists, reaction sheets, preventive maintenance...): ☐
g. Visual aids are posted: ☑
h. Operators and other functions are trained: ☑
i. Proof of training is avalaible (records,5 ' meeting): ☐
j. Operators can correctly describe what they must do: ☐
k. Other: ☐

An evidance of modification:
- PH_3.75__Soudure_Self_sur_PTH.pdf
- IC700__A_CM4_CM3_updated_ (1).pdf
- Current_conrole_in_welding_station_ (1).mp4
- Questionnaire_audit_process_CM4..pdf
- session_training_of_welding_thermal_switch_choke.pdf

6. Potential applicability

LLC Applicability Product: **(503-773-99-99)**

LLC Applicability Line / process: **CM4**

LLC Applicability Plant: **AVO**

Sorting Approval

Approval of sorting / rework