		outside circle of the housing									
3/operator training levelB	opeartor level	polyvalence level for operator should be level B	polyvalence level for operator should be level B	polyvalence level for operator should be level B	Yes	Yes	No action to reproduce the defect		No		No

2 Result(s)

Nidec Comment

5 Whys's

Date of 5 why's: **3/20/2024** Update of 5 Why's:

PROBLEM DESCRIPTION

Problem description: **double DMC on brush card**

OCCURENCE

Relevant factors from FTA	1st WHY?	1st Check	2nd WHY?	2nd Check	3rd WHY?	3rd Check	4th WHY?	4th Check	5th
1/re-test parts on production line	parts with double marking passed in opeartion of re-test parts		there is no specific standard of re-testing parts in production line		risk of doubel marking was not considerate				

1 Result(s)

NON DETECTION

Relevant factors from FTA	1st WHY?	1st Check	2nd Check	2nd WHY?	3rd WHY?	3rd Check	4th WHY?	4th Check	5th
2/vision tester	in re-test operation, the DMC printer is still activated.			the setter mixed between the printer device and the reader device	there is no specific standard of disactivation printer during the re-test opearation				

1 Result(s)

Nidec Comment

Lesson Learned Card

LLC Type

Date of LLC:

Logistics: ☐ Management: ☐

Product: ☐ Detection: ☐

Occurence: ☐ Process: ☐

1. What was the problem?

What happened?

double DMC on brush card

Who detected it?

operator

Where was it detected?

CM4 line

2. What is the cause?

standard not exist :
There is no specific standard for operation re-testing.

How was it detected?

visually

Why is it a problem?

double DMC on brush card

When did it happen?

2/6/2024 12:00:00 AM (your local time)

How many parts ?

1.00

3. Description of the applied modification

BEFORE	AFTER
no Standard of re-test parts operation No Specific instruction of vision tester for operation re-test parts (mentioned the printer device must be disactivate and the reader must be activate)	Apply (create) Standard of re-test parts operation create Specific instruction of vision tester for operation re-test parts (mentioned the printer device must be disactivate and the reader must be activate) changement mode.pdf

4. What we learned?

ERADICATION

What is the countermeasure that was put in place to avoid recurrence ?

For occurence
*Standard of re-test parts operation
*/Training session for Quality agent and supervison and setter reading the new standard
For non-detection
*/Specific instruction of vision tester for operation re-test parts (mentioned the printer device must be disactivate and the reader must be activate)
*/Training session of final opeartor for defect double DMC

CHECKING

What is the method (who, what, how) for the countermeasures?

Who : AVO
What
*/For occurence : check the apply of standar of re-test opeartion during each opeartion
*/For non detection : check the apply of new instruction of vison tester during the re-test opeartion

SIGNALING

What is the countermeasure supposed to do or make or h detecting a non conformity ?

In case of detection of NOK parts with double DMC on brush card in the production line : alert and block all stock for sorting
+ Alert and block the parts in transit

5. What has been modified?

a. Proces is modified according to Before/ After sheet:	☐	g. Visual aids are posted:	☑
b. All documents have been updated and has been validated with the operators:	☑	h. Operators and other functions are trained:	☑
c. Procedures and work instructions:	☑	i. Proof of training is avalaible (records,5 ' meeting):	☑
d. Control Plan and PFMEA:	☐	j. Operators can correctly describe what they must do:	☑
e. Maintenance instructions:	☐	k. Other:	☐
f. Records (start-up checklists, reaction sheets, preventive maintenance...):	☑		

EOL_test_audit_station (1).pdf

An evidance of modification: instruction_relecture_updated (1).pdf

6. Potential applicability

LLC Applicability Product: **Brush mounting plate assy**

LLC Applicability Line / process: **CM4**

LLC Applicability Plant: **AVO**

Sorting Approval

Approval of sorting / rework

This document must be sent to Nidec within 24 hour(s) after claim notification

Date of page: Update: