2: Methode of control	in the final control station the opertor make the control the welding aspect of fuse choke and control visual the height of fuse choke	according to IC700 control instruction , control the height of fuse choke	OK part passed value of height fuse choke is less than 8 mm	NOK parts detecetd value of height fuse choke is 10.187 mm	Yes	Yes	no action to reproduice the defect		No	IC_700_ 243___7 (2).pdf
3: EOL electrical test : test the height of fuse choke	EOL 100% control of height of fuse choke	According to drawing A14116701A the value of fuse choke height is 5.6 min to 8 max	ok parts passed ok on electrical test	NOK parts are not passed on electrical test	Yes	Yes	no action to reproduice the defect		No	Média1.

2 Result(s)

Nidec Comment

5 Whys's

Date of 5 why's: **2/29/2024** Update of 5 Why's:

PROBLEM DESCRIPTION

Problem description: **Fuse Choke Leg Height NOK**

OCCURENCE

Relevant factors from FTA	1st WHY?	1st Check	2nd WHY?	2nd Check	3rd WHY?	3rd Check	4th WHY?	4th
1: methode of management of rework opeartion	risk not defined	>	There is no specific standard to manage the reworked palette requested by the customer.	>	no risk analysis done	X		

1 Result(s)

NON DETECTION

Relevant factors from FTA	1st WHY?	1st Check	2nd Check	2nd WHY?	3rd WHY?	3rd Check	4th WHY?	4th Check	5th WHY?	5th Check

Nidec Comment

Lesson Learned Card

LLC Type

Date of LLC: **3/14/2024**

Logistics: ☐ Management: ☐

Product: ☐ Detection: ☑

Occurence: ☑ Process: ☐

1. What was the problem?

What happened?

Fuse Choke Leg Height measured at 10.19 - drawing spec 5.6min to 8max SPPC

Who detected it?

11TA Line Operator

2. What is the cause?

lack of standard : there is no standard of rework operation
Our Production team receive this palettes to checked and change the spring NOK and passed again in Electrical test.

Where was it detected?

Assembly Line Electrical Test Station

How was it detected?

Shorticuit at Electrical Test

Why is it a problem?

Shortcircuit risk with the Motor Rear Cover

When did it happen?

2/20/2024 12:00:00 AM (your local time)

How many parts ?

14.00

After the rework, the pallet was still waiting for the availability of the electrical test, and due to the miscommunication between the production team and warehouse, the agent of the warehouse entered the pallet to be delivered

3. Description of the applied modification

BEFORE	AFTER
No standard of returned palette from customer and rework flow	create standard for the rework spring Create a general instruction for the rework of returned palettes.

4. What we learned?

ERADICATION

What is the countermeasure that was put in place to avoid recurrence ?

For occurence
1/ create standard of rework spring
2/ Create a general instruction for the rework of returned palettes
For non-detection
risk analysis in PFMEA : adding action of rework spring

CHECKING

What is the method (who, what, how) for the countermeasures?

Who: Supplier
What :
*/For occurence : check the apply the standard of returned palettes
*/For non-detection : take consideration all the risk in PFMEA

SIGNALING

What is the countermeasure supposed to do or m non conformity ?

In case of detection NOK parts with Fuse Choke Le Height NOK parts in the production line : alert and all stock for the sorting
+ ALert and block the parts in the transit

5. What has been modified?

- a. Proces is modified according to Before/ After sheet: ☐
- b. All documents have been updated and has been validated with the operators: ☑
- c. Procedures and work instructions: ☑
- d. Control Plan and PFMEA: ☑
- e. Maintenance instructions: ☐
- f. Records (start-up checklists, reaction sheets, preventive maintenance...): ☐
- g. Visual aids are postec
- h. Operators and other functions are trainec
- i. Proof of training is avalaible (records,5 ' meeting
- j. Operators can correctly describe what they must dc
- k. Other

An evidance of modification:

Standard_Gestion_des_palettes_retour_client_updated (1).pdf

Copie_de_Instruction_de_chgt_ressort (1).pdf

sheet training returned pallets.pdf

audit process ok.pdf

6. Potential applicability

LLC Applicability Product: A14116701A

LLC Applicability Line / process: 11TA/B8

LLC Applicability Plant: AVO

Sorting Approval

Approval of sorting / rework

This document must be sent to Nidec within 24 hour(s) after claim notification

Date of page: Update:

CLAIM ISSUER	CLAIM RECEIVER
Author: Lledo Alfons	Name: NEILI Amen Allah
Position: Supplier Quality Assurance	Position: Quality Engineer