AVO Carbon INDIA	8D REPORT	Fromat no:F/QAD/8D/09 Rev no:00 Rev date:16.08.2022

Customer Name : M/S.Rajamane Industries Pvt Ltd

8D-no: 1 **Submit Date:**

Status:

Title: Braided Wire Cut **Supplier:** AVO Carbon india Pvt ltd

Part No: 0399C57074 Avo Part # 2557-0 **Place:** Chennai-98

Reported Date:18.05.2024

Editor: A.suresh **Supplier Agent:** Mr.Ramkumar

D1 Team

Member		Phone	E-Mail	Department
1	Gayathri.N	+91 44 42926571	gayathti.n@avocarbon.com	Quality -HOD
2	Suresh.P	+91 44 42926541	suresh.p@avocarbon.com	Head production
3	Saravanan.B	+91 44 42926573	saravanan.b@avocarbon.com	Marketing
4	Ramkumar.P	+91 44 42926502	ramkumar.p@avocarbon.com	Asst Manager-QAD
5	Sundaresan.R	+ 914442926521	sundaresan.r@avocarbon.com	Process Engg-HOD

D2 Problem Description

Problem no: 1 **Quantity**

Problem Date: 18.05.2024 **Tested Quantity**

Manufacturing Date/ Month: **Failure Quantity**

Repeated Failure: [ ] Yes [x] No

Compliant Text: **Braided Wire Cut**

D3 Immediate

	Title	Responsible	Plan End
1	**Sorters, Operators, Inspectors & Supervisors are alerted about the compliant. And displayed the signed copy of Q-Alert with respective**	A. Suresh	Immediate
2	**Avo India avilable stock 100 % containment done by vernier caliper found all brushes ok**	A. Senthil	18.05.2024

D4 Causes analysis

Supposed Root cause

Root cause	Responsible	Plan End
Why? -Braided wire cut Why? - braided wire sleeve cut Why? - Sleeve partially shrink Why? - Process setting **Root cause:** As per defect shown in the picture and further investigation flexible wire was made up core and sleeve double layer, wire cut happen with sleeve, the sleeve may lighlty up during flexible insertion during setting and part flow with production parts it leads to wire cut with flexible sleeve. wire cut findout when bend the flexible wire, so not detected with inspection..	Saravanan	20.05.2024

D5 possible remedial action(s)

Title	Responsible	Plan End
While process setting instruct all operator to dispose all parts to scrap bin sourndng with machine before going to start of production. Also insertion of both sleeve and core must be check with first off inspection before start of production.	Saravanan	20.05.2024

D6 Remedial Action(s)

Title	Responsible	Plan End
While process setting instruct all operator to dispose all parts to scrap bin sourndng with machine before going to start of production. Also insertion of both sleeve and core must be check with first off inspection before start of production.	Saravanan	20.05.2024

D7 Preventive Measures

Title	Responsible	Plan End
This will ensure during First off Inspection	Pandiraj	20.05.2024

D8 Final Discussion

Thanks giving to team **End Date:** 21.05.2024