PRINÉTA

ATM Error Codes



Error Code	Model(s)	Error Description	Solution
20001	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Unable To Detect Cassette	Remove and replace cassette - Check the micro-switch located on the inside left wall of the dispenser. Adjust the micro-switch if needed, also check the white plastic clips that hold the cassette in place. If they are broken the cassette will not stay in the dispenser.
20002	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Low Cash	Low cash warning sensor on dispenser is open. When "Low Cash Warning" is enabled in the Transaction Setup menu, this sensor will open when the cassette reaches (+/-) 75 bills. If this machine is typically stocked with a low amount of bills, we recommend disabling this function.
20003	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Reject Bin is Full	Empty reject bin - if bin is empty, do a Cassette Total (from the settlement menu) - If that doesn't help then check that AP, BIOS and CDU ROM versions are compatible.
20004	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Vault Door is Open	This error occurs when the circuit between the mainboard and the door switch is open. Check vault door switch. This white plunger switch is located in the upper left corner of the vault, or on along the front edge of the cash dispenser tray. Also check that black and white, 2 wire connector is properly connected at rear of main board. Move the vault switch forward to aid door clearance problems. Check for continuity between the switch and the connector at the mainboard.
20005	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CDU Type Mismatch	CDU ROM does not match AP software. The dispenser and mainboard are programmed with a country code (USA or Canada). The two codes must match. If they do not the 20005 error will occur in which case the CDU will need to be reprogrammed to match the AP on the mainboard. Also, if the wrong parameters are entered when the CDU is programmed, this error can occur.
20010	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Receipt Paper Jam	Remove jammed paper - Release receipt paper drawer by pressing the tab with the green sticker located at the front of the printer. In most cases you may have to remove the printer to locate difficult jams. NOTE: Do NOT use metal objects to clear jams, use a business card or stiff paper. Make sure you only are using 21# paper. Paper of a lesser thickness is more prone to jamming.

20012	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Receipt printer feed lever open	Close the feed tray on the printer. If the paper tray is already closed, try opening and closing the tray, try the printer reset switch. Otherwise the printer may require service.
20013	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Receipt paper is empty	Replenish the paper roll, if there is already paper in the printer look for jams or obstructions. Try the printer reset switch. If it still has the error the printer may require service.
20014	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Thermal printer is overheated	If this error occurs during the printing of a long journal, then allow the printer to cool and try again. You may also want to try the reset button on the printer to clear this error. If this error persists, the printer will require service.
20215	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CDU detects bills prior to dispensing	This means that while the ATM was initializing it detected a blocked sensor in the cash dispenser (CS2 sensor). Remove any jammed bills from the dispenser, if no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Check and reseat all belts. Loose belts can slip off rollers and block sensors.
21315	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CDU detects bills prior to dispensing	This means that while the ATM was initializing it detected a blocked sensor in the cash dispenser (CS13 sensor). Remove any jammed bills from the dispenser, if no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Check and reseat all belts. Loose belts can slip off rollers and block sensors.
90001	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Error during card swipe	This error occurs when customer attempts to swipe their card and are unsuccessful. It may indicate that the card reader needs to be cleaned, repositioned or simply that the customer didn't swipe their card properly. If persistent, clean and test the card reader in diagnostics. NOTE: it is very common to see this error in the error summary and does not usually indicate a bad or defective part.
99999	1800CE, 1800SE, 2700CE, 2700T, 4000W, 5000CE, 5000SE, 5000XP, 5050CE, 5050XP, 5300CE, 5300XP, Halo, Halo II	NVRAM is broken	The NVRAM has been cleared, and the master password must be reset to default before the ATM can be reprogrammed. This error is either caused by loss of power to the main board, or is the result of a successful bootloader installation. Corrective steps: 1. Press Enter -> Clear -> Cancel -> 1 -> 2 -> 3. If there is an option to

			reset the master password and clear the error, select it. 2. Follow the master password reset process for the ATM. Open the vault door. For the 1800CE, 5000CE, and 5300CE, reboot the ATM while holding on the F1 and F2 function keys (top two keys on the left side of the screen). Reset the password when prompted. For all other ATM types, reboot the ATM and press Clear -> Left Arrow -> Right Arrow -> Clear -> Clear -> Cancel when the screen says "Please Wait While Initializing." Press "Yes" to reset the Master Password and clear the keypad. 3. Once the master password has been reset to 555555, enter the operator functions and clear the NVRAM under System Setup -> System Control. 4. Re-program the ATM. 5. If the error will not clear on an 1800CE, 5000CE, or 5300CE, the IO board battery may be dead.
400400	1800CE, 2700CE, 5000CE, 5300CE	Error of being removed 2nd cassette before separate rejection	1. Set cassette #2 correctly 2. Check the catcher inside cassette #2 guide
972211	1800CE, 2700CE, 5000CE, 5300CE	Field is not Found	1. Reboot ATM 2. Call your attendant
972212	1800CE, 2700CE, 5000CE, 5300CE	Field Error (This Field must have initial value)	1. Reboot ATM 2. Call your attendant
972213	1800CE, 2700CE, 5000CE, 5300CE	Non-Indexed value for Indexed Field	1. Reboot ATM 2. Call your attendant
972214	1800CE, 2700CE, 5000CE, 5300CE	Invalid Field	1. Reboot ATM 2. Call your attendant
972215	1800CE, 2700CE, 5000CE, 5300CE	Invalid Field (This Field's width is 0)	1. Reboot ATM 2. Call your attendant
1030100	1800CE, 2700CE, 5000CE, 5300CE	DEV_PIN (Key data error from host)	Contact to host
1101910	1800CE, 2700CE, 5000CE, 5300CE	LOST CARD\", DEV_MCU	N/A
1102910	1800CE, 2700CE, 5000CE, 5300CE	LOST WITHDRAW CASH\", DEV_CSH	N/A
1102920	1800CE, 2700CE, 5000CE, 5300CE	LOST DEPOSIT CASH\", DEV_CSH	N/A
1103910	1800CE, 2700CE, 5000CE, 5300CE	LOST CARD & SLIP\", DEV_MCU | DEV_SPR	N/A
1106910	1800CE, 2700CE, 5000CE, 5300CE	LOST SLIP\", DEV_SPR	N/A
2000100	1800CE, 2700CE, 5000CE, 5300CE	No cassette	Insert or re-insert the cassette(s). Check cassette sensor.
2000200	1800CE, 2700CE, 5000CE, 5300CE	Note shortage	Replenish the cassette.
2000300	1800CE, 2700CE, 5000CE, 5300CE	Reject bin full	Remove notes from the reject bin and try the Cassette Total function again.
2000400	1800CE, 2700CE, 5000CE, 5300CE	Vault door open	Close the vault door. Check door switch.

2000500	1800CE, 2700CE, 5000CE, 5300CE	Cash Dispenser Unit data setting error	Check Cash Dispenser Unit information. (Currency, Denomination, etc)
2001000	1800CE, 2700CE, 5000CE, 5300CE	Receipt paper jam	Remove any jammed paper from the printer.
2001200	1800CE, 2700CE, 5000CE, 5300CE	Receipt printer feed plate open	Close the feed plate.
2001300	1800CE, 2700CE, 5000CE, 5300CE	Out of receipt (Receipt paper empthy)	Replenish the receipt paper.
2001400	1800CE, 2700CE, 5000CE, 5300CE	Receipt printer head overheated before printing	Check the printer head and change if necessary.
2001600	1800CE, 2700CE, 5000CE, 5300CE	Note detected in stacker (shutter or presenter type)	Clear any notes from the stacker.
2010100	1800CE, 2700CE, 5000CE, 5300CE	Receipt printer lever opened	Close the lever of print head completely
2010200	1800CE, 2700CE, 5000CE, 5300CE	Receipt printer head overheated	Wait the time until the temperature of head adequately slow down and try to initialize
2010300	1800CE, 2700CE, 5000CE, 5300CE	Receipt paper jam	Remove jammed paper between printer head and rollers
2010400	1800CE, 2700CE, 5000CE, 5300CE	Receipt paper empty	1. Replenish receipt paper 2. Check the status of sensor and its connector
2010500	1800CE, 2700CE, 5000CE, 5300CE	Receipt paper setting error	1. Check the status of setting paper 2. Check the status of sensor and its connector
2010600	1800CE, 2700CE, 5000CE, 5300CE	Command is received while doing self-test	After terminating self-test and initialize receipt printer
2010700	1800CE, 2700CE, 5000CE, 5300CE	No receipt paper	1. Replenish receipt paper in paper charger 2. Check the status of Near End sensor and its connector
2010800	1800CE, 2700CE, 5000CE, 5300CE	Receipt paper cutting error	1. Check the Cutter module 2. Check if printer head lever is properly close
2010900	1800CE, 2700CE, 5000CE, 5300CE	No sensing black mark (dark sensor)	1. Check the status of Black mark sensor 2. Check if Dip switch # 6 is correctly set (Dip switch # 6 is set by On in case of not using Black mark)
2021500	1800CE, 2700CE, 5000CE, 5300CE	Sensor detects note in delivery path before CDU dispenses	Remove note from the CDU delivery path.
2080100	1800CE, 2700CE, 5000CE, 5300CE	Receipt printer lever opened	Close the lever of print head completely
2080200	1800CE, 2700CE, 5000CE, 5300CE	Receipt printer head overheated	Wait the time until the temperature of head adequately slow down and try to initialize
2080300	1800CE, 2700CE, 5000CE, 5300CE	Receipt paper jam	Remove jammed paper between printer head and rollers
2080400	1800CE, 2700CE, 5000CE, 5300CE	Receipt paper empty	1. Replenish receipt paper 2. Check the status of sensor and its connector
2080500	1800CE, 2700CE, 5000CE, 5300CE	Receipt paper setting error	1. Check the status of setting paper 2. Check the status of sensor and its connector
2080600	1800CE, 2700CE, 5000CE, 5300CE	Command is received while doing self-test	After terminating self-test and initialize receipt printer

2080700	1800CE, 2700CE, 5000CE, 5300CE	No receipt paper	1. Replenish receipt paper in paper charger 2. Check the status of Near End sensor and its connector
2080800	1800CE, 2700CE, 5000CE, 5300CE	Receipt paper cutting error	1. Check the Cutter module 2. Check if printer head lever is properly close
2080900	1800CE, 2700CE, 5000CE, 5300CE	No sensing black mark (dark sensor)	1. Check the status of Black mark sensor 2. Check if Dip switch # 6 is correctly set (Dip switch # 6 is set by On in case of not using Black mark)
2131500	1800CE, 2700CE, 5000CE, 5300CE	CS4 sensor detects note in delivery path before CDU dispenses. Sensor is located along the delivery path right before the reject bin.	Remove note from the CDU delivery path.
4000000	1800CE, 2700CE, 5000CE, 5300CE	Cash Dispenser(CDU) received the undefined command from AP software	1. Get the trace file and log files in D:\trace2. Call your attendant
4001100	1800CE, 2700CE, 5000CE, 5300CE	Detecting CS2 Dark (Front Access Type:Reject box is opened.)	1. Remove notes on CS2 sensor 2. Clean CS2
4001400	1800CE, 2700CE, 5000CE, 5300CE	CS4A sensor detects note in delivery path before/after CDU dispenses	1. Remove note from the CDU delivery path.2. Clean CS4A
4001500	1800CE, 2700CE, 5000CE, 5300CE	CS2 or CS4A sensor detects note in delivery path before/after CDU dispenses	1. Remove note from the CDU delivery path.2. Clean CS2 and CS4A
4001800	1800CE, 2700CE, 5000CE, 5300CE	CS4B sensor detects note in delivery path before/after CDU dispenses	1. Remove note from the CDU delivery path.2. Clean CS4B
4001900	1800CE, 2700CE, 5000CE, 5300CE	CS2 or CS4B sensor detects note in delivery path before/after CDU dispenses	1. Remove note from the CDU delivery path.2. Clean CS2 and CS4B
4002100	1800CE, 2700CE, 5000CE, 5300CE	CS1A sensor detects note in delivery path before/after CDU dispenses	1. Remove note from the CDU delivery path.2. Clean CS1A
4002200	1800CE, 2700CE, 5000CE, 5300CE	CS1B sensor detects note in delivery path before/after CDU dispenses	1. Remove note from the CDU delivery path.2. Clean CS1B
4002300	1800CE, 2700CE, 5000CE, 5300CE	CS1A or CS1B sensor detects note in delivery path before/after CDU dispenses	1. Remove note from the CDU delivery path.2. Clean CS1A and CS1B
4002800	1800CE, 2700CE, 5000CE, 5300CE	CS13 sensor detects note in delivery path before/after CDU dispenses	1. Remove note from the CDU delivery path.2. Clean CS13
4002900	1800CE, 2700CE, 5000CE, 5300CE	CS1A or CS13 sensor detects note in delivery path before/after CDU dispenses	1. Remove note from the CDU delivery path.2. Clean CS1A and CS13
4003000	1800CE, 2700CE, 5000CE, 5300CE	Failed in checking the main motor echo	1. Initialize 2. Check Main Motor Encoder Slit 3. Initialize after Power On/Off 4. Check Encoder Sensor CS8 BRKT 5. Check CS8 Sensor Cable 6. Change Main Motor Encoder Slit Sensor CS8

4003100	1800CE, 2700CE, 5000CE, 5300CE	Failed in checking the reject gate solenoid echo	N/A
4003200	1800CE, 2700CE, 5000CE, 5300CE	Failed in checking the present gate solenoid echo	N/A
4003300	1800CE, 2700CE, 5000CE, 5300CE	Check sum error (No information is set)	1. Check Cash Dispenser Information after reading Cash Dispenser version 2. Initialize 3. Initialize after executing Cash Dispenser Information Set(?P?) Command 4. Change Cash Dispenser B/D
4003400	1800CE, 2700CE, 5000CE, 5300CE	Error of two sheets detecting sensor(CS5_1) for initializing	1. Check CS5_1 Sensor Cable 2. Check second Dip Switch in Cash Dispenser B/D 3. Change CS5_1 Sensor
4003600	1800CE, 2700CE, 5000CE, 5300CE	Error of CS 2, CS13 sensor during initialization	N/A
4003700	1800CE, 2700CE, 5000CE, 5300CE	Error of 2 sheets detecting sensor (CS5_1 / CS5_2) for dispensing	1. Check Cash Dispenser Board Segment 2. Initialize 3. Read data of ?Read Double Sensor? Command
4003800	1800CE, 2700CE, 5000CE, 5300CE	Error in checking SRAM	N/A
4003900	1800CE, 2700CE, 5000CE, 5300CE	Gate operation sensor (CS3) error before initial recovery	1. Initialize after removing notes or dust over Gate 2. Check CS3 Sensor BKRT 3. Check CS3 Sensor Cable 4. Exchange Sensor after abnormal operating CS3 Gate detecting Sensor 5. Replace Reject Solenoid 1
4004000	1800CE, 2700CE, 5000CE, 5300CE	Cassette is removed during dispensing	1. Check the cassette catcher 2. Set the cassette properly
4004100	1800CE, 2700CE, 5000CE, 5300CE	Error if re-driving is over 5 times during separated rejection	1. Check notes in Reject Box 2. Rearrange notes in Cassette 2. Rearrange notes in Cassette 3. Remove dust in CS15AB, CS31AB, CS41AB, CS1AB Sensor 4. Check dust existing in CS5 Sensor Guide 5. Check dust existing in Main Motor Encoder Slit 6. Check index value of notes each cassette
4004200	1800CE, 2700CE, 5000CE, 5300CE	In case the number of notes detected outlet sensor(CS13) is less than the number of required notes	1. Check notes dispensed and rejected 2. Remove notes jammed in CDU 3. Remove dust in CS13 Sensor 4. Exchange sensor after abnormal operating CS13 Sensor
4004300	1800CE, 2700CE, 5000CE, 5300CE	Error if total reject is more than 20 sheets	1. Check notes in Reject Box 2. Rearrange notes in Cassette 3. Remove dust in CS1AB, CS15AB, CS31AB, CS41AB Sensor 4. Check dust in existence CS5 Sensor Guide 5. Check notes index value
4004400	1800CE, 2700CE, 5000CE, 5300CE	Error if continuous 5 times are rejected	1. Check notes in Reject Box 2. Rearrange notes in Cassette 3. Check dust in Main Motor Encoder Slit 4. Remove dust in CS15AB, CS31AB, CS1AB Sensor 5. Exchange CS8 Encoder Slit Sensor
4004500	1800CE, 2700CE, 5000CE, 5300CE	In case the number of notes detected outlet sensor(CS13) is more than required notes	1. Check notes dispensed and rejected 2. Remove dust in CS13 Sensor 3. Exchange sensor after abnormal operating
4004600	1800CE, 2700CE, 5000CE, 5300CE	Program error(Separated rejection)	1. Initialize after Reset Power 2. Upgrade Cash Dispenser Firmware or re-download 3. Exchange Cash Dispenser B/D

4004700	1800CE, 2700CE, 5000CE, 5300CE	1 cassette mis-feed error (Separated rejection)	1. Check notes in 1 Cassette 2. Check Sensor(CS6) Poll 3. Check jam in 1 cassette and reload 4. Remove dust in CS1A, CS1B Sensor 5. Exchange 1 cassette box when there are many error
4004800	1800CE, 2700CE, 5000CE, 5300CE	Error if the number of dispensed notes is not matched to the requested	1. Check CS13 sensor (note jam and dust) 2. Replace CS13 sensor
4004900	1800CE, 2700CE, 5000CE, 5300CE	Error to dispense 0 sheets to be required (Separated rejection)	1. Check received command 2. Check communication cable 3. Check Cash Dispenser Firmware Version
4005100	1800CE, 2700CE, 5000CE, 5300CE	Received a request for over 150 notes dispensing on the Cash Dispenser from the upper unit.	1. Check the Cash Dispenser received command 2. Check the abnormal communication cable. 3. Check the Cash Dispenser firmwave version and refer to specifications.
4005200	1800CE, 2700CE, 5000CE, 5300CE	The remaining notes at the sensor in front of the CST after dispense operation (CS1A, CS1B)	1. Remove the remaining notes at a sensor in front of the CST 2. Realign notes in the cassette 3. Check abnormal clutch. 4. Check abrasion of the cassette box pick unit.
4005300	1800CE, 2700CE, 5000CE, 5300CE	Error for the double note detection during separation.	N/A
4005400	1800CE, 2700CE, 5000CE, 5300CE	Cash Dispenser EP Program Error during dispense operation (failed table search)	1. Initialize after resetting the power 2. Upgrade the Cash Dispenser firmware or download software again 3. Replace the Cash Dispenser B/D
4005500	1800CE, 2700CE, 5000CE, 5300CE	Timeout due to note?s length error passed through the CS13 during dispense operation	1. Remove a jammed note between the tray and Cash Dispenser 2. Remove a jammed note at the position of the CS13 sensor 3. Remove a dust on the CS13 sensor
4005600	1800CE, 2700CE, 5000CE, 5300CE	Abnormal operation of the gate solenoid during dispense operation.	1. Remove a jammed note on the gate 2. Remove notes in the reject box and remount the reject box 3. Check if the CS3 sensor bracket is bent 4. Check if the CS3 sensor cable is disconnected 5. Exchange a sensor after abnormal operating CS3 Gate detecting sensor. 6. Replace the reject solenoid 1
4005700	1800CE, 2700CE, 5000CE, 5300CE	Cash dispenser configuration error	1. Replace cash dispenser PCB 2. Reconfigure cash dispenser setup data
4005800	1800CE, 2700CE, 5000CE, 5300CE	Retract box position error during command reserved operation	1. Mount the retract box or open the box cover 2. Check if CS62 sensor poll is abnormal 3. Check if the CS62 sensor cable is disconnected (Cash Dispenser Board CN10 #5~2).
4005900	1800CE, 2700CE, 5000CE, 5300CE	Initial jam time error	1. Remove jammed notes 2. Clean the sensors (CS1~CS15) in cash dispenser
4006000	1800CE, 2700CE, 5000CE, 5300CE	Something is detected in C31AB sensor before dispensing bills from 3rd cassette.	N/A
4006100	1800CE, 2700CE, 5000CE, 5300CE	Something is detected in C31AB sensor before dispensing bills.	N/A
4006200	1800CE, 2700CE, 5000CE, 5300CE	Bills are remained in CS1AB sensor after dispensing bills.	N/A

4006300	1800CE, 2700CE, 5000CE, 5300CE	Bills are remained in CS31AB sensor after dispensing bills	N/A
4007000	1800CE, 2700CE, 5000CE, 5300CE	Something is detected on CS41AB sensor before dispensing bills from fourth cassette.	N/A
4007200	1800CE, 2700CE, 5000CE, 5300CE	Something is detected on CS41AB sensor during dispensing bills.	N/A
4007300	1800CE, 2700CE, 5000CE, 5300CE	Bills is remained in CS41AB sensor after dispensing bills.	N/A
4008000	1800CE, 2700CE, 5000CE, 5300CE	Something is detected on CS15AB sensor before dispensing operation	N/A
4008100	1800CE, 2700CE, 5000CE, 5300CE	Something is detected in C15AB sensor during dispensing operation	N/A
4008200	1800CE, 2700CE, 5000CE, 5300CE	Bill is remained in CS15AB sensor after dispensing operation	N/A
8216091	1800CE, 2700CE, 5000CE, 5300CE	Cash jammed on Cash Dispenser	1. Remove jammed notes on Cash Dispenser return path 2. Remove dust in CS1~CS4 sensor
8217091	1800CE, 2700CE, 5000CE, 5300CE	Card in card reader	Remove card
9701010	1800CE, 2700CE, 5000CE, 5300CE	Failed to connect communication between SP of PIN and EP of one	Check if communication cable or COM port is not connected
9701012	1800CE, 2700CE, 5000CE, 5300CE	Failed to deliver to data of EPP?s SP	Check if communication cable or COM port is not connected
9701016	1800CE, 2700CE, 5000CE, 5300CE	Received data time out of EPP	Check if communication cable or COM port is not connected
9701017	1800CE, 2700CE, 5000CE, 5300CE	Delivered data time out of EPP	Check if communication cable or COM port is not connected
9701031	1800CE, 2700CE, 5000CE, 5300CE	Failed to read Register of EPP	Reboot ATM
9701040	1800CE, 2700CE, 5000CE, 5300CE	Failed to produce Thread of EPP	Reboot ATM
9701060	1800CE, 2700CE, 5000CE, 5300CE	Failed to create buffer	Reboot ATM
9701111	1800CE, 2700CE, 5000CE, 5300CE	BCC error of EPP	Check BCC logic of EPP
9701151	1800CE, 2700CE, 5000CE, 5300CE	EPP is down when it receives an 'Get Status' command	1. Reboot ATM 2. Replace pinpad
9701152	1800CE, 2700CE, 5000CE, 5300CE	EPP is down when it receives an 'Clear Func Key' command	1. Reboot ATM 2. Replace pinpad
9712000	1800CE, 2700CE, 5000CE, 5300CE	Failed to create file	1. Reboot ATM 2. Reinstall software 3. Replace hard disk drive
9712100	1800CE, 2700CE, 5000CE, 5300CE	Failed to read file	1. Reboot ATM 2. Reinstall software
9712200	1800CE, 2700CE, 5000CE, 5300CE	Failed to write file	1. Reboot ATM 2. Reinstall software 3. Replace hard disk drive

9712300	1800CE, 2700CE, 5000CE, 5300CE	Failed to close file	1. Reboot ATM 2. Reinstall software 3. Replace hard disk drive
9712400	1800CE, 2700CE, 5000CE, 5300CE	Failed to delete file	1. Reboot ATM 2. Reinstall software 3. Replace hard disk drive
9712500	1800CE, 2700CE, 5000CE, 5300CE	Failed to copy file	1. Reboot ATM 2. Reinstall software 3. Replace hard disk drive
9712600	1800CE, 2700CE, 5000CE, 5300CE	Failed to create directory	1. Reboot ATM 2. Reinstall software 3. Replace hard disk drive
9719000	1800CE, 2700CE, 5000CE, 5300CE	Failed to execute an extra command in the status of Cash Unit Exchange	1. Reboot ATM 2. Reinstall software 3. Replace hard disk drive
9719100	1800CE, 2700CE, 5000CE, 5300CE	In case of not being the status of Cash Unit Exchange out of End Exchange	1. Reboot ATM 2. Reinstall software 3. Replace hard disk drive
9719200	1800CE, 2700CE, 5000CE, 5300CE	In case of carrying out Cash In Start command at two times	1. Reboot ATM 2. Reinstall software 3. Replace hard disk drive
9719300	1800CE, 2700CE, 5000CE, 5300CE	In case of not being the status of Cash In out of End Cash In	1. Reboot ATM 2. Reinstall software 3. Replace hard disk drive
9719400	1800CE, 2700CE, 5000CE, 5300CE	Invalid Cash Unit ID	Reconfigure cash dispenser setup data
9719500	1800CE, 2700CE, 5000CE, 5300CE	Invalid Cash Unit number	Reconfigure cash dispenser setup data
9719600	1800CE, 2700CE, 5000CE, 5300CE	The abnormal of the number of Cash Unit	Reconfigure cash dispenser setup data
9719700	1800CE, 2700CE, 5000CE, 5300CE	No. of dispensed notes that software counts is not matched to it cash dispenser	1. Initialize after resetting the power 2. Upgrade the Cash Dispenser firmware or download software again 3. Replace the Cash Dispenser
9720000	1800CE, 2700CE, 5000CE, 5300CE	Receipt printer communication error during SP opening	Check if communication cable or COM port is not connected
9721111	1800CE, 2700CE, 5000CE, 5300CE	Off line status	1. Check communication cable connected properly 2. Check power cable connected properly
9721121	1800CE, 2700CE, 5000CE, 5300CE	Mechanics Error	1. Recover printers mechanical error 2. Reboot ATM
9721122	1800CE, 2700CE, 5000CE, 5300CE	Recoverable Error	1. Recover printer errors 2. Reboot ATM
9721123	1800CE, 2700CE, 5000CE, 5300CE	Unrecoverable Error	1. Reboot ATM
9721124	1800CE, 2700CE, 5000CE, 5300CE	Paper jammed	1. Remove jammed paper
9722010	1800CE, 2700CE, 5000CE, 5300CE	Receipt Printer communication failure during COM port open	1. Do RESET at Operator Function 2. Reboot ATM
9722020	1800CE, 2700CE, 5000CE, 5300CE	File Open Error	1. Reboot ATM 2. Call your attendant
9722060	1800CE, 2700CE, 5000CE, 5300CE	Memory Allocate Error	1. Reboot ATM 2. Call your attendant
9722068	1800CE, 2700CE, 5000CE, 5300CE	Invalid Media Name	

9723010	1800CE, 2700CE, 5000CE, 5300CE	Failed to open device	Check the serial port or cable
9723016	1800CE, 2700CE, 5000CE, 5300CE	Time out to receive data	Check the serial port or cable
9723019	1800CE, 2700CE, 5000CE, 5300CE	Polling down	Check the serial port or cable
9730100	1800CE, 2700CE, 5000CE, 5300CE	IC CARD DENIAL	N/A
9730200	1800CE, 2700CE, 5000CE, 5300CE	IC CARD ONLINE DATA ERROR	N/A
9730300	1800CE, 2700CE, 5000CE, 5300CE	IC CARD ERROR	N/A
9740000	1800CE, 2700CE, 5000CE, 5300CE	Cash Dispenser communication failure during COM port open	1. Do RESET at Operator Function 2. Reboot ATM
9740020	1800CE, 2700CE, 5000CE, 5300CE	Failed to create file	1. Reboot ATM 2. Call your attendant
9740025	1800CE, 2700CE, 5000CE, 5300CE	Failed to copy file	1. Reboot ATM 2. Call your attendant
9740101	1800CE, 2700CE, 5000CE, 5300CE	In case incorrect cassette type is set.	N/A
9740102	1800CE, 2700CE, 5000CE, 5300CE	In case nonexistent Note Index is set.	N/A
9741100	1800CE, 2700CE, 5000CE, 5300CE	When sensing CS2 Dark (Error code, 400FF00 is subdivided by location of sensor.)	N/A
9741400	1800CE, 2700CE, 5000CE, 5300CE	When sensing CS4A Dark (Error code, 400FF00 is subdivided by location of sensor.)	N/A
9741800	1800CE, 2700CE, 5000CE, 5300CE	When sensing CS4B Dark (Error code, 400FF00 is subdivided by location of sensor.)	N/A
9742100	1800CE, 2700CE, 5000CE, 5300CE	When sensing CS21A,B Dark (Error code, 400FF00 is subdivided by location of sensor.)	N/A
9742800	1800CE, 2700CE, 5000CE, 5300CE	When sensing CS13 Dark (Error code, 400FF00 is subdivided by location of sensor.)	N/A
9744700	1800CE, 2700CE, 5000CE, 5300CE	Cash picking-up fail while cash in cassette #1 is enough	1. Check bill jam or no note in cassette #1
9745500	1800CE, 2700CE, 5000CE, 5300CE	System power off while dispensing	1. Reboot ATM 2. Call your attendant
9799301	1800CE, 2700CE, 5000CE, 5300CE	MCU RETRACT OVER	Clear the count of retracted card at OP mode
9799499	1800CE, 2700CE, 5000CE, 5300CE	DISPENSER COUNT ERROR	Check the sensor on cash dispenser
9799901	1800CE, 2700CE, 5000CE, 5300CE	DOOR CHECK	1. Reboot ATM 2. Call your attendant

9799902	1800CE, 2700CE, 5000CE, 5300CE	LIGHT ERROR	1. Reboot ATM 2. Call your attendant
9799903	1800CE, 2700CE, 5000CE, 5300CE	SPL ERROR	1. Reboot ATM 2. Call your attendant
9799904	1800CE, 2700CE, 5000CE, 5300CE	PIN ERROR	1. Reboot ATM 2. Call your attendant
9799905	1800CE, 2700CE, 5000CE, 5300CE	SENSOR CHECK	1. Reboot ATM 2. Call your attendant
9799907	1800CE, 2700CE, 5000CE, 5300CE	UPS ERROR	1. Reboot ATM 2. Call your attendant
9799908	1800CE, 2700CE, 5000CE, 5300CE	SCREEN ERROR	1. Reboot ATM 2. Call your attendant
2010A00	1800CE, 2700CE, 5000CE, 5300CE	The size of image print data is abnormal	Check the AP version and initialize
2080A00	1800CE, 2700CE, 5000CE, 5300CE	The size of image print data is abnormal	Check the AP version and initialize
21A15	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CDU detects bills prior to dispensing	This means that while the ATM was initializing it detected a blocked sensor in the cash dispenser (CS1A sensor). Remove any jammed bills from the dispenser, if no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Check and reseat all belts. Loose belts can slip off rollers and block sensors.
21A1500	1800CE, 2700CE, 5000CE, 5300CE	CS1A sensor detects note in delivery path before CDU dispenses. Sensor is located along the delivery path right after where the note exits the 1st cassette.	Remove note from the CDU delivery path.
21B15	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CDU detects bills prior to dispensing	This means that while the ATM was initializing it detected a blocked sensor in the cash dispenser (CS1B sensor). Remove any jammed bills from the dispenser, if no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Check and reseat all belts. Loose belts can slip off rollers and block sensors.
21B1500	1800CE, 2700CE, 5000CE, 5300CE	CSB sensor detects note in delivery path before CDU dispenses. Sensor is located along the delivery path right after where the note exits the 1st cassette.	Remove note from the CDU delivery path.
24A15	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CDU detects bills prior to dispensing	This means that while the ATM was initializing it detected a blocked sensor in the cash dispenser (CS4A sensor). Remove any jammed bills from the dispenser, if no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Check and reseat all

			belts. Loose belts can slip off rollers and block sensors.
24A1500	1800CE, 2700CE, 5000CE, 5300CE	CS3A sensor detects note in delivery path before CDU dispenses. Sensor is located along the delivery path right after where the note exits the 3rd cassette.	Remove note from the CDU delivery path.
24B15	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CDU detects bills prior to dispensing	This means that while the ATM was initializing it detected a blocked sensor in the cash dispenser (CS4B sensor). Remove any jammed bills from the dispenser, if no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Check and reseat all belts. Loose belts can slip off rollers and block sensors.
24B1500	1800CE, 2700CE, 5000CE, 5300CE	CS3B sensor detects note in delivery path before CDU dispenses. Sensor is located along the delivery path right after where the note exits the 3rd cassette.	Remove note from the CDU delivery path.
4001C00	1800CE, 2700CE, 5000CE, 5300CE	CS4A or CS4B sensor detects note in delivery path before/after CDU dispenses	1. Remove note from the CDU delivery path.2. Clean CS4A and CS4B
4001D00	1800CE, 2700CE, 5000CE, 5300CE	CS2, CS4A or CS4B sensor detects note in delivery path before/after CDU dispenses	1. Remove note from the CDU delivery path.2. Clean CS2, CS4A and CS4B
4002A00	1800CE, 2700CE, 5000CE, 5300CE	CS1B or CS13 sensor detects note in delivery path before/after CDU dispenses	1. Remove note from the CDU delivery path.2. Clean CS1B and CS13
4002B00	1800CE, 2700CE, 5000CE, 5300CE	CS1A, CS1B or CS13 sensor detects note in delivery path before/after CDU dispenses	1. Remove note from the CDU delivery path.2. Clean CS1A, CS1B and CS13
4003A00	1800CE, 2700CE, 5000CE, 5300CE	When more than 5 sheets of cash dispensing is required during a test	1. Check command that Cash Dispenser is received 2. Check Cash Dispenser EP ROM Version or specification
4003B00	1800CE, 2700CE, 5000CE, 5300CE	When CS15A or CS 15B sensor is detected as dark after initial recovery	1. Remove notes or dust on CS15A Sensor 2. Check CS15A Sensor Cable 3. Exchange Sensor after abnormal operating
4004A00	1800CE, 2700CE, 5000CE, 5300CE	Error of note jam (Separated rejection)	1. Remove jammed notes on Cash Dispenser return path 2. Remove dust in CS1~CS4 sensor 3. Install after rearranging notes in cassette
4004B00	1800CE, 2700CE, 5000CE, 5300CE	Continuous 3 times error if note is long (once tried, twice retried)=>Separated rejection	1. Check state of notes in reject box 2. Rearrange notes in cassette 3. Check Index of notes 4. Check foreign objects in the main motor encoder slit 5. Replace the CS8 encoder slit sensor
4004C00	1800CE, 2700CE, 5000CE, 5300CE	In case the number of notes detected outlet sensor(CS13) is	1. Check CS1 sensor 2. Reconnect CS1 sensor

		more than that of notes detected on CS1A,B sensor	
4004D00	1800CE, 2700CE, 5000CE, 5300CE	Error of being removed 1st cassette before separate rejection	1. Set cassette #1 correctly 2. Check the catcher inside cassette #1 guide
4005B00	1800CE, 2700CE, 5000CE, 5300CE	2 Cassette Miss Feed Error (Fail to reject bill separately.)	N/A
4005D00	1800CE, 2700CE, 5000CE, 5300CE	Continuously detected 2 notes for three times or more during dispense operation	1. Check notes status in the reject box 2. Realign notes in the cassette 3. Check foreign objects at the position of the CS5 4. Check if the CS5 cable is disconnected (CS5_1:Cash Dispenser B/D CN10 #11~12, 25~28/ CS5_2:CN12)
4006A00	1800CE, 2700CE, 5000CE, 5300CE	CS15AB ~ CS13 Time out(Jam) during dispensing bills from second cassette.	N/A
4006B00	1800CE, 2700CE, 5000CE, 5300CE	Something is detected on CS31A, CS31B sensor during initialization	N/A
4007A00	1800CE, 2700CE, 5000CE, 5300CE	CS31AB ~ CS13 Time out (Jam) during dispensing bills from fourth cassette.	N/A
4007B00	1800CE, 2700CE, 5000CE, 5300CE	Something is detected on CS41A, CS41B sensor in initialization	N/A
4007C00	1800CE, 2700CE, 5000CE, 5300CE	Missfeed error in 4th cassette	N/A
4007D00	1800CE, 2700CE, 5000CE, 5300CE	Trying to dispense bills from 4th cassette but the 4th cassette doesn't installed.	N/A
4008F00	1800CE, 2700CE, 5000CE, 5300CE	CS13 sensor detects a bill with hole during dispensing	N/A
4009A00	1800CE, 2700CE, 5000CE, 5300CE	CS31AB~CS13 Time out(Jam) during dispensing from 3rd cassette.	N/A
4009D00	1800CE, 2700CE, 5000CE, 5300CE	Trying to dispense bills from 3rd cassette but the 3rd cassette doesn't installed.	N/A
4009F00	1800CE, 2700CE, 5000CE, 5300CE	3 cassette miss feed error	N/A
400AC00	1800CE, 2700CE, 5000CE, 5300CE	Something is detected on CS2 sensor after dispense operation	N/A
400BC00	1800CE, 2700CE, 5000CE, 5300CE	Communication error - Command Length doesn't match.	N/A
400BE00	1800CE, 2700CE, 5000CE, 5300CE	Bill pickup sensor(CS1, CS15) recognized has a hole and CS4 sensor detects it or CS4 sensor detects the gap too close	N/A
400C700	1800CE, 2700CE, 5000CE, 5300CE	Something is detected on CS12 sensor during dispensing bills or initialization.-MB TTW	N/A

400C800	1800CE, 2700CE, 5000CE, 5300CE	Something is detected on CS14 sensor during dispensing bills or initialization.-MB TTW	N/A
400C900	1800CE, 2700CE, 5000CE, 5300CE	Something is detected on CS14 sensor after dispense operation	N/A
400CC00	1800CE, 2700CE, 5000CE, 5300CE	Bill is remained on the sensor in front of cassette during resetting.	N/A
400D000	1800CE, 2700CE, 5000CE, 5300CE	Bills are passed on CS13~CS12 sensor - Timeout[Jam], MB TTW	N/A
400D100	1800CE, 2700CE, 5000CE, 5300CE	Bills are passed on CS12~CS14 sensor - Timeout[Jam], MB TTW	N/A
400FF00	1800CE, 2700CE, 5000CE, 5300CE	Bill jam	1. Remove the jammed notes 2. Initialize
4DN0000	1800CE, 2700CE, 5000CE, 5300CE	Cash Dispenser communication failure during sending command to cash dispenser	1. Do RESET at Operator Function 2. Reboot ATM
4DN0100	1800CE, 2700CE, 5000CE, 5300CE	Cash Dispenser communication failure during receiving command to cash dispenser	1. Do RESET at Operator Function 2. Reboot ATM
4DN8100	1800CE, 2700CE, 5000CE, 5300CE	Communication error of Shutter	N/A
971A000	1800CE, 2700CE, 5000CE, 5300CE	Invalid Denomination	B/D Reconfigure denomination at supervisor mode
971A100	1800CE, 2700CE, 5000CE, 5300CE	Invalid Currency	1. Reconfigure currency at supervisor mode
971A200	1800CE, 2700CE, 5000CE, 5300CE	CASSETTE OFF POSITION?. Not dispensable	1. Reconfigure denomination 2. Reconfigure currency
971A300	1800CE, 2700CE, 5000CE, 5300CE	In case the number of bills dispensed exceeds the maximum dispensing bill	1. Check cash dispenser driver (CDM SP) version 2. Reconfigure the maximum dispensable count
971A400	1800CE, 2700CE, 5000CE, 5300CE	In case the number of coins dispensed exceeds the maximum dispensing coin	1. Check coin dispenser driver version 2.Reconfigure the maximum dispensable count
971A500	1800CE, 2700CE, 5000CE, 5300CE	Invalid mix number	1. Reconfigure cash dispenser at supervisor mode
971A600	1800CE, 2700CE, 5000CE, 5300CE	In case automatic Retry of SP fails 3 times	Set Denomination
971A700	1800CE, 2700CE, 5000CE, 5300CE	There is no setting information about automatic Retry standard	N/A
971B000	1800CE, 2700CE, 5000CE, 5300CE	In case of being executed Reject or Retract command without being the bills in stacker.	1. Check a dust in stacker 2. Reconfigure the maximum dispensable count
971C000	1800CE, 2700CE, 5000CE, 5300CE	Not supported command	Reinstall software
971D100	1800CE, 2700CE, 5000CE, 5300CE	Partial dispense	1. Check the replenished amount and replenish 2. Check the notes in cassette #1

971D200	1800CE, 2700CE, 5000CE, 5300CE	Partial dispense from cassette #2	1. Check the replenished amount and replenish 2. Check the notes in cassette #2
971D300	1800CE, 2700CE, 5000CE, 5300CE	Partial dispense from cassette #3	1. Check the replenished amount and replenish 2. Check the notes in cassette #3
971DX00	1800CE, 2700CE, 5000CE, 5300CE	In case partial bills dispensed by dispensing demand when Partial Dispense option is on. ?X? means cassette number.	N/A
97221A2	1800CE, 2700CE, 5000CE, 5300CE	Invalid Unit	
97221C1	1800CE, 2700CE, 5000CE, 5300CE	Form is not Found	1. Reboot ATM 2. Call your attendant
97221C4	1800CE, 2700CE, 5000CE, 5300CE	Form Name is NULL	1. Reboot ATM 2. Call your attendant
97221C5	1800CE, 2700CE, 5000CE, 5300CE	Invalid Form	1. Reboot ATM 2. Call your attendant
97221C6	1800CE, 2700CE, 5000CE, 5300CE	PrintForm() offset is Invalid	1. Reboot ATM 2. Call your attendant
97221C7	1800CE, 2700CE, 5000CE, 5300CE	Invalid Form (Too many Fields in the form)	1. Reboot ATM 2. Call your attendant
97221D1	1800CE, 2700CE, 5000CE, 5300CE	Media is not Found	1. Reboot ATM 2. Call your attendant
97221D3	1800CE, 2700CE, 5000CE, 5300CE	Media Overflow when form size is larger than media size	1. Reboot ATM 2. Call your attendant
97221D4	1800CE, 2700CE, 5000CE, 5300CE	Media Name is NULL	1. Reboot ATM 2. Call your attendant
97221D5	1800CE, 2700CE, 5000CE, 5300CE	Invalid Media (Attribute for Media definition is not proper)	1. Reboot ATM 2. Call your attendant
97221D6	1800CE, 2700CE, 5000CE, 5300CE	Invalid Media (Area size is larger than media size)	1. Reboot ATM 2. Call your attendant
97221D7	1800CE, 2700CE, 5000CE, 5300CE	Invalid Media (Size of Media Name is exceeded to 2048 bytes totally)	1. Reboot ATM 2. Call your attendant
9722DN0	1800CE, 2700CE, 5000CE, 5300CE	Receipt Printer communication failure during sending command to Receipt Printer	1. Do RESET at Operator Function 2. Reboot ATM
9743B00	1800CE, 2700CE, 5000CE, 5300CE	When sensing CS15A,B Dark (Error code, 400FF00 is subdivided by location of sensor.)	N/A
9745B00	1800CE, 2700CE, 5000CE, 5300CE	Cash picking-up fail while cash in cassette #2 is enough	1. Check bill jam or no note in cassette #2 2. Check cash dispenser
9746B00	1800CE, 2700CE, 5000CE, 5300CE	When sensing CS31A,B Dark (Error code, 400FF00 is subdivided by location of sensor.)	N/A
9747B00	1800CE, 2700CE, 5000CE, 5300CE	When sensing CS41A, B Dark (Error code, 400FF00 is subdivided by location of sensor.)	N/A

9747C00	1800CE, 2700CE, 5000CE, 5300CE	Cash picking-up fail while cash in cassette #4 is enough	1. Check bill jam or no note in cassette #2 2. Check cash dispenser
9749F00	1800CE, 2700CE, 5000CE, 5300CE	Cash picking-up fail while cash in cassette #3 is enough	1. Check bill jam or no note in cassette #2 2. Check cash dispenser
974FF00	1800CE, 2700CE, 5000CE, 5300CE	When sensing bills in the Stacker (Error code, 400FF00 is subdivided by location of sensor.)	N/A
97911XX	1800CE, 2700CE, 5000CE, 5300CE	DEV_JPR Timeover Error Code	1. Reboot ATM 2. Call your attendant
97912XX	1800CE, 2700CE, 5000CE, 5300CE	DEV_SPR Time Over Error	1. Reboot ATM 2. Call your attendant
97913XX	1800CE, 2700CE, 5000CE, 5300CE	DEV_MCU Timeover Error Code	1. Reboot ATM 2. Call your attendant
97914XX	1800CE, 2700CE, 5000CE, 5300CE	DEV_Cash Dispenser Timeover Error Code	1. Reboot ATM 2. Call your attendant
97915XX	1800CE, 2700CE, 5000CE, 5300CE	DEV_BRM Timeover Error Code	1. Reboot ATM 2. Call your attendant
97916XX	1800CE, 2700CE, 5000CE, 5300CE	DEV_PBM Timeover Error Code	1. Reboot ATM 2. Call your attendant
97918XX	1800CE, 2700CE, 5000CE, 5300CE	DEV_PIN Timeover Error Code	1. Reboot ATM 2. Call your attendant
9791AXX	1800CE, 2700CE, 5000CE, 5300CE	DEV_FNG Timeover Error Code	1. Reboot ATM 2. Call your attendant
9791BXX	1800CE, 2700CE, 5000CE, 5300CE	DEV_VFD Timeover Error Code	1. Reboot ATM 2. Call your attendant
97921XX	1800CE, 2700CE, 5000CE, 5300CE	DEV_JPR FATALERROR (WARNING)	1. Reboot ATM 2. Call your attendant
97922XX	1800CE, 2700CE, 5000CE, 5300CE	DEV_SPR FATALERROR (WARNING)	1. Reboot ATM 2. Call your attendant
97923XX	1800CE, 2700CE, 5000CE, 5300CE	DEV_MCU FATALERROR (WARNING)	1. Reboot ATM 2. Call your attendant
97924XX	1800CE, 2700CE, 5000CE, 5300CE	DEV_Cash Dispenser FATAL ERROR (WARNING)	1. Reboot ATM 2. Call your attendant
97925XX	1800CE, 2700CE, 5000CE, 5300CE	DEV_BRM FATALERROR (WARNING)	1. Reboot ATM 2. Call your attendant
97926XX	1800CE, 2700CE, 5000CE, 5300CE	DEV_PBM FATALERROR (WARNING)	1. Reboot ATM 2. Call your attendant
97928XX	1800CE, 2700CE, 5000CE, 5300CE	DEV_PIN FATALERROR (WARNING)	1. Reboot ATM 2. Call your attendant
9792AXX	1800CE, 2700CE, 5000CE, 5300CE	DEV_FNG FATALERROR (WARNING)	1. Reboot ATM 2. Call your attendant
9792BXX	1800CE, 2700CE, 5000CE, 5300CE	DEV_VFD FATALERROR (WARNING)	1. Reboot ATM 2. Call your attendant
991@@91	1800CE, 2700CE, 5000CE, 5300CE	ON TRANSACTION POWER OFF	1. Check power supply 2. Check backup battery

A0008	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Receipt paper cutter error	Remove any jammed paper. You may need to remove the printer to clear jams. NOTE: Do not use metal objects to clear the jam. Use a business card or stiff paper to clear jams. Otherwise try the reset button or have the printer serviced.
A010100	1800CE, 2700CE, 5000CE, 5300CE	Detecting the lever opened before executing command	Close the feed lever.
A010200	1800CE, 2700CE, 5000CE, 5300CE	Printer thermal head overheated while executing command	Check the thermal printer head and change if necessary.
A010300	1800CE, 2700CE, 5000CE, 5300CE	Paper jam detected before executing command	Remove any jammed paper from the printer.
A010400	1800CE, 2700CE, 5000CE, 5300CE	Paper setting error detected before executing command	Remove and re-install the receipt paper.
A010500	1800CE, 2700CE, 5000CE, 5300CE	Paper check error detected before executing command	Remove and re-install the receipt paper.
A010800	1800CE, 2700CE, 5000CE, 5300CE	Paper cutter software check error detected before executing command	Check for and remove any jammed paper.
A080100	1800CE, 2700CE, 5000CE, 5300CE	Open lever detected while executing command	Remove any jammed paper.
A080200	1800CE, 2700CE, 5000CE, 5300CE	Receipt printer head overheated while printing	Check the thermal printer head and change if necessary.
A080300	1800CE, 2700CE, 5000CE, 5300CE	Paper jam detected while executing command	Remove and re-install the receipt paper.
A080400	1800CE, 2700CE, 5000CE, 5300CE	Paper setting error detected before executing command	Remove and re-install the receipt paper.
A080500	1800CE, 2700CE, 5000CE, 5300CE	Paper check error in doing command	Remove any jammed paper.
A080800	1800CE, 2700CE, 5000CE, 5300CE	Paper cutter software check error detected while executing command	Check for and remove any jammed paper.
ADN0100	1800CE, 2700CE, 5000CE, 5300CE	No response detected for 30 seconds after sending command	Check cable and connection between the CE and printer.
ADN04	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Printer connection error	Check cables between Printer and Mainboard, remove cables (even though they may be attached) and re-connect. Use an electrical parts contact cleaner to clean the terminals. Try the reset button on the printer. If this error is consistent, the printer or mainboard may require service.
ADN0F	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Printer connection error	Check cables between Printer and Mainboard, remove cables (even though they may be attached) and re-connect. Use an electrical parts contact cleaner to clean the terminals. Try the reset button on the printer. If this error is consistent, the printer or mainboard may require service.

ADN0F00	1800CE, 2700CE, 5000CE, 5300CE	No response detected for 30 seconds after sending command sending command	Check cable and connection between the CE and printer.
ADN1100	1800CE, 2700CE, 5000CE, 5300CE	No response detected after 3 retries	Check cable and connection between the CE and printer.
ADN1200	1800CE, 2700CE, 5000CE, 5300CE	No response detected between ENQ-ACK after 5 retries of ENQ	Check cable and connection between the CE and printer.
ADN1300	1800CE, 2700CE, 5000CE, 5300CE	No response detected after 5 retries because of timeout between STX-BCC interval	Check cable and connection between the CE and printer.
ADNxx	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Printer connection error	Check cables between Printer and Mainboard, remove cables (even though they may be attached) and re-connect. Use an electrical parts contact cleaner to clean the terminals. Try the reset button on the printer. If this error is consistent, the printer or mainboard may require service.
Axxx2	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Thermal printer is overheated - during operation	If this error occurs during the printing of a long journal, then allow the printer to cool and try again. You may also want to try the reset button on the printer to clear this error. If this error persists, the printer will require service.
Axxx3	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Receipt Paper Jam	Remove jammed paper - Release receipt paper drawer by pressing the tab with the green sticker located at the front of the printer. You may need to remove the printer from the ATM to access the jam. NOTE: Do NOT use metal objects to clear jams, use a business card or stiff paper to poke around.
Axxx4	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Receipt paper is empty	Replenish the paper roll. If roll is ok, then try the reset button on the printer. Otherwise the printer needs service.
Axxx5	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Receipt paper is jamming during loading	Remove any jammed paper and then reload. You may need to remove the printer to clear jams. NOTE: Do not use metal objects to clear the jam. Use a business card or stiff paper to clear jams. Otherwise try the reset button or have the printer serviced.
C0011	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CDU sensor is tripped	This indicates that during a dispense, the sensor located at the front of the CDU shows a blockage (CS13 or CS2). The primary reason for this is a bill which bounces back from the cash tray (sometimes from a customers fingers). Check the front of the CDU and the cash tray for blockage. Reinitialize the ATM to put back in service. In

			the case of a dispute from the error, use CDU data in the journal to verify how many notes were actually dispensed.
C0014	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CDU sensor is tripped	Similar to the COO11 error, this would indicate a bill jam close to the exit of the CDU or near the reject bin. Check for jammed notes or blocked sensors.
C001x	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CDU sensor is tripped	Most typically a COO11 error, this would indicate a bill jam at the exit sensor of the Cash Dispenser. Usually caused by a customer putting fingers in the cash drawer during dispense. Other than upgrading the cash tray or using a sign to warn customers, you can loosen the screws that hold the dispenser and slide it back.
C0028	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CDU sensor is tripped	Check dispenser for jammed bills and restart the machine. If no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Otherwise the dispenser may require service
C002x	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CDU sensor is tripped	Check dispenser for jammed bills and restart the machine. If no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Otherwise the dispenser may require service
C0030	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CDU motor failure	Motor speed (measured at the encoder wheel) was not within spec. Verify that CS8 or encoder wheel sensor is in place and wire connection is good. Can indicate a bad motor or encoder sensor.
C0031	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CDU Gate solenoid error	The CDU did not respond to its solenoid function check. Check the wiring connections to the solenoid(s). Check wiring connections to the CDU main board.
C0032	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Outlet solenoid error	Check and verify all connections to the dispenser circuit board. Check wiring to the solenoid(s).

C0033	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CDU Encoder error	Usually caused by loss of battery power to the CDU mainboard. The only way to recover from this error is to reprogram the CDU data. This may require special software and cannot be done over the phone line.
C0034	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Double Note detect module failure	Double detect module reporting error, check wiring to the module.
C0035	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Double Note detect module failure (2)	Double detect module reporting error, check wiring to the module.
C0036	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Detected notes in path before initializing	One or more sensors in the dispenser detected a blockage prior to initializing. Check for notes in the Cash Dispenser. If no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Otherwise the dispenser may require service.
C0037	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Sensor(NS7) for detecting Double is covered during dispensing note	None
C0039	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Gate sensor open during initializing	Check the sensor that is activated when you close the reject bin door (2k/4k dispensers only). If the sensor is not being pressed then the error will occur. Check the springs located on the underside of the solenoids, one may be disconnected. Otherwise the CDU will require repair / replacement.
C003B	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Notes detected during installation	Check for notes in the Cash Dispenser. If no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Otherwise the dispenser may require service.
C0040	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000,	Cassette removed during dispense	Reset the cassette, check position of microswitch on right rear wall of cassette bay in the dispenser. Check the condition of the white

	MB1500, MB1800, MB2000, MB2100, T4000		plastic cassette retaining clips in the dispenser.
C0041	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Tried to dispense notes more than 5 times	Check the condition of the cash in the cassette. Verify that the cash is of good quality. The CDU belts or the Cassette rollers may need to be cleaned (rubbing alcohol). Check that the denomination in Transaction setup matches the actual denomination loaded.
C0042	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Note jam	Check for notes in the Cash Dispenser. If no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Otherwise the dispenser may require service
C0043	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	More than 10 notes rejected during one transaction	Verify the quality of the cash. Straighten and shuffle cash in the cassette. Check the reject analysis to determine the cause of reject (reports menu). If the cash is of known good quality then try cleaning the cassette and dispenser. Otherwise service to cassette or dispenser may be required.
C0044	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	More than 5 notes rejected consecutively	Verify the quality of the cash. Straighten and shuffle cash in the cassette. Check the reject analysis to determine the cause of reject (reports menu). If the cash is of known good quality then try cleaning the cassette and dispenser. Otherwise service to cassette or dispenser may be required.
C0045	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Notes Overdispensed	Check NS4 Sensor
C0046	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CDU Hardware Failure	Error reported during CDU initialization. Check cabling and potential blockages and power cycle ATM.
C0047	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Feed error	This error occurs when the dispenser attempts to pull a bill from the cassette and is unsucessfull before the dispenser times out. Depending on the model of dispenser there are different causes and possible solutions. It can be as simple as the cassette being empty, rollers need cleaning to a firmware upgrade to the CDU.

C0048	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Incorrect bill count	Verify cash count in the Settlement menu.
C004A	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Jammed notes	Check for notes in the Cash Dispenser. If no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Otherwise the dispenser may require service
C004B	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Long note detected 3 times consecutively	Verify the quality of the cash. Straighten and shuffle cash in the cassette. Try cleaning the cassette and dispenser. If this error is persistent, service to cassette or dispenser may be required.
C004C	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Miscount of notes between sensors	Verify operation of exit gate. Check the number of dispensed notes. Clean the dispenser and test using diagnostics. Dispenser may require service.
C004D	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Cash cassette not properly set	Reset the cassette, check position of microswitch on right rear wall of cassette bay in the dispenser. Check the condition of the white plastic cassette retaining clips in the dispenser. MB1000 check condition of the clutch alignment screw.
C004E	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Miscount of notes between sensors	Test CDU using diagnostics, use journal to verify amount of dispensed notes versus requested notes. Clean dispenser and cassette. If error is persistent the dispenser may require service.
C004F	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Miscount of notes between sensors	Test CDU using diagnostics, use journal to verify amount of dispensed notes versus requested notes. Clean dispenser and cassette. If error is persistent the dispenser may require service.
C0050	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000,	Power failure during dispense	Remove any notes from path. Before reinitializing the ATM, first the verify amount of dispensed notes in the cassette against the journal.

	MB1500, MB1800, MB2000, MB2100, T4000		
C0051	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Over 150 notes requested	Possibly due to too many rejects, may require repair or cleaning if consistent. Check the Reject Analysis, this may help determine the cause. Cash quality, condition of the rollers in the cassette can effect this condition.
C0052	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Detected notes in path after dispense	Remove any notes from path, verify amount of dispensed notes. Clean dispenser. Verify the amount of bills against the journal.
C0053	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CDU double detect module failure.	Double detect module may require adjustment. Check wiring and CDU mainboard connections.
C0055	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Detected long notes at outlet sensor	(See definition of C0011 error) this is typically a bounce back of a bill during dispense causing the exit sensor to remain blocked for a longer time than is expected.
C0056	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Exit gate sensor failure	Check condition of exit gate, and the exit gate sensor.
C0057	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Cassette information is not properly set	CDU programming is not accurate or complete.
C0059	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Cash cassette 2 removed prior to dispense.	Set the cash cassette. Inspect the cassette detection microswitch. Reposition the microswitch if necessary.

C005A	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Cash cassette 1 removed prior to dispense	Set the cash cassette. Inspect the cassette detection microswitch. Reposition the microswitch if necessary.
C005B	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Cash cassette 2 misfeed	Check cassette for jams, check condition of bills in cassette.
C005D	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Double detect constantly	Inspect double detect module and adjust as necessary. Check and clean the cassette and rollers, verify the quality of cash.
C005E	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Dispense command size check error	Re-initialize machine, verify connections to mainboard. Check for unplugged sensors.
C005F	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Dispense command error	Re-initialize machine, verify connections, check for unplugged sensors.
C006x	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Sensor failure	Check for notes in the Cash Dispenser. If no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Otherwise the dispenser may require service
C007x	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Sensor failure	Check for notes in the Cash Dispenser. If no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Otherwise the dispenser may require service
C0082	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000,	Shutter failure	Check all wiring connections to CDU mainboard. Reinitialize CDU

	MB1500, MB1800, MB2000, MB2100, T4000		
C0083	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Stacker sensor failure	Check all wiring connections to CDU mainboard. Reinitialize CDU
C0084	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Shutter close error	Check all wiring connections to CDU mainboard. Reinitialize CDU.
C009F	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	3Cassette misfeed error	Check if notes available in cassette
C00AB	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Notes detected before initalizing	Clear notes from dispenser. Possibly dust or foreign object blocking sensor.
C00C7	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CS12 Sensor blocked	MB2100T - The CS12 sensor, which is located at the upper part of the cash tray was blocked while the machine was either dispensing or initializing. Clear the cash tray of any bills or foreign objects. If the error persists, the vault assembly may need to be removed to inspect / access the cash tray sensors.
C00C8	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CS14 Sensor blocked	MB2100T - The CS14 sensor, which is located close to front of the cash tray, was blocked while the machine was either dispensing or initializing. Clear the cash tray of any bills or foreign objects. If the error persists, the vault assembly may need to be removed to inspect / access the cash tray sensors.
C00C9	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CS12 & CS14 Sensors blocked	MB2100T - Both the CS12 and CS14 sensors were blocked while the machine was either dispensing or initializing. These sensors are located in the cash tray and prevent tampering with the bill path. Clear the cash tray of any bills or foreign objects. If the error persists, the vault assembly may need to be removed to inspect / access the cash tray sensors.

C00D0	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Sensor block while dispensing	MB2100T - A blockage was detected between the CS13 (CDU exit gate) and CS12 cash tray sensors. There may be a note stuck in the upper part of the cash tray ramp. Try clearing the cash tray of notes or foreign objects. Open the vault and slide the dispenser back to access the exit gate area. Both sensors must be blocked for this error to occur.
C00D1	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Sensor blocked while dispensing	MB2100T - A blockage was detected between the CS12 (upper cash tray sensor) and CS14 (lower cash tray sensor). There may be a note stuck in the cash tray ramp. Try clearing the cash tray of notes or foreign objects. Open the vault and slide the dispenser back to access the exit gate area. Both sensors must be blocked for this error to occur.
C00E0	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	NS2A, NS2B dark	Nanocash only - verify connections to sensors. Check wiring to mainboard.
C00E1	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	NS4 dark	Verify connections to NS4 sensor. Check all wiring to mainboard.
C00FF	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Sensor blocked	None
CDN01	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	No Response after send command	None
CDN04	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, MB2500, T4000	CDU Connection Failure	Check cables between CDU and Mainboard, remove cables (even though they may be attached) and re-connect. Use an electrical parts contact cleaner on terminals. This error is of concern only if it is repeated. Outside interference may cause it (neon signs, lights).
CDN05	1700, 1700W, 2100T, C4000,	CDU connection failure	Check cables between CDU and Mainboard, remove cables (even though they may be attached) and

	G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000		re-connect. Use an electrical parts contact cleaner on terminals. This error is of concern only if it is repeated. Outside interference may cause it (neon signs, lights).
CDN0F	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CDU connection failure	Check cables between CDU and Mainboard, remove cables (even though they may be attached) and re-connect. Use an electrical parts contact cleaner on terminals. This error is of concern only if it is repeated. Outside interference may cause it (neon signs, lights).
CDN11	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	No Response after 3 retry of command	None
CDN12	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	No Response between ENQ-ACK after 5 retry of ENQ	None
CDN13	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	No Response after 5 retry because of timeout between STX-BCC interval	None
CDNxx	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CDU connection failure	Check cables between CDU and Mainboard, remove cables (even though they may be attached) and re-connect. Use an electrical parts contact cleaner on terminals. This error is of concern only if it is repeated. Outside interference may cause it (neon signs, lights).
D0001	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Modem initialization error	Check modem in diagnostics or modem test. If persistent, it could be a defective modem. Note: If the modem is defective, this error will most likely occur frequently. One or two instances of this error does not usually indicate a defective part.
D000100	1800CE, 2700CE, 5000CE, 5300CE	Error while modem initializing	Check the modem connection and the modem test.
D0002	1700, 1700W, 2100T, C4000, G1900, G2500,	Reversal transaction failed.	The ATM attempted to do a reversal and could not. Check transaction with the processor. Verify CDU functionality with diagnostics. Verify phone

	GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000		connection. Look in error summary for D1800, D2000.
D000200	1800CE, 2700CE, 5000CE, 5300CE	Reversal transaction failure	Check for any CDU error codes and the number of notes dispensed to customer. Transaction was denied by host
D000300	1800CE, 2700CE, 5000CE, 5300CE	PIN ERROR	Transaction was denied by host
D000400	1800CE, 2700CE, 5000CE, 5300CE	INVALID PIN	Reboot ATM
D0005	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Undefined network processing error	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D000500	1800CE, 2700CE, 5000CE, 5300CE	BANK UNAVAILABLE	Transaction was denied by host
D000600	1800CE, 2700CE, 5000CE, 5300CE	CARD NOT SUPPORTED	Transaction was denied by host
D000700	1800CE, 2700CE, 5000CE, 5300CE	INSUFFICIENT FUNDS	Transaction was denied by host
D000800	1800CE, 2700CE, 5000CE, 5300CE	INELIGIBLE TRANSACTION	Transaction was denied by host
D000900	1800CE, 2700CE, 5000CE, 5300CE	INELIGIBLE ACCOUNT	Transaction was denied by host
D001000	1800CE, 2700CE, 5000CE, 5300CE	DAILY LIMIT EXCEEDED	Transaction was denied by host
D0011	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Format error in the message.	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D001100	1800CE, 2700CE, 5000CE, 5300CE	UNABLE TO PROCESS	Transaction was denied by host
D0012	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Invalid Transaction	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D001200	1800CE, 2700CE, 5000CE, 5300CE	Invalid transaction	Check the transaction from the host and try again.

D0013	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Invalid Amount	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D001300	1800CE, 2700CE, 5000CE, 5300CE	Invalid amount	Check the transaction from the host and try again.
D0014	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Invalid Card Number	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D001400	1800CE, 2700CE, 5000CE, 5300CE	Invalid card number	Check the transaction from the host and try again.
D001500	1800CE, 2700CE, 5000CE, 5300CE	UNABLE TO PROCESS	Transaction was denied by host
D001600	1800CE, 2700CE, 5000CE, 5300CE	WITHDRAWAL LIMIT ALREADY REACHED	Transaction was denied by host
D001700	1800CE, 2700CE, 5000CE, 5300CE	INVALID AMOUNT	Transaction was denied by host
D001800	1800CE, 2700CE, 5000CE, 5300CE	EXTERNAL DECLINE	Transaction was denied by host
D0019	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Reenter the entire transaction	Code reported by host processor (Shazam). Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D001900	1800CE, 2700CE, 5000CE, 5300CE	SYSTEM ERROR	Transaction was denied by host
D0020	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Surcharge screen should have been displayed	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D002000	1800CE, 2700CE, 5000CE, 5300CE	Surcharge screen should have been displayed	Check the transaction from the host and try again. Check BIN List
D002100	1800CE, 2700CE, 5000CE, 5300CE	ROUTING LOOKUP PROBLEM	Transaction was denied by host
D002200	1800CE, 2700CE, 5000CE, 5300CE	UNABLE TO PROCESS	Transaction was denied by host
D002300	1800CE, 2700CE, 5000CE, 5300CE	TRANSACTION NOT SUPPORTED	Transaction was denied by host

D0024	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Exceeds issuer withdrawal limit	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D002400	1800CE, 2700CE, 5000CE, 5300CE	Exceeds Issuer Withdrawal Limit	Check the transaction from the host and try again.
D0031	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Issuer financial institution is not supported by a processor	Code reported by host processor (Shazam). Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D0039	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	No credit account	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D003900	1800CE, 2700CE, 5000CE, 5300CE	No Credit Account	Check the transaction from the host and try again.
D0041	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	No credit account found for the CCN	Code reported by host processor (Shazam). Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D0043	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Stolen Card	Code reported by host processor (Shazam). Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D0050	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Transaction is not approved	Code reported by host processor (Shazam). Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D0051	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800,	Insufficient funds	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.

	MB2000, MB2100, T4000		
D005100	1800CE, 2700CE, 5000CE, 5300CE	Insufficient Funds	Check the transaction from the host and try again. Try Balance Inquiry
D0052	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	No checking account	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D005200	1800CE, 2700CE, 5000CE, 5300CE	No Checking Account	Check the transaction from the host and try again.
D0053	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	No savings account	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D005300	1800CE, 2700CE, 5000CE, 5300CE	No Savings Account	Check the transaction from the host and try again.
D0054	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Expired Card	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D005400	1800CE, 2700CE, 5000CE, 5300CE	Expire Card	Check the transaction from the host and try again.
D0055	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Invalid PIN	Code reported from host processor - Verify all programming. In the case of a new installation, if master keys are not bound properly, Terminal ID is not active or if programming is not correct for the host this can occur. If all programming appears correct, contact the processor and have them trace the Terminal ID.
D005500	1800CE, 2700CE, 5000CE, 5300CE	Incorrect Pin	Check the transaction from the host and try again.
D0056	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	No card record found	Code reported by host processor (Shazam). Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D0057	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000,	Transaction not permitted - card	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or

	MB1500, MB1800, MB2000, MB2100, T4000		you cannot complete a test transaction because of this error.
D005700	1800CE, 2700CE, 5000CE, 5300CE	Transaction not Permitted ? Card	Check the transaction from the host and try again.
D0058	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Transaction not permitted - Terminal	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D005800	1800CE, 2700CE, 5000CE, 5300CE	Transaction not Permitted ? Terminal	Check the transaction from the host and try again.
D0059	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Customer should contact his or her financial institution	Code reported by host processor (Shazam). Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D0060	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Allowable withdrawal limit is exceeded	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D0061	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Exceeded withdrawal limit	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D006100	1800CE, 2700CE, 5000CE, 5300CE	Exceeds Withdrawal Limit	Check the transaction from the host and try again.
D0065	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Exceeds withdrawal frequency limit	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D0067	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Capture card at the terminal (requires card be picked up at ATM only).	Code reported by host processor (Shazam). Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.

D0075	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Number of PIN tries exceeded	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D007500	1800CE, 2700CE, 5000CE, 5300CE	PIN Tries Exceeded	Check the transaction from the host and try again.
D0078	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	No Account	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D007800	1800CE, 2700CE, 5000CE, 5300CE	No Account	Check the transaction from the host and try again.
D0080	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Invalid Date	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D008000	1800CE, 2700CE, 5000CE, 5300CE	Invalid Date	Check the transaction from the host and try again.
D0081	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Time out: response not received in time allowed (SHAZAM switch-in-front (SIF) terminals).	Code reported by host processor (Shazam). Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D0082	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Cashback limit exceeded.	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D0083	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Cannot verify PIN	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D008300	1800CE, 2700CE, 5000CE, 5300CE	Can not Verify PIN	Check the transaction from the host and try again. Try different cards.

D0084	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Processor not available; acquirer processor unable to send message	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D0086	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Cannot verify PIN	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D008600	1800CE, 2700CE, 5000CE, 5300CE	Can not Verify PIN	Check the transaction from the host and try again. Try different cards.
D0090	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Cutoff complete for terminal; cannot process prior days business	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D0091	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Bank unavailable	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D009100	1800CE, 2700CE, 5000CE, 5300CE	Bank Unavailable	Check the transaction from the host and try again.
D0092	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	System unavailable	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
D009200	1800CE, 2700CE, 5000CE, 5300CE	System Unavailable	Check the transaction from the host and try again.
D0093	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Transaction serial number mismatch	Verify all programming, contact host processor
D009300	1800CE, 2700CE, 5000CE, 5300CE	Transaction Serial Number mismatch	Check the terminal setting from the host.

D0094	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Record format mismatch	Verify all programming, contact host processor
D009400	1800CE, 2700CE, 5000CE, 5300CE	Record format mismatch.	Check the terminal setting from the host.
D0095	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Routing ID mismatch	Verify Routing ID number - contact host processor
D009500	1800CE, 2700CE, 5000CE, 5300CE	Routing ID mismatch.	Check the terminal setting from the host.
D0096	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Terminal ID mismatch	Verify Terminal ID number - contact host processor
D009600	1800CE, 2700CE, 5000CE, 5300CE	Terminal ID mismatch.	Check the terminal setting from the host.
D0097	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Response type mismatch (reversal)	Verify all programming, contact host processor
D009700	1800CE, 2700CE, 5000CE, 5300CE	Response Type mismatch (Reversal)	Check the terminal setting from the host.
D0098	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Response type mismatch (day-close)	Verify all programming, contact host processor
D009800	1800CE, 2700CE, 5000CE, 5300CE	Response Type mismatch (Day Close)	Check the terminal setting from the host.
D0099	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800,	Response type mismatch (Configuration)	Verify all programming, contact host processor

	MB2000, MB2100, T4000		
D009900	1800CE, 2700CE, 5000CE, 5300CE	Response Type mismatch (Config.)	Check the terminal setting from the host.
D009A	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Response type mismatch (Withdrawal, Balance, Transfer)	Verify all programming, contact host processor
D009A00	1800CE, 2700CE, 5000CE, 5300CE	Response Type mismatch (Withdrawal/Balance/Transfer)	Check the terminal setting from the host.
D009B	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	STX omitted	Verify all programming, contact host processor
D009B00	1800CE, 2700CE, 5000CE, 5300CE	STX error	Check the terminal setting from the host.
D009C	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	ETX omitted	Verify all programming, contact host processor
D009C00	1800CE, 2700CE, 5000CE, 5300CE	ETX error	Check the terminal setting from the host.
D009D	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	FS omitted (after response code)	Verify that version of Mini-Bank Software matches host processor. Contact host processor
D009D00	1800CE, 2700CE, 5000CE, 5300CE	FS out (after response code)	Check the terminal setting from the host.
D009E	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	FS omitted (after retrieval reference number)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
D009E00	1800CE, 2700CE, 5000CE, 5300CE	FS out (after retrieval reference number)	Check the terminal setting from the host.

D009F	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	FS omitted (after system trace audit number)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
D009F00	1800CE, 2700CE, 5000CE, 5300CE	FS out (after system trace audit number)	Check the terminal setting from the host.
D00A0	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	FS omitted (after account balance)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
D00A000	1800CE, 2700CE, 5000CE, 5300CE	FS out (after account balance)	Check the terminal setting from the host.
D00A1	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	FS omitted (after available balance)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
D00A100	1800CE, 2700CE, 5000CE, 5300CE	FS out (after available balance)	Check the terminal setting from the host.
D00A2	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	FS omitted (after available balance)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor (Check T-DES Type)
D00A200	1800CE, 2700CE, 5000CE, 5300CE	FS out (after surcharge amount)	Check the terminal setting from the host.
D00A3	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	FS omitted (after authorization response text)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
D00A300	1800CE, 2700CE, 5000CE, 5300CE	FS out (after authorization response text)	Check the terminal setting from the host.
D00A4	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800,	ETX is in wrong place	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor

	MB2000, MB2100, T4000		
D00A400	1800CE, 2700CE, 5000CE, 5300CE	ETX wrong position	Check the terminal setting from the host.
D00A5	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	FS omitted (after total cash dispense amount in day close)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
D00A500	1800CE, 2700CE, 5000CE, 5300CE	FS out (after total cash dispense amount)	Check the terminal setting from the host.
D00A6	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	FS omitted (after total non cash dispense amount in day close)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
D00A600	1800CE, 2700CE, 5000CE, 5300CE	FS out (after total non-cash dispense amount)	Check the terminal setting from the host.
D00A7	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	FS omitted (after surcharge amount in day close message)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
D00A700	1800CE, 2700CE, 5000CE, 5300CE	FS out (after total surcharge amount)	Check the terminal setting from the host.
D00A8	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	FS omitted (after surcharge amount in configuration message)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Check that Dual Master Key is disabled (non Coredata). Contact host processor
D00A800	1800CE, 2700CE, 5000CE, 5300CE	FS out (after config surcharge amount)	Check the terminal setting from the host.
D00A9	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	ETX omitted (from configuration message)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
D00A900	1800CE, 2700CE, 5000CE, 5300CE	ETX out (config)	Check the terminal setting from the host.
D00AC00	1800CE, 2700CE, 5000CE, 5300CE	Invalid data received from the host (MAC data mismatch)	Check the terminal setting from the host.

D00B0	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Invalid Terminal ID	Contact host processor
D00B000	1800CE, 2700CE, 5000CE, 5300CE	TERMINAL ID MISMATCHED	N/A
D00B100	1800CE, 2700CE, 5000CE, 5300CE	TRANSACTION CODE MISMATCHED	N/A
D00B200	1800CE, 2700CE, 5000CE, 5300CE	SECOND FIELD ID CODE MISMATCHED	N/A
D00B300	1800CE, 2700CE, 5000CE, 5300CE	FIRST DES KEY WRONG SIZE	N/A
D00B400	1800CE, 2700CE, 5000CE, 5300CE	SURCHARGE AMOUNT WRONG SIZE	N/A
D00B500	1800CE, 2700CE, 5000CE, 5300CE	Sequence Number MISMATCHED	N/A
D00B600	1800CE, 2700CE, 5000CE, 5300CE	INVALID RESPONSE CODE ERROR	N/A
D00B700	1800CE, 2700CE, 5000CE, 5300CE	Authorization Number Error	N/A
D00B800	1800CE, 2700CE, 5000CE, 5300CE	BUSINESS DATE Error	N/A
D00B900	1800CE, 2700CE, 5000CE, 5300CE	Transaction time Number Error	N/A
D00BA00	1800CE, 2700CE, 5000CE, 5300CE	BUSINESS DATE Error	N/A
D00BB00	1800CE, 2700CE, 5000CE, 5300CE	Balance amount Error	N/A
D00BC00	1800CE, 2700CE, 5000CE, 5300CE	Actual Surcharge Error	N/A
D00BD00	1800CE, 2700CE, 5000CE, 5300CE	Sequence Number MISMATCHED	N/A
D00BF00	1800CE, 2700CE, 5000CE, 5300CE	BUSINESS DATE Error	N/A
D00C000	1800CE, 2700CE, 5000CE, 5300CE	Settlement Error	N/A
D00C100	1800CE, 2700CE, 5000CE, 5300CE	Host Mac result error	Check the key mode and MAC value
D00C200	1800CE, 2700CE, 5000CE, 5300CE	ATM Mac result error	Check the key mode and MAC value
D0100	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800,	Transaction approved	None

	MB2000, MB2100, T4000		
D0101	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Expired card	None
D0102	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Unauthorized usage	None
D0103	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	PIN error	None
D0104	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Invalid PIN	None
D0105	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Bank unavailable	None
D0106	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Card not supported	None
D0107	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Insufficient funds	None

D0108	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Ineligible transaction	None
D0109	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Ineligible account	None
D0110	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Number of daily withdrawals exceeded	None
D0111	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Cannot process transaction	None
D011100	1800CE, 2700CE, 5000CE, 5300CE	REVERSAL DECLINED	N/A
D0112	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Amount too large	None
D0113	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Account closed	None
D0114	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	PIN tries exceeded	None

D0115	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Database problem	None
D0116	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Withdrawal limit already reached	None
D0117	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Invalid amount	None
D0118	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	External decline	None
D0119	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	System error	None
D0120	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Contact card issuer	None
D0121	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Routing lookup problem	None
D0122	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000,	Message edit error	None

	MB1500, MB1800, MB2000, MB2100, T4000		
D0123	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Transaction not supported	None
D0124	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Insufficient funds	None
D0125	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Western Union sender data error	None
D0126	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Western Union receiver data error	None
D0127	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	CRC error	None
D0128	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Pre-pay transaction failed	None
D0129	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Pre-pay transaction rejected	None

D0130	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Invalid mobile phone number	None
D0131	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Pre-pay account limit reached	None
D0132	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Pre-pay system unavailable	None
D0133	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Response would exceed message size limit	None
D0134	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Necessary information missing to precess transaction	None
D0135	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Second Invalid PIN(second "Invalid PIN" try in a row and one try is left before deactivation)	None
D022200	1800CE, 2700CE, 5000CE, 5300CE	PIN CHANGE DECLINED	N/A
D0300	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Modem is not responding	Use diagnostic or modem test to test modem. If error is persistent, modem may be defective.

D030000	1800CE, 2700CE, 5000CE, 5300CE	Modem is not responding	Check the modem controller.
D030100	1800CE, 2700CE, 5000CE, 5300CE	The target call address has call blocking enabled.	1. Check modem cable 2. Contact to technician support team
D030200	1800CE, 2700CE, 5000CE, 5300CE	The specified terminal identifier is invalid.	1. Check modem cable 2. Contact to technician support team
D030300	1800CE, 2700CE, 5000CE, 5300CE	All call appearances on the specified address are currently in use.	1. Check modem cable 2. Contact to technician support team
D030400	1800CE, 2700CE, 5000CE, 5300CE	The disable address parameter contains dialing control characters that are not processed by the service provider	1. Check modem cable 2. Contact to technician support team service provider.
D030500	1800CE, 2700CE, 5000CE, 5300CE	The specified country/region code is invalid.	1. Check modem cable 2. Contact to host and phone company
D030600	1800CE, 2700CE, 5000CE, 5300CE	The operation failed for an unspecified or Contact to technician support team unknown reason.	N/A
D030700	1800CE, 2700CE, 5000CE, 5300CE	Insufficient resources to complete the operation Contact to technician support team	N/A
D1000	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	No Connection	Use diagnostic or modem test to test modem. If error is persistent, modem may be defective.
D100000	1800CE, 2700CE, 5000CE, 5300CE	No connection	1. Check phone number 2. Check modem cable 3. Contact telephone company
D1100	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	ENQ not received from host	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
D110000	1800CE, 2700CE, 5000CE, 5300CE	Cannot receive ENQ from the host	1. Check phone number 2. Check modem cable 3. Contact telephone company
D1200	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Transmission error	Use diagnostic or modem test to test modem. If error is persistent, modem may be defective
D120000	1800CE, 2700CE, 5000CE, 5300CE	Transmission error : Failed to receive the whole data within 5	1. Check modem and modem cable connection 2. Contact telephone company

		seconds after requesting the modem to send the data.	
D1300	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	NAK sent 3 times to host	Verify host phone number - See D170x. If persistent, it could be a defective modem.
D130000	1800CE, 2700CE, 5000CE, 5300CE	Receiving NAK more than 3 times	1. Check modem and modem cable connection 2. Contact telephone company
D140100	1800CE, 2700CE, 5000CE, 5300CE	Disconnected by Unknown Reason	1. Check modem and modem cable connection 2. Contact telephone company
D140200	1800CE, 2700CE, 5000CE, 5300CE	Disconnected by rejected call from remote party Try again later.	N/A
D140300	1800CE, 2700CE, 5000CE, 5300CE	Disconnected because the local phone was picked up	Try again later.
D140400	1800CE, 2700CE, 5000CE, 5300CE	Disconnected by Forwarded	1. Check modem and modem cable connection 2. Contact telephone company
D140500	1800CE, 2700CE, 5000CE, 5300CE	Disconnected by Unreachable	1. Check modem and modem cable connection 2. Contact telephone company
D140600	1800CE, 2700CE, 5000CE, 5300CE	Disconnected by Congestion	1. Check modem and modem cable connection 2. Contact telephone company
D140700	1800CE, 2700CE, 5000CE, 5300CE	Disconnected by Incompatible	1. Check modem and modem cable connection 2. Contact telephone company
D140800	1800CE, 2700CE, 5000CE, 5300CE	Disconnected by un-known reason	1. Check modem and modem cable connection 2. Contact telephone company
D140900	1800CE, 2700CE, 5000CE, 5300CE	Disconnected by Bad Address	1. Check modem and modem cable connection 2. Contact telephone company
D141000	1800CE, 2700CE, 5000CE, 5300CE	Disconnected by Unavailable	1. Check modem and modem cable connection 2. Contact telephone company
D1500	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Modem connection time out - host not responding	Verify host phone number - verify modem speed - See D170x. If consistent, it can be a defective modem
D150000	1800CE, 2700CE, 5000CE, 5300CE	1. Modem dial connection time-out (while dialing the modem). 2. No response from host for 60 seconds.	1. Check modem and modem cable connection 2. Contact telephone company
D160100	1800CE, 2700CE, 5000CE, 5300CE	Disconnected by Bad Address	1. Check modem and modem cable connection 2. Contact telephone company
D160200	1800CE, 2700CE, 5000CE, 5300CE	Disconnected by Unavailable	1. Check modem and modem cable connection 2. Contact telephone company
D160300	1800CE, 2700CE, 5000CE, 5300CE	Disconnected by Out of Order	1. Check modem and modem cable connection 2. Contact telephone company

D170000	1800CE, 2700CE, 5000CE, 5300CE	No carrier (while sending/receiving data after dial connection)	Check host.
D170100	1800CE, 2700CE, 5000CE, 5300CE	No Carrier during ENQ data receive from host	Check host.
D1702	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Modem connection error	Phone line connected to ATM will not support data communication. In line filter may help this. Excessive EMI emissions from outside source (neon sign, freezer)are likely causes. This can also be a problem with programming, check all programming (especially Dual Master Key setting and Host Processor Mode).
D170200	1800CE, 2700CE, 5000CE, 5300CE	No Carrier before sending data send to host	Check host.
D170300	1800CE, 2700CE, 5000CE, 5300CE	No Carrier during sending data send to host	Check host.
D1704	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, MB2500, T4000	Modem connection error	Phone line connected to ATM will not support data communication. In line filter may help this. Excessive EMI emissions from outside source (neon sign, freezer)are likely causes. This can also be a problem with programming, check all programming (especially Dual Master Key setting and Host Processor Mode).
D170400	1800CE, 2700CE, 5000CE, 5300CE	No Carrier during ACK/NAK data send to host	Check host.
D170500	1800CE, 2700CE, 5000CE, 5300CE	No Carrier during ACK/NAK data receive from host	Check host.
D1706	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Modem connection error	Phone line connected to ATM will not support data communication. In line filter may help this. Excessive EMI emissions from outside source (neon sign, freezer)are likely causes. This can also be a problem with programming, check all programming (especially Dual Master Key setting and Host Processor Mode).
D170600	1800CE, 2700CE, 5000CE, 5300CE	No Carrier during receiving data	Check host.
D170700	1800CE, 2700CE, 5000CE, 5300CE	NAK retry error.	1. Check modem and modem cable connection 2. Contact telephone company
D170800	1800CE, 2700CE, 5000CE, 5300CE	Send retry error	1. Check modem and modem cable connection 2. Contact telephone company
D170900	1800CE, 2700CE, 5000CE, 5300CE	Modem initialize fail	Check modem
D170x	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Modem cannot support connection - excessive line noise (usually D1704/06)	Phone line connected to ATM will not support Data-communication. In line filter may fix this. Excessive EMI emissions from outside source (neon sign, freezer). This can also be a problem with programming, check all programming (especially Dual Master Key setting and Host Processor Mode).

D171000	1800CE, 2700CE, 5000CE, 5300CE	Modem Comport Failed	Check modem
D1800	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	No dial tone	Verify that incoming phone line is plugged into "Line" rather than "Phone" on mainboard. Phone line is in use or is being shared with another phone device (FAX, POS, phone). NOTE: This error occurs only if there is no dial tone at the mainboard.
D180000	1800CE, 2700CE, 5000CE, 5300CE	No Dial Tone(in Modem dial connection)	Check telephone line connection. Test Modem.
D1900	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	No answer	Verify host phone number - See D170x, there is no answer from the host modem.
D190000	1800CE, 2700CE, 5000CE, 5300CE	No Answer	1. Contact telephone company (Check telephone line connection. Check phone number.)
D2000	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Phone line Busy	Verify host phone number - call line with handset and check for busy signal - See D170x. ATM modem is receiving a busy signal when it dials out.
D200000	1800CE, 2700CE, 5000CE, 5300CE	Dial (Line) busy	Try again later. Check phone number.
D2100	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Modem initialization error	Check modem in diagnostics or modem test. If persistent, it could be a defective modem. Note: If the modem is defective, this error will most likely occur frequently. One or two instances of this error does not usually indicate a defective part.
D210000	1800CE, 2700CE, 5000CE, 5300CE	Time out(30sec.) for initializing modem before Modem Dial connecting	Check telephone line connection. Test Modem.
D2200	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	EOT not received from host	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
D220000	1800CE, 2700CE, 5000CE, 5300CE	not receiving EOT from HOST	Check telephone line connection. Test Modem. Check host.
D230000	1800CE, 2700CE, 5000CE, 5300CE	No response from Host - Dialing time out to Host	Check telephone line connection. Test Modem. Check phone number.
D2500	1700, 1700W, 2100T, C4000,	Cannot connect to the host	Check the connection

	G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000		
D250000	1800CE, 2700CE, 5000CE, 5300CE	Cannot connect to the host	Check telephone line connection
D2510	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Timeout while Sending	None
D251000	1800CE, 2700CE, 5000CE, 5300CE	Timeout while Sending	Check telephone line connection
D2511	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Communication error while Sending	None
D251100	1800CE, 2700CE, 5000CE, 5300CE	Communication error while Sending	Check telephone line connection
D251200	1800CE, 2700CE, 5000CE, 5300CE	Socket error while Sending	Check telephone line connection
D2513	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Timeout while Receiving	None
D251300	1800CE, 2700CE, 5000CE, 5300CE	Timeout while Receiving	Check telephone line connection
D2514	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Communication error while Receiving	None
D251400	1800CE, 2700CE, 5000CE, 5300CE	Communication error while Receiving	Check telephone line connection
D2515	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800,	Socket Error while Receiving	None

	MB2000, MB2100, T4000		
D251500	1800CE, 2700CE, 5000CE, 5300CE	Socket Error while Receiving	Check telephone line connection
D320100	1800CE, 2700CE, 5000CE, 5300CE	Outbound call is aborted	Check telephone line connection. Test Modem.
D320200	1800CE, 2700CE, 5000CE, 5300CE	Fail to dial out	Check telephone line connection. Test Modem.
D320300	1800CE, 2700CE, 5000CE, 5300CE	No Line Reply	N/A
D3204	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Invalid Host phone number	Verify the Host phone number is programmed correctly. Do not use spaces or dashes in the phone number string.
D320400	1800CE, 2700CE, 5000CE, 5300CE	Get Line ID Failed	N/A
D320500	1800CE, 2700CE, 5000CE, 5300CE	Modem Comport Failed	N/A
D320600	1800CE, 2700CE, 5000CE, 5300CE	Call Failed	N/A
D320700	1800CE, 2700CE, 5000CE, 5300CE	No Answer	N/A
D320800	1800CE, 2700CE, 5000CE, 5300CE	Modem Call Other Error	N/A
D410000	1800CE, 2700CE, 5000CE, 5300CE	CRC Mismatch	Check telephone line connection
D410100	1800CE, 2700CE, 5000CE, 5300CE	No CRC Received	Make sure that the host is using CRC
DA0xxx0	1800CE, 2700CE, 5000CE, 5300CE	Host Denial Error	Refer to E7. Description for error code organization
E000x	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	RMS port failure, response time out, modem failure, no dial tone	Verify RMS settings (Host Setup) - See D170x
F0001	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Current Number of Bills is 0	Load notes into the cash cassette - use Add Cassette function in Settlement
F000100	1800CE, 2700CE, 5000CE, 5300CE	Number of Bill is not inputted	Enter number of bill. (required)

F0002	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	No Surcharge Owner set	Set Surcharge owner - (Customer Setup)
F000200	1800CE, 2700CE, 5000CE, 5300CE	Parameter is not properly set (Surcharge Owner)	Enter surcharge owner. (required)
F0003	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	No Surcharge Amount	Set Surcharge amount - (Customer Setup)
F000300	1800CE, 2700CE, 5000CE, 5300CE	Parameter is not properly set (Surcharge Amount)	Enter surcharge amount. (required)
F0004	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	No refresh timer set when advertisement is enabled	Set refresh timer - (Customer Setup)
F000400	1800CE, 2700CE, 5000CE, 5300CE	Parameter is not properly set (Adver. Text Refreshing Timer)	Enter Ad text refresh timer.
F0005	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	No Advertisement text when advertisement is enabled	Set Advertisement text - (Customer Setup)
F000500	1800CE, 2700CE, 5000CE, 5300CE	Parameter is not properly set (Advertisement Text)	Enter Ad text.
F0006	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Dispense limit set error (must be less than 25 notes)	Set Dispense limit - (Transaction Setup)
F000600	1800CE, 2700CE, 5000CE, 5300CE	Parameter is not properly set (Dispense limit)	Enter Dispense limit.
F0007	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800,	Denomination Set error	Valid Denominations are $10, $20, $50, $100 - (Transaction Setup)

	MB2000, MB2100, T4000		
F000700	1800CE, 2700CE, 5000CE, 5300CE	Parameter is not properly set (Denomination)	Enter Denomination. (required)
F0008	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Fast Cash Set error (cannot exceed dispense limit)	Check fast cash settings (Transaction Setup)
F000800	1800CE, 2700CE, 5000CE, 5300CE	Parameter is not properly set (Fast Cash)	Enter Fast Cash amount.
F0009	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Master Key index is invalid	Check Master Key index - verify checksum (Host Setup)
F000900	1800CE, 2700CE, 5000CE, 5300CE	Master Key Index invalid	Check Master key index.
F000A	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Master Key is empty	Check Master Key checksum - reinject key (Host Setup)
F000A00	1800CE, 2700CE, 5000CE, 5300CE	Master Key empty	Enter Master key. (required)
F000B	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Host Telephone Number is not set	Set Host Telephone Number - (Host Setup)
F000B00	1800CE, 2700CE, 5000CE, 5300CE	Host Phone Number is not inputted	Enter Host phone number. (required)
F000C	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Error Retry timer is not set	Set Error retry timer (Host Setup)
F000C00	1800CE, 2700CE, 5000CE, 5300CE	Error Retry Timer is not inputted	Enter Retry timer.
F000D	1700, 1700W, 2100T, C4000,	RMS Password is not set when RMS is enabled	Set RMS Password - (Host Setup)

	G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000		
F000D00	1800CE, 2700CE, 5000CE, 5300CE	RMS Password is not inputted in RMS Enable	Enter RMS password.
F000E	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	RMS phone number is not set when RMS send is enabled	Set RMS Phone number - (Host Setup)
F000E00	1800CE, 2700CE, 5000CE, 5300CE	RMS Phone Number is not inputted in RMS Enable	Enter RMS phone number.
F000F	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Terminal ID is not set	Set Terminal ID number - (Host Setup)
F000F00	1800CE, 2700CE, 5000CE, 5300CE	Terminal Number is not inputted	Enter Terminal number. (required)
F0010	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Routing ID is not set	Set Routing ID number - (Host Setup)
F001000	1800CE, 2700CE, 5000CE, 5300CE	Routing ID is not inputted	Enter Routing ID. (required)
F0011	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Master Key Serial number is not set	Set Master Key serial number - (Host Setup)
F001100	1800CE, 2700CE, 5000CE, 5300CE	Master Key Serial Number is not inputted	Enter Master key serial number.
F001200	1800CE, 2700CE, 5000CE, 5300CE	Non-Cash Type text is not inputted	Enter Non-cash type text.
F0013	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800,	NVRAM Failure	Fatal error, defective memory chip. Replace Mainboard

	MB2000, MB2100, T4000		
F001300	1800CE, 2700CE, 5000CE, 5300CE	Parameter is not properly set	Check proper parameters in setting.
F0014	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	NVRAM Failure	Fatal error, defective memory chip. Replace Mainboard
F001400	1800CE, 2700CE, 5000CE, 5300CE	NVRAM Failure	Try to clear NVRAM
F0015	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	ATM Serial No. Empty	None
F001500	1800CE, 2700CE, 5000CE, 5300CE	ATM Serial No. Empty	Enter ATM serial number. (required)
F0016	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Default Master Password is not changed	None
F001600	1800CE, 2700CE, 5000CE, 5300CE	Default master password was not changed	Change Master Password
F001F00	1800CE, 2700CE, 5000CE, 5300CE	Machine serial number is not set	Check serial number. 2. Set serial number.
F0020	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Host IP Address is not inputted	None
F0021	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	RMS IP or Port is not inputted in RMS Enable	None
F002F00	1800CE, 2700CE, 5000CE, 5300CE	Host type is not set	Check host type. 2. Set host type.
F003F00	1800CE, 2700CE, 5000CE, 5300CE	Communication ID invalid (only triton)	Contact to technician support team .

F004F00	1800CE, 2700CE, 5000CE, 5300CE	EPP(Pinpad) key mode is invalid	1. Check modem cable 2. Contact to technician support team
F005F00	1800CE, 2700CE, 5000CE, 5300CE	Denomination is invalid	1. Check modem cable 2. Contact to technician support team
F006F00	1800CE, 2700CE, 5000CE, 5300CE	Failed Host Connection!	1. Check Host Connection. 2. Contact to technician support team.
P0001	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Deposit Error	Deposit Error
P0002	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Deposit Timeout	Deposit Timeout
P0003	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Invalid Deposit	Invalid Deposit
P0004	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	Deposit Cancelled	Deposit Cancelled
PDN01	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	EPP Cmmunication Error	None
W0001	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	WebRMS failed to dial into the ATM	This does not mean that the ATM is down; it's a warning message that WebRMS could not dial into the ATM after three attempts during its daily scheduled dial-in period. Make sure the ATM is turned on, the phone line fits securely on both ends, and not shared with a voice phone nor experiences static.
W0002	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000,	WebRMS low cash warning	This is a courtesy alert warning, along with an email message, that you requested to receive when the total bill count is under a certain amount.

	MB1500, MB1800, MB2000, MB2100, T4000		If you wish to change this warning, please update your preferences through our website.
W0003	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	WebRMS could not retrieve the local ATM time	Although webRMS successfully retrieved the journal information, it could not find the ATM's local time. (This is equivalent to the "-1/-1/-001" error when using Windows RMS). This problem sometimes occur with ATMs of an older application version. Make sure you are running the latest application version.
W0004	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	The ATM time, as set in the Operator Function Menu, is incorrect	WebRMS has detected that the ATM probably has incorrect date and time settings. You will need to physically go to the ATM location and manually reset the correct date with the Master Password.
W0005	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	WebRMS coincidentally detected that the ATM was in Operator mode at the time the ATM was dialed into.	This is not an error in particular, but a simple warning that someone was locally on-site at the ATM, and used its Operator Function menu.
W0006	1700, 1700W, 2100T, C4000, G1900, G2500, GT3000, MB1000, MB1500, MB1800, MB2000, MB2100, T4000	WebRMS has failed to dial into the ATM consecutively for more than 3 days.	Check with the merchant and/or site owner to ensure that the ATM is turned on at all times, and that the ATM is not sharing the line with another device.