
Operation of Single-phase Autor transformer:

The working of an auto-transformer is Similar to that of a two-winding transformer, Att shown below.



In the above size diagram, the AB is the primary winding of transformer and 'CB' is secondary winding where the tapping is provided.



When a supply voltage V₁ is applied to the primary winding AB, an alternating flux set up in the core due to which an induced emf E₁' is devoloped.

Since the secondary winding is a part of the primary winding, a part of the induced emf E₁, is taken in to which the load is connected.

The is taken in to which the load is connected.

Let E₂ be the induced emf in the secondary winding

- -> Let E2 be the induced of the current in the secondary -> This induced emf drives the current in the secondary winding and hence the load connected to it.
- As in an ordinary transformer, the transformation ration is turn ratio as


$$K = \frac{N_2}{N_1} = \frac{E_2}{E_1} = \frac{V_2}{V_1} = \frac{I_1}{I_2}$$

- -> The power delivered to loud is P_ = 1/2 Iz
- But in Auto transformer

-> When $N_1>N_2 \rightarrow is$ Stepdown Fransformer. $N_1< N_2 \rightarrow is$ Step-up Fransformer. * A miniature circuit breaker is an electromechanical device which makes and breaks the circuit in normal operation and disconnects the circuit under the abnormal condition when current exceeds a preset value.

* MCB is a high fault capacity current limiting, trip free, automatic switching device with thermal and magnetic operation to provide protection against overload and short circuit.

- * It is necessary to use MCB because of its following features
- 1) Its operation is very fast and opens in less than one milli second.
- 2) No tripping circuit is necessary and the operation is automatic.
- 3) provides protection against overload and short circuit, without noise, smoke or flame.
- 4) It can be reset very quickly after correcting the fault, Just by switching a button. No rewiring is required.
- 5) It can not be reclosed if fault persists.
- 6) The mechanical life is upto or more than one lakh operating cycle.
- * Hence now a days MCBs are used rather than rewirable fuse.
- * Generally McBs are rated for a.c voltage of 240 v for single phase, 415 v for three phase or 280 v d.c. The current rating available is from 0.5A to 63A. It is available as single pole (SP), Double pole (DP), Tripple pole (TP) with short circuit breaking capacity from 1kA to 10kA with a rated frequency.
- * A typical wiew of MCB and its practical appearance is shown in Fig. . below.



* The othere phase induction motor consists of two main party, namely.

1) The part carrying three phase windings, which is stationary
called stator.

- 2) The part which rotates and is connected to the mechanical load through shaft called rotor.
- 1. Stator) The statur has a laminated type of construction made up of stampings which are 0.4 to 0.5mm thick.
- * The stampings are slotted on its periphery to carry the stator winding. The stampings are insulated from each other. such a construction essentially keeps the iron losses to a minimum value.
- * The number of stampings are stamped together to build the stator core.
- * The slots on the periphery of the stator core Carries a three-phase winding, connected either in star or delta. This three phase winding is called stator winding. It is wound for definite number of poles.

* The radial duts are provided for the cooling purpose. The rig

Fig. 2.35.1 Stator lamination


3) Rotor: - The notor is placed inside the stator


* The air gap between Stator and the rotor is 0.4mm to 4mm.

* The two types of rotor constructions which are used for induction motor are, a. squirrel cage rotor and b. slip ring or phase wound rotor.

a) squirrel cage rotor:-

- # The rotor core is cylindrical and slotted on its periphery.
- * The rotor consists of uninsulated copper (or) aluminium bars called rotor conductors. The bars are placed in the slots.
- * These bars are permanently shorted at each end with the help of conducting copper ring called end ring. The bars are usually brazed to the end rings to provide good mechanical strength.
- * The entire structure looks like a cage, forming a closed electrical circuit. So the notor is called squinrel cage notor The construction is Shown in the Fig. Q. 35.2.





16) Symbolic representation

(a) (age type structure of rotor

) Slip Ring Rotor (or) phase wound Rotor!


* In this type of construction, notor winding is exactly similar to the stator.

F The rotor carries a three phase star (or) delta connected, distributed winding, wound for same number of poles as that of stator.

The rotor construction is laminated and slotted. The slots contain the rotor winding.

K The three ends of three phase winding, available after connecting the winding in star (or) delta, are permanently connected to the slip rings.

* with the helps of slip rings, the enternal ruistances can be added in series with each phase of the rotor winding. This



In the running condition, the slip rings are shorted.

torking principle of three phase induction motori-

nduction motor works on the principle of electromagnetic Induction. When a three phase supply is given to the three phase stator inding, a notating magnetic field of constant magnitude is roduced. The speed of this rotating magnetic field is synchronous speed, No r.p.m.

Ns = 1201 = speed of rotating magnetic field.

This rotating field produces an effect of rotating poles around

NIs = 120f = speed of rotating magnetic field.

- * This rotating field produces an effect of rotating poles around a rotor.
- * At this instant rotor is stationary and statox flux R.M.F. is rotating. so its obvious that there exists a relative motion between the R.M.F and rotor conductors.
- * hitherever conductor cuts of flum, e.m.f gets induced init. so e.m.f gets induced in the rotor conductors called rotor induced e.m.f
- * As votor forms closed circuit, induced emit circulates through

rotor called rotor current

- * Any current carrying conductor produces its own flux. so rotor produces its flum called rotor flum.
- * The two flames, stator flum and the rotor flum interact with each other such that on one side of rotor conductor, two fluxes are in same direction hence add up to get high flux area while on other side, two fluxes cancel each other to produce low flux area
- * As flux lines act as stretched rubber band, high flux density area exerts a push on rotor conductor toward low flux density area. So rotor conductor experiences a forces due to interaction of the two fluxes.
- * As all the rotor conductors emperiences a force, the overall rotor emperiences a torque and starts rotating.
- * According to Lenz's law the direction of induced current in the rotor is so as to oppose the cause producing it.
- * The cause of rotor current is the induced e.m.f. which is induced because of relative motion present between the rotating magnetic field and the rotor conductors.
- * Hence to oppose the relative motion i.e. to reduce the relative speed, the rotor experiences a torque in the same direction as that of R.M.F. and tries to catch up the speed to rotating

Slip of Induction motori-

The differente between the speed of rotating magnetic field and the actual rotor speed is called slip speed i.e. Ns-N=slip Speed of the motor.

* slip of the induction motor is defined as the difference between the synchronous speed (Ns) and actual speed of rotor i.e. motor (N) expressed as a fraction of the synchronous speed (Ns). This is also called absolute slip (or) fractional slip and is denoted as 's !.

Slip,
$$S = \frac{Ns-N}{Ns}$$
 and $1/.$ $S = \frac{Ns-N}{Ns} \times 100$

Torque equation of three phase inductor motors-

The torque developed by the rotor is directly proportional to i, rotor current

ii, notor E.m.f

ill, power factor of the rotor circuit

TX E2 12 COS \$2

Rotor current
$$\underline{T}_1 = \frac{SE_1}{\overline{E}_2} = \frac{SE_2}{\sqrt{R_1^2 + (SX_1)^2}}$$

$$\cos \phi_1 = \frac{R_2}{Z_1} = \frac{R_2}{\sqrt{R_1^2 + (Sx_2)^2}}$$
; $\gamma = \frac{KSE_1^2R_2}{R_1^2 + (Sx_2)^2}$

Starting Torque i.e. at S=1 (slip)

So starting Porque is given by

$$T_S = KE_2 I_1 \cos \beta_2$$

$$T_S = KE_1 \times \frac{E_2}{\sqrt{R_1^2 + X_2^2}} \times \frac{R_2}{\sqrt{R_2^2 + X_2^2}}$$


$$T_S = \frac{kE_2^2R_2}{(R_1^2 + x_2^2)}$$

Grenerally, the startor supply voltage is constant (V), so that flum set up by the stator also fixed, This in turn means that the Emf induced in the Rotor will be constant, so.

EMF- equation of Transformer

When the primary winding is excited by an alternating voltage V, it circulates alternating current producing an alternating flux o',

The waveform for alternating flux '&' can drawn as for time period 211




N1 = No of primary turns N2 = No. of Secondary turns

E1 = primary induced emf in RMS

Ez = Secondary induced emf in RMS

f = frequency of Supply.



- According to Faraday's law of electromagnetic induction the average emt induced por oin each turn is proportional to the average rate of change of flux.

.. Average empl per turn = Average rate of change of flux

i.e
$$\frac{d\phi}{dt} = \frac{\text{change in flux}}{\text{Time required for @ change in flux}}$$

In above above figure initial flux (\$ =0) and

after 14th" cycle the fluxes are mornimum i.e &m, so

1.e
$$\frac{d\phi}{dt} = \frac{\phi_{m} - 0}{(\frac{1}{4}f)} = 4f \phi_{m}$$
 wb/sec

So, Average emf per turn = 4+0m volts. i.e emf = 4+0m

→ The RMS value of induced emf per turn

- If primary winding has 'N,' of no. of turns, then DMS Value of induced emf in primary

- If primary winding has 'Ni' of no. of turns, then RMS Value of induced emt in primary

Simillarly, in secondary

Transformation ratio(K)


If transformer having primary induced emb (E1) and Secondary induced emd (Ez), then

i.e
$$K = \frac{\epsilon_2}{\epsilon_1}$$

and $K = \frac{N_2}{N_1}$

$$K = \frac{V_2}{V_1}$$
 i.e $\frac{\epsilon_2}{\epsilon_1} = \frac{N_2}{N_1} = \frac{V_2}{V_1} = K = \frac{T_1}{T_2}$

problems: - O , The montimum flux density in the core of



As shown in the Fig. Q.51 ELCB consists of a small current transformer surrounding live and neutral wire. The secondery winding of current transformer is connected to relay circuit which can trip the circuit breaker which is connected in the circuit.

under normal conditions, the current in line and neutral Conductor is same so the net current (IL-IN) flowing through the core is zero. Eventually there will not be any production of flux in the core and no induced erm. I. So the breaker does not trip.

* If there is a fault due to leakage from live wire to earth or a person by mistake touching to the live terminal then the net current through to the core will no longer remain as 3 ero but equal to II-In or II which will set up flux and emf in C.T. As per the present value, the unbalance in Current is detected by C.T. and relay coil is energized which will give tripping signed for the circuit breaker. As c.T. operates with low value of current, the core must be very permeable at low flux densities.

* Thus ELCB provides protection against electric shock when

* A properly connected ELCB detects such small currents in milliamperes flowing to earth through human body or earth wire and breaks the circuit to reduce the risk of clectrocution to humans.

- 1) provides protection to a human against the electric shock.
- 2) Detects very small leakage currents.
- 3) Reduces the Risk of fire due to hot Spots.
- 4) saves electrical energy due to leakage. In poly many
- 5) Energy conservation can be achieved.

^{*} There are certain situations where leakge current can flow through the metal bodies of appliances, when person touches to Such appliances. Thus person can get a shock.

^{*} Similarly there is risk of fire due to such earth leakage

^{*} Thus a protective device is necessary which say can sense small leakage current and disconnect the circuit from supply. Such a device is called earth leakage circuit breakers (ELCB).