Brungard Aviation LLC. WO 6995

303-440-4791 3323 Airport Rd, Boulder, CO 80301

AIRFRAME LOG

DATE:	10/12/2024	REGISTRATION	N9248C	AFTT:	7041.36	TACH:	1477.46
MAKE:	Cessna	MODEL:	180	Serial #:	31347	HOBBS:	N/A

Work Performed

1. Complied with AD 2020-21-22. During inspection, found 7 cracks on the bulkhead assembly. Found worn tailcone RH reinforcement plate. Found LH/RH tailgear mounting worn beyond limits. Found and LH/RH bracket stabilizer worn beyond limits. The tailcone was reassembled with: New bulkhead assembly P/N: 0712207-3 ,New RH reinforcement plate P/N: 0712304-4, New LH tailgear mounting P/N: 0712305-31, New RH tailgear mounting P/N: 0712305-4, New LH bracket stabilizer P/N: 0712302-1, New RH bracket stabilizer P/N: 0712304-2, New tube 0742100-5. See form 337 Dated 10/12/2024 for repair details. AD 2020-21-22 has been accomplished and the next inspection is due 10/12/2029 or Total Time 7485.2 whichever comes first.

2. Found Cessna service kit SK185-27 (stabilizer jack screw access cover) improperly installed, removed and installed Cessna service kit SK185-27 per the service kit instructions.

3. Replaced bent and worn elevator jack screws with new McFarlane Aviation Inc. Stabilizer jack screw actuators and installed with new hard wear IAW STC SA02441AK, McFarlane Inc. Drawing number 111-1REV, original date June 1, 2010. and AC43.13-13 Ch. 4, Sec 4, Ch. 7 and Cessna Service manual. See 337 dated 10/12/2024 for elevator jack screw STC install.

4. Replaced two damaged ribs in left wing with new rib P/N On/Off: Rib outer 0523515-3, inner Rib 0720608-7, and fabricated new top wing skin using the same materials 2024-T3, .32 thickness, using the old top skin as a template. Top skin was cleaned (bonderite C-iC 33), Alodined (bonerite M-CR 1201) and painted with zinc chromate primer. All riveting was accomplished using standard practices as outlined in AC 43.13-1B, chapter 4 – section 4, Chapter 7 and the Cessna service manual P/N 0720601-17 See 337 dated 10/12/2024 for repair details.

5. Rigged and set cable tension on Left and Right aileron IAW Cessna 180 Service manual Ch. 6-11

6. Replaced all flap rollers on left and right Inboard and outboard flap rollers with (new outboard flap roller kit 2X P/N: FLP-KT-IU-U) and (New inboard flap roller kit 2X P/S: MCSK-100) IAW Cessna 180 service manual. Operational check is satisfactory.

7. Removed and replaced worn horizontal stabilizer bearings with (new 5x P/N NAS296-4A) operational check is satisfactory.

8. The elevator trim wheel was found to be missing friction stops. Installed new friction stops on the friction stop bracket.

9. Properly routed and secured loose wiring in LH wing..

10. Replaced both rudder cables with new stainless steel McFarland rudder cables 2X P/N MC01010S-126. Rigged rudder cables IAW Cessna 180 service manual. Rigging check is satisfactory.

11. Replaced rudder trim pulley bracket with serviceable unit P/N ON /OFF: 0712212-5 Rigged Rudder trim. Operational check and rigging check of rudder trim is satisfactory.

12. Installed AeroPod jackscrew inspection panels STC SA00858DE IAW Aero pod master drawing list document number AP-0005-MDL revision IR. Dated January 20th 2017. Weight and balance change negligible. See 337 dated 10/12/2024.

13. Installed later series 180 R/H Door Assy Air Vent P/N: 0713135-1. Minor alteration. I.A.W. AC-43.13-1B Change. 1.

14. Installed new friction stops on elevator trim wheel bracket P/N: 073023-7. Operational check is satisfactory.

I certify that the above stated maintenance and/or inspection was performed in accordance with the current regulations of the FAA, and the aircraft, engine, propeller, or component identified above was determined to be in an airworthy condition only for the work performed.

Samuel I. Perez Baptista A&P IA 3815080 _____ 10/12/2024

Besided the above state repairs and inspections work performed associated with Brungard Aviation LLC work order 6995 was halted before it could be fully completed. The annual inspection was not completed and neither were upgrades or repairs to the aircraft finished. This aircraft N9248C S/N 31347 is out of annual, and list of discrepancies known at this time has been transferred to the owner/operator.