JET LINX AVIATION, LLC
AIRCRAFT MAINTENANCE AND DISCREPANCY LOG

JET LINX AVIATION, LLC

AIRCRAFT MAINTENANCE AND DISCREPANCY LOG

Date: 10/18/24	N# 420EH	ACTT: 5888.0	ACTL: 4375	Trip ID# 111826-1
Eng 1 TT: 5828.3	Eng 2 TT: 5828.3	Eng 3 TT:	APU TT:	
Eng 1 TC: 4333.0	Eng 2 TC: 4329.0	Eng 3 TC:	APU TC:	
Signature:	Printed Name: Michael Mosher	Circle: Crew / Mech.	Leg # 1	

Discrepancy: Right Boost pump fail in flight and fuel Low press R illuminated in flight

Deferred By:	Date:	MEL Ref:	Category: A B C D
MEL Entry:			
Signature:	Date:	MEL Expiration Date:	
Circle MEL Ext: 1 2 3	Extension Authorized By:	Date Authorized:	
Reason for Extension:		Extended to:	

Corrective Action	Repair Date: 10/20/24	ACTT: 5888.0	ACTL: 4375
Engine: 1 2 3 APU		Engine TT:	Engine TC:

Repair Action: Found R/H fuel PC board to be burnt and Inop. Removed R/H PC fuel board, (P/N:631834-6, S/N:0146), and L/H fuel PC board, (P/N:631834-6, S/N:0146). Installed new R/H fuel PC board, (P/N:631834-11, S/N:0794), and L/H fuel PC board, (P/N:631834-11, S/N:0793), in Reference with SB525A-28-02, OPs checked in reference with 525A AMM, 28-20-00

Signature: Caleb O'Mara	Printed Name: Caleb O'Mara
Certificate #: CRSK55R339N	RII Insp (if required): Sam Perez
Name of Facility: Elevate MRO	Facility Location: Elevate MRO (KBJC)

Please fax to Jet Linx Aviation, LLC MX Control at: 202-403-0545 or email to mxcontrol@jetlinx.com

Log Number: 39759