\

Brungard Aviation LLC. WO 6995

303-440-4791 3323 Airport Rd, Boulder, CO 80301

PROPELLER LOG

DATE: 10/12/2024	REGISTRATION: N9248C	TTSMO: 0.00	TACH: 1477.46
MAKE. MT-Propeller	MODEL: MTV-15-D	Serial #: 221596	HOBBS: N/A

Item #	.	Work Performed
1		Installed MTV-15-D propeller P/N:MTV-15-D/210/58 S/N: 221596 expedition series 83" blades in accordance with STC installation instructions #SA01296WI. Installation is not complete due to operational/leak check, missing weight and balance and propeller balance.
2		Installed new propeller governor control bracket P/N B-20935

All work was performed in reference to the MT Propeller Installation Instructions E-124 Issue 73 May 15th, 2024. I certify that the above stated maintenance was performed in accordance with the current regulations of the FAA, and the aircraft, engine, propeller, or component only for the work performed.

Samuel I. Perez Baptista A&P IA 3815080 10/12/2024

Besided the above stated maintance performed associated with Brungard Aviation LLC work order 6995 was halted before it could be fully completed

\

Brungard Aviation LLC. WO 6995

303-440-4791 3323 Airport Rd, Boulder, CO 80301

ENGINE LOG

DATE: 10/12/2024	REGISTRATION: N9248C	TTSMO: 0.00	TACH: 1477.46
MAKE Continental / Northpoint	MODEL: IO-520-D116	Serial #: 1045854	HOBBS: N/A

Item #	.	Work Performed
	1	Installed Northpoint XP470 engine in accordance with installation instructions STC #SA00468WI. Installation not complete, due to missing aircraft weight and balance required. Form 337 needs to be completed and filed.
	2	Airbox assembly P/N 0750144-33AWL installed.
	3	Added 12 qts of 20W-50 Type M. Grade mineral piston engine aircraft oil.
	4	Installed carb heat shroud kit SK182-78.
	5	Installed exhaust package 400-1EX.
	6	Installation of intake boot expander in progress.
	7	Operational checks required.

All work was performed in reference to the Continental / Northpoint IO-520-D116 installation instructions EMM and AC 43.13-1B change 1. I certify that the above stated maintenance was performed in accordance with the current regulations of the FAA, and the aircraft, engine, propeller, or component only for the work performed.

Samuel I. Perez Baptista A&P IA 3815080 10/12/2024

Besided the above stated maintance performed associated with Brungard Aviation LLC work order 6995 was halted before it could be fully completed

\

Brungard Aviation LLC. WO 6995

303-440-4791 3323 Airport Rd, Boulder, CO 80301

AIRFRAME LOG

DATE: 10/12/2024 MAKE: Cessna	REGISTRATION: N9248C MODEL: 180	AFTT: 7041.36 Serial #: 31347	TACH: 1477.46 HOBBS: N/A

Work Performed

1. Complied with AD 2020-21-22. During inspection, found 7 cracks on the bulkhead assembly. Found worn tailcone RH reinforcement plate. Found LH/RH tailgear mounting worn beyond limits. Found and LH/RH bracket stabilizer worn beyond limits. The tailcone was reassembled with: New bulkhead assembly P/N: 0712207-3 ,New RH reinforcement plate P/N: 0712304-4, New LH tailgear mounting P/N: 0712305-31, New RH tailgear mounting P/N: 0712305-4, New LH bracket stabilizer P/N: 0712302-1, New RH bracket stabilizer P/N: 0712304-2, New tube 0742100-5. See form 337 Dated 10/12/2024 for repair details. AD 2020-21-22 has been accomplished and the next inspection is due 10/12/2029 or Total Time 7485.2 whichever comes first.

2. Found Cessna service kit SK185-27 (stabilizer jack screw access cover) improperly installed, removed and installed Cessna service kit SK185-27 per the service kit instructions.

3. Replaced bent and worn elevator jack screws with new McFarlane Aviation Inc. Stabilizer jack screw actuators and installed with new hard wear IAW STC SA02441AK, McFarlane Inc. Drawing number 111-1REV, original date June 1, 2010. and AC43.13-13 Ch. 4, Sec 4, Ch. 7 and Cessna Service manual. See 337 dated 10/12/2024 for elevator jack screw STC install.

4. Replaced two damaged ribs in left wing with new rib P/N On/Off: Rib outer 0523515-3, inner Rib 0720608-7, and fabricated new top wing skin using the same materials 2024-T3, .32 thickness, using the old top skin as a template. Top skin was cleaned (bonderite C-iC 33), Alodined (bonerite M-CR 1201) and painted with zinc chromate primer. All riveting was accomplished using standard practices as outlined in AC 43.13-1B, chapter 4 – section 4, Chapter 7 and the Cessna service manual P/N 0720601-17 See 337 dated 10/12/2024 for repair details.

5. Rigged and set cable tension on Left and Right aileron IAW Cessna 180 Service manual Ch. 6-11

6. Replaced all flap rollers on left and right Inboard and outboard flap rollers with (new outboard flap roller kit 2X P/N: FLP-KT-IU-U) and (New inboard flap roller kit 2X P/S: MCSK-100) IAW Cessna 180 service manual. Operational check is satisfactory.

7. Removed and replaced worn horizontal stabilizer bearings with (new 5x P/N NAS296-4A) operational check is satisfactory.

8. The elevator trim wheel was found to be missing friction stops. Installed new friction stops on the friction stop bracket.

9. Properly routed and secured loose wiring in LH wing.

10. Replaced both rudder cables with new stainless steel McFarland rudder cables 2X P/N MC01010S-126. Rigged rudder cables IAW Cessna 180 service manual. Rigging check is satisfactory.

11. Replaced rudder trim pulley bracket with serviceable unit P/N ON /OFF: 0712212-5 Rigged Rudder trim. IAW Cessna AMM. Operational check and rigging check of rudder trim is satisfactory.

12. Installed AeroPod jackscrew inspection panels STC SA00858DE IAW Aero pod master drawing list document number AP-0005-MDL revision IR. Dated January 20th 2017. Weight and balance change negligible. See 337 dated 10/12/2024.

13. Installed later series 180 R/H Door Assy Air Vent P/N: 0713135-1. Minor alteration. I.A.W. AC-43.13-1B Change. 1.

14. Installed new friction stops on elevator trim wheel bracket P/N: 073023-7. Operational check is satisfactory.

15. Removed original tailwheel assembly and installed new AB1 10" tail wheel assy P/N AB1-3450-00 with new tailwheel spacer IAW AB1 STC SA01636SE. This 337 STC is not submitted due to missing updated weight and balance.

16. Removed fuel line to fuel selector. Due to improper routing and chafing against the control column. New fuel line needs to be installed.

17. Corrosion was found on the Bulkhead assy Aft section. Corrosion was removed. Airworthiness determination required.

18. Installed Oregon Aircraft Design LLC Engine Mount Heat Shields Cessna Model Equipped with Seaplanes West Engine Mount. P/N: 180107 heat shield, P/N: QS200-16H 2 places P/N: QS200-16H. Work is not finished. Pending weight and balance of aircraft. Form 337 needs to be completed.

19. Installed new Seaplane west engine mount Model 400-1 S/N IOGPV IAW Seaplanes West modification data summary MDS323411, REV 4. Install not complete due to weight and balance. Form 337 needs to be completed.

I certify that the above stated maintenance was performed in accordance with the current regulations of the FAA, and the aircraft, engine, propeller, or component only for the work performed.

Samuel I. Perez Baptista A&P IA 3815080 10/12/2024

Besided the above statement for maintenance and work performed associated with Brungard Aviation LLC work order 6995 was halted before it could be fully completed.