NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

8. Description of Work Accomplished
(If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)

N9248C — Nationality and Registration Mark

10/12/2024 — Date

Replaced the following Parts.
Left Wing:
0523515-3 Rib
0720608-7 Rib
0720601-17 Skin

Tail:
0712207-3 Bulkhead assembly tailcone
0712302-1 Bracket stabilizer hinge LH
0712302-2 Bracket Stabilizer Hinge RH
0712304-4 Fitting - Tailcone reinforcement RH
0712305-3 Casting - Tailgear mounting LH
0712305-4 Casting - Tallgear mounting RH
0712212 Bracket - Pulley
0742100-5 Tube

Removed incorrectly installed Cessna Service Kit SK185-27 and installed Cessna Service Kit SK185-27 per the service kit installation instructions.

Fabricated new top wing skin 0720601-17 using same materials 2024-T3, .032 thickness, using the old top skin as a template. Top skin was cleaned (Bonderite C-IC 33), alodined (Bonderite M-CR 1201) and paint with zinc chromate primer.

All riveting was accomplished using standards practices, as outlined in AC43.13-1B, Chapter4-section 4, Chapter 7 and the Cessna service manual.

The tail was assembled with all new hardware and rigged in accordance with the Cessna Service Manual.

----------END----------

☐ Additional Sheets Are Attached