JSX

5616 Haven St. Suite A, ATTN: JSX PARTS
Las Vegas, NV, US, 89119
AMO: Attn. Parts

**N950JX**
EMB-145LR
SN 145640

Work Order / Plan No. SLC MX-687
Service Center Elevate MRO

**CUS-0004** **A/F (145640)**

Line Service Check

5 - Inspection (AVG MAN HRS: 2) (APX COST: 2.64) (UPDATE NOTE: C/W)

Task: - Req: JSX
1. RE 2 Days

| Requirement | Due |
|---|---|
| 2 Days | 23-Sep-2024 |
| Hrs | |
| Ldg | |

Accepted Technical Publications Status: No technical publications attached
Zone: , Access:

| Compliance A/F (145640) | Days | Hrs | Ldg | Other |
|---|---|---|---|---|
| | 23/09/2024 | 38,890.39 | 31,217 | |

**Task Findings:**

- [x] Satisfactory
- [ ] Unsatisfactory
- [ ] Damage
- [ ] Corrosion Lvl. 1
- [ ] No fault Found
- [ ] Fault Found
- [ ] Leak
- [ ] Corrosion Lvl. 2
- [ ] Within Limits
- [ ] Outside Limits
- [ ] Requires Rewor
- [ ] Corrosion Lvl. 3
- [ ] Other:

**TSI**
Days
Hrs
Ldg

Compliance Notes:

**Cost**

**Man Hrs.**

## Associated Tasks

| **Task Number** / Description<br>ATA Major Assembly | PN | SN | Requirement | **Due**<br>Association Type |
|---|---|---|---|---|
| **CUS-0004**<br>Line Service Check + TPC checks combined<br>5-20 A/F | | | 1. RE A/R | Compliance Share Double |

Technician Name: Nathan Acuna

| License | Signature |
|---|---|
| CRSK55R339N | |

Inspector Name: Samuel L. Perez Baptista

| License | Signature |
|---|---|
| FAA CRSKS5R339N | |

JSX

5616 Haven St. Suite A, ATTN: JSX PARTS
Las Vegas, NV, US, 89119
AMO: Attn. Parts

**N950JX**
EMB-145LR
SN 145640

Work Order / Plan No.

Service Center

## Checklist

**CUS-0004**

**Line Service Check + TPC checks combined**

**1. RE A/R**

Step info

Complete

1 **External Walk-around**

Perform general visual walk around of aircraft for leaks, missing hardware, panel security, presence of static wicks, and other obvious defects.

2 **Nose Landing Gear Wheels and Tires**

Perform a general visual check for condition a. Check LH and RH NLG Wheels for general condition. Ref AMM 32-49-05-200-801-A, Subtask 212-002-A b. Check LH and RH NLG Tires for general condition. Ref AMM Task 32-49-04-200-802-A, Subtask 212-003-A.

3 **Right Main Landing Gear Brake Wear Indicators**

Check Right Main Landing Gear Brake Wear Indicators (UPPER & LOWER) per AMM 32-49-03- 200-801-A. a. If either wear indicator measures 1/64" or less, but not flat, change brake. May be deferred for 5 flight cycles if replacement brake not available. Contact MOC if deferral is necessary b. Indicators that are flat, or do not extend out of the wear indicator sleeve, may not be deferred and brake must be replaced prior to flight

4 **Right Main Landing Gear Wheels and Tires**

a. Check RH MLG wheels for general condition. Ref. AMM Task 32-49-02-200-801 b. Check RH MLG tires for wear and general condition. Ref. AMM Task 32-49-01-200-802-A i. If tread depth is worn to the bottom of any groove at the point of maximum wear around the tire circumference, replace tire ii. If tread depth is less than 1/32" but above flush at the point of maximum wear around the tire circumference, replace tire. If tire not available, replacement may be deferred for a maximum of 10 cycles or at the next RON, whichever occurs first. Contact MOC for deferral iii. Refer to AMM task for tread cut limits

5 **Right Engine**

a. Service the RH engine oil as necessary i. Service oil to the 2 Qts low level on engine sight glass If oil is added, make entry in Traxxall and enter amount (PINTS) of oil used

6 **APU**

a. Service the APU oil as necessary If oil is added, make entry in Traxxall and enter amount (PINTS) of oil used

7 **Left Engine**

a. Service the LH engine oil as necessary i. Service oil to the 2 Qts low level on engine sight glass. If oil is added, make entry in Traxxall and enter amount (PINTS) of oil used

8 **Left MLG Brake Wear Indicators**

Check Left Main Landing Gear Brake Wear Indicators (UPPER & LOWER) per AMM 32-49-03- 200-801-A 8. a. If either wear indicator measures 1/64" or less, but not flat, change brake. May be deferred for 5 flight cycles if replacement brake not available. Contact MOC if deferral is necessary. b. Indicators that are flat, or do not extend out of the wear indicator sleeve, may not be deferred and brake must be replaced prior to flight

9 **Left Main Landing Gear Wheels and Tires**

a. Check LH MLG wheels for general condition. Ref. AMM Task 32-49-02-200-801 b. Check LH MLG tires for wear and general condition. Ref. AMM Task 32-49-01-200-802-A i. If tread depth is worn to the bottom of any groove at the point of maximum wear around the tire circumference, replace tire ii. If tread depth is less than 1/32" but above flush at the point of maximum wear around the tire circumference, replace tire. If tire not available, replacement may be deferred for a maximum of 10 cycles or at the next RON, whichever occurs first. Contact MOC for deferral. iii. Refer to AMM task for tread cut limits

10 **Hydraulic Quantity**

****NOTE: Ensure you fully release the pressure from the hydraulic systems prior to servicing.**** a. Check Hydraulic System No. 1 and 2 fluid levels on the MFD hydraulic synoptic page. At a minimum, ensure QTY is halfway into the green band. ***If servicing is required, make an Aircraft Discrepancy Log entry

JSX

5616 Haven St. Suite A, ATTN: JSX PARTS
Las Vegas, NV, US, 89119
AMO: Attn. Parts

**N950JX**
EMB-145LR
SN 145640

Work Order / Plan No.
Service Center

## CUS-0004 - Line Service Check + TPC checks combined (Continued)

### Checklist

**CUS-0004**
**Line Service Check + TPC checks combined**

**1. RE A/R**

Step info

| | | Complete |
|---|---|---|
| 11 | **Crew Oxygen**<br>a. Visually check crew oxygen pressure is above 1600 PSI. i. System above 1600 (Check) Yes ✓ No_____ ii. If system is below 1600 PSI, service crew oxygen pressure to 1850 psi per AMM Task 12-14- 00-600-801. If servicing is required, make an Aircraft Discrepancy Log entry. | ☑ |
| 12 | **Left and Right MLG Tire Inflation Pressure** MRB Task 32-49-01-610-001-A00<br>LANDING GEAR - Check MLG Tire Inflation Pressure - [SVC] If tires are serviced, make an entry in Traxxall documenting original tire pressure and adjusted tire pressure. | ☑ |
| 13 | **NLG Tire Inlation Pressure** MRB Task 32-49-04-610-001-A00<br>LANDING GEAR - Check NLG Tire Inflation Pressure - [SVC] If tires are serviced, make an entry in Traxxall documenting original tire pressure and adjusted tire pressure. | ☑ |
| 14 | **FINAL**<br>a. Audit Work Card to ensure header information is complete and all line items are initialed. The technician completing the Line service check shall enter his/her signature, printed name, cert type and number, initials and date below. If more than one technician has completed the line service check please enter their information in the additional lines. b. Document accomplishment of Service Check in the Aircraft Discrepancy Log Block 2 "Line Service Check" section. Enter Signature, Cert type & number, Date & time, and airframe time. | ☑ |

Accepted Technical Publications Status: No technical publications attached
Zone: , Access:

| Compliance A/F (145640) | Mos | Hrs | Ldg | Other |
|---|---|---|---|---|
| | 23/09/2024 | 38,890.39 | 31217 | |

Compliance Notes: Added 1Qt (2 pints) to R/H engine.
Added 1Qt (2pints) to L/H engine.

Cost:

Man Hrs.: 2 HRS

Technician Name: Nathan Acuna
License: CRS K5SR339N
Signature:

Inspector Name: Samuel I. Perez Bautista
License: CRS K5SR339N
Signature:

JSX

5616 Haven St. Suite A, ATTN: JSX PARTS
Las Vegas, NV, US, 89119
AMO: Attn. Parts

**N950JX**
EMB-145LR
SN 145640

Work Order / Plan No. SLCMX-687
Service Center Elevate MRO

**0JX-240921-417** **A/F (145640)**

Reference No.:MEL 21-51-00 Cond 3

During descent, PACK 2 OVHT EICAS message displayed. Followed QRH and message resolved. PACK 2 OVHT message displayed again on final approach. During climb out, noticed bleed 2 temperatures slower to rise to normal temperatures.

21-50 - Snag

(Date reported: 21-Sep-2024), (Reported by: Hudson Bebo, Title: Pilot), (Event category: En Route), (Reported severity: Minor), (Leg Information: 977 BUR-BJC, 1)(Classification date: 21-Sep-2024), (Recorded by: Seacott, Shane, Title: Administrator), (Operational restrictions: )

Task: Discrepancy Req: Mel - Cat. C

Mel - Cat. C

| Requirement | Due |
|---|---|
| Mos | [01-Oct-2024] |
| Hrs | |
| Ldg | |

Accepted Technical Publications Status: No technical publications attached
Zone: , Access:

| Compliance A/F (145640) | Mos | 23/Sep/2024 | Hrs | 38,890.39 | Ldg | 31217 | Other | |
|---|---|---|---|---|---|---|---|---|

Action Taken Troubleshot MEL 21-51-00 Cond 3 'PACK 2 OVHT' EICAS message in reference to Embraer 145 FIM Chapter 21-51-00-810-804A. No fault found and cleared MEL.

Cost

Man Hrs. 7.0

| Component Description | P/N OFF | S/N OFF |
|---|---|---|
| N/A | N/A | N/A |
| | P/N ON | S/N ON |
| | N/A | N/A |

| Component Description | P/N OFF | S/N OFF |
|---|---|---|
| N/A | N/A | N/A |
| | P/N ON | S/N ON |
| | N/A | N/A |

Technician Name: Nathan Acuna
CRS K55R339N
License
Signature

Inspector Name: Samuel I. Perez Bautista
FAA CRS K55R339N
License
Signature

WCTP864216S-09/2024

JSX

5616 Haven St. Suite A, ATTN: JSX PARTS
Las Vegas, NV, US, 89119
AMO: Attn. Parts

**N950JX**
EMB-145LR
SN 145640

Work Order / Plan No. SLCMK-681
Service Center Elevate MRO

**0JX-240924-418**

**A/F (145640)**

Task: Discrepancy Req: AOG

AOG

LH Engine REQ OIL

| Requirement | Due |
|---|---|
| Mos | [23-Sep-2024] |
| Hrs | |
| Ldg | |

12-20 - Snag

(Date reported: 23-Sep-2024), (Reported by: Abera, Beniam, Title: CAMO), (Event category: Maintenance Find) (Classification date: 23-Sep-2024), (Recorded by: Abera, Beniam, Title: Technician), (Operational restrictions: )

Accepted Technical Publications Status: No technical publications attached
Zone: , Access:

| Compliance | Mos | Hrs | Ldg | Other |
|---|---|---|---|---|
| A/F (145640) | 23/09/2024 | 38,890.39 | 31,217 | |

Action Taken: Serviced L/H engine with 1qt (2 pints) ~~[illegible]~~ of 2380 turbine oil in reference to EMM 12-10-79-600-801

Cost:

Man Hrs.: .5

| Component Description | P/N OFF | S/N OFF |
|---|---|---|
| | P/N ON | S/N ON |

| Component Description | P/N OFF | S/N OFF |
|---|---|---|
| | P/N ON | S/N ON |

Technician Name: Nathan Hanna

License: CRSK55R339N

Signature:

Inspector Name: Samuel U Perez Baptista

License: FAA CRSK55R339N

Signature:

JSX

5616 Haven St. Suite A, ATTN: JSX PARTS
Las Vegas, NV, US, 89119
AMO: Attn. Parts

**N950JX**
EMB-145LR
SN 145640

Work Order / Plan No. SLC-MX-687
Service Center Elevate MRO

**0JX-240924-419**

**A/F (145640)**

RH Engine REQ OIL

12-20 - Snag

(Date reported: 23-Sep-2024), (Reported by: Abera, Beniam, Title: CAMO), (Event category: Maintenance Find) (Classification date: 23-Sep-2024), (Recorded by: Abera, Beniam, Title: CAMO), (Operational restrictions: )

Task: Discrepancy Req: AOG

AOG

| Requirement | Due |
|---|---|
| Mos | [23-Sep-2024] |
| Hrs | |
| Ldg | |

Accepted Technical Publications Status: No technical publications attached
Zone: , Access:

| Compliance A/F (145640) | Mos | Hrs | Ldg | Other |
|---|---|---|---|---|
| | 23 09 2024 | 38,890.39 | 31,217 | |

Action Taken: Serviced R/H engine with 1qt (2 pints) of 2080 turbine oil in reference to EMM 12-10-79-600-801

Cost:

Man Hrs.: .5

| Component Description | P/N OFF | S/N OFF |
|---|---|---|
| | P/N ON | S/N ON |

| Component Description | P/N OFF | S/N OFF |
|---|---|---|
| | P/N ON | S/N ON |

Technician Name: Nathan Acuna
License: CR5K55R339N
Signature:

Inspector Name: Samuel I. Perez Baptista
License: FAA CR5K55R339N
Signature:

ELEVATE MRO
—AN ELEVATE AVIATION GROUP COMPANY—

# Log Book Entry

237 N 2370 W
Salt Lake City, UT 84116
United States

Telephone: +1 (385) 509-3780 Fax:

23 September, 2024

**Registration #:** N950JX
**Manufacturer:** Embraer
**Part/Model number:** RJ-145
**Work Order No:** SLC-MX687

**Total AC Time:** 38,890.39
**Total AC Cycles:** 31,217.00
**Aircraft Serial Number:** 145640
**Date:** 23-Sep-2024

**Squawk**

**2.1** Performed Line Service Check in reference to JSX line service checklist CUS-0004.

**2.2** Performed external walk-around in reference to JSX line service checklist CUS-004

**2.3** Inspected NLG wheels and tires in reference to Embraer 145 AMM 32-49-05-200-801-A, and AMM 32-49-04-200-802-A.

**2.4** Performed right MLG brake wear indicators inspection in reference to Embraer 145 AMM 32-49-03-200-801-A.

**2.5** Performed right MLG wheels and tires inspection in reference to Embraer 145 AMM 32-49-02-200-801 b, and 32-49-01-200-802-A i.

**2.6** Serviced number RH engine oil with 1 QT 2380Turbine Oil in reference to AE 3007A EMM 12-10-79-600-801

**2.7** Checked APU engine oil as needed in reference to JSX Line Service Check CUS-0004. No oil needed.

**2.8** Serviced number LH engine oil with 1 QT 2380 TurbineOil in reference to AE 3007A EMM 12-10-79-600-801

**2.9** Performed left MLG brake wear indicators inspection in reference to Embraer 145 AMM 32-49-03-200-801-A 8. a.

**2.10** Performed Left MLG wheels and tires inspection in reference to Embraer 145 AMM 32-49-02-200-801 b, and 32-49-01-200-802-A i.

**2.11** Performed Hydraulic Quantity inspection in reference to JSX Line Service Check CUS-0004. Level shows full at present time.

**2.12** Inspected crew oxygen pressure (1700psi) in reference to Embraer AMM 12-14-00-600-801.

**2.13** Inspected left and right MLG tire inflation pressure (169psi) in reference to Embraer AMM 32-49-01-610-001-A00.

**2.14** Inspected NLG tire inflation pressure (106psi) in reference to Embraer AMM 32-49-04-610-001-A00.

**2.15** Troubleshot MEL 21-51-00 Cond 3 PACK 2 OVHT EICAS message in reference to Embraer 145 FIM Chapter 21-51-00-810-804-A. No fault found and cleared MEL.

I certify the airframe, engine and/or component identified herein was repaired and inspected in accordance with the current Elevate MRO Repair Manual System and the Federal Aviation Regulations under which the operator is certified, and was determined to be in an Airworthy Condition at this date and time with regards to the inspection(s) alterations and/or maintenance performed, and is approved for return to service as per those requirements. Pertinent details of the repair(s) are on file at this facility.

Samuel I. Perez Baptista
FAA CRS K5SR339N

These items identified above were repaired and/or inspected in accordance with current Federal Aviation Regulations and the repairs are approved for return to service. Pertinent details of these repairs are on file at the repair station under Work Order Number SLC-MX687.

*** End of Document ***