

All Defects Report



Date 21-5-2024
Date Range 01/01/2024 to 20/05/2024
Client Shangri-La Hotel (Cairns) Pty Ltd Trading As Shangri-La Hotel The Marina Cairns
Contract Shangri-La Hotel (Cairns) Pty Ltd Trading As Shangri-La Hotel The Marina Cairns

FVS Fire Pty Ltd

P.O Box 1204
Springwood 4127 QLD
Australia
ABN: ABN 52 096 882 576
Lic. No. QBCC: 745564

Property Shangri-La Hotel The Marina Cairns

Asset No.	Area / Location	Level	Equipment Type	Defect Description	Status	ID	Date Recorded	Age (Days)	Log Sheet ID	PO Num
				The Telstra 3G network is being disconnected from 30/6/24. The current installed auto dialler is only connected to the 3G network so will cease to operate when the 3G network is disconnected. This quotation allows for it to be replaced with one new 4G Voice & SMS Auto Dialler.	InProgress (Quote ID: 163025)	638625	04/03/2024			SLMCR2400445
				Please Note: Upon approval, client is to provide a suitable Sim Card to be installed into the auto dialler so it can send messages, and the contact numbers they require adding into the auto dialler.						
Exit & Emergency Lighting Single Point System										
8	Mezzanine offices	Retail mezzanine	Legrand Recessed Bladelight	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629280	08/01/2024	134		
9	Mezzanine offices	Retail mezzanine	Stanilite Recessed Spitfire	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629281	08/01/2024	134		
812	Top main entry stairs	Events	Stanilite Recessed Spitfire	Still faulty	Resolved	629282	08/01/2024			
853	Inside entry door to toilet corridor	Events	Stanilite Recessed Spitfire	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629283	08/01/2024	134		

Asset No.	Area / Location	Level	Equipment Type	Defect Description	Status	ID	Date Recorded	Age (Days)	Log Sheet ID	PO Num
844	Marlin II	Events	Stanilite Quickfit	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629284	08/01/2024	134		
823	Above double doors to staff offices	Events	Legrand Recessed Bladelight	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved (Quote ID: 152463)	629285	08/01/2024			
219	Entry executive offices	Retail mezzanine	Stanilite Recessed Spitfire		Resolved	629286	08/01/2024			
229	Female toilet	Retail mezzanine	Stanilite Recessed Spitfire	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	629287	08/01/2024			
4	Mezzanine offices corridor outside office	Retail mezzanine	Stanilite Recessed Spitfire	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629288	08/01/2024	134		
226	Toilet passage	Retail mezzanine	Stanilite Quickfit	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629289	08/01/2024	134		
61F	Corridor to engineering office	Engineering	Stanilite Recessed Spitfire	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629290	08/01/2024	134		
875	Balcony pillar adjacent Hurney Partners	Retail mezzanine	Stanilite Recessed Spitfire	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629291	08/01/2024	134		
149C	Outside 1013	L1	Clevertronics Recessed Spitfire	Failed 90 minute discharge test	Quoted (Quote ID: 166509)	629477	08/01/2024	134		
120	Adjacent tenant switchboard	Commonwealth offices	Stanilite Econofit Exit	Ignition key missing unable to test lights requires new key	Quoted (Quote ID: 166509)	629478	08/01/2024	134		
121	Kitchen	Commonwealth offices	Stanilite Econofit Exit	Ignition key missing unable to test lights requires new key	Quoted (Quote ID: 166509)	629479	08/01/2024	134		
122	Open area	Commonwealth offices	Stanilite Econofit Exit	Ignition key missing unable to test lights requires new key	Quoted (Quote ID: 166509)	629480	08/01/2024	134		
123	Open area	Commonwealth offices	Stanilite Recessed Spitfire	Ignition key missing unable to test lights requires new key	Quoted (Quote ID: 166509)	629481	08/01/2024	134		
124	Adjacent fire extinguisher #33	Commonwealth offices	Stanilite Recessed Spitfire	Ignition key missing unable to test lights requires new key	Quoted (Quote ID: 166509)	629482	08/01/2024	134		
268	Adjacent exit to north tower walkway	Plantroom	Haneco Vista 20w	Failed 90 minute discharge test	Quoted (Quote ID: 166509)	629598	09/01/2024	133		

Asset No.	Area / Location	Level	Equipment Type	Defect Description	Status	ID	Date Recorded	Age (Days)	Log Sheet ID	PO Num
274	Above switchboard H3C	Plantroom	Haneco Vista 20w	Failed 90 minute discharge test	Quoted (Quote ID: 166509)	629599	09/01/2024	133		
279	Door stair 11	Plantroom	Stanilite Economy Slide Connect	Failed 90 minute discharge test	Quoted (Quote ID: 166509)	629600	09/01/2024	133		
252	LMR	Plantroom	Stanilite Quickfit	Failed 90 minute discharge test	Quoted (Quote ID: 166509)	629601	09/01/2024	133		
2B	Male toilet adjacent main exit to marina	Ground retail	Stanilite Recessed Spitfire	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629697	08/01/2024	134		
119	Public disabled toilet	Ground retail	Stanilite Recessed Spitfire	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629698	08/01/2024	134		
113	Public toilet corridor	Ground retail	Stanilite Recessed Spitfire	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629699	08/01/2024	134		
76A	Rubbish compactus above MCP	Ground BOH	Stanilite Weatherproof Maintained Batten	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629700	08/01/2024	134		
109	Lift foyer	Reception	Stanilite Economy Slide Connect	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629701	08/01/2024	134		
102	Reception foyer entry from wharf	Reception	Stanilite Quickfit	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629702	08/01/2024	134		
76B	Ground passageway baby changeroom	Stair 3	Clevertronics Recessed Spitfire	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629703	08/01/2024	134		
37	Ground exit to esplanade	Stair 6	Stanilite Weatherproof w/ Sensor Maintained Batten	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629704	08/01/2024	134		
CPA13	Fire exit tunnel adjacent carpark 48	Carpark	Stanilite Quickfit	Still faulty	Resolved	629705	09/01/2024			
CPA5	Entry stair 9	Carpark	Stanilite Quickfit	Still faulty	Resolved	629706	09/01/2024			
121	Ground to carpark	Stair 9	Stanilite Quickfit	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629707	09/01/2024	133		
160B	Disused corridor from loading dock to g Horizon	Engineerin g	Stanilite Quickfit	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629708	09/01/2024	133		

Asset No.	Area / Location	Level	Equipment Type	Defect Description	Status	ID	Date Recorded	Age (Days)	Log Sheet ID	PO Num
393	Top of stairs	Stair 10	1x36W Fluoro Bare w/ Wire Guard Cage Maintained E/tronic	Still faulty	Resolved	629709	09/01/2024			
394	Exit to engineering	Stair 11	Stanilite Quickfit	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629710	09/01/2024	133		
272	L2/plantroom	Stair 9	1x36W Fluoro Bare w/ Wire Guard Cage Maintained E/tronic	Still faulty	Resolved	629711	09/01/2024			
175	Lift foyer adjacent window overlooking foyer	Ballroom	Stanilite Economy Slide Connect	Failed 90 minute discharge test	Quoted (Quote ID: 166509)	629848	10/01/2024	132		
198	Shangri-La I	Ballroom	Stanilite Recessed Spitfire	Failed 90 minute discharge test	Quoted (Quote ID: 166509)	629849	10/01/2024	132		
193	Shangri-La I	Ballroom	Stanilite Recessed Spitfire	Failed 90 minute discharge test	Quoted (Quote ID: 166509)	629850	10/01/2024	132		
221	Male toilet	Ballroom	Stanilite Recessed Spitfire	Failed 90 minute discharge test	Quoted (Quote ID: 166509)	629851	10/01/2024	132		
216A	Kitchen outside chemical store	Ballroom	Stanilite Recessed Spitfire	Failed 90 minute discharge test	Quoted (Quote ID: 166509)	629852	10/01/2024	132		
214	Kitchen	Ballroom	Stanilite Quickfit	Failed 90 minute discharge test	Quoted (Quote ID: 166509)	629853	10/01/2024	132		
137	Kitchen exit to accomodation	L1	Stanilite Quickfit	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629878	10/01/2024	132		
160E	Disused corridor from loading dock	Engineerin g	18w Fluro Single	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629879	10/01/2024	132		
131	Kitchen adjacent toilets	L1	Stanilite Quickfit	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	629880	10/01/2024	132		
54	Outside room 43	Horizon	Clevertronics Recessed Spitfire	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	629881	10/01/2024			
93	Room 11	Horizon	Clevertronics Recessed Spitfire	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	629882	10/01/2024			
92	Room 12	Horizon	Clevertronics Recessed Spitfire	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	629883	10/01/2024			

Asset No.	Area / Location	Level	Equipment Type	Defect Description	Status	ID	Date Recorded	Age (Days)	Log Sheet ID	PO Num
66	Room 38	Horizon	Clevertronics Recessed Spitfire	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	629884	10/01/2024			
FIP1	Retail FIP panel	External	2x18W Fluoro Bare Maintained		Resolved	629922	10/01/2024			
252	LMR	Plantroom	Stanilite Quickfit	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	643665	04/04/2024		N/A	
264	Door stair 5	Plantroom	Stanilite Quickfit	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	643666	04/04/2024		N/A	
268	Adjacent exit to north tower walkway	Plantroom	Haneco Vista 20w	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	643667	04/04/2024		N/A	
274	Above switchboard H3C	Plantroom	Haneco Vista 20w	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	643668	04/04/2024		N/A	
269	North end adj door to rooftop walkway	Plantroom	Haneco Vista 20w	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	643669	04/04/2024		N/A	
267	Above doorway in block wall adjacent stair 6	Plantroom	Stanilite Quickfit	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	643670	04/04/2024		N/A	
262	Adj DB H3B	Plantroom	Haneco Vista 20w	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	643671	04/04/2024		N/A	
263A	Door stair 4	Plantroom	Stanilite Quickfit	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	643672	04/04/2024		N/A	
257	Adj AHU H3-1	Plantroom	Haneco Vista 20w	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	643673	04/04/2024	47	N/A	
251D	Adj Main Lobby A/C unit	Plantroom	Haneco Vista 20w	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	643674	04/04/2024	47	N/A	
248	Above switchboard H3-7	Plantroom	Haneco Vista 20w	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	643675	04/04/2024	47	N/A	
261	Adj KEF R3-2	Plantroom	Haneco Vista 20w	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	643676	04/04/2024		N/A	

Asset No.	Area / Location	Level	Equipment Type	Defect Description	Status	ID	Date Recorded	Age (Days)	Log Sheet ID	PO Num
393	Top of stairs	Stair 10	1x36W Fluoro Bare w/ Wire Guard Cage Maintained E/tronic	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	648163	02/05/2024		N/A	
272	L2/plantroom	Stair 9	1x36W Fluoro Bare w/ Wire Guard Cage Maintained E/tronic	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	648164	02/05/2024		N/A	
394	Exit to engineering	Stair 11	Stanilite Quickfit	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	648165	02/05/2024		N/A	
37	Generator Room	Services	2x36W Fluoro Bare Maintained E/tronic	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	648166	02/05/2024		N/A	
279	Door stair 11	Plantroom	Stanilite Economy Slide Connect	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	648167	02/05/2024		N/A	
250A	Outside LMR adjacent stair 11	Plantroom	Haneco Vista 20w	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	648168	02/05/2024		N/A	
37	Ground exit to esplanade	Stair 6	Stanilite Weatherproof w/ Sensor Maintained Batten	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	648169	02/05/2024		N/A	
121	Ground to carpark	Stair 9	Stanilite Quickfit	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	648170	02/05/2024		N/A	
CPA5	Entry stair 9	Carpark	Stanilite Quickfit	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	648246	02/05/2024		N/A	
CPA13	Fire exit tunnel adjacent carpark 48	Carpark	Stanilite Quickfit	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Resolved	648247	02/05/2024		N/A	
CPA4	Adjacent carpark 101	Carpark	Stanilite Quickfit	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	648393	02/05/2024	19	N/A	
74A	Walkway lobby to retail	Ground retail	Stanilite Recessed Spitfire	Light fitting failed 90 minute discharge test and requires replacing with new fitting to comply with AS2293.2.	Quoted (Quote ID: 166509)	648394	02/05/2024	19	N/A	
Fire Doorsets - Hinged & Pivoted										
167	S/Well 3 L 1 Door		Fire Doorset Hinged & Pivoted	Door stop device required.	Resolved	647741	30/04/2024		N/A	
182	S/Well 5 L 1 Door		Fire Doorset Hinged & Pivoted	Door has minor damage at edge of door near lock set. Repair damage with fire rated filler.	Resolved	647742	30/04/2024		N/A	
244	L 1 Events Access Door		Fire Doorset Hinged & Pivoted	Excessive gap under door. Install FDBU20 door seal to bottom of door to bridge gap between door and floor.	Resolved	647743	30/04/2024		N/A	
188	S/Well 6 Mez Door	Toilet passageway	Fire Doorset Hinged & Pivoted	Striker plate missing	Resolved	647744	30/04/2024		N/A	

Asset No.	Area / Location	Level	Equipment Type	Defect Description	Status	ID	Date Recorded	Age (Days)	Log Sheet ID	PO Num
188	S/Well 6 Mez Door	Toilet passageway	Fire Doorset Hinged & Pivoted	Fire door is missing the travel limiting device and requires one new travel limiting device in accordance with AS1851-2012.	Resolved	647745	30/04/2024		N/A	
194	S/Well 7 L2 Door		Fire Doorset Hinged & Pivoted	Door stop is required	Resolved	647746	30/04/2024		N/A	
189	S/Well 6 L2 Door		Fire Doorset Hinged & Pivoted	Latch strike plate missing from frame. Install standard strike to frame.	Resolved	647747	30/04/2024		N/A	
189	S/Well 6 L2 Door		Fire Doorset Hinged & Pivoted	Door stop is required.	Resolved	647748	30/04/2024		N/A	
183	S/Well 5 L2 Door		Fire Doorset Hinged & Pivoted	Gap too wide lock side bottom up approximately 1470mm of intermittent strip required	Resolved	647749	30/04/2024		N/A	
183	S/Well 5 L2 Door		Fire Doorset Hinged & Pivoted	Striker plate missing a screw	Resolved	647750	30/04/2024		N/A	
176	S/Well 4 L2 Door		Fire Doorset Hinged & Pivoted	Strike plate missing from frame. Install new strike plate.	Resolved	647751	30/04/2024		N/A	
176	S/Well 4 L2 Door		Fire Doorset Hinged & Pivoted	Door closer needs to be remounted to Door	Quoted (Quote ID: 166512)	647752	30/04/2024	21	N/A	
153	S/Well 2 L2 Door		Fire Doorset Hinged & Pivoted	Gap too wide hinge side from top down, approximately 1000mm of intermittent strip is required.	Resolved	647753	30/04/2024		N/A	
153	S/Well 2 L2 Door		Fire Doorset Hinged & Pivoted	Door closer is leaking oil needs to be replaced with new closer	Resolved	647754	30/04/2024		N/A	
159	S/Well 2 Roof Door 2		Fire Doorset Hinged & Pivoted	Gap too wide lock side approximately 2050mm of intermittent strip required	Resolved	647755	30/04/2024		N/A	
159	S/Well 2 Roof Door 2		Fire Doorset Hinged & Pivoted	Door has delaminated at bottom hinge. Replace door and reuse handle set and closer. 2040 x 920 x 47 Ply face 2050mm of intermittent strip required	Resolved	647756	30/04/2024		N/A	
158	S/Well 2 Roof Door 1		Fire Doorset Hinged & Pivoted	Door has delaminated at bottom hinge. Replace door and reuse lock set and closer. 2040 x 920 x 47 Ply face	Resolved	647757	30/04/2024		N/A	
156	Roof Ceiling Access 1		Fire Doorset Hinged & Pivoted	Hole in frame	Resolved	647758	30/04/2024		N/A	
152	L2 Stair 2 behind lifts		Fire Doorset Hinged & Pivoted	Gap too wide hinge side from top down, approximately 1000mm of intermittent strip required.	Resolved	647759	30/04/2024		N/A	
203	S/Well 8 Roof Door		Fire Doorset Hinged & Pivoted	Edge of door leaf damaged around lock. Repaire damage with fire rated filler.	Resolved	647760	30/04/2024		N/A	
212	S/Well 9 Roof Door		Fire Doorset Hinged & Pivoted	Edge of door leaf damaged around lock. Repaire damage with fire rated filler.	Resolved	647761	30/04/2024		N/A	
229	S/Well 11 Roof Door		Fire Doorset Hinged & Pivoted	Top of door requires approximately 1mt of intermittent strip.	Resolved	647762	30/04/2024		N/A	
229	S/Well 11 Roof Door		Fire Doorset Hinged & Pivoted	Striker plate missing	Resolved	647763	30/04/2024		N/A	

Asset No.	Area / Location	Level	Equipment Type	Defect Description	Status	ID	Date Recorded	Age (Days)	Log Sheet ID	PO Num
230	S/Well 11 L2 Door	Beside goods lift Banquet area	Fire Doorset Hinged & Pivoted	Holes in door from previous hardware	Resolved	647764	30/04/2024		N/A	
271	Horizon club entry from staff area	Mez adj staff lunch room	Fire Doorset Hinged & Pivoted		Resolved	647765	30/04/2024		N/A	
202	S/Well 8 L2 Door		Fire Doorset Hinged & Pivoted	Door stop device is required	Resolved	647766	30/04/2024		N/A	
245	Mezz Events Access 1	From loading dock	Fire Doorset Hinged & Pivoted	Locksets and latches, closers and pivots, hinges and sequence selectors Description: Door leaf selector broken and not holding door. Replace with new 305mm leaf selector.	Resolved	648012	01/05/2024		N/A	
187	S/Well 6 Mezz Door (1)	Near event centre	Fire Doorset Hinged & Pivoted	Lock set missing escutcheon cover for cylinder. Install new escutcheon.	Resolved	648013	01/05/2024		N/A	
164	Mezz Plantroom Corridor		Fire Doorset Hinged & Pivoted	Large gap between tongue/door & frame	Resolved	648014	01/05/2024		N/A	
240	Event Centre Office 2	Beside sales office	Fire Doorset Hinged & Pivoted	Door leaf selector broken and not holding door. Replace with new 305mm leaf selector.	Resolved	648015	01/05/2024		N/A	
240	Event Centre Office 2	Beside sales office	Fire Doorset Hinged & Pivoted	Meeting styles have been damaged and preventing door from closing. Replace meeting styles with Pryo Panel brand meeting styles at 3000mm long.	Resolved	648016	01/05/2024		N/A	
179	S/Well 5 Switch Room RMA	Mez from function rooms	Fire Doorset Hinged & Pivoted	Fire door is splitting around the lock, new fire door required. 2100x895x450	Resolved	648017	01/05/2024		N/A	
173	S/Well 4 Events Access		Fire Doorset Hinged & Pivoted	Head gap; Due to an excessive head gap door requires a seal in accordance with AS1851-2012.	Resolved	648018	01/05/2024		N/A	
286	Horizon Dock Access to loading dock		Fire Doorset Hinged & Pivoted	Holes in frame from previous hardware	Resolved	648019	01/05/2024		N/A	
273	Level M adj rm 17	From Horizon club side	Fire Doorset Hinged & Pivoted	Door has no travel limiting device causing door handle to hit wall. Install travel limiting device	Resolved	648020	01/05/2024		N/A	
274	Level M adj rm 21		Fire Doorset Hinged & Pivoted	Door has no travel limiting device causing door handle to hit wall. Install travel limiting device	Quoted (Quote ID: 166512)	648021	01/05/2024	20	N/A	
276	Horizon Fire Exit 3 (2)		Fire Doorset Hinged & Pivoted	No certification tags present on door. If original installer can't be contacted to supply certification documentation or install certification tags then a new fire door is required	Resolved	648022	01/05/2024		N/A	
276	Horizon Fire Exit 3 (2)		Fire Doorset Hinged & Pivoted	Door requires a travel limiting device.	Resolved	648023	01/05/2024		N/A	
218	S/Well 10 Mezz Door		Fire Doorset Hinged & Pivoted	A door stopper is required	Resolved	648024	01/05/2024		N/A	
199	S/Well 8 Internal Exit Ground		Fire Doorset Hinged & Pivoted	Hole in door next to closer	Resolved	648025	01/05/2024		N/A	

Asset No.	Area / Location	Level	Equipment Type	Defect Description	Status	ID	Date Recorded	Age (Days)	Log Sheet ID	PO Num
263	Car Park Air Plenum 2	1	Fire Doorset Hinged & Pivoted	Gap too wide lock side, approximately 1m of intermittent strip required.	Resolved	648026	01/05/2024		N/A	
64	L1 Kitchen Access Door 197		Fire Doorset Hinged & Pivoted	Holes in frame, required to be filled	Resolved	648027	01/05/2024		N/A	
262	Car Park Air Plenum 1		Fire Doorset Hinged & Pivoted	Excessive gap between door and frame above latch, fire rated seal required. Must be 1000mm long	Resolved	648028	01/05/2024		N/A	
270	Car Park Door 3		Fire Doorset Hinged & Pivoted	Fire door has begun to delaminate near bottom hinge, new fire door required 2000x1145x500	Resolved	648029	01/05/2024		N/A	
208	Ground Toilet Access	Ground	Fire Doorset Hinged & Pivoted	No door signage fitted, requires 'fire safety door do not obstruct do not keep open' sign in accordance with the Australian Standards.	Resolved	648030	01/05/2024		N/A	
247	Ground retail into F/E3		Fire Doorset Hinged & Pivoted	Holes in door internally require rectification, with appropriate fire retardant.	Resolved	648031	01/05/2024		N/A	
258	Car Park S/Well 5A Fire Exit		Fire Doorset Hinged & Pivoted	Door frame tag has been painted over.	Resolved	648032	01/05/2024		N/A	
109	L2 Service Door 339		Fire Rated Hatch	Door is delaminating at bottom and no bottom rail left in door. Replace door and reuse mortice lock and closer. 2040 x 820 x 37 Ply face	Resolved	648148	02/05/2024		N/A	
113	L2 Service Door 352	2	Fire Rated Hatch	Gap too wide lock side top down, approximately 190mm of intermittent strip is required.	Resolved	648149	02/05/2024		N/A	
115	L2 Service Door 358	2	Fire Rated Hatch	Gap too wide lock side bottom up approximately 1200mm of intermittent strip required.	Resolved	648150	02/05/2024		N/A	
123	L2 Service Door 383	2	Fire Rated Hatch	Gap is too wide lock side top to bottom, approximately 2055mm of intermittent strip is required.	Resolved	648151	02/05/2024		N/A	
126	L2 Service Door 389	2	Fire Rated Hatch	Closer requires adjustment, door not self latching.	Resolved	648152	02/05/2024		N/A	
89	L2 Service Door 280	2	Fire Rated Hatch	Gap too wide across top of door, approximately 820mm of intermittent strip is required.	Resolved	648153	02/05/2024		N/A	
90	L2 Service Door 281	2 between rooms 2039/2041	Fire Rated Hatch	Unable to unlock door to do inspection, lock to be fixed so inspection can be done.	Resolved	648154	02/05/2024		N/A	
91	L2 Service Door 288	2	Fire Rated Hatch	Gap too wide across top of door, approximately 820mm of intermittent strip required. For defect previously reported, approximately 2055mm of intermittent strip is required.	Resolved	648155	02/05/2024		N/A	
17	L1 Service Door 45	1	Fire Rated Hatch	Gap too wide top of door lock side top down approximately 210mm of intermittent strip required.	Resolved	648156	02/05/2024		N/A	
22	L1 Service Door 62	1	Fire Rated Hatch	Holes in frame beside closer plate.	Resolved	648157	02/05/2024		N/A	
28	L1 Service Door 86	1	Fire Rated Hatch	Door frame tag has been painted over	Resolved	648158	02/05/2024		N/A	

Asset No.	Area / Location	Level	Equipment Type	Defect Description	Status	ID	Date Recorded	Age (Days)	Log Sheet ID	PO Num
71	L2 Service Door 2003	2	Fire Rated Hatch	Gap too wide lock side top down, approximately 2050mm of intermittent strip is required.	Resolved	648159	02/05/2024		N/A	
72	L2 Service Door 2007	2	Fire Rated Hatch	Gap too wide lock side top down, approximately 2050mm of intermittent strip is required.	Resolved	648160	02/05/2024		N/A	
78	L2 Service Door 233	2	Fire Rated Hatch	Gap too wide across top of door, approximately 830mm if intermittent strip is required. Gap too wide hinge side from top down, approximately 1720mm of intermittent strip is required.	Resolved	648161	02/05/2024		N/A	
77	L2 Service Door 232	2	Fire Rated Hatch	Gap too wide lock side top down, approximately 260mm of intermittent strip is required.	Resolved	648162	02/05/2024		N/A	
46	L1 Service Door 141	1	Fire Rated Hatch	Gap too wide top of door from lock side approximately 300mm of intermittent strip required.	Resolved	648210	02/05/2024		N/A	
49	L1 Service Door 151	1	Fire Rated Hatch	Gap too wide hinge side on top of door, approximately 420mm of intermittent strip required.	Resolved	648211	02/05/2024		N/A	
60	L1 Service Door 185	1	Fire Rated Hatch	Holes in frame from previous hardware	Resolved	648212	02/05/2024		N/A	
288	Compactor Lift Lobby 2		Fire Doorset Hinged & Pivoted	Door selector requires replacement	Quoted (Quote ID: 166512)	648380	02/05/2024	19	N/A	
288	Compactor Lift Lobby 2		Fire Doorset Hinged & Pivoted	Damage has been done to doors, possibly can fix with appropriate fire retardant.	Quoted (Quote ID: 166512)	648381	02/05/2024	19	N/A	
66	L2 BOH Lift Lobby 2	2	Smoke Door - Even Pair - SD	Door selector is required	Resolved	648385	02/05/2024		N/A	
66	L2 BOH Lift Lobby 2	2	Smoke Door - Even Pair - SD	Holes in top of frame requires rectification.	Resolved	648386	02/05/2024		N/A	
66	L2 BOH Lift Lobby 2	2	Smoke Door - Even Pair - SD	Doors have excessive damage on hinge side and will require replacing. Reuse Lock set and door closers 2040 x 1850 x 47 Ply face	Resolved	648387	02/05/2024		N/A	
68	L2 Service Riser B	2	Fire Rated Hatch	: Excessive gap between door and frame, fire rated seal required, must be 2040mm long	Resolved	648388	02/05/2024		N/A	
68	L2 Service Riser B	2	Fire Rated Hatch	Fire door needs a new saba 876 closer and has a Non-compliant door looks	Resolved	648389	02/05/2024		N/A	
67	L2 Service Riser A	2	Fire Rated Hatch	Excessive gap between door and frame, fire rated seal required, must be 2040mm long.	Quoted (Quote ID: 166512)	648390	02/05/2024	19	N/A	
67	L2 Service Riser A	2	Fire Rated Hatch	Fire door needs a new saba 876 closer and has a Non-compliant door looks	Quoted (Quote ID: 166512)	648391	02/05/2024	19	N/A	

Asset No.	Area / Location	Level	Equipment Type	Defect Description	Status	ID	Date Recorded	Age (Days)	Log Sheet ID	PO Num
70	L2 Communications 1 Adj Room 2044	2	Fire Doorset Hinged & Pivoted	No access to fire door during routine maintenance	Resolved	648392	02/05/2024		N/A	
Fire Doorsets - Horizontal Sliding										
293	Sliding Door next to The Backyard		Fire Doorset Horizontal Sliding	HOME LOGOUT - RECORD ID 882961 Routine Activity - Check Defects Cancel Checking Defects Defects ID Detected Period 443133 11/08/2020 Prompt: Description: Fire Door is not sliding on pulleys/cables correctly and is rubbing/binding on the floor, there are no recessed handles built into the door and there is no signage on the door. This price allows for technician to carry out the following scope of works: - Install two new long sliding fire door signs for above the door - Install two new short sliding fire door signs for the face of the doors - Install two new flush pull handles for each face of the door - Carry out adjustments to the sliding of the door to ensure it begins to slide freely Please Note: In the event that the adjustment of the door does not prevent the rubbing/binding, FVS will provide further quotation for repairs.	Resolved	648382	02/05/2024		N/A	
293	Sliding Door next to The Backyard		Fire Doorset Horizontal Sliding	No certification tags present on door. If original installer can't be contacted to supply certification documentation or install certification tags then a new fire door is required.	Resolved	648383	02/05/2024		N/A	
293	Sliding Door next to The Backyard		Fire Doorset Horizontal Sliding	Fire door magnet is not holding door open, new magnet required. See photo for type of magnetic door holder. Fire door is not self closing, the pulley system is not operational. A quote has been previously provided to rectify issue.	Resolved	648384	02/05/2024		N/A	
Fire Extinguishers										
46	Walkway to Kitchen from Pool.	Level 1	4.5KG AB(E) DCP Extinguisher	Fire extinguisher is due for a 5 yearly service and requires replacing with new extinguisher in accordance with AS1851-2012.	Quoted (Quote ID: 166511)	643813	05/04/2024	46	N/A	
35	Gardeners store top loading dock		4.5KG AB(E) DCP Extinguisher	Fire extinguisher is due for a 5 yearly service and requires replacing with new extinguisher in accordance with AS1851-2012.	Quoted (Quote ID: 166511)	643814	05/04/2024	46	N/A	

Asset No.	Area / Location	Level	Equipment Type	Defect Description	Status	ID	Date Recorded	Age (Days)	Log Sheet ID	PO Num
P51	Main switch room	Mezzanine	9.0KG AB(E) DCP Extinguisher	Fire extinguisher is due for a 5 yearly service and requires replacing with new extinguisher in accordance with AS1851-2012.	Quoted (Quote ID: 166511)	643815	05/04/2024	46	N/A	
P52	Main switch room	Mez	5.0KG C02 Extinguisher	Fire extinguisher is due for a 5 yearly service and requires replacing with new extinguisher in accordance with AS1851-2012.	Quoted (Quote ID: 166511)	643816	05/04/2024	46	N/A	
S5	Main plant rm mezz lvl	Mezzanine	9.0KG AB(E) DCP Extinguisher	Fire extinguisher is due for a 5 yearly service and requires replacing with new extinguisher in accordance with AS1851-2012.	Quoted (Quote ID: 166511)	643817	05/04/2024	46	N/A	
115	LIFT 7 TOP OF STAIRS 10	Sth tower top stairs, middle plant	4.5KG AB(E) DCP Extinguisher	Fire extinguisher is due for a 5 yearly service and requires replacing with new extinguisher in accordance with AS1851-2012.	Quoted (Quote ID: 166511)	643818	05/04/2024	46	N/A	
100A	ROOM 2107	Level 2	2.0KG AB(E) DCP Extinguisher	Fire extinguisher is due for a 5 yearly service and requires replacing with new extinguisher in accordance with AS1851-2012.	Quoted (Quote ID: 166511)	643819	05/04/2024	46	N/A	
107	NEAR WASH BASIN banquet kitchen	Level 2	4.5KG AB(E) DCP Extinguisher	Fire extinguisher is due for a 5 yearly service and requires replacing with new extinguisher in accordance with AS1851-2012.	Quoted (Quote ID: 166511)	643820	05/04/2024	46	N/A	
9	ADJ ROOM 28	Mezzanine	4.5KG AB(E) DCP Extinguisher	Fire extinguisher is due for a 5 yearly service and requires replacing with new extinguisher in accordance with AS1851-2012.	Quoted (Quote ID: 166511)	647620	30/04/2024	21	N/A	
49	ADJ ROOM 45	Mezzanine	4.5KG AB(E) DCP Extinguisher	Fire extinguisher is due for a 5 yearly service and requires replacing with new extinguisher in accordance with AS1851-2012.	Quoted (Quote ID: 166511)	647621	30/04/2024	21	N/A	
307	ROOF SPACE STAIR 6		2.5KG AB(E) DCP Extinguisher	Fire extinguisher is due for a 5 yearly service and requires replacing with new extinguisher in accordance with AS1851-2012.	Quoted (Quote ID: 166511)	647622	30/04/2024	21	N/A	
Cp2a	Carpark	Ground	4.5KG AB(E) DCP Extinguisher	Fire extinguisher is due for a 5 yearly service and requires replacing with new extinguisher in accordance with AS1851-2012.	Quoted (Quote ID: 166511)	647623	30/04/2024	21	N/A	
CP5	Carpark east on post	Carpark	4.5KG AB(E) DCP Extinguisher	Fire extinguisher is due for a 5 yearly service and requires replacing with new extinguisher in accordance with AS1851-2012.	Quoted (Quote ID: 166511)	647624	30/04/2024	21	N/A	
290	Lvl 1 cabinet next lift S/E	Level 1 around from toilets	2.0KG AB(E) DCP Extinguisher	Fire extinguisher requires right angle location signage on corner wall opposite extinguisher in accordance with AS2444. Cupboard also requires Fire Hydrant and Fire Hose Reel word location label on door in accordance with AS2441.	Resolved	647739	30/04/2024		N/A	

Asset No.	Area / Location	Level	Equipment Type	Defect Description	Status	ID	Date Recorded	Age (Days)	Log Sheet ID	PO Num
P8	East entrance switchroom RGC	Nth Ground - Switch rm adj asset P7	2.5KG AB(E) DCP Extinguisher	Fire extinguisher is due for a 5 yearly service and requires replacing with new extinguisher in accordance with AS1851-2012.	Quoted (Quote ID: 166511)	647740	30/04/2024	21	N/A	
SB 1	Switchboard room Behind rubbish compactor area	Ground	4.5KG AB(E) DCP Extinguisher	Fire extinguisher is due for a 5 yearly service and requires replacing with new extinguisher in accordance with AS1851-2012.	Quoted (Quote ID: 166511)	648146	02/05/2024	19	N/A	
4	Function kitchen	Function	3.5KG CO2 Extinguisher	Fire extinguisher is due for a 5 yearly service and requires replacing with new extinguisher in accordance with AS1851-2012.	Quoted (Quote ID: 166511)	648147	02/05/2024	19	N/A	
General Sprinkler & Hydrant Pumpsets										
1			Combined Sprinkler/Hydrant Electric Pumpset	Pump stop switch has been damaged and one must physically open the pump panel to press stop 240 v electrical tech to investigate and fix	Resolved	633228	01/02/2024			
Sound Systems										
4	Shangri La		QE90	During monthly test, did not get sound in lobby area, near reception and the fire panel. This requires further investigation to ascertain cause and corrective action. Please allow \$375 + GST for investigation and \$130 per additional hour. If costs are likely to exceed this amount FVS will contact you and discuss further costs before proceeding. Please note: If replacement parts are required please discuss with client for approval while onsite.	InProgress (Quote ID: 165472)	645789	17/04/2024			SLMCO2400922