

## SRUJANA ENTERPRISES

## PREVENTIVE MAINTENANCE CHECK LIST

| CUSTOMER: <b>MINDA</b>                         |                                                                                                                                                    | PART NAME: <b>TERMINAL Lug</b>                                                                                 | IM-F-05<br>REV.NO.01<br>2024                                   | Date: 23-05- |
|------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|--------------|
| PART NO: <b>00-12-23-088-17</b>                |                                                                                                                                                    | DATE: <b>09/04/26</b>                                                                                          |                                                                |              |
| SL NO                                          | CHECK POINT                                                                                                                                        | CHECKING METHOD                                                                                                | OBSERVATION                                                    |              |
| 1                                              | All Cutting Punches and die insert should be sharp                                                                                                 | Check with Microscope                                                                                          | ALL cutting punches checked<br>blunted punches Resharped       |              |
| 2                                              | Bending punch and die should not be no scoring mark or Damage                                                                                      | Check with Microscope                                                                                          | There is not found any<br>scoring or damage in insert          |              |
| 3                                              | Die insert land should have minimum 0.5mm and Maximum 3.0mm                                                                                        | Check by using pin gauge or slip gauge                                                                         | Die insert Land<br>Observed 2.6 to 2.7mm                       |              |
| 4                                              | Manual Check for lifter spring and lifter pin surface should not be damaged or broken.                                                             | Visual                                                                                                         | Manual checked 2 spring<br>Dimige new spring Replaced          |              |
| 5                                              | Their should not have any damage in ball cage & Ball should rotate freely without any obstruction in cage.                                         | Manual Free rotation check                                                                                     | Manual checked their is<br>not found any obstruction           |              |
| 6                                              | Check relief for slug falling in die back plate and bottom plate - No obstruction & damage for Slug falling.                                       | Visual                                                                                                         | Manual slug cleaned<br>There is not found any obstruction      |              |
| 7                                              | Pilot Sensor - POKA YOKE verification<br>Movement of sensor pin and bending cam or adjuster should be free movement.                               | Manually - Check the spring movement in assembly condition.                                                    | Cross checked sensor pin<br>& spring                           |              |
| 8                                              | Check the Allen bolt Threads and hex gon head no slippages and damage on thread and hexagon area.                                                  | Visual                                                                                                         | No Damage found                                                |              |
| 9                                              | Remove the foreign objects from pilot holes in die plate - Check for clearing of miss feed slug in die plate. If any slug, clear it by Air Blower. | Manual check by Using Air Blower                                                                               | Pilot hole slug are<br>cleared manually                        |              |
| 10                                             | Check air blowing at air ejection pin after assembly. Ensure no blockages in Air ejector tracks by passing Air thru Air blowing connectors.        | Manual check by Using Air Blower                                                                               | air ejection pin checked<br>blockages cleaned done air blowing |              |
| 11                                             | Dowel holes and Dowel pins should not no scoring mark and damage.                                                                                  | Check the surface with microscope.                                                                             | Dowel holes & pin checked<br>No scoring mark & Damage          |              |
| 12                                             | Ensure the tool should be cleaned by Blowing Air while assembly.                                                                                   | Visual                                                                                                         | Tool cleaned by blowing<br>air                                 |              |
| 13                                             | Check all the screws are tightened. Plates and inserts clamped rigidly.                                                                            | Check for tightness of the Screws by Allen key. Visual check for Plates & inserts for Proper clamping in tool. | Cross checked all the screws                                   |              |
| REMARKS                                        |                                                                                                                                                    |                                                                                                                |                                                                |              |
| NOTE                                           |                                                                                                                                                    |                                                                                                                |                                                                |              |
| Preventive maintenance done by: <b>Anand P</b> |                                                                                                                                                    | Verified by: <b>Chelana</b>                                                                                    |                                                                |              |