

SRUJANA ENTERPRISES

PREVENTIVE MAINTENANCE CHECK LIST

CUSTOMER: <i>TE connectivity.</i>		PART NAME: <i>Ring tongue</i>	TM-F-05 REV.NO.01 2024	Date: 23-05-
PART NO: <i>2430010-1</i>		DATE: <i>6/04/26</i>		
SL NO	CHECK PIONT	CHECKING METHOD	OBSERVATION	
1	All Cutting Punches and die insert should be sharp	Check with Microscope	All cutting punches checked blunted punches re-sharpen.	
2	Bending punch and die should not be no scoring mark or Damage	Check with Microscope	There is not found any scoring or damage in inserts.	
3	Die insert land should have minimum 0.5mm and Maximum 3.0mm	Check by using pin gauge or slip gauge	New die insert replaced $\phi 4.40$ Land observed 2.5. to 2.8mm	
4	Manual Check for lifter spring and lifter pin surface should not be damaged or broken.	Visual	Manually checked springs pressure damaged springs replaced.	
5	Their should not have any damage in ball cage & Ball should rotate freely without any obstruction in cage.	Manual Free rotation check	Manually checked there is not found any obstruction	
6	Check relief for slug falling in die back plate and bottom plate - No obstruction & damage for Slug falling.	Visual	Manually slug cleared there is not found any obstruction	
7	Pilot Sensor - POKA YOKE verification Movement of sensor pin and bending cam or adjuster should be free movement.	Manually - Check the spring movement in assembly condition.	Cross checked sensor pin & Spring.	
8	Check the Allen bolt Threads and hex gon head no slippages and damage on thread and hexagon area.	Visual	Damaged screws replaced.	
9	Remove the foreign objects from pilot holes in die plate - Check for clearing of miss feed slug in die plate. If any slug, clear it by Air Blower.	Manual check by Using Air Blower	Pilot hole slugs are cleared manually.	
10	Check air blowing at air ejection pin after assembly. Ensure no blockages in Air ejector tracks by passing Air thru Air blowing connectors.	Manual check by Using Air Blower	In this tool there is not any air ejector provision.	
11	Dowel holes and Dowel pins should not no scoring mark and damage.	Check the surface with microscope.	No need to opnd the dowel.	
12	Ensure the tool should be cleaned by Blowing Air while assembly.	Visual	Tool cleaned by blowing air.	
13	Check all the screws are tightened. Plates and inserts clamped rigidly.	Check for tightness of the Screws by Allen key. Visual check for Plates & inserts for Proper clamping in tool.	Cross checked all the screws.	
REMARKS				
NOTE				
Preventive maintenance done by: <i>A darsh. S. K</i>		Verified by: <i>chetan</i>		