

INDIAN OIL CORPORATION LIMITED // REFINERIES DIVISION

RESTRICTED // FOR OFFICIAL USE ONLY
NOTE FOR APPROVAL (NFA)

File No: IOCL/GHR/HCU-11/NFA/2026-09/042 | Date: 16-September-2026 | Unit: Hydrocracker (HCU-11)
Initiating Department: Inspection & Asset Integrity Division

SUBJECT: Emergency Repair Sanction — Statutory ASME Thickness Breach on 11-V-102 (1st Stage HP Separator Drum)

1. Background & NDT Ultrasonic Survey Defect Discovery

During routine ultrasonic thickness gauging of the 1st Stage High-Pressure Separator (11-V-102), an acute wall thinning anomaly was detected at location **BK-01** (Bottom Knuckle). Base material is **2.25Cr-1Mo + 347 SS cladding**. The field inspector recorded a measured wall thickness of **138.20 mm** against an accelerated corrosion rate of **0.75 mm/yr**.

2. Statutory Code Calculations (ASME Sec VIII Div 1 & API 510)

Verification using the ASME Sec VIII Div 1 UG-27 cylindrical shell formula yielded the following findings:

Parameter / Statutory Metric	Engineering Finding & Status
Design Pressure (P)	14.5 MPa (145.0 barg)
Minimum Required Thickness (t_min)	138.57 mm (ASME UG-27)
Actual Measured Thickness (t_actual)	138.20 mm at Point BK-01
Safety Margin Delta (t_actual - t_min)	-0.37 mm [STATUTORY CODE BREACH]
API 510 Remaining Safe Service Life	-0.49 Years (BELOW ZERO)
Recommended Derated MAWP	144.6 barg (Immediate operational limit)

3. CVC Guidelines & Emergency Procurement Justification

CVC Circular No. 02/02/2004 & DOP Clause 4.2

4. Recommended Action & Financial Sanction

Emergency single-source weld overlay and turnaround replacement.

Estimated Total Expenditure: Rs. 88.0 Lakhs (Covered under Refinery Turnaround Capex Budget Code HCU-2026-CAP).

5. Submission & Approval Block

Prepared By:	Verified By:	Approved By:
Sr. Inspection Engineer Emp ID: 448102	Chief Manager (Integrity) Emp ID: 310294	Executive Director & Refinery Head Competent Financial Authority (DOP 2.1)