Job 2 - On-site Inspection, full job to clearance

Attic. Inspection -> estimate -> remediation -> clearance report -> paid in full

Property	31 Ross St E, Smiths Falls, ON (house, out-of-town area)
Client	Homeowner, selling the house
Service	Scope of Work Assessment (short on-site visit to price the work)
Paid	Visit $95 + HST = $107.35 (paid). Remediation $2,700 + HST = $3,051 (paid)
Booked by	Natasa - client support
Inspector	Luka Markovic, MSC ME, CMI
Report written / reviewed by	Stefan (admin support) / Goran (admin support)
Remediation	Team 2 (out-of-town crew), Tue Sep 22
Follow-up	Close CRM SMS + client support

Why the client called

A home inspector found visible traces of mold, probably in the attic. Booking note: 'Visible traces of mold found by home inspector. They think it is attic in question.' The client later said they are selling the house.

Step by step

When (Eastern)	Step	System	What happened
Tue Sep 1, 2026 10:23	Booking	Google Calendar (MB - Out of Town)	Client support (Natasa) books a 'SoW - OOT' visit (Scope of Work, $95 + tax) for Sep 3, 2-3 PM.
Thu Sep 3, 14:00	Site visit	On site	Inspector visits the house: attic, thermal camera, moisture meter, hygrometer.
Fri Sep 4, 13:43-13:56	Raw notes	Telegram (OTT-GAT & OOT Area Deliverables)	Inspector posts: 'Please send an invoice for $95 + tax', a note about the client expecting a 3-5 h full home inspection for a $95 service, report bullets, 18 photos with captions, and the estimate ($2,700 + tax, 6-8 h). Office replies 'GOOD TO GO!'.
Tue Sep 8	Invoice, report, estimate	FreshBooks + Brain + Asana	Invoice MU767 ($107.35) and estimate MO994 created. Report written and reviewed the same day. Asana card created automatically at 16:43.
Wed Sep 9, 09:20-12:03	Report sent	Asana + email	'Report and estimate prepared, awaiting payment.' Client pays the $107.35 invoice, then the report and estimate are sent.
Fri Sep 11	Client question	Close CRM (SMS)	Client asks if we can also check two other attic areas. Answer: yes, the crew will look while on site; extra work would get a separate estimate.
Mon Sep 14, 11:51-11:58	Client says yes	Close CRM (SMS)	After a follow-up SMS the client replies: 'Yes, we would like MB to remediate the mold issue... How should we proceed?' Support asks them to click Accept on the estimate.
Tue Sep 15	Accepted + deposit	FreshBooks + Close + Asana	Estimate accepted. 40% booking deposit ($1,080) paid. Card moves to 'Active Projects'.
Wed Sep 16 - Thu Sep 17	Upsell	Close CRM (email + SMS)	Email 'Your project is booked - optional add-ons'. SMS offers Whole-Home Treatment for $600 + tax (or $850 later). Client: 'Not useful to us, as we are selling the house'.
Tue Sep 22, 10:00	Remediation	On site (Team 2)	Crew does the attic job. Supervisor takes swab tests; instant swab negative; clearance grade 4 (best).
Wed Sep 23, 09:34	Clearance report + final invoice	Brain + FreshBooks	Project Clearance Report (20 photos: before, during, after) and the final invoice are sent. Card tagged PROJECT COMPLETED.

When (Eastern)	Step	System	What happened
Thu Sep 24, 10:23-10:29	Paid in full + review	FreshBooks + Close (SMS)	Final invoice paid ($3,051 total). Automated SMS asks for a Google review. Second review SMS on Oct 1.

What the inspector found

- Attic: visible discoloration, no rot or structural damage, no moisture problems.
- Only one layer of fiber batt insulation; some soffits blocked by insulation.
- Thermal camera: uneven, disturbed insulation on the ceilings and at the attic hatch.
- Popcorn ceiling that may contain asbestos, with several exposed holes.
- Humidity normal.

Recommendations in the report

- Professional mold remediation
- Bring attic insulation to R-50 and spread it evenly
- Unblock soffits, add baffles for airflow
- Contain the holes in the popcorn ceiling until asbestos testing

Estimate MO994

Amount	$2,700 + 13% HST = $3,051
Project time	6-8 hours
Status	Accepted Sep 15, invoiced (MU815), paid in full Sep 24

- Attic job, main attic about 600 sq ft, hard to access, fiber batt insulation
- Containment at the attic hatch, negative pressure if possible
- Wire-brushing + HEPA vacuum + stain remover on sheathing and trusses; remove bad insulation as needed
- HEPA vacuum + fogging with fungicide, air scrubber for odors
- Clearance: visual check + swab tests by the supervisor, written clearance report

Files in this folder

File	What it is
Report_1_Inspection_redacted.pdf	Inspection report the client received (19 pages)
Report_2_Clearance_after_remediation_redacted.pdf	Project Clearance Report after the work (15 pages)
Estimate_MO994.pdf	The estimate, rebuilt from FreshBooks data
Photos/1_Inspection/ (15 JPG)	Photos from the inspection report, named by caption
Photos/2_Remediation/ (20 JPG)	Before / during / after photos from the clearance report
Raw_notes_from_Telegram.txt	What the inspector posted right after the visit, before any office work
Job_Story.pdf / job_timeline.json	This story, and the same data for code