

PLUMBING FAILURE REPORT

Tideline Mechanical · Our reference TM-2026-0502

INSTRUCTIONS

Instructed by:	Harborcrest Community Management, LLC
On behalf of:	Bayview Terrace Condominium Association, Inc.
Policy number:	
Author:	Ferdinand Achebe-Lindqvist, Master Plumber
Instructed by:	Harborcrest Community Management, LLC
Instructed on:	2 May 2026, 06:40
Site attendance:	2 May 2026
Scope:	Cause of the riser failure and the condition of the remaining risers

BUILDINGS AND UNITS AFFECTED

Community:	Bayview Terrace Condominiums, 96 units in four buildings, built 1998
Building affected:	Building 2 only, 24 units, west stack
Uninhabitable:	2-301, 2-201 and 2-101
Moderate:	2-302, 2-202, 2-102 at the shared demising walls
Common elements:	Central chase, corridors, stairwell landing, sub-panel

PLUMBING FAILURE REPORT

Circumstances and findings

CIRCUMSTANCES

Circumstances:

Four residential buildings of wood frame construction, three storeys, built in 1998, on a single parcel. Each building has a central chase carrying the domestic hot and cold water risers. The failure is in Building 2 between the second and third floors.

FINDINGS

Findings:

The failed section is 2-inch type M copper. The failure initiated as a pinhole on the invert and opened into a longitudinal split approximately 90 mm long. Wall thickness at the failure measures 0.31 mm against a nominal 0.71 mm. The interior surface shows classic hemispherical pitting with tubercles, consistent with pitting corrosion driven by water chemistry over a long period rather than with a discrete event. On opening the chase further, comparable wall thinning was found at two other locations in the same riser. The failed section has been cut out, bagged, labelled and retained in the maintenance room.

Date of loss:	2 May 2026
Cause of loss:	Escape of water — pitting corrosion failure of a copper hot water riser
Incident reference:	BTC-2026-0502
Injuries reported:	0

PLUMBING FAILURE REPORT

Preliminary quantum and reserve advice

PRELIMINARY QUANTUM

Basis:

The figures below are preliminary and are given for reserving purposes only. They are subject to verification and may move as the investigation continues.

Riser repair and chase reinstatement:	USD 46,000
Building repairs, nine units and common areas:	USD 285,000
Cabinetry and flooring:	USD 118,000
Emergency mitigation and drying:	USD 108,000
Storage locker contents, owner property:	USD 34,000
Estimated loss:	697,400
Currency:	USD

ON THE REMAINING RISERS

Comment:

The wall thinning found at two further locations in the Building 2 riser is very likely present in the other three buildings, which were built at the same time with the same material and are on the same water supply. A full riser replacement programme should be planned. That is a capital matter for the association and is not part of this claim.

RECOMMENDATION

Recommendation:

Replace the whole Building 2 hot water riser rather than patching the failed section. Commission a water chemistry assessment before specifying replacement material.