

EMERGENCY MITIGATION REPORT

RestorTech Industrial Services, LLC · Our reference RTI-2026-0447

INSTRUCTIONS

Instructed by:	Talbot & Rennick Insurance Brokers, Inc.
On behalf of:	Harborline Cold Storage & Logistics, LLC
Policy number:	
Author:	Solveig Marchetti-Adeyinka, IICRC CDS
Instructed by:	Harborline Cold Storage & Logistics, LLC
Instructed on:	1 February 2026, 07:35
Site attendance:	1 to 8 February 2026
Scope:	Emergency extraction, drying and contents handling

LOCATION AND PROPERTY AFFECTED

Location:	Delaware terminal — dry storage and cross-dock, 72,500 sq ft
Note:	This is the insured's secondary premises, not the Baltimore cold store
Floor area affected:	31,000 sq ft, standing water to 4 in at the trench drain
Electrical:	Two 480V panels and one MCC, not re-energised
Stock:	214 pallets water-affected, 137 customer-owned

EMERGENCY MITIGATION REPORT

Circumstances and findings

CIRCUMSTANCES

Circumstances:

A single-storey metal frame dry storage and cross-dock building of about 72,500 sq ft, leased by the insured. The client refers to it internally as the Delaware terminal. It is not the Baltimore refrigerated facility and the two should not be confused on the file.

FINDINGS

Findings:

Approximately 118,000 gallons were extracted between 1 and 3 February. Eighty-four air movers, twenty-two LGR dehumidifiers and four desiccant units were required; desiccant was necessary because of ambient temperature. Vinyl-faced blanket insulation was removed from the north and west walls to 8 feet across 340 linear feet as unsalvageable. Contents were segregated at pallet level with every label photographed, because the affected stock is a mixture of the client's own goods and customer-owned goods held under warehousing agreements. A contributing fact is recorded without comment on cover: the dock canopy unit heater serving the area where the line split was tagged out of service on 14 January with a failed ignition module, and the replacement part was on order.

Date of loss:	1 February 2026
Cause of loss:	Freeze — frozen sprinkler branch line
Incident reference:	RTI-2026-0447
Injuries reported:	0

EMERGENCY MITIGATION REPORT

Preliminary quantum and reserve advice

PRELIMINARY QUANTUM

Basis:

The figures below are preliminary and are given for reserving purposes only. They are subject to verification and may move as the investigation continues.

Extraction, 118,000 gallons, and ice removal	USD 50,850 USD 50,850
Drying equipment and technician labour	USD 191,680 USD 191,680
Containment, insulation removal and disposal	USD 45,650 USD 45,650
Contents handling and third-party storage	USD 53,100 USD 53,100
Electrical drying, dock pits, antimicrobial treatment:	USD 65,950 USD 65,950
Estimated loss:	1,240,000
Currency:	USD

ON THE FIRE WATCH AND THE SPRINKLER IMPAIRMENT

Comment:

The split line was isolated by the client's fire protection contractor at 06:40 on 1 February and a continuous fire watch was established at 07:00, maintained until the system was restored to service at 16:20 on 4 February. The local authority was notified. RestorTech did not perform that work and offers no view on the protective safeguards warranty; the log is held by the client.

RECOMMENDATION

Recommendation:

Complete drying before reinstatement. Do not re-energise the panels or the MCC until the client's electrician has meggered and certified them.