

STRUCTURAL ASSESSMENT

Sawtooth Structural Engineering · Our reference SSE-2025-1107

INSTRUCTIONS

Instructed by:	Harkness-Vaillancourt Insurance Agency
On behalf of:	Kestrel Ridge Holdings, LP
Policy number:	CP-9038-64115
Author:	Marielle Okonjo-Sandberg, PE, SE
Instructed by:	Aspenwall Commercial Realty, LLC
Instructed on:	6 November 2025
Site attendance:	6 November 2025, 10:30
Scope:	Whether the entry canopy remains supported and safe for public use

BUILDING AND ELEMENTS AFFECTED

Building:	Building 02, anchor space Suite 200, 31,200 sq ft
Tenant in occupation:	Wilder & Pine Home Goods, lease to 2029
Storefront:	34 lin ft framing, nine glazing panels, two sliding doors
Structural:	One bearing mullion, 26 ft entry canopy shored
Fire protection:	One sprinkler head discharged, 900 sq ft water

STRUCTURAL ASSESSMENT

Circumstances and findings

CIRCUMSTANCES

Circumstances:

Building 02 is a single-storey masonry non-combustible anchor unit built in 2008 with an aluminium storefront system and a projecting entry canopy over the pedestrian approach. The canopy is carried at its outer edge by the storefront mullions, one of which was destroyed by the impact.

FINDINGS

Findings:

The mullion at grid line 3 has been removed by the impact over its full height. It is a bearing element for the canopy above and not, as the storefront supplier's shop drawings suggest, a purely infill member. With it gone the canopy is cantilevered from a connection detailed for a propped condition and is not safe for public use. Temporary shoring was designed and installed on the day of loss. Deflection measured at the canopy leading edge before shoring was 21 mm against a serviceability limit of 8 mm.

Date of loss:	6 November 2025
Cause of loss:	Impact by vehicle — pickup through the anchor storefront
Incident reference:	ACR-2025-1106
Injuries reported:	2

STRUCTURAL ASSESSMENT

Preliminary quantum and reserve advice

PRELIMINARY QUANTUM

Basis:

The figures below are preliminary and are given for reserving purposes only. They are subject to verification and may move as the investigation continues.

Structural repair — mullion, canopy connection, engineering:	USD 118,000 USD 11,000
Storefront framing, glazing and automatic door:	USD 96,000 USD 96,000
Interior vestibule finishes and lighting:	USD 62,000
Bollards, striping, wheel stops, light standards, landscaping:	USD 34,000 USD 34,000
Sprinkler head, fire alarm devices, restoration:	USD 19,000 USD 19,000
Water damage repair to the sales floor:	USD 27,000
Sign band and substrate:	USD 16,000
Estimated loss:	408,500
Currency:	USD

ON THE SHORING AUTHORISATION

Comment:

Emergency shoring cost USD 21,400 against a policy pre-authorisation of USD 15,000. This engineer would not accept an unshored cantilevered canopy over a public entrance overnight, and the alternative was closing the pedestrian approach entirely. Retrospective approval is sought on that basis.

RECOMMENDATION

Recommendation:

Maintain the shoring until the replacement mullion is installed and the canopy connection is reinstated to the propped condition it was detailed for.